

June 13, 2015

42306-01891 Version 13

Safety Recall: Driver's Airbag Inflator Can Be Over-Pressurized

This bulletin is replaced by S/B 15-033, Recall: Driver's Airbag inflator Can Be Over-Pressurized

If you did Service Bulletin 09-093 on or before June 8, 2015. Make sure to use Warranty Claim Information provided below.

WARRANTY CLAIM INFORMATION

Replacing the driver's airbag inflator.

Year/Model	Operation Number	Replacement Part Number	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
2003 3.2CL	7521F4	04770-S5A-305	0.5 hr	5SZ00	R1300	09-033N	06770-S84-A11ZA
	7521F4	04770-S5A-405	0.5 hr	5SZ00	R1300	09-033P	06770-S84-A11ZA
2002-03 3.2TL	7521F4	04770-S5A-305	0.5 hr	5SZ00	R1300	09-033Q	06770-S84-A11ZA
	7521F4	04770-S5A-405	0.5 hr	5SZ00	R1300	09-033R	06770-S84-A11ZA

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.