

June 13, 2015

51971-01938 Version 11

Safety Recall: Replacement Driver's Airbag Inflator Can Be Over-Pressurized

This bulletin is replaced by S/B 15-040, Recall: Driver's Airbag inflator Can Be Over-Pressurized

If you did Service Bulletin 10-039 on or before June 8, 2015. Make sure to use Warranty Claim Information provided below.

WARRANTY CLAIM INFORMATION

The normal warranty applies.

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Failed Part Number
7525A6	Replace the driver's airbag inflator	0.5 hr	5US00	R5400	06770-S84-A11ZA
7525A9	Remove and reinstall the Autoliv airbag.	0.3 hr	5US00	R5400	

Skill Level: Repair Technician

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.