
June 13, 2015

01724-01890 Version 6

Recall: Driver's Airbag Inflator May Produce Excessive Pressure After Long-Term Exposure to High Absolute Humidity

This bulletin is replaced by S/B 15-040, Recall: Driver's Airbag inflator Can Be Over-Pressurized

If you did Service Bulletin 15-022 on or before June 8, 2015. Make sure to use Warranty Claim Information provided below.

WARRANTY CLAIM INFORMATION

The normal warranty applies.

Year/Model	Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Failed Part Number
2008 Pilot	7521H7	Replace the driver's airbag inflator.	0.5 hr	5VJ00	JP700	06770-S9V-A01ZA

Skill Level: Repair Technician

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.