

Part 573 Safety Recall Report**15V-350**

Manufacturer Name : Nova Bus
Submission Date : MAY 28,2015
NHTSA Recall No. : 15V-350
Manufacturer Recall No. : CR3405

**Manufacturer Information :**

Manufacturer Name : Nova Bus
 Address : 1000 Industriel Blvd
 Saint-Eustache Quebec, Canada 00 JR7 5A5
 Company phone : 450-472-6410

Population :

Number of potentially involved : 250
 Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2001-2004 Nova LFS
 Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES
 Body Style : OTHER
 Power Train : DIESEL
 Descriptive Information : Certain 2001-2004 LFS model buses

Selection of vehicles was based on vehicles affected by Service Bulletin BS1352A and Information Letter LI1353A

Production dates are being confirmed

Production Dates : JAN 01, 2001 - DEC 31, 2004

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Description of Defect :

Description of the Defect : Certain air hoses may have been incorrectly connected to the R14 valve. If this occurred, there will be a delay (approximately 1 to 2 seconds) in application of the park brake.

Description of the Safety Risk : This may result in the bus rolling forward or rearward a few feet, which increases the risk of personal injury to occupants entering/ exiting the bus and pedestrians in front of or behind the bus.

Nova Bus has not received reports of personal injury associated with this defect.

Description of the Cause : Potential assembly error.

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

03/25/15 Nova Bus discusses service program with NHTSA at Quarterly meeting

05/19/15 Product Safety Committee determined a safety-related defect exists

05/27/15 Safety -related defect report submitted to NHTSA

Description of Remedy :

Description of Remedy Program : Nova Bus is confirming that all buses were inspected and repaired. Any buses not addressed under service program will be repaired. Owner Notification Letters if required will be provided to NHTSA for review and approval prior to release.

How Remedy Component Differs from Recalled Component : The hose are connect to the correct ports.

Identify How/When Recall Condition was Corrected in Production : n/a

Recall Schedule :

Description of Recall Schedule : Nova Bus is confirming that all buses were inspected and repaired. Any buses not addressed under service program will be repaired. Owner Notification Letters if required will be provided to NHTSA for review and approval prior to release.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported