

June 13, 2015

51971-01939 Version 11

Recall: Driver's Airbag Inflator May Produce Excessive Pressure After Long-Term Exposure to High Absolute Humidity

This bulletin is replaced by S/B 15-040, Recall: Driver's Airbag inflator Can Be Over-Pressurized

If you did Service Bulletin 14-045 on or before June 8, 2015. Make sure to use Warranty Claim Information provided below.

WARRANTY CLAIM INFORMATION

The normal warranty applies.

Year/Model	Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Failed Part Number
2001–02 Accord	7521H1	Replace the driver's airbag inflator.	0.5 hr	5VZ00	JJ500	06770-SDA-A80ZA
2003–07 Accord	7521H1		0.5 hr	5VZ00	JJ500	06770-SDA-A80ZA
2001–05 Civic	7521H1		0.5 hr	5VZ00	JG700	06770-S5A-A10ZA
2001–05 Civic GX	7521H1					
2003–05 Civic Hybrid	7521H1					
2002–06 CR-V	7521H1					
2003–11 Element	7521H1					
2002–04 Odyssey	7521H2		0.5 hr	5VX00	JH000	06770-S0X-A10ZA
2003–07 Pilot	7521H2		0.5 hr	5VX00	JH100	06770-S9V-A01ZA
2006 Ridgeline	7521H2		0.5 hr	5VX00	JH200	06770-SJC-A10ZA
2001–05 Civic	7525A9	Remove and reinstall the Autoliv airbag.	0.3 hr	5VZ00	JG700	06770-S5A-A10ZA

Skill Level: Repair Technician

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.