

June 17, 2015

51970-01893 Version 10

Recall: Driver's Airbag Inflator May Produce Excessive Pressure After Long-Term Exposure to High Absolute Humidity

This bulletin is replaced by S/B 15-033, Recall: Driver's Airbag inflator Can Be Over-Pressurized

If you did Service Bulletin 14-029 on or before June 8, 2015. Make sure to use Warranty Claim Information provided below.

WARRANTY CLAIM INFORMATION

Replacing the driver's airbag inflator.

Year/Model	Operation Number	Replacement Part Number	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
2003 3.2CL	7521H1	04770-S5A-305	0.5 hr	5VZ00	JH300	14-029N	06770-SY8-A90ZA
	7521H1	04770-S5A-405	0.5 hr	5VZ00	JH300	14-029R	06770-SY8-A90ZA
2003-06 MDX	7521H1	04770-S9A-306	0.5 hr	5VZ00	JH400	14-029P	06770-S3V-A20ZB
	7521H1	04770-S9A-405	0.5 hr	5VZ00	JH400	14-029S	06770-S3V-A20ZB
	7521H1	04770-S9A-409	0.5 hr	5VZ00	JH400	14-029T	06770-S3V-A20ZB
2002-03 3.2TL	7521H1	04770-S5A-305	0.5 hr	5VZ00	JH500	14-029Q	06770-S0K-A90ZA
	7521H1	04770-S5A-405	0.5 hr	5VZ00	JH500	14-029U	06770-S0K-A90ZA

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.