

June 25, 2015

02111 Version 1

Safety Recall: A/C Compressor Clutch Bolt

AFFECTED VEHICLES

Year	Model	Trim	VIN range
2014–15	MDX	ALL with 2WD	Check the iN VIN status for eligibility
2014–15	MDX	ALL with SH-AWD	Check the iN VIN status for eligibility

BACKGROUND

As a result of a manufacturing error, the A/C compressor clutch bolt may come loose and fall out or break. If the bolt comes off, the A/C clutch drive plate may also fall off the vehicle while it is being driven.

This bulletin will be revised in the future once the repair procedure, parts information, and warranty claim information are available.

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by “do-it-yourselfers,” and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.