

GM CUSTOMER CARE AND AFTERSALES
DCS3709
URGENT - DISTRIBUTE IMMEDIATELY

Date: July 8, 2015

Subject: 12190B – Safety Recall
Fuel Odor or Spotting on Ground – Inspect Fuel Pump Module
Revised Part Information, Service Procedure, and Warranty
Transaction Information Sections

Models: 2007 Chevrolet Equinox, Pontiac Torrent Originally Sold or
Currently Registered in Arizona, California, Nevada, Texas

2007 Chevrolet Cobalt, Pontiac G5 Originally Sold or Currently
Registered in Arizona, California, Florida, Nevada, Texas

2008 Chevrolet Cobalt, Pontiac G5 Originally Sold or Currently
Registered in Arizona

2009 Chevrolet Cobalt, Pontiac G5 Originally Sold or Currently
Registered in Arkansas, Arizona, California, Nevada, Oklahoma,
Texas

To: All GM Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

The Service Procedure section has been revised for 2007 and 2008 model year Chevrolet Cobalt and Pontiac G5 vehicles. If it is determined that the fuel pump module requires replacement on 2007-2008 Cobalt or G5, dealers are to also replace the fuel tank and fuel tank filler pipe, if necessary. There is no change for 2007-2008 Equinox or Torrent, or 2009 model year vehicles. Please discard all copies of bulletin 12190A.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES