



MAZDA DEALER EMAIL

zoom-zoom

zoom-zoom

zoom-zoom

July 17, 2015

Attention: Mazda Service and Parts Managers

Subject: Safety Recall 8315F – B-Series Passenger Frontal Air Bag Inflator Replacement

Mazda Motor Corporation has decided that a defect which relates to motor vehicle safety exists in 2004-2006 B-series vehicles.

In the subject vehicles, continued exposure to high levels of absolute humidity may cause the front air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the passenger-side frontal air bag. An inflator rupture could result in metal fragments striking and potentially seriously injuring vehicle occupants. Dealers are to replace the passenger frontal air bag inflators of subject vehicles with a new one. The original inflator must be returned to the manufacturer for analysis.

All 2004-2006 model year B-Series trucks nationwide are involved in Safety Recall 8315F for passenger frontal air bag inflator replacement. **For these vehicles only, 8315F replaces 8114L.**

SUBJECT VEHICLES

Model	VIN Range
2004-2006 B-Series	All

PARTS INFORMATION

A web page to order parts for this recall is available in MXConnect. A complete VIN is needed to process the order.

Description	Part Number	Quantity	Model
Passenger-side Front Air Bag Inflator	1FTT-57-K50	1	2004-2006 B-series truck

WARRANTY INFORMATION

The Warranty System has been updated to accept B-Series passenger air bag inflator replacement claims for recall 8315F.

For B-Series recall repairs performed under recall 8114L:

Submit a claim for recall 8315F with process number **J1503A** as explained below.

	Replacement of Passenger Side Front Air Bag Inflator
Warranty Type	R
Process Number	J1503A
Symptom Code	99
Damage Code	99
Part Number Main Cause / Quantity	5555-15-003A / 0
Related Part Number / Quantity	1FTT-57-K50 / 1
Labor Operation Number	YY775XRX
Labor Hours	0.8 hrs.

For models other than B-Series recall repairs performed under recall 8114L:

Continue to submit warranty claims following the information provided in recall 8114L, and available on MS3.

OWNER NOTIFICATION

Owners of subject vehicles will be notified by first class mail beginning July 28, 2015. Mazda is requesting owners to make appointments for this repair, which allows time for dealers to order the air bag inflator using the customer's VIN. Dealers should encourage customers to utilize the appointment process.

We apologize for any inconvenience this recall may cause your dealership and your customers. Your understanding and support in carrying out this safety recall are greatly appreciated.

Mazda Technical Services