

July 25, 2015

46196-01892 Version 15

## Safety Recall: Replacement Driver's Airbag Inflator Can Be Over-Pressurized

Supersedes 10-026. Dated June 13, 2015, to revise the information highlighted in **yellow**.

If you did Service Bulletin 10-026 on or before June 8, 2015. Make sure to use Warranty Claim Information provided below.

### REVISION SUMMARY

Under WARRANTY CLAIM INFORMATION, Failed Part Number was updated.

### WARRANTY CLAIM INFORMATION

Replacing the driver's airbag inflator.

Year/Model	Operation Number	Replacement Part Number	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
2003 3.2CL	7525A6	04770-S5A-305	0.5 hr	5US00	R5500	10-026N	06770-S84-A11ZA
	7525A6	04770-S5A-405	0.5 hr	5US00	R5500	10-026P	
2002-03 3.2TL	7525A6	04770-S5A-305	0.5 hr	5US00	R5500	10-026Q	
	7525A6	04770-S5A-405	0.5 hr	5US00	R5500	10-026R	

**CLIENT INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.