



This Service Information Bulletin supersedes SI M65 02 15 **dated April 2015.**

NEW designates changes to this revision

SUBJECT

Recall 15V-205: OC3 Seat Occupancy Mat

MODEL

R50 (Cooper)

R52 (Cooper Convertible, Cooper S Convertible)

R53 (Cooper S)

SITUATION

BMW AG is conducting a Voluntary Safety Recall involving the front passenger seat occupancy detection mat sensor in certain Model Year 2005-2006 MINI Cooper and Cooper S models, produced January 2005 through November 2006, and Model Year 2005-2008 MINI Cooper Convertible and Cooper S Convertible models produced January 2005 through July 2008.

The front passenger seat occupancy detection mat sensor may not function correctly due to several manufacturing, installation and field-exposure issues.

NEW On June 2, 2015, an interim letter will be mailed out to customers, informing them that their vehicle is affected by this Recall. However, at this time, we are not ready for the customer to visit the dealer for the repair.

For your reference, a Q&A has been attached.

This bulletin will be updated with repair instructions, parts and warranty information when it becomes available.

Please contact your field representatives if you have any questions.

ATTACHMENTS

View PDF attachment [M650215 Q&A](#).

View PDF attachment [M650215 Interim Letter](#).

[Copyright ©2015 BMW of North America, Inc.]