



IMPORTANT SAFETY RECALL

Models Affected:

RECARO ProRIDE and Performance RIDE manufactured under the Part/Model Numbers 332.01.AK21, 332.01.KAEC, 332.01.KAEG, 332.01.KK91, 332.01.MC11, 332.01.MJ15, 332.01.QA56, 332.01.QA9N, 332.01.QQ11, 332.01.QQ14, 332.01.QQ95, 333.01.CHIL, 333.01.HABB, 333.01.HAZE, 333.01.JEBB, 333.01.JETT, 333.01.KNGT, 333.01.MABB, 333.01.MARI, 333.01.MNGT, 333.01.PLBB, 333.01.PLUM, 333.01.REBB, 333.01.REDD, 333.01.ROBB, 333.01.ROSE, 333.01.SABB, 333.01.SAPH, 333.01.SLBB, 333.01.SLTE, 333.01.VIBB, 333.01.VIBE

Dates Affected:

April 9, 2010 – June 9, 2015

Units Affected:

173,063 Units

Description:

RECARO Child Safety LLC (RECARO) is recalling certain RECARO ProRIDE and Performance RIDE model child restraints, manufactured from April 9, 2010 through June 9, 2015. When the affected child seats are installed using the top tether, the top portion of the restraint can crack and allow the top tether to separate from the restraint. As such, these seats fail to conform to the requirements of Federal Motor Vehicle Safety Standard No. 213, "Child Restraint Systems."

Consequence:

In the event of a crash, the child restraint could fail to protect the child from contacting interior surfaces of the vehicle, increasing the risk of injury. No injuries or serious problems have been reported.

Remedy:

RECARO will notify registered owners to contact the RECARO Customer Service Department to receive a load limiting strap along with instructions on how to install it. Owners may contact RECARO at 1-888-973-2276 or info-usa@recaro-cs.com. Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

