



**IMPORTANT SAFETY RECALL NOTICE**

17 August 2015

VIA EXPRESS MAIL



Subject: **Motor Vehicle Safety Recall 15V-485  
Agility Fuel Systems – Pressure Relief Devices**

Dear Mr. [REDACTED]:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

New Flyer of America Inc. (“New Flyer”) has decided, that a defect which relates to motor vehicle safety, exists on certain New Flyer transit vehicles. This recall is based on information provided by Agility Fuel Systems (“Agility”). Further investigation has revealed that the following vehicles, operated by [REDACTED] are affected:

**Make: NABI**  
**Model: 334000 2014 42BRT**  
**VIN:**

- |                   |                   |                   |
|-------------------|-------------------|-------------------|
| 1N9420729EA140486 | 1N942072XEA140495 | 1N9420727EA140504 |
| 1N9420724EA140489 | 1N942072XEA140500 | 1N9420729EA140505 |
| 1N9420722EA140491 | 1N9420721EA140501 | 1N9420726EA140512 |
| 1N9420726EA140493 | 1N9420723EA140502 | 1N9420728EA140513 |
| 1N9420728EA140494 | 1N9420725EA140503 | 1N942072XEA140514 |

Agility has informed New Flyer that they have declared recall (15E-058) on specific models of pressure relief devices installed by Agility on New Flyer fuel systems between August of 2014 and June of 2015.

It has been determined that the interior bore surface condition may not have been machined to specification on these pressure relief devices during their manufacture by a sub-supplier. The surface condition of the bore could result in a delayed function or a complete non-function of the pressure relief device in the event of a vehicle fire.

**The pressure relief devices on the CNG fuel tanks may not function  
as required to vent the fuel safely in the event of a vehicle fire.**

This recall is being conducted by Agility with the assistance of New Flyer. Parts and labor required to accomplish the recall corrective action will be provided at no cost. Agility will be contacting your agency to schedule the replacement of these components with certified parts. Their intention is to conduct this retrofit in a manner which will hopefully cause the least amount of disruption to your normal operations.

**Headquarters/**  
Winnipeg Facility  
711 Kernaghan Ave.  
Winnipeg, Manitoba  
R2C 3T4 Canada  
Ph: (204) 224-1251

**Aftermarket Facility**  
630 Kernaghan Ave.  
Door 76  
Winnipeg, Manitoba  
R2C 5G1 Canada  
Ph: (204) 982-8400

**New Product**  
Development  
630 Kernaghan Ave.  
Winnipeg, Manitoba  
R2C 5G1 Canada  
Ph: (204) 982-8400

**Crookston**  
Facility  
214 5th Ave. SW  
Crookston, Minnesota  
56716 USA  
Ph: (218) 281-5752

**St. Cloud**  
Facility  
6200 Glenn Carlson Dr.  
St. Cloud, Minnesota  
56301 USA  
Ph: (320) 203-0576

**Anniston**  
Facility  
106 National Drive  
Anniston, AL  
36207 USA  
Ph: (256) 831-4296



Your New Flyer Field Service Team Leader, Chris Macedo will assist in the coordination of getting the Agility representatives to your location, in order to conduct the retrofit of the buses identified above. The attached Field Service Bulletin outlines the procedure the Agility personnel will be conducting.

If you are a lessor of vehicles which are identified above, it is required that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, or it has been removed from operation permanently, please inform the undersigned.

If you had this corrective action performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If New Flyer and Agility are unable to correct this defect within a reasonable time, you may submit a written complaint to the:

**Administrator,  
National Highway Traffic Safety Administration,  
1200 New Jersey Ave. SE,  
Washington, DC, 20590,  
Or call 1-888-327-4236 (TTY: 1-800-424-9153);  
or go to  
<http://www.safercar.gov>.**

We regret any inconvenience which this action may cause you. However, we are concerned about the safety of your passengers and employees.

Thank you for your attention to this important matter.

Sincerely,  
**NEW FLYER OF AMERICA INC.**



By: Kerry Legg  
Vehicle Safety & Regulatory Compliance Manager  
(204) 224-6706

cc: Chris Stoddart – Vice President Engineering Services  
Chris Macedo – Sr. Team Leader, Field Service West

Attachment: Agility Fuel Systems - Field Service Bulletin ENP-414 (28 July 2015)