

# Federal Recall Information

---

**213-B**

## Description

In the Models 579 and 567, the external lights may go out when the pre-trip inspection switch is activated while the truck is in motion.

---

## Release Date

2/18/2013

---

## Introduction

Peterbilt Motors Company has decided that a defect which relates to exterior lighting exists in certain Peterbilt Model 579 and 567 vehicles when the pre-trip external lighting inspection switch is activated when the truck is moving.

---

## Situation

In the Models 579 and 567, the external lights may go out when the pre-trip inspection switch is activated while the truck is in motion.

---

## Resolution

Disconnect the pre-trip Inspection function by replacing the pre-trip switch with a switch plug (S67-1016) and disabling the pre-trip software parameter.

---

**It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.**

---

## Warranty

The SIR system will indicate affected chassis with the designator of "213-B" in the campaign field.

**Submit Quick Claim 213-B**

---

## Parts

This recall will cover parts purchased through PACCAR Parts (dealer net+ 30% parts mark up) according to the following table:

| Quantity | Part Number | Description |
|----------|-------------|-------------|
| 1        | S67-1016    | Switch Plug |

---

## Labor

This recall will reimburse for 0.50 hours labor for software update and switch replacement included in quick claim 213-B

---

## Procedure

- Remove the Pre-Trip Switch and replace with a switch plug
  - Disable the Pre-Trip Switch programming parameter through ESA
- 

## Attachments

Chassis List