

Part 573 Safety Recall Report**15V-550****Manufacturer Name :** Kawasaki Motors Corp., U.S.A.**Submission Date :** AUG 31,2015**NHTSA Recall No. :** 15V-550**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Kawasaki Motors Corp., U.S.A.

Address : PO Box 25252

Santa Ana CA 92799-5252

Company phone : 949-770-0400

Population :

Number of potentially involved : 11,836

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2009-2015 Kawasaki Vulcan 1700 Voyager and Vaquero

Vehicle Type : MOTORCYCLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : The affected vehicles containing the problem are 2009-2015 Vulcan 1700 Voyager, Voyager ABS, Vaquero, Vaquero ABS.

Production Dates : FEB 02, 2009 - MAR 20, 2015

VIN (Vehicle Identification Number) Range

Begin : JKBNRA169A000102

End : JKBNRK15FA006760

 Not sequential VINs**Description of Defect :**

Description of the Defect : On eligible units, one of the ignition switch wires could chafe and short against the bottom of the fuel tank.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : This could result in the engine stalling possible creating the potential for a crash resulting in injury or death.

Description of the Cause : One of the ignition switches could chafe and short against the bottom of the fuel tank.

Identification of Any Warning that can Occur : none

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported