

October 1, 2015

ATB 51811-01884 Version 13

Safety Recall: Front Passenger's Airbag Inflator Can Be Over-Pressurized

This bulletin is replaced by S/B 15-067, Safety Recall: Front Passenger's Airbag Inflator Can Be Over-Pressurized

If you did the repair in Service Bulletin 14-040 on or before September 30, 2015 (RO date), use the Warranty Claim Information provided below.

WARRANTY CLAIM INFORMATION

| Year/Model | Operation Number | Replacement Part Number | Flat Rate Time | Defect Code | Symptom Code | Template ID | Failed Part Number |
|--|------------------|-------------------------|----------------|-------------|--------------|-------------|--------------------|
| 2003 Accord | 7541A9 | 04785-SDA-307 | 0.7 hr | 5JK00 | JJ600 | 14-040Z | 06780-SDA-A80ZA |
| | 7541A9 | 04790-SDA-308 | 0.7 hr | 5JK00 | JJ600 | 14-040Y | 06780-SDA-A80ZA |
| 2002-03 Civic 2002-03 Civic GX 2003 Civic Hybrid | 7541A9 | 04785-S5A-307 | 0.7 hr | 5JK00 | JJ700 | 14-040X | 06780-S5A-A80ZA |
| | 7541A9 | 04790-S5A-308 | 0.7 hr | 5JK00 | JJ700 | 14-040W | 06780-S5A-A80ZA |
| 2002-03 CR-V | 7541A9 | 04785-S9A-307 | 0.7 hr | 5JK00 | JJ800 | 14-040V | 06780-S9A-A80ZA |
| | 7541A9 | 04790-S9A-308 | 0.7 hr | 5JK00 | JJ800 | 14-040U | 06780-S9A-A80ZA |
| 2003 Element | 7541A9 | 04785-SCV-307 | 0.8 hr | 5JK00 | JJ900 | 14-040T | 06780-SCV-A80ZA |
| | 7541A9 | 04790-SCV-308 | 0.8 hr | 5JK00 | JJ900 | 14-040S | 06780-SCV-A80ZA |
| 2002 Odyssey | 7541A0 | 04785-S0X-307 | 0.7 hr | 5UK00 | JK000 | 14-040S | 06780-S0X-A10ZA |
| | 7541A0 | 04790-S0X-308 | 0.7 hr | 5UK00 | JK000 | 14-040R | 06780-S0X-A10ZA |
| 2003 Odyssey | 7541A0 | 04785-S0X-306 | 0.7 hr | 5UK00 | JK000 | 14-040R | 06780-S0X-A10ZA |
| | 7541A0 | 04790-S0X-305 | 0.7 hr | 5UK00 | JK000 | 14-040Q | 06780-S0X-A10ZA |
| 2003 Pilot | 7541A0 | 04785-S9V-307 | 0.8 hr | 5UK00 | JK100 | 14-040Q | 06780-S9V-A80ZA |
| | 7541A0 | 04790-S9V-308 | 0.8 hr | 5UK00 | JK100 | 14-040Q | 06780-S9V-A80ZA |

Skill Level: Repair Technician

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.