

October 9, 2015

02575 Version 3

## Safety Recall: Electrical Noise May Cause Inadvertent Front Airbag Deployment

This bulletin is replaced by S/B 15-011, *Safety Recall: SRS Unit*

If you did the repair in Service Bulletin 13-038 on or before October 8, 2015 (RO date), use the Warranty Claim Information provided below.

### WARRANTY CLAIM INFORMATION

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
7521G7	Replace the SRS subharness with a new one that includes a noise suppressor.	0.7 hr	5JN00	JC300	13-038A	77960-S3V-A81

**CLIENT INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.