
October 9, 2015

02581 Version 3

Safety Recall: Electrical Noise May Cause Inadvertent Front Airbag Deployment

This bulletin is replaced by S/B 15-013, *Safety Recall: SRS Unit*

If you did the repair in Service Bulletin 13-088 on or before October 8, 2015 (RO date), use the Warranty Claim Information provided below.

WARRANTY CLAIM INFORMATION

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
7521G7	Replace the SRS subharness with a new one that includes a noise suppressor.	1.0 hr	5JN00	JC200	13-088A	77960-S0X-L81

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.