



# IMPORTANT SAFETY RECALL

Mitsubishi Motors North America, Inc.

6400 Katella Avenue  
Cypress, CA 90630  
Telephone: 714-372-6000  
www.mitsubishicars.com

This notice applies to your vehicle, \_\_\_\_\_.

Date: October, 2015

Dear Mitsubishi Owner,

This notice has been sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

**Reason for notice:** Mitsubishi Motors North America, Inc. (MMNA) has decided that a defect which relates to motor vehicle safety exists in certain 2014 – 2015 Lancer Ralliart and Lancer Evolution vehicles. Due to an installation error, the right parking brake cable may have insufficient clearance with the fuel tank, causing abrasive contact between the two components. The coating on the fuel tank could deteriorate from this abrasive contact and potentially allow for rust formation.

Rusting could cause a pin hole to develop in the fuel tank and allow for fuel leakage, which increases the risk of fire in the presence of an ignition source.

**What you should do:** Please contact your local Authorized Mitsubishi Motors dealer and schedule an appointment to have the recall remedy performed on your vehicle. When you bring your vehicle in, please show the dealer this letter. (If you misplace this letter, the dealer will still make this inspection/repair to your vehicle, free of charge.)

**What your dealer will do:** The dealership will replace the right parking brake cable and inspect the fuel tank. If the fuel tank's coating exhibits damage from abrasive contact with the right parking brake cable, the fuel tank will also be replaced.

**How long will it take?** The time needed for right parking brake cable replacement is approximately **1.5 hrs.** If the fuel tank requires replacement, both operations require approximately **3.5 hrs** total. The dealer may need your vehicle for a longer period of time due to service scheduling issues, but every effort will be made to minimize your inconvenience.

If you experience any problem having your vehicle repaired promptly and/or at no charge, please inform us by calling the Mitsubishi Customer Relations Department at **888-648-7820**. Hours: Monday through Friday 7 a.m. to 4 p.m. (Pacific Time).

If, after contacting Mitsubishi Customer Relations, you still have a problem getting this repair made promptly and/or without charge, write to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington, D.C. 20590, or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

If you have already encountered a problem with the right parking brake cable rubbing against the fuel tank and had them replaced as a result of this specific condition and have paid for the repair, you may send your original repair order or invoice, **and** original receipt/proof of payment to the following address for reimbursement consideration:

Mitsubishi Customer Relations Department, P.O. Box 6400, Cypress, CA 90630-0064

**If you are the lessor of this vehicle**, please forward a copy of this notice to the lessee within ten days to comply with federal regulations.

We appreciate your prompt attention to this matter.

Sincerely,

Mitsubishi Motors North America, Inc.

C1510W