

GM CUSTOMER CARE AND AFTERSALES
DCS3829
URGENT - DISTRIBUTE IMMEDIATELY

Date: October 30, 2015

Subject: 15386A – Safety Recall
Inner Tie Rod Not Torqued to Specification
Customer Letter Added

Models: 2013 Chevrolet Cruze (One Canadian Vehicle)
2014-2015 Chevrolet Cruze
2014 Chevrolet Volt

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New or Used Vehicle Sales
Manager, and Warranty Administrator

Bulletin 15386 has been revised to include a copy of the customer letter. Please discard all copies of bulletin 15386.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES