

Close

- Published
Request ID: 13161
- Message
- Channel
- Recipients
- Options
- Approve
- Preview
- Print
- eMail Preview
- Edit Request

Communication

Title	TT06004 P36 Safety Recall Update
Start Date:	10/14/2015 3:21 PM
End Date:	12/31/2015 12:00 AM
Note:	All times are EST

Message



DATE: October 14, 2015

TO: Service Directors, Service Managers, Training Coordinators and Service Technicians

SUBJECT: P36 Sun Visor Safety Recall Update Tech Tube

FCA Performance Institute is pleased to announce the launch of a new tech tube (**course code TT06004**) to educate service personnel on the August revision of the P36 Sun Visor Recall. This tech tube compliments the original P36 recall tech tube (TT06003), and highlights the added steps, including the taping procedure. This tech tube should be viewed after watching TT06003.

The tech tube is intended to highlight the additional steps of the P36 Sun visor Recall introduced in the August revision. These steps include the deburring of sheetmetal seams and placing special tape patches over certain critical areas to prevent wire chafing.





This tech tube is a compliment to the previous P36 Safety Recall Technical Advisory Tech Tube (TT06003). TT06003 should be viewed first, prior to viewing TT06004 for a full understanding of the recall procedure.

It is the goal of FCA Performance Institute to make training as effective and convenient as possible for our dealers. Please take a moment at the end of the course to fill out the survey.

Sincerely,
FCA Performance Institute

Attachments [TT06004 P36 Safety Recall Update.pdf](#)

File Attachment Information

File Size (MB)	File Name
0.26	TT06004 P36 Safety Recall Update.pdf

Published
Request ID: 13161

Message
Channel
Recipients
Options
Approve

Preview

Print

eMail Preview

Edit Request