



11/25/2015

New Safety Recall Advanced Communication – R64112515

FCA US LLC announced a safety recall on certain 2015 model year (VF) RAM ProMaster vehicles.

Some of the above vehicles may have intermittent electrical circuit(s) in the ignition switch electrical contact holder block. A loss of electrical power, due to intermittent electrical circuit(s), can result in a partial or complete loss of the following safety system(s):

- Airbag Function
- Anti-Lock Brakes (ABS) Function
- Electronic Stability Control (ESC) Function
- Instrument Panel Cluster Function

The lack of a functioning ABS and/or ESC system(s) could change the braking and/or handling characteristics of the vehicle and cause a crash without warning.

The loss of airbag deployment could increase the risk and/or severity of vehicle occupant injuries during a crash.

FCA will conduct a voluntary safety recall to replace the ignition switch electrical contact holder block on all involved vehicles.

Dealers will be notified of the launch of this safety recall by way of established methods used in the past.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries on involved vehicles.

Customer Services Field Operations
FCA US LLC