

| | |
|---|---------------------------|
| <p>WRENCH LIGHT ILLUMINATED—DIAGNOSTIC TROUBLE CODE (DTC) P166A—MEMORY SEAT RECALL FUNCTION INOPERATIVE DURING PASSIVE ENTRY</p> | <p>TSB 13-6-16</p> |
|---|---------------------------|

FORD:
2013 Fusion

LINCOLN:
2013 MKZ

ISSUE

Some 2013 Fusion and MKZ vehicles may exhibit an illuminated wrench light with DTC P166A stored in the powertrain control module (PCM), or the memory seat recall function may be inoperative during passive entry.

ACTION

Reprogram the body control module (BCM) to the latest calibration using Integrated Diagnostic System (IDS) release 85.02 and higher. Calibration files may also be obtained at www.motorcraft.com.

| OPERATION | DESCRIPTION | TIME |
|-----------------------|--|-----------------------|
| 130616A | 2013 Fusion And MKZ: Check DTCs And Reprogram The BCM Includes Time To Clear Codes After Repair (Do Not Use With Any Other Labor Operations) | 0.3 Hr. |
| DEALER CODING | | |
| BASIC PART NO. | | CONDITION CODE |
| 15604 | | 42 |

WARRANTY STATUS: Eligible Under Provisions Of New Vehicle Limited Warranty Coverage Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.