



## TECH TIP: Fluttering Noise From Glove Box

NUMBER: TT015

MODEL: 2013 Sorento (XM)

DATE: 11/15/2013

**Symptom:** Fluttering noise at highway speeds originating behind glove box

**Repair:** Examine the fender liner in area where a mud guard would be mounted. You'll see a piece of plastic overlapping a larger piece. Install a screw through the smaller piece to secure it onto the larger piece beneath. This should correct the noise concern.

Note: Tech Tips are not a substitute for proper diagnosis.