

June 14, 2016

51969-01908 Version 11

Recall: Front Passenger's Airbag Inflator May Produce Excessive Pressure After Long-Term Exposure To High Absolute Humidity

This bulletin is replaced by S/B 16-028, Safety Recall: Front Passenger's Airbag Inflator Can Be Over-Pressurized (Phase 1)

If you did Service Bulletin 14-030 on or before June 13, 2016. Make sure to use Warranty Claim Information provided below.

WARRANTY CLAIM INFORMATION

Replacing the front passenger's airbag inflator

Year/Model	Operation Number	Replacement Part number	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
2003-05 MDX	7541A7	04785-S3V-306	0.7 hr	5NX00	JJ300	14-030N	06780-S3V-A10ZA
		04790-S3V-305	0.7 hr	5NX00	JJ300	24-030N	06780-S3V-A10ZA
		04790-S3V-315	0.7 hr	5NX00	JJ300	34-030N	06780-S3V-A10ZA
2005 RL	7541A7	04785-SJA-306	0.8 hr	5NX00	JJ400	14-030P	06780-SJA-A80
		04790-SJA-305	0.8 hr	5NX00	JJ400	24-030P	06780-SJA-A80
		04790-SJA-315	0.8 hr	5NX00	JJ400	34-030P	06780-SJA-A80

Skill Level: Repair Technician

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.