



GROUP
Safety Recall
Campaign

MODEL
2006~2012MY
Sedona (VQ)


NUMBER
SC100

DATE
December 2013

VOLUNTARY SAFETY RECALL CAMPAIGN

SUBJECT: FRONT LOWER CONTROL ARM INSPECTION, REPLACEMENT OR APPLICATION OF PREVENTATIVE ANTI-CORROSION MATERIAL (SC100)

This bulletin provides the procedure to inspect for corrosion damage and, if necessary, replace or apply additional anti-corrosion protection to the front lower control arms of some Sedona (VQ) vehicles, built from the start of production (SO) through August 14, 2012. The selected vehicles are currently registered, or were originally sold, in states where heavy amounts of road salt are used for de-icing in the winter months. The 21 states which are known to use heavy amounts of road salt are: CT, DC, DE, IA, IL, IN, MA, MD, ME, MI, MN, MO, NH, NJ, NY, OH, PA, RI, VT, WI and WV. To correct this concern and improve customer satisfaction, Kia is launching this safety recall campaign to inspect and, if necessary, replace or apply additional anti-corrosion protection to the front lower control arms on all affected vehicles.



* NOTICE

There is no charge to the vehicle owner for this repair. Under applicable law, you may not sell or otherwise deliver any affected Sedona (VQ) until it has been repaired pursuant to the procedures set forth in this bulletin.

* NOTICE

To assure complete customer satisfaction, always remember to refer to WebDCS Warranty Coverage (validation) Inquiry Screen (Service > Warranty Coverage >Warranty Coverage Inquiry) for a list of any additional campaigns that may need to be performed on the vehicle before returning it to the customer.

File Under: <Voluntary Safety Recall Campaign>

Circulate To: General Manager Service Manager Parts Manager

Service Advisor(s) Technician(s) Body Shop Manager Fleet Repair

SUBJECT: FRONT LOWER CONTROL ARM INSPECTION, REPLACEMENT OR APPLICATION OF PREVENTATIVE ANTI-CORROSION MATERIAL (SC100)

Inspection Procedure:


⚠ WARNING

To prevent possible injury, make sure to wear eye and ear protection while performing the procedures described within. In addition, a dust mask should be worn to prevent inhaling any airborne rust particles or chemical vapors.

1. Place the vehicle on a lift and inspect the condition of the lower control arms. If any perforations or open cavities are present on either control arm, proceed to the Service Procedure on Page 4. If not, proceed to step 2.

*** NOTICE**

Make sure to perform steps 2, 3, and 5 on both lower control arms.



2. Use a hammer to strike the lower control arm at multiple spots. Check for weak spots in the metal and overall integrity of the lower control arm. If the lower control arm fails, proceed to the Service Procedure on Page 4. If overall integrity is confirmed, proceed to step 3.



3. Insert a wire wheel pick up tool inside the lower control arm to remove any loose rust flakes.

⚠ WARNING

Wear eye protection to prevent possible injury from flying debris. In addition, a dust mask should be worn to prevent inhaling any airborne rust particles or debris.




SUBJECT: FRONT LOWER CONTROL ARM INSPECTION, REPLACEMENT OR APPLICATION OF PREVENTATIVE ANTI-CORROSION MATERIAL (SC100)

4. Remove any remaining debris from the inside of the lower control arm using an air gun. Make sure to insert the nozzle in multiple holes and rotate it in all directions to completely remove any foreign material or rust flakes.

*** NOTICE**

Repeat step 4 a total of three (3) times per lower control arm.




5. After removing all loose rust flakes from inside the lower control arm, use the S gauge (see below) to check the material thickness at all holes in the lower control arm, as shown.

*** NOTICE**



SST P/N: 54500 18GA



6. If the gauge can be inserted over the material's edge, proceed to the Service Procedure on Page 4.
7. If the gauge cannot be inserted over the material's edge, and the lower control arm passed the visual inspection and the hammer strike test, proceed to the Reconditioning Procedure on Page 7.

SUBJECT: FRONT LOWER CONTROL ARM INSPECTION, REPLACEMENT OR APPLICATION OF PREVENTATIVE ANTI-CORROSION MATERIAL (SC100)

Service Procedure:

1. Remove the front wheels.
2. Place a transmission jack under the sub-frame for support.



3. Loosen but do not remove the three (3) nuts securing the lower control arm to the ball joint.

Tightening torque:
65.1 ~ 86 lb-ft (9 ~ 120 Nm)



4. Remove the rear bolt and nut and from the lower control arm. Then, use a mallet or air hammer to remove the two (2) front "wheel-stop" type bolts and the nuts.

*** NOTICE**

Make sure to use the bolts and nuts included with the replacement parts kit when reinstalling the lower control arm to the ball joint.



SUBJECT: FRONT LOWER CONTROL ARM INSPECTION, REPLACEMENT OR APPLICATION OF PREVENTATIVE ANTI-CORROSION MATERIAL (SC100)


- 5. Remove three (3) bolts securing the sub-frame and the sub-frame bracket.

Tightening torque:
115.7 ~ 130.2 lb-ft (156.9 ~ 176.5 Nm)



- 6. Remove the bolt and nut securing the rear mounting location for the lower control arm.

Tightening torque:
115.7 ~ 130.2 lb-ft (156.9 ~ 176.5 Nm)



- 7. Remove the bolt securing the front mounting location for the lower control arm.

Tightening torque:
115.7 ~ 130.2 lb-ft (156.9 ~ 176.5 Nm)



SC CLOSURE REFER TO SC133

SUBJECT: FRONT LOWER CONTROL ARM INSPECTION, REPLACEMENT OR APPLICATION OF PREVENTATIVE ANTI-CORROSION MATERIAL (SC100)

- 8. Use an air hammer with a chisel bit to remove the lower control arm from the ball joint.



WARNING

To avoid possible injury, make sure to support the lower control arm prior to removing it from the ball joint.



- 9. Perform the reinstallation of the lower control arms in the following sequence:
 - 1. Front mounting location.
 - 2. Ball joint mounting location (use new hardware included with kit).
 - 3. Rear mounting location.
 - 4. Sub-frame bracket and bolts.
- 10. Reinstall all other removed components.

SC CLOSED - REFER TO SC133

SUBJECT: FRONT LOWER CONTROL ARM INSPECTION, REPLACEMENT OR APPLICATION OF PREVENTATIVE ANTI-CORROSION MATERIAL (SC100)

Reconditioning Procedure:

⚠ WARNING

To avoid possible injury, this procedure must be performed in a well-ventilated area and safety glasses must be worn at all times. In addition, do **NOT** smoke and avoid open flames while applying cavity wax and underbody coating, as they are highly flammable!

★ NOTICE

This procedure should only be performed in temperatures above 32° F (0° C). Ensure that all surfaces are completely dry and free of moisture before applying cavity wax or underbody coating.

1. Use a metal bristle brush to remove any surface rust from the lower control arms.



2. Use shop air to remove any loose dust from the lower control arm surfaces.



⚠ WARNING

Wear eye protection to prevent possible injury from flying debris. In addition, a dust mask should be worn to prevent inhaling any airborne rust particles or debris.

SC CLOSED - REFER TO SC133

SUBJECT: FRONT LOWER CONTROL ARM INSPECTION, REPLACEMENT OR APPLICATION OF PREVENTATIVE ANTI-CORROSION MATERIAL (SC100)

- Spray cavity wax into every hole in the lower control arm, as shown. To evenly apply cavity wax, turn the nozzle in all directions while spraying and make sure to use ONLY half (½) of the contents in each can per lower control arm.



! WARNING

Cavity wax is extremely flammable! Do NOT smoke and avoid any open flames during application, to avoid possible injury.

- Spray underbody coating onto the upper and lower surfaces of the lower control arm. Avoid over-spraying other parts of the vehicle.



! WARNING

Underbody coating is extremely flammable! Do NOT smoke and avoid any open flames during application, to avoid possible injury. In addition, latex gloves and a dust mask should be used.

SC100 CLOSED - REFER TO SC133

REQUIRED PARTS:

Part Name	Part No.	Qty.	Figure	Comments
Left Lower Control Arm	54500 4D102QQK	1		Includes Replacement bolts for ball joint mounting location
Right Lower Control Arm				

SUBJECT: FRONT LOWER CONTROL ARM INSPECTION, REPLACEMENT OR APPLICATION OF PREVENTATIVE ANTI-CORROSION MATERIAL (SC100)

REQUIRED TOOLS:

Part Name	Part No.	Qty.	Figure	Comments
Thickness Gauge	54500 18GAP	1		Shipped to Dealer (can be reordered through Kia SST Program)

REQUIRED PARTS:

Part Name	Part No.	Qty.	Figure	Comments
Cavity Wax	UM011 CH057	1		Limit one (1) can per vehicle (Order through Kia Chemicals)
Underbody Coating	UM010 CH044	1		Limit one (1) can per vehicle (Order through Kia Chemicals)

AFFECTED VEHICLE PRODUCTION RANGE:

Model	Production Date Range
Suona (N)	From SC through August 14, 2012

WARRANTY CLAIM INFORMATION:

Claim Type	Causal P/N	Qty.	N Code	C Code	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
R	54500 4D101	0	N56	C05	(SC100) Control Arm (FRT/Lower/LH/RT) Inspection & Wax Apply	131110R0	0.7 M/H	UM011 CH057 UM010 CH044	1 1
R	54500 4D102	1	N56	C05	(SC100) Control Arm (FRT/Lower/LF/RT) Inspect and Replace	131110R1	1.2 M/H	54500 4D102QQK	1

*** NOTICE**

To assure complete customer satisfaction, always remember to refer to WebDCS Warranty Coverage (validation) Inquiry Screen (Service > Warranty Coverage >Warranty Coverage Inquiry) for a list of any additional campaigns that may need to be performed on the vehicle before returning it to the customer.