



# Service Bulletin

File in Section: -

Bulletin No.: 16-NA-124

Date: April, 2016

## TECHNICAL

**Subject:** Spare Key Not Fully Retained in Remote and/or Remote Button Not Fully Released

**Attention:** This Bulletin also applies to any of the models that may be Export vehicles.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Camaro	2016	2016			All	All
Chevrolet	Malibu (VIN Z)	2016	2016			All	All
Chevrolet	Volt	2016	2016			All	All

<b>Condition</b>	Some customers may comment that their spare key is not fully retained within the vehicles remote.
<b>Cause</b>	This may be caused by a defect within the key itself.

### Correction

Upon inspection, the technician may find that the key is not inserting fully into the vehicles remote assembly, preventing the button latch from fully securing the key.

If the button does not fully release to a flush position when the key is inserted, replace the key.

### Warranty Information

Labor Operation	Description	Labor Time
0530010	Door Lock and Ignition Lock Key Replacement	0.2 hr
Add	To Cut Key if required	0.1 hr

<b>Version</b>	1
<b>Modified</b>	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION