



# Service Bulletin

## INFORMATION

**Subject:** Radio turns on unwanted at startup

**Models:** 2016 Buick LaCrosse, Regal  
2016 Cadillac ATS, ATS-V, CT6, CTS, CTS-V, ELR, Escalade models, XT5, XTS  
2016 Chevrolet Camaro, Colorado, Corvette, Impala, Malibu, Silverado, Suburban, Tahoe, Volt  
2016 GMC Canyon, Sierra, Yukon models  
Equipped with RPO code IO5 or IO6

*This PI has been updated to change Recommendations/Instructions. Please discard PIC6186A.*

### Condition/Concern

Customers may comment that they will have the radio shut off, and when restarting the vehicle the radio will turn on unwanted.

### Recommendation/Instructions

Contact General Motors Technical Assistance (GM TAC) to report the concern and obtain a case number.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION