

Subject: SES Lamp With DTC P015A

**Models: 2012-2016 Chevrolet Equinox
2012-2016 GMC Terrain
2013-2016 Buick Verano
2013-2016 Cadillac ATS
2013-2016 Chevrolet Malibu
2014-2016 Chevrolet Impala
2015-2016 Chevrolet Colorado
2015-2016 GMC Canyon
Equipped with engine 2.4L LEA, 2.5L LCV and 2.5L LKW**

This PI was superseded to update Recommendations / Instructions. Please discard PIP5389A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer may comment on an SES light with DTC P015A set.

Recommendation/Instructions

If SI diagnostics have been completed and a repair has not been established, inspect the engine oil level for being overfilled.

If the engine oil level is found to be overfilled, readjust to correct level and re-evaluate the concern.

If the above steps do not lead to a resolution, advise the customer that engineering is aware of this concern and is working on a repair.

To assist engineering, inquire if the customer is utilizing the transmission manual / tap shift feature and record this information on the repair order.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.