



10/12/2016

New Safety Recall Advanced Communication – S75101216

FCA US LLC (“FCA US”) announced a safety recall on certain 2016 model year (ZD) Dodge Viper models.

Some of the above vehicles may have been built with misaligned Driver Airbag (DAB) inflator connectors. The misaligned DAB connector resulted in a misrouting of the DAB airbag wiring. The misrouting of the DAB wires caused the potential for pinched and/or damaged DAB wires.

Pinched and/or damaged DAB wires may compromise the DAB system and illuminate the Airbag Warning Light (ABWL). A compromised DAB could increase the risk of injury or death to the vehicle driver during a crash.

FCA US will conduct a voluntary safety recall to replace the DAB and the steering column airbag clockspring on all involved vehicles.

Dealers will be notified of the launch of this safety recall by way of established methods used in the past.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries on involved vehicles.

Customer Services Field Operations
FCA US LLC