



AFTERSALES

CODE OF PRACTICE VEHICLE SAFETY RECALL – LOTUS EVORA SUPERCHARGED

Dear Dealer/Importer

You may already be aware that Lotus has announced a recall in the USA and Canada of a number of Lotus Evora Supercharged vehicles that were built between December 2010 and November 2011.

In summary, the defect relates to the VVT oil feed pipe that is situated to the right hand rear of the engine. Lotus has identified that the pipe may fail, depositing oil onto the engine and the exhaust system. This could cause an engine failure and an increased risk of fire because of the presence of flammable vapour.

The reason for this notification is to inform you that this defect also affects vehicles that have been distributed for retail in other territories worldwide.

Lotus is in the process of contacting all the relevant authorities, importers and dealers in those territories. If you have not already been contacted individually you will be sent all the relevant information, including the identity of the affected vehicles and the remedial action, as soon as possible.

Should you require any further information in the meantime or have any questions, please do not hesitate to contact the undersigned.

Neil Turner – Customer Services, Warranty & Technical Manager
LOTUS AFTERSALES,
Units 6 & 7 John Hyrne Way,
Longwater Business Park,
Costessey, Norwich,
Norfolk,
NR5 0AF
England.

T +44 (0)1603 732194
nturner@lotuscars.com