HONDA
AUTOMOBILE DIVISION
American Honda Motor Co., Inc.
1919 Torrance Blvd., - P.O. Box 2215
Torrance, CA 90509-9870

August 2014

RE: 2006-07 S2000
NHTSA Recall 13V-246

IMPORTANT

- **Your vehicle is included in a safety recall and should have the recall service done as soon as possible.**
- **Any authorized Honda dealer will perform the recall service at no charge to you.**

Dear Honda S2000 Owner:

What is the reason for this notice?

Our records indicate that an important SAFETY RECALL has not been completed on this vehicle; refer to the address card for the affected VIN. There is potential for a vacuum leak within the brake booster which may cause a decrease in brake assist. A decrease in brake assist can increase the risk of a crash.

What should you do?

Please immediately contact any authorized Honda dealer to schedule a service appointment. The dealer will inspect and, if necessary, replace the brake booster. This work will be done *free of charge*.

If you have questions

If you have any questions about this notice, or you need assistance locating a dealer, contact American Honda's customer service at 800-999-1009 and select option 4. You may also find this information at *www.Hondacars.com*.

We apologize for any inconvenience this safety recall may cause you. We are taking this action in the interest of your safety and continued satisfaction with your Honda vehicle.

Sincerely,

American Honda Motor Co., Inc.
Honda Automobile Division

NOTICE: If this is a leased vehicle, please forward this notice to the lessee.

Agosto del 2014

RE: 2006-07 S2000
Campaña de seguridad NHTSA 13V-246

IMPORTANTE

- **Su vehículo está incluido en una campaña de seguridad y debe completar el servicio de la campaña lo más pronto posible.**
- **Cualquier concesionario autorizado Honda podrá realizar el servicio de la campaña de seguridad, sin costo alguno.**

Estimado propietario de un vehículo Honda S2000:

¿Cuál es el motivo de esta notificación?

Nuestros registros indican que no se ha completado una CAMPAÑA DE SEGURIDAD importante en este vehículo; consulte la tarjeta de dirección para ver el VIN afectado. Existe una posibilidad de que exista una fuga de vacío en el servo de los frenos el cual podría ocasionar una disminución en la asistencia en el frenado. Una disminución de la asistencia en el frenado puede aumentar el riesgo de una colisión.

¿Qué debe hacer?

Por favor comuníquese inmediatamente con cualquier concesionario autorizado Honda para programar una cita de servicio. El concesionario inspeccionará y si es necesario reemplazará el servo de los frenos. Este trabajo se realizará *sin costo alguno*.

Si tiene preguntas

Si tiene preguntas acerca de este aviso o necesita asistencia para ubicar un concesionario, comuníquese con Servicio al Cliente de Honda al 800-999-1009 y seleccione la opción 4. Usted también puede encontrar esta información en *www.Hondacars.com*.

Le pedimos disculpas por cualquier inconveniente que esta campaña de seguridad pudiera causarle. Nosotros estamos tomando esta acción en el interés de su seguridad y satisfacción continua con su vehículo Honda.

Atentamente,

American Honda Motor Co., Inc.
División Automotriz de Honda

AVISO: Si este es un vehículo arrendado, por favor envié esta notificación al arrendatario.