MITSUBISHI MOTORS

**Mitsubishi Motors North America, Inc.**
6400 Katella Avenue
Cypress, CA 90630
Tel: 714-372-6000
www.mitsubishicars.com

January 29, 2010

Kathleen DeMeter, Esq.
Director, Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave. SE
Washington, D.C. 20590

Subject: Quarterly Campaign Progress Report – 4th Quarter 2009

Dear Ms. DeMeter:

Attached is the Quarterly Campaign Progress Report prepared in accordance with Federal Regulation 573.6 for the calendar quarter October 1 through December 31, 2009 (4th Quarter 2009).

If you have any questions concerning this report, please do not hesitate to contact me directly during normal business hours.

Sincerely,

Sharon Kaplan
Sr. Specialist, Technical Compliance
Mitsubishi Motors North America, Inc.
Telephone: (714) 372-6148
Fax: (714) 934-4202
E-mail: skkaplan@mmsa.com

cc: Kelly Schuler (Email)

Enclosure

MMNA 4th Quarter 2009
Campaign Progress Report

| NHTSA Recall Number | MMNA Recall Number | Campaign Name | Owner Notification Start | Owner Notification End | Total Number of Vehicles Involved | Number Vehicles inspected and Repaired | Number Vehicles inspected not needing Repair | Vehicles Exported | Vehicles Stolen | Vehicles Scrapped | Notification Undeliverable | Sold or Traded | Quarters Reported |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 08V139 | SR-08-003 | Endeavor Shift Interlock | 7-Jul-08 | 7-Jul-08 | 112,405 | 60,801 | NA | 0 | 0 | 745 | 4,185 | 660 | 6 |
| 08V276 | SR-08-004 | Galant Shift Interlock | 2-Sep-08 | 2-Sep-08 | 69,926 | 28,144 | NA | 0 | 0 | 1100 | 4,025 | 306 | 6 |
| 08V454 | SR-08-005 | Fuel Tank Bracket | 30-Sep-08 | 30-Sep-08 | 45,988 | 751 | 24,889 | 0 | 0 | 474 | 1,600 | 250 | 6 |
| 08V680 | SR-09-001 | Outlander Stop Lamp Switch | 24-Feb-09 | 24-Feb-09 | 19,852 | 14,110 | NA | 0 | 0 | 68 | 627 | 67 | 4 |
| 09V077 | SR-09-002 | Lancer/Outlander Brake Booster Check Valve | 5-May-09 | 5-May-09 | 48,844 | 34,076 | NA | 0 | 0 | 201 | 1,887 | 118 | 3 |
| 09V361 | SR-09-003 | Endeavor Side Air Bag Anchor Bracket | 29-Sep-09 | 29-Sep-09 | 531 | 5 | 406 | 0 | 0 | 0 | 0 | 0 | 2 |
| 09V349 | SR-09-004 | Lancer Ralliart/ Evolution/ Sportback Fuel Return Pipe | 29-Sep-09 | 29-Sep-09 | 7,083 | 3,642 | NA | 0 | 0 | 31 | 384 | 29 | 2 |
| 09V435 | SR-09-005 | Lancer/Lancer Evolution SRS Front Impact Sensor | 27-Nov-09 | 27-Nov-09 | 29,779 | 8,090 | NA | 6 | 2 | 81 | 854 | 74 | 1 |