THE NEW AMERICAN MOTORCYCLE™

September 5, 2003

03V-336 ① of (193)

National Highway Traffic Safety Administration
Patricia Wallace, Office of Defects Investigation (ODI)
400 Seventh Street, S.W.
Washington, D.C. 20590
T: (202) 366-5232
F: (202) 366-7882

573.6 Defect Information Report

573.6.c.1.
Vehicle manufacturer's full name:
Polaris Industries Inc., Victory Motorcycle Division
Address:
2100 Highway 55
Hamel, MN 55340-9800

573.6.c.2.
Vehicles potentially containing defect:
MY 1999 V92C Standard Cruiser
MY 2000 V92C Standard Cruiser
MY 2000 V92SC SportCruiser
MY 2000 V92C Standard Cruiser, Special Edition
MY 2001 V92C Standard Cruiser
MY 2001 V92SC SportCruiser
MY 2001 V92DC Deluxe Cruiser

RECEIVED
NVS-215
2003 SEP 12 P 4:59
OFFICE OF
DEFECTS INVESTIGATION

Vehicle Identification Numbers:
Complete list of affected VINs attached.

Inclusive dates of manufacture:
All motorcycles assembled from 7-1-98 through 7-25-01.

Basis for recall population:
All motorcycles built from 1999 through 2001 model years use a similar sidestand assembly and frame rail. Later models have higher ground clearance and different frame rails that afford greater protection against damage to the sidestand assembly.

573.6.c.3.
Total number of vehicles being recalled:
9,120

573.6.c.4.
Percentage of vehicles estimated to actually contain defect:
All vehicles have a similar design, but potential for unintended sidestand deployment is strongly affected by the handling and operation of the motorcycle.

573.6.c.5.
Brief Summary:
In certain instances the sidestand spring and /or the pin used to attach the spring to the frame may be damaged, allowing unintended deployment of the sidestand.

Detailed description:
The sidestand used on Victory motorcycles is attached to the lower left side frame rail and utilizes an extension spring to retract and hold the sidestand against the frame rail while the vehicle is in motion. The spring is attached at one end through a hole in the sidestand and at the other end to a pin which is welded in a vertical position to the lower frame rail. During aggressive operation, it is possible for the spring to come in contact with the road, grinding a portion of the spring material away and leaving it in a weakened condition in which it may break unexpectedly. The pin used to attach the spring to the frame rail may also be damaged due to aggressive operation or when the motorcycle is moved onto or off of an incline (e.g., bent while loading the vehicle onto a trailer). Such damage to the pin may reduce the spring tension while the sidestand is in an upright position and allow the spring to fall from the assembly. Damage to the spring or pin may ultimately result in unintended deployment of the sidestand.

573.6.c.6.
Chronology:
Victory has recently conducted a thorough review of customer complaints and warranty records pertaining to this issue as a result of NHTSA Preliminary Evaluation 03-022. Although the sidestand is designed to retract if it deploys while the vehicle is in motion, this review persuaded Victory that the condition may still have some potential to cause an accident.

573.6. c.8.
Remedy program:
Victory will inspect all affected vehicles and replace the sidestand spring and frame rail bracket with newly designed components when available. Victory will also reimburse claimants who can provide documentation that they have paid for repairs due to this

condition, unless those repairs would have been covered under warranty. Additional details of the reimbursement plan will be provided with the proposed owner letter.

Estimated date on which notifications to Owners will begin:
Not yet determined.

Estimated date on which notification will be completed:
Not yet determined.

573.6.c.10.
Owner letter:
A proposed owner notification letter will be provided as soon as it is available.

573.6.c.11.
Manufacturer's campaign number:
V-03-05

Signed: Suzanne K. Peterson Date: 9-5-03
Suzanne K. Peterson
Victory Motorcycle Division, Polaris Industries Inc.

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D7X3000001
5VPCB15D9X3000002
5VPCB15D0X3000003
5VPCB15D2X3000004
5VPCB15D4X3000005
5VPCB15D6X3000006
5VPCB15D8X3000007
5VPCB15DXX3000008
5VPCB15D1X3000009
5VPCB15D8X3000010
5VPCB15DXX3000011
5VPCB15D1X3000012
5VPCB15D3X3000013
5VPCB15D5X3000014
5VPCB15D7X3000015
5VPCB15D9X3000016
5VPCB15D0X3000017
5VPCB15D2X3000018
5VPCB15D4X3000019
5VPCB15D0X3000020
5VPCB15D2X3000021
5VPCB15D4X3000022
5VPCB15D6X3000023
5VPCB15D8X3000024
5VPCB15DXX3000025
5VPCB15D1X3000026
5VPCB15D3X3000027
5VPCB15D5X3000028
5VPCB15D7X3000029
5VPCB15D3X3000030
5VPCB15D5X3000031
5VPCB15D7X3000032
5VPCB15D9X3000033
5VPCB15D0X3000034
5VPCB15D2X3000035
5VPCB15D4X3000036
5VPCB15D6X3000037
5VPCB15D8X3000038
5VPCB15DXX3000039
5VPCB15D6X3000040
5VPCB15D8X3000041
5VPCB15DXX3000042
5VPCB15D1X3000043
5VPCB15D3X3000044
5VPCB15D5X3000045
5VPCB15D7X3000046
5VPCB15D9X3000047
5VPCB15D0X3000048

M.Y. 1999 through 2001 motorcycles assembled from 7-1-96 through 7-25-01
Number of affected vehicles: 9120

03V-336 ⑤ (193)

Vehicle Identification Numbers
5VPCB15D2X3000049
5VPCB15D9X3000050
5VPCB15D0X3000051
5VPCB15D2X3000052
5VPCB15D4X3000053
5VPCB15D6X3000054
5VPCB15D8X3000055
5VPCB15DXX3000056
5VPCB15D1X3000057
5VPCB15D3X3000058
5VPCB15D5X3000059
5VPCB15D1X3000060
5VPCB15D3X3000061
5VPCB15D5X3000062
5VPCB15D7X3000063
5VPCB15D9X3000064
5VPCB15D0X3000065
5VPCB15D2X3000066
5VPCB15D4X3000067
5VPCB15D6X3000068
5VPCB15D8X3000069
5VPCB15D4X3000070
5VPCB15D6X3000071
5VPCB15D8X3000072
5VPCB15DXX3000073
5VPCB15D1X3000074
5VPCB15D3X3000075
5VPCB15D6X3000076
5VPCB15D7X3000077
5VPCB15D9X3000078
5VPCB15D0X3000079
5VPCB15D7X3000080
5VPCB15D9X3000081
5VPCB15D0X3000082
5VPCB15D2X3000083
5VPCB15D4X3000084
5VPCB15D6X3000085
5VPCB15D8X3000086
5VPCB15DXX3000087
5VPCB15D1X3000088
5VPCB15D3X3000089
5VPCB15DXX3000090
5VPCB15D1X3000091
5VPCB15D3X3000092
5VPCB15D6X3000093
5VPCB15D7X3000094
5VPCB15D9X3000095
5VPCB15D0X3000096

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of effected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D2X3000097
5VPCB15D4X3000098
5VPCB15D6X3000099
5VPCB15DX13000100
6VPCB15D9X3000100
5VPCB15D9Y3000101
5VPCB15D113000101
5VPCB15D0X3000101
6VPCB15D0Y3000102
5VPCB15D313000102
5VPCB15D2X3000102
5VPCB15D2Y3000103
5VPCD15D213000103
5VPCB15D4X3000103
5VPCB15D4Y3000104
5VPCD15D413000104
5VPCB15D6X3000104
6VPCB15D6Y3000105
5VPCD15D613000105
5VPCB15D8X3000105
5VPCB15D8Y3000106
5VPCS15D013000106
5VPCB15DXX3000106
5VPCB15DXY3000107
5VPCS15D213000107
6VPCB15D1X3000107
5VPCB15D1Y3000108
5VPCS15D413000108
5VPCB15D3X3000108
5VPCB15D3Y3000109
5VPCS15D613000109
5VPCB15D5X3000109
5VPCB15DXY3000110
5VPCS15D213000110
5VPCB15D1X3000110
6VPCB15D1Y3000111
5VPCS15D413000111
5VPCB15D3X3000111
5VPCB15D3Y3000112
5VPCS15D613000112
5VPCB15D5X3000112
5VPCB15D5Y3000113
5VPCS15D613000113
5VPCB15D7X3000113
5VPCS15D7Y3000114
5VPCS15DX13000114
5VPCB15D9X3000114
5VPCS15D9Y3000115

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D113000115
5VPCB15D0X3000115
5VPCS15D0Y3000116
5VPCB15D313000116
5VPCB15D2X3000116
5VPCS15D2Y3000117
5VPCB15D4X3000117
5VPCS15D4Y3000118
5VPCB15D6X3000118
5VPCS16D6Y3000119
5VPCB15D8X3000119
5VPCS15D2Y3000120
5VPCB15D4X3000120
5VPCS15D4Y3000121
5VPCB15D6X3000121
5VPCS15D6Y3000122
5VPCB15D8X3000122
5VPCS15D8Y3000123
5VPCB15DXX3000123
5VPCS15DXY3000124
5VPCB15D1X3000124
5VPCS15D1Y3000125
5VPCB15D3X3000125
5VPCS15D3Y3000126
5VPCB15D5X3000126
5VPCS15D5Y3000127
5VPCB15D7X3000127
5VPCB15D9X3000128
5VPCB15D0X3000129
5VPCB15D7X3000130
5VPCB15D9X3000131
5VPCB15D0X3000132
5VPCB15D2X3000133
5VPCB16D4X3000134
5VPCB15D6X3000135
5VPCB15D8X3000136
5VPCB15DXX3000137
5VPCB15D1X3000138
5VPCB15D3X3000139
5VPCB15DXX3000140
5VPCB15D1X3000141
5VPCB15D3X3000142
5VPCB15D5X3000143
5VPCB15D7X3000144
5VPCB15D9X3000145
5VPCB15D0X3000146
5VPCB15D2X3000147
5VPCB15D4X3000148

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D6X3000149
5VPCB15D2X3000150
5VPCB15D4X3000151
5VPCB15D6X3000152
5VPCB15D8X3000153
5VPCB15DXX3000154
5VPCB15D1X3000155
5VPCB15D3X3000156
5VPCB15D5X3000157
5VPCB15D7X3000158
5VPCB15D9X3000159
5VPCB15D5X3000160
5VPCB15D7X3000161
5VPCB15D9X3000162
5VPCB15D0X3000163
5VPCB15D2X3000164
5VPCB15D4X3000165
5VPCB15D6X3000166
5VPCB15D8X3000167
5VPCB15DXX3000168
5VPCB15D1X3000169
5VPCB15D8X3000170
5VPCB15DXX3000171
5VPCB15D1X3000172
5VPCB15D3X3000173
5VPCB15D5X3000174
5VPCB15D7X3000175
5VPCB15D9X3000176
5VPCB15D0X3000177
5VPCB15D2X3000178
5VPCB15D4X3000179
5VPCB15D0X3000180
5VPCB15D2X3000181
5VPCB15D4X3000182
5VPCB15D6X3000183
5VPCB15D8X3000184
5VPCB15DXX3000185
5VPCB15D1X3000186
5VPCB15D3X3000187
5VPCB15D5X3000188
5VPCB15D7X3000189
5VPCB15D3X3000190
5VPCB15D5X3000191
5VPCB15D7X3000192
5VPCB15D9X3000193
5VPCB15D0X3000194
5VPCB15D2X3000195
5VPCB15D4X3000196

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D6X3000197
5VPCB15D8X3000198
5VPCB15DXX3000199
5VPCB15D2X3000200
5VPCS15D2Y3000201
5VPCB15D4X3000201
5VPCS15D4Y3000202
5VPCB15D6X3000202
5VPCS15D6Y3000203
5VPCB15D8X3000203
5VPCS15D8Y3000204
5VPCB15DXX3000204
5VPCS15DXY3000205
5VPCB15D1X3000205
5VPCS15D1Y3000206
5VPCB15D3X3000206
5VPCS15D3Y3000207
5VPCB15D5X3000207
5VPCS15D5Y3000208
5VPCB15D7X3000208
5VPCS15D7Y3000209
5VPCB15D9X3000209
5VPCS15D3Y3000210
5VPCB15D5X3000210
5VPCS15D5Y3000211
5VPCB15D7X3000211
5VPCS15D7Y3000212
5VPCB15D9X3000212
5VPCS15D9Y3000213
5VPCB15D0X3000213
5VPCS15D0Y3000214
5VPCB15D2X3000214
5VPCS15D2Y3000215
5VPCB15D4X3000215
5VPCS15D4Y3000216
5VPCB15D6X3000216
5VPCB15D6Y3000217
5VPCB15D8X3000217
5VPCB15D8Y3000218
5VPCB15DXX3000218
5VPCB15DXY3000219
5VPCB15D1X3000219
5VPCB15D6Y3000220
5VPCB15D8X3000220
5VPCB15D8Y3000221
5VPCB15DXX3000221
5VPCB15DXY3000222
5VPCB15D1X3000222

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D1Y3000223
5VPCB15D3X3000223
5VPCB15D3Y3000224
5VPCB15D5X3000224
5VPCB15D6Y3000225
5VPCB15D7X3000225
5VPCB15D7Y3000226
5VPCB15D9X3000226
5VPCB15D9Y3000227
5VPCB15D0X3000227
5VPCB15D0Y3000228
5VPCB15D2X3000228
5VPCB15D2Y3000229
5VPCB15D4X3000229
5VPCB15D8Y3000230
5VPCB15D0X3000230
5VPCB15D0Y3000231
5VPCB15D2X3000231
5VPCB15D2Y3000232
5VPCB15D4X3000232
5VPCB15D4Y3000233
5VPCB15D6X3000233
5VPCB15D6Y3000234
5VPCB15D8X3000234
5VPCB15D8Y3000235
5VPCB15DXX3000235
5VPCB15DXY3000236
5VPCB15D1X3000236
5VPCB15D1Y3000237
5VPCB15D3X3000237
5VPCB15D3Y3000238
5VPCB15D5X3000238
5VPCB15D6Y3000239
5VPCB15D7X3000239
5VPCB15D1Y3000240
5VPCB15D3X3000240
5VPCB15D3Y3000241
5VPCB15D5X3000241
5VPCB15D5Y3000242
5VPCB15D7X3000242
5VPCB15D7Y3000243
5VPCB15D9X3000243
5VPCB15D9Y3000244
5VPCB15D0X3000244
5VPCB15D0Y3000245
5VPCB15D2X3000245
5VPCB15D2Y3000246
5VPCB15D4X3000246

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D4Y3000247
5VPCB15D6X3000247
5VPCB15D6Y3000248
5VPCB15D8X3000248
5VPCB15D8Y3000249
5VPCB16DXX3000249
5VPCB15D4Y3000250
5VPCB15D6X3000250
5VPCB15D8Y3000251
5VPCB15D8X3000251
5VPCB15D8Y3000252
5VPCB15DXX3000252
5VPCB15DXY3000253
5VPCB15D1X3000253
5VPCB15D1Y3000254
5VPCB15D3X3000254
5VPCB15D3Y3000255
5VPCB15D5X3000255
5VPCB15D5Y3000256
5VPCB15D7X3000256
5VPCB15D7Y3000257
5VPCB16D9X3000257
5VPCB15D9Y3000258
5VPCB16D0X3000258
5VPCB15D0Y3000259
5VPCB15D2X3000259
5VPCB15D7Y3000260
5VPCB15D9X3000260
5VPCB15D9Y3000261
5VPCB15D0X3000261
5VPCB15D0Y3000262
5VPCB15D2X3000262
5VPCB15D2Y3000263
5VPCB16D4X3000263
5VPCB15D4Y3000264
5VPCB16D6X3000264
5VPCB15D6Y3000265
5VPCB15D8X3000265
5VPCB15D8Y3000266
5VPCB16DXX3000266
5VPCB15DXY3000267
5VPCB16D1X3000267
5VPCB16D1Y3000268
5VPCB16D3X3000268
5VPCB15D3Y3000269
5VPCB16D6X3000269
5VPCB15DXY3000270
5VPCB16D1X3000270

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D1Y3000271
5VPCB15D3X3000271
5VPCB15D3Y3000272
5VPCB15D5X3000272
5VPCS15D5Y3000273
5VPCB15D7X3000273
5VPCS15D7Y3000274
5VPCB15D9X3000274
5VPCS15D9Y3000275
5VPCB15D0X3000275
5VPCS15D0Y3000276
5VPCB15D2X3000276
5VPCS15D2Y3000277
5VPCB15D4X3000277
5VPCS15D4Y3000278
5VPCB15D6X3000278
5VPCS15D6Y3000279
5VPCB15D8X3000279
5VPCS15D2Y3000280
5VPCB15D4X3000280
5VPCS15D4Y3000281
5VPCB15D6X3000281
5VPCS15D6Y3000282
5VPCB15D8X3000282
5VPCS15D8Y3000283
5VPCB15DXX3000283
5VPCS15DXY3000284
5VPCB15D1X3000284
5VPCS15D1Y3000285
5VPCB15D3X3000286
5VPCS15D3Y3000286
5VPCB15D5X3000286
5VPCS15D5Y3000287
5VPCB15D7X3000287
5VPCS15D7Y3000288
5VPCB15D9X3000288
5VPCS15D9Y3000289
5VPCB15D0X3000289
5VPCS15D5Y3000290
5VPCB15D7X3000290
5VPCS16D7Y3000291
5VPCB15D9X3000291
5VPCS16D9Y3000292
5VPCB15D0X3000292
5VPCS15D0Y3000293
5VPCB15D2X3000293
5VPCS15D2Y3000294
5VPCB15D4X3000294

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D4Y3000295
5VPCB15D6X3000295
5VPCS15D6Y3000296
5VPCB15D8X3000296
5VPCS15D8Y3000297
5VPCB15DXX3000297
5VPCS15DXY3000298
5VPCB15D1X3000298
5VPCS15D1Y3000299
5VPCB15D3X3000299
5VPCS15D4Y3000300
5VPCB15D6X3000300
5VPCS15D6Y3000301
5VPCB15D8X3000301
5VPCS15D8Y3000302
5VPCB15DXX9000302
5VPCS15DXY3000303
5VPCB15D1X3000303
5VPCS15D1Y3000304
5VPCB15D3X3000304
5VPCS15D3Y3000305
5VPCB15D5X3000305
5VPCS15D5Y3000306
5VPCB15D7X3000306
5VPCS15D7Y3000307
5VPCB15D9X3000307
5VPCS15D9Y3000308
5VPCB15D0X3000308
5VPCS15D0Y3000309
5VPCB15D2X3000309
5VPCS15D7Y3000310
5VPCB15D9X3000310
5VPCS15D9Y3000311
5VPCB15D0X3000311
5VPCS15D0Y3000312
5VPCB15D2X3000312
5VPCS15D2Y3000313
5VPCB15D4X3000313
5VPCS15D4Y3000314
5VPCB15D6X3000314
5VPCS15D6Y3000315
5VPCB15D8X3000315
5VPCS15D6Y3000316
5VPCB15DXX3000316
5VPCS15DXY3000317
5VPCB15D1X3000317
5VPCS15D1Y3000318
5VPCB15D3X3000318

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D3Y3000319
5VPCB15D5X3000319
5VPCS15DXY3000320
5VPCB15D213000320
5VPCB15D1X3000320
5VPCS15D1Y3000321
5VPCB15D413000321
5VPCB15D3X3000321
5VPCS15D3Y3000322
5VPCB15D613000322
5VPCB15D5X3000322
5VPCS15D5Y3000323
5VPCB15D813000323
5VPCB15D7X3000323
5VPCS15D7Y3000324
5VPCB15DX13000324
5VPCB15D9X3000324
5VPCS15D9Y3000325
5VPCB15D113000325
5VPCB15D0X3000325
5VPCS15D0Y3000326
5VPCB15D313000326
5VPCB15D2X3000326
5VPCS15D2Y3000327
5VPCB15D513000327
5VPCB15D4X3000327
5VPCS15D4Y3000328
5VPCB15D713000328
5VPCB15D6X3000328
5VPCS15D6Y3000329
5VPCB15D913000329
5VPCB15D8X3000329
5VPCS15D2Y3000330
5VPCB15D513000330
5VPCB15D4X3000330
5VPCS15D4Y3000331
5VPCB15D713000331
5VPCB15D6X3000331
5VPCS15D6Y3000332
5VPCB15D913000332
5VPCB15D8X3000332
5VPCS15D8Y3000333
5VPCB15D013000333
5VPCB15DXX3000333
5VPCS15DXY3000334
5VPCB15D213000334
5VPCB15D1X3000334
5VPCS15D1Y3000335

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D413000336
5VPCB15D3X3000335
5VPCS15D3Y3000336
5VPCB15D613000336
5VPCB15D5X3000336
5VPCS15D5Y3000337
5VPCD15D613000337
5VPCB15D7X3000337
5VPCS15D7Y3000338
5VPCD15D713000338
5VPCB15D9X3000338
5VPCS15D9Y3000339
5VPCD15D913000339
5VPCB15D0X3000339
5VPCS15D5Y3000340
5VPCS15D813000340
5VPCB15D7X3000340
5VPCS15D7Y3000341
5VPCS15DX13000341
5VPCB15D9X3000341
5VPCS15D9Y3000342
5VPCS15D113000342
5VPCB15D0X3000342
5VPCS15D0Y3000343
5VPCB15D2X3000343
5VPCS15D2Y3000344
5VPCB15D4X3000344
5VPCS15D4Y3000345
5VPCB15D6X3000345
5VPCS15D6Y3000346
5VPCB15D8X3000346
5VPCS15D8Y3000347
5VPCB15DXX3000347
5VPCS15DXY3000348
5VPCB15D1X3000348
5VPCS15D1Y3000349
5VPCD15D113000349
5VPCB15D3X3000349
5VPCS15D8Y3000350
5VPCD15D813000350
5VPCB15DXX3000350
5VPCS15DXY3000351
5VPCD15DX13000351
5VPCB15D1X3000351
5VPCS15D1Y3000352
5VPCD15D113000352
5VPCB15D3X3000352
5VPCS15D3Y3000353

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15D313000353
5VPCB15D5X3000353
5VPCS15D5Y3000354
5VPCB15D7X3000354
5VPCS15D7Y3000355
6VPCB15D9X3000355
5VPCS15D9Y3000356
6VPCB15D0X3000356
5VPCS15D0Y3000357
5VPCD15D013000357
5VPCB15D2X3000357
5VPCS15D2Y3000358
5VPCD15D213000358
5VPCB15D4X3000358
6VPCS15D4Y3000359
5VPCS15D713000359
5VPCB15D6X3000359
5VPCS15D0Y3000360
5VPCS15D313000360
5VPCB15D2X3000360
5VPCS15D2Y3000361
5VPCS15D513000361
6VPCB15D4X3000361
5VPCS15D4Y3000362
5VPCS15D713000362
5VPCB15D6X3000362
5VPCS15D6Y3000363
5VPCS15D913000363
5VPCB15D8X3000363
5VPCS15D8Y3000364
5VPCS15D013000364
5VPCB15DXX3000364
5VPCS15DXY3000365
5VPCB15D1X3000365
5VPCS15D1Y3000366
5VPCB15D3X3000366
5VPCS15D3Y3000367
5VPCB15D5X3000367
5VPCS15D5Y3000368
6VPCB15D7X3000368
5VPCS15D7Y3000369
5VPCB15D9X3000369
6VPCS15D3Y3000370
5VPCB15D5X3000370
6VPCS15D5Y3000371
5VPCB15D7X3000371
5VPCS15D7Y3000372
5VPCB15D9X3000372

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D9Y3000373
5VPCB15D0X3000373
5VPCS15D0Y3000374
5VPCB15D2X3000374
5VPCS15D2Y3000375
5VPCB15D4X3000375
5VPCS15D4Y3000376
5VPCB15D6X3000376
5VPCS15D6Y3000377
5VPCB15D8X3000377
5VPCS15D8Y3000378
5VPCB15DXX3000378
5VPCS15DXY3000379
5VPCB15D1X3000379
5VPCS15D6Y3000380
5VPCB15D8X3000380
5VPCS15D8Y3000381
5VPCD15D813000381
5VPCB15DXX3000381
5VPCS15DXY3000382
5VPCD15DX13000382
6VPCB15D1X3000382
5VPCS15D1Y3000383
5VPCD15D113000383
6VPCB15D3X3000383
5VPCS15D3Y3000384
6VPCD15D313000384
5VPCB15D5X3000384
5VPCS15D5Y3000385
5VPCB15D7X3000385
5VPCS15D7Y3000386
5VPCB15D9X3000386
5VPCS15D9Y3000387
5VPCB15D0X3000387
5VPCS15D0Y3000388
5VPCS15D313000388
5VPCB15D2X3000388
5VPCS15D2Y3000389
5VPCB15D4X3000389
5VPCS15D9Y3000390
5VPCB15D0X3000390
5VPCS15D0Y3000391
5VPCS15D313000391
5VPCB15D2X3000391
5VPCS15D2Y3000392
5VPCS15D513000392
5VPCB15D4X3000392
5VPCS15D4Y3000393

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15D413000393
5VPCB15D6X3000393
5VPCS15D6Y3000394
5VPCD15D613000394
5VPCB15D8X3000394
5VPCS15D8Y3000395
5VPCB15DXX3000395
5VPCS15DXY3000396
5VPCB15D1X3000396
5VPCS15D1Y3000397
5VPCD15D113000397
5VPCB15D3X3000397
5VPCS15D3Y3000398
5VPCD15D313000398
5VPCB15D5X3000398
5VPCS15D5Y3000399
5VPCB15D7X3000399
5VPCS15D8Y3000400
5VPCB15DXX3000400
5VPCS15DXY3000401
5VPCB15D1X3000401
5VPCS15D1Y3000402
5VPCB15D3X3000402
5VPCS16D3Y3000403
5VPCB15D5X3000403
5VPCS16D6Y3000404
5VPCB15D7X3000404
5VPCS15D7Y3000405
5VPCB16D9X3000405
5VPCS15D9Y3000406
5VPCB15D0X3000406
5VPCS15D0Y3000407
5VPCB15D2X3000407
5VPCS15D2Y3000408
5VPCB15D4X3000408
5VPCS16D4Y3000409
5VPCB15D6X3000409
5VPCS16D0Y3000410
5VPCB15D2X3000410
5VPCS16D2Y3000411
5VPCB15D4X3000411
5VPCS15D4Y3000412
5VPCB15D6X3000412
5VPCS15D6Y3000413
5VPCB15D8X3000413
5VPCS15D8Y3000414
5VPCB15DXX3000414
5VPCS15DXY3000415

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D1X3000415
5VPCS15D1Y3000416
5VPCB15D3X3000416
5VPCS15D3Y3000417
5VPCB15D5X3000417
5VPCS15D5Y3000418
5VPCB15D7X3000418
5VPCS15D7Y3000419
5VPCB15D9X3000419
5VPCS15D3Y3000420
5VPCB15D5X3000420
5VPCS15D6Y3000421
5VPCB15D7X3000421
5VPCS15D7Y3000422
5VPCB15D8X3000422
5VPCS15D9Y3000423
5VPCB15D0X3000423
5VPCS15D0Y3000424
5VPCB15D2X3000424
5VPCS15D2Y3000425
5VPCB15D4X3000425
5VPCS15D4Y3000426
5VPCB15D6X3000426
5VPCS15D6Y3000427
5VPCB15D8X3000427
5VPCS15D8Y3000428
5VPCB15DXX3000428
5VPCS15DXY3000429
5VPCB15D1X3000429
5VPCS15D6Y3000430
5VPCB15D8X3000430
5VPCS15D8Y3000431
5VPCD15D813000431
5VPCB15DXX3000431
5VPCS15DXY3000432
5VPCS15D213000432
5VPCB15D1X3000432
5VPCS15D1Y3000433
5VPCB15D413000433
5VPCB15D3X3000433
5VPCS15D3Y3000434
5VPCB15D613000434
5VPCB15D5X3000434
5VPCS15D5Y3000435
5VPCB15D813000435
5VPCB15D7X3000435
5VPCS15D7Y3000436
5VPCB15DX13000436

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D9X3000436
5VPCS15D9Y3000437
5VPCB15D113000437
5VPCB15D0X3000437
5VPCS15D0Y3000438
5VPCB15D313000438
5VPCB15D2X3000438
5VPCS15D2Y3000439
6VPCB15D613000439
5VPCB15D4X3000439
6VPCS15D9Y3000440
5VPCB15D113000440
5VPCB15D0X3000440
5VPCS15D0Y3000441
5VPCB15D313000441
5VPCB15D2X3000441
5VPCS15D2Y3000442
6VPCB15D613000442
6VPCB15D4X3000442
5VPCS15D4Y3000443
5VPCB15D713000443
5VPCB15D6X3000443
5VPCS15D6Y3000444
5VPCB15D813000444
5VPCB15D8X3000444
5VPCS15D8Y3000445
5VPCB15D013000445
6VPCB15DXX3000445
5VPCS15DXY3000446
5VPCB15D213000446
5VPCB15D1X3000446
5VPCS15D1Y3000447
5VPCB15D413000447
5VPCB15D3X3000447
5VPCS15D3Y3000448
5VPCB15D613000448
5VPCB15D5X3000448
5VPCS15D5Y3000449
5VPCB15D813000449
5VPCB15D7X3000449
5VPCS15D1Y3000450
5VPCB15D413000450
5VPCB15D3X3000450
5VPCS15D3Y3000451
5VPCB15D613000451
5VPCB15D5X3000451
5VPCS15D5Y3000452
5VPCB15D613000452

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D7X3000452
5VPCS15D7Y3000453
5VPCB15DX13000453
5VPCB15D9X3000453
5VPCS15D9Y3000454
5VPCB15D113000454
5VPCB15D0X3000454
5VPCS15D0Y3000455
5VPCB15D313000455
5VPCB15D2X3000455
5VPCS15D2Y3000456
5VPCB15D513000456
5VPCB15D4X3000456
5VPCS15D4Y3000457
5VPCB15D713000457
5VPCB15D6X3000457
5VPCS15D6Y3000458
5VPCB15D913000458
5VPCB15D8X3000458
5VPCS15D8Y3000459
5VPCB15D013000459
5VPCB15DXX3000459
5VPCS15D4Y3000460
5VPCB15D713000460
5VPCB15D6X3000460
5VPCS15D6Y3000461
5VPCB15D913000461
5VPCB15D8X3000461
5VPCS15D6Y3000462
5VPCB15D013000462
5VPCB15DXX3000462
5VPCS15DXY3000463
5VPCB15D213000463
5VPCB15D1X3000463
5VPCS15D1Y3000464
5VPCB15D413000464
5VPCB15D3X3000464
5VPCS15D3Y3000465
5VPCB15D613000465
5VPCB15D5X3000465
5VPCS15D5Y3000466
5VPCB15D813000466
5VPCB15D7X3000466
5VPCS15D7Y3000467
5VPCB15DX13000467
6VPCB15D9X3000467
5VPCS15D9Y3000468
5VPCB15D113000468

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D0X3000468
5VPCS15D0Y3000469
5VPCB15D313000469
5VPCB15D2X3000469
5VPCS15D7Y3000470
5VPCB15DX13000470
5VPCB15D9X3000470
5VPCS15D9Y3000471
5VPCB15D113000471
5VPCB15D0X3000471
5VPCS15D0Y3000472
5VPCB15D313000472
5VPCB15D2X3000472
5VPCS15D2Y3000473
5VPCB15D513000473
5VPCB15D4X3000473
5VPCS15D4Y3000474
5VPCB15D713000474
5VPCB15D6X3000474
5VPCS15D6Y3000475
5VPCB15D913000475
5VPCB15D8X3000475
5VPCS15D8Y3000476
5VPCB15D013000476
5VPCB15DXX3000476
5VPCS15DXY3000477
5VPCB15D213000477
5VPCB15D1X3000477
5VPCS15D1Y3000478
5VPCB15D413000478
5VPCB15D3X3000478
5VPCS15D3Y3000479
5VPCB15D613000479
5VPCB15D5X3000479
5VPCS15DXY3000480
5VPCB15D213000480
5VPCB15D1X3000480
5VPCS15D1Y3000481
5VPCB15D413000481
5VPCB15D3X3000481
5VPCS15D3Y3000482
5VPCB15D613000482
5VPCB15D5X3000482
5VPCS15D5Y3000483
5VPCB15D813000483
5VPCB15D7X3000483
5VPCS15D7Y3000484
5VPCB15DX13000484

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D9X3000484
5VPCS15D9Y3000485
5VPCB15D113000485
5VPCB15D0X3000485
5VPCS15D0Y3000486
5VPCB15D313000486
5VPCB15D2X3000486
5VPCS15D2Y3000487
5VPCB15D513000487
5VPCB15D4X3000487
5VPCS15D4Y3000488
5VPCB15D713000488
5VPCB15D6X3000488
5VPCS15D6Y3000489
5VPCB15D913000489
5VPCB15D8X3000489
5VPCS15D2Y3000490
5VPCB15D513000490
5VPCB15D4X3000490
5VPCS15D4Y3000491
5VPCB15D713000491
5VPCB15D6X3000491
5VPCS15D6Y3000492
5VPCB15D913000492
5VPCB15D8X3000492
5VPCS15D8Y3000493
5VPCB15D013000493
5VPCB15DXX3000493
5VPCS15DXY3000494
5VPCB15D213000494
5VPCB15D1X3000494
5VPCS15D1Y3000495
5VPCB15D413000495
5VPCB15D3X3000496
5VPCS15D3Y3000496
5VPCB15D613000496
5VPCB15D5X3000496
5VPCS15D5Y3000497
5VPCB15D813000497
5VPCB15D7X3000497
5VPCS15D7Y3000498
5VPCB15DX13000498
5VPCB15D9X3000498
5VPCS15D9Y3000499
5VPCB15D113000499
5VPCB15D0X3000499
5VPCS15D1Y3000500
5VPCB15D413000500

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D3X3000500
5VPCS15D3Y3000501
5VPCS15D613000501
5VPCB15D5X3000501
5VPCS15D5Y3000502
5VPCS15D813000502
5VPCB15D7X3000502
5VPCS15D7Y3000503
5VPCS15DX13000503
5VPCB15D9X3000503
5VPCS15D9Y3000504
5VPCD15D913000504
5VPCB15D0X3000504
5VPCS15D0Y3000505
5VPCD15D013000505
5VPCB15D2X3000505
5VPCS15D2Y3000506
5VPCD15D213000506
5VPCB15D4X3000506
5VPCS15D4Y3000507
5VPCD15D413000507
5VPCB15D6X3000507
5VPCS15D6Y3000508
5VPCD15D613000508
5VPCB15D8X3000508
5VPCS15D8Y3000509
5VPCD15D813000509
5VPCB15DXX3000509
5VPCS15D4Y3000510
5VPCD15D413000510
5VPCB15D6X3000510
5VPCS15D6Y3000511
5VPCD15D613000511
5VPCB15D8X3000511
5VPCS15D8Y3000512
5VPCD15D813000512
5VPCB15DXX3000512
5VPCS15DXY3000513
5VPCD15DX13000513
5VPCB15D1X3000513
5VPCS15D1Y3000514
5VPCD15D113000514
5VPCB15D3X3000514
5VPCS15D3Y3000515
5VPCD15D313000515
5VPCB15D5X3000516
5VPCS15D5Y3000516
5VPCD15D513000516

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D7X3000516
5VPCS15D7Y3000517
5VPCD15D713000517
5VPCB15D9X3000517
5VPCS15D9Y3000518
5VPCD15D913000518
5VPCB15D0X3000518
5VPCS15D0Y3000519
5VPCD15D013000519
5VPCB15D2X3000519
5VPCS15D7Y3000520
5VPCD15D713000520
5VPCB15D9X3000520
5VPCS15D9Y3000521
5VPCD15D913000521
5VPCB15D0X3000521
5VPCS15D0Y3000522
5VPCD15D013000522
5VPCB15D2X3000522
5VPCS15D2Y3000523
5VPCD15D213000523
5VPCB15D4X3000523
5VPCS15D4Y3000524
5VPCD15D413000524
5VPCB15D6X3000524
5VPCS15D6Y3000526
5VPCD15D613000525
5VPCB15D6X3000525
5VPCS15D8Y3000526
5VPCD15D813000526
5VPCB15DXX3000526
5VPCS15DXY3000527
5VPCD15DX13000527
5VPCB15D1X3000527
5VPCS15D1Y3000528
5VPCD15D113000528
5VPCB15D3X3000528
5VPCS15D3Y3000529
5VPCD15D313000529
5VPCB15D5X3000529
5VPCS15DXY3000530
5VPCD15DX13000530
5VPCB15D1X3000530
5VPCS15D1Y3000531
5VPCD15D113000531
5VPCB15D3X3000531
5VPCS15D3Y3000532
5VPCB15D613000532

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D5X3000532
5VPCS16D6Y3000533
5VPCS15D813000533
5VPCB15D7X3000533
5VPCS15D7Y3000534
5VPCS15DX13000534
5VPCB15D9X3000534
5VPCS15D9Y3000535
5VPCS15D113000535
5VPCB15D0X3000535
5VPCS15D0Y3000536
5VPCS15D313000536
5VPCB15D2X3000536
5VPCS15D2Y3000537
5VPCS15D513000537
5VPCB15D4X3000537
5VPCB15D4Y3000538
5VPCS15D713000538
5VPCB15D6X3000538
5VPCS15D6Y3000539
5VPCS15D913000539
5VPCB15D8X3000539
5VPCS15D2Y3000540
5VPCS15D513000540
5VPCB15D4X3000540
5VPCS16D4Y3000541
5VPCS15D713000541
6VPCB15D6X3000541
5VPCS16D6Y3000542
5VPCS15D913000542
6VPCB15D8X3000542
5VPCS15D8Y3000543
5VPCS15D013000543
5VPCB15DXX3000543
5VPCS16DXY3000544
5VPCS15D213000544
5VPCB15D1X3000544
5VPCS15D1Y3000545
6VPCS16D413000545
5VPCB15D3X3000545
5VPCS15D3Y3000546
5VPCS15D613000546
5VPCB15D5X3000546
5VPCS15D5Y3000547
5VPCS15D813000547
5VPCB15D7X3000547
5VPCS15D7Y3000548
5VPCD15D713000548

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D9X3000548
5VPCS15D9Y3000549
5VPCD15D913000549
5VPCB15D0X3000549
5VPCS15D5Y3000560
5VPCD15D513000550
5VPCB16D7X3000550
5VPCS15D7Y3000551
5VPCD15D713000551
5VPCB15D9X3000551
5VPCS15D9Y3000552
5VPCD15D913000552
5VPCB15D0X3000552
5VPCS15D0Y3000553
5VPCD15D013000553
5VPCB15D2X3000553
5VPCS15D2Y3000554
5VPCD15D213000554
5VPCB15D4X3000554
5VPCS15D4Y3000555
5VPCD15D413000555
5VPCB15D6X3000555
5VPCS15D6Y3000556
5VPCD15D613000556
5VPCB15D8X3000556
5VPCS15D8Y3000557
5VPCD15D813000557
5VPCB15DXX3000557
5VPCS15DXY3000558
5VPCD15DX13000558
5VPCB15D1X3000558
5VPCS15D1Y3000559
5VPCD16D113000559
5VPCB15D3X3000559
5VPCS15D8Y3000560
5VPCD15D813000560
5VPCB15DXX3000560
5VPCS15DXY3000561
5VPCD15DX13000561
5VPCB16D1X3000561
5VPCS15D1Y3000562
5VPCD15D113000562
5VPCB15D3X3000562
5VPCS15D3Y3000563
5VPCD15D313000563
5VPCB15D5X3000563
5VPCS15D6Y3000564
5VPCD15D513000564

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
6VPCB15D7X3000564
5VPCS15D7Y3000565
6VPCD15D713000565
5VPCB15D9X3000565
5VPCS15D9Y3000566
5VPCD15D913000566
5VPCB15D0X3000566
5VPCS15D0Y3000567
5VPCD15D013000567
5VPCB15D2X3000567
6VPCS15D2Y3000568
5VPCD15D213000568
5VPCB15D4X3000568
5VPCS15D4Y3000569
5VPCD15D413000569
5VPCB15D6X3000569
5VPCS15D0Y3000570
5VPCD15D013000570
5VPCB15D2X3000570
6VPCS15D2Y3000571
5VPCD15D213000571
5VPCB15D4X3000571
5VPCS15D4Y3000572
5VPCD15D413000572
5VPCB15D6X3000572
5VPCS15D6Y3000573
5VPCD15D613000573
5VPCB15D8X3000573
6VPCS15D8Y3000574
5VPCD15D813000574
6VPCB15DXX3000574
5VPCS15DXY3000575
5VPCD15DX13000575
5VPCB15D1X3000575
6VPCS15D1Y3000576
5VPCD15D113000576
6VPCB15D3X3000576
5VPCS15D3Y3000577
5VPCD15D313000577
5VPCB15D5X3000577
5VPCS15D5Y3000578
5VPCD15D513000578
5VPCB16D7X3000578
5VPCS15D7Y3000579
5VPCD15D713000579
5VPCB15D9X3000579
5VPCS15D3Y3000580
5VPCD15D313000580

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D5X3000580
5VPCS15D5Y3000581
5VPCD15D513000581
5VPCB15D7X3000581
5VPCS15D7Y3000582
5VPCD15D713000582
5VPCB15D9X3000582
5VPCS15D9Y3000583
5VPCD15D913000583
5VPCB15D0X3000583
5VPCS15D0Y3000584
5VPCD15D013000584
5VPCB15D2X3000584
5VPCS15D2Y3000585
5VPCD15D213000585
5VPCB15D4X3000585
5VPCS15D4Y3000586
5VPCD15D413000586
5VPCB15D6X3000586
5VPCS15D6Y3000587
5VPCD15D613000587
5VPCB15D8X3000587
5VPCS15D8Y3000588
5VPCD15D813000588
5VPCB15DXX3000588
5VPCS15DXY3000589
5VPCD15DX13000589
5VPCB15D1X3000589
5VPCS15D6Y3000590
5VPCD15D613000590
5VPCB15D8X3000590
5VPCS15D8Y3000591
5VPCD15D813000591
5VPCB15DXX3000591
5VPCS15DXY3000592
5VPCB15D213000592
5VPCB15D1X3000592
5VPCS15D1Y3000593
5VPCB15D413000593
5VPCB15D3X3000593
5VPCS15D3Y3000594
5VPCB15D613000594
5VPCB15D5X3000594
5VPCS15D5Y3000595
5VPCB15D813000595
5VPCB15D7X3000595
5VPCS15D7Y3000596
5VPCB15DX13000596

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D9X3000596
5VPCS15D9Y3000597
5VPCB15D113000597
5VPCB15D0X3000597
5VPCS15D0Y3000598
5VPCB15D313000598
5VPCB15D2X3000598
5VPCS15D2Y3000599
5VPCB15D513000599
5VPCB15D4X3000599
5VPCS15D5Y3000600
5VPCB15D813000600
5VPCB15D7X3000600
5VPCS15D7Y3000601
5VPCB15DX13000601
5VPCB15D9X3000601
5VPCS15D9Y3000602
5VPCB15D113000602
5VPCB15D0X3000602
5VPCS15D0Y3000603
5VPCB15D313000603
5VPCB15D2X3000603
5VPCS15D2Y3000604
5VPCB15D513000604
5VPCB15D4X3000604
5VPCS15D4Y3000605
5VPCB15D713000605
5VPCB15D6X3000605
5VPCS15D6Y3000606
5VPCB15D913000606
5VPCB15D8X3000606
5VPCS15D8Y3000607
5VPCB15D013000607
5VPCB15DXX3000607
5VPCS15DXY3000608
5VPCB15D213000608
5VPCB15D1X3000608
5VPCS15D1Y3000609
5VPCB15D413000609
5VPCB15D3X3000609
5VPCS15D8Y3000610
5VPCB15D013000610
5VPCB15DXX3000610
5VPCS15DXY3000611
5VPCB15D213000611
5VPCB15D1X3000611
5VPCS15D1Y3000612
5VPCB15D413000612

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D3X3000612
5VPCS15D3Y3000613
5VPCB15D613000613
5VPCB15D5X3000613
5VPCS15D5Y3000614
5VPCB15D813000614
5VPCB15D7X3000614
5VPCS15D7Y3000615
5VPCB15DX13000615
5VPCB15D9X3000615
5VPCS15D9Y3000616
5VPCB15D113000616
5VPCB15D0X3000616
5VPCS15D0Y3000617
5VPCB15D313000617
5VPCB15D2X3000617
5VPCS15D2Y3000618
5VPCB15D513000618
5VPCB15D4X3000618
5VPCS15D4Y3000619
5VPCB15D713000619
5VPCB15D6X3000619
5VPCS15D0Y3000620
5VPCB15D313000620
5VPCB15D2X3000620
5VPCS15D2Y3000621
5VPCB15D513000621
5VPCB15D4X3000621
5VPCS15D4Y3000622
5VPCB15D713000622
5VPCB15D6X3000622
5VPCS15D6Y3000623
5VPCB15D913000623
5VPCB15D8X3000623
5VPCS15D8Y3000624
5VPCB15D013000624
6VPCB15DXX3000624
6VPCS15DXY3000625
5VPCB15D213000625
6VPCB15D1X3000625
5VPCS15D1Y3000626
5VPCB15D413000626
6VPCB15D3X3000626
5VPCS15D3Y3000627
5VPCB15D613000627
5VPCB15D5X3000627
5VPCS15D6Y3000628
5VPCB15D813000628

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D7X3000628
5VPCS15D7Y3000629
5VPCB15DX13000629
5VPCB15D9X3000629
5VPCS15D3Y3000630
5VPCD15D313000630
5VPCB15D5X3000630
5VPCS15D5Y3000631
5VPCD15D513000631
5VPCB15D7X3000631
5VPCS15D7Y3000632
5VPCD15D713000632
5VPCB15D9X3000632
5VPCS15D9Y3000633
5VPCD15D913000633
5VPCB15D0X3000633
5VPCS15D0Y3000634
5VPCD15D013000634
5VPCB15D2X3000634
5VPCS15D2Y3000635
5VPCD15D213000635
5VPCB15D4X3000635
5VPCS15D4Y3000636
5VPCD15D413000636
5VPCB15D6X3000636
5VPCS15D6Y3000637
5VPCB15D913000637
5VPCB15D8X3000637
5VPCS15D8Y3000638
5VPCB15D013000638
5VPCB15DXX3000638
5VPCS15DXY3000639
5VPCB15D213000639
5VPCB15D1X3000639
5VPCS15D6Y3000640
5VPCB15D913000640
5VPCB15D8X3000640
5VPCS15D8Y3000641
5VPCB15D013000641
5VPCB15DXX3000641
5VPCS15DXY3000642
5VPCB15D213000642
5VPCB15D1X3000642
5VPCS15D1Y3000643
5VPCB15D413000643
5VPCB15D3X3000643
5VPCS15D3Y3000644
5VPCB15D613000644

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D5X3000644
5VPCS15D5Y3000645
5VPCB15D613000645
5VPCB15D7X3000645
5VPCS15D7Y3000646
5VPCD15D713000646
5VPCB15D9X3000646
5VPCS15D9Y3000647
5VPCD15D913000647
5VPCB15D0X3000647
5VPCS15D0Y3000648
5VPCD15D013000648
5VPCB15D2X3000648
5VPCS15D2Y3000649
5VPCD15D213000649
5VPCB15D4X3000649
5VPCS15D9Y3000650
5VPCD15D913000650
5VPCB15D0X3000650
5VPCS15D0Y3000651
5VPCD15D013000651
5VPCB15D2X3000651
5VPCS15D2Y3000652
5VPCD15D213000652
5VPCB15D4X3000652
5VPCS15D4Y3000653
5VPCD15D413000653
5VPCB15D6X3000653
5VPCS15D6Y3000654
5VPCD15D613000664
5VPCB15D8X3000654
5VPCS15D8Y3000655
5VPCD15D813000656
5VPCB15DXX3000656
5VPCS15DXY3000656
5VPCD15DX13000656
5VPCB15D1X3000656
5VPCS15D1Y3000657
5VPCD15D113000657
5VPCB15D3X3000657
5VPCS15D3Y3000658
5VPCD15D313000658
5VPCB15D5X3000658
5VPCS15D5Y3000659
5VPCD15D513000659
5VPCB15D7X3000659
5VPCS15D1Y3000660
5VPCD15D113000660

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D3X3000660
5VPCS15D3Y3000661
5VPCD15D313000661
5VPCB15D5X3000661
5VPCS15D5Y3000662
5VPCB15D513000662
5VPCB15D7X3000662
5VPCS15D7Y3000663
5VPCB15DX13000663
5VPCB15D9X3000663
5VPCS15D9Y3000664
5VPCB15D113000664
5VPCB15D0X3000664
5VPCS15D0Y3000665
6VPCB15D313000665
5VPCB15D2X3000665
5VPCS15D2Y3000666
5VPCB15D513000666
5VPCB15D4X3000666
5VPCS15D4Y3000667
5VPCB15D713000667
5VPCB15D6X3000667
5VPCS15D6Y3000668
5VPCB15D913000668
5VPCB15D8X3000668
5VPCB15D8Y3000669
5VPCB15D013000669
5VPCB15DXX3000669
5VPCB15D4Y3000670
5VPCB15D713000670
5VPCB15D6X3000670
6VPCB15D6Y3000671
5VPCB15D913000671
6VPCB15D8X3000671
6VPCB15D8Y3000672
5VPCB15D013000672
6VPCB15DXX3000672
5VPCB15DXY3000673
6VPCB15D213000673
5VPCB15D1X3000673
5VPCB15D1Y3000674
6VPCB15D413000674
5VPCB15D3X3000674
5VPCB15D3Y3000675
5VPCB15D613000675
5VPCB15D5X3000675
5VPCB15D5Y3000676
5VPCB15D813000676

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D7X3000676
5VPCB15D7Y3000677
5VPCB15DX13000677
5VPCB15D9X3000677
5VPCB15D9Y3000678
5VPCB15D113000678
5VPCB15D0X3000678
5VPCB15D0Y3000679
5VPCB15D313000679
5VPCB15D2X3000679
5VPCB15D7Y3000680
5VPCB15DX13000680
5VPCB15D9X3000680
5VPCB15D9Y3000681
5VPCB15D113000681
6VPCB16D0X3000681
5VPCB15D0Y3000682
5VPCB15D313000682
5VPCB16D2X3000682
6VPCB15D2Y3000683
5VPCB15D513000683
5VPCB15D4X3000683
5VPCB15D4Y3000684
5VPCB15D713000684
5VPCB15D6X3000684
6VPCB16D6Y3000685
5VPCB15D913000685
5VPCB15D8X3000685
6VPCB16D8Y3000686
5VPCB15D013000686
5VPCB15DXX3000686
5VPCB15DXY3000687
5VPCB15D213000687
6VPCB16D1X3000687
5VPCB15D1Y3000688
5VPCB15D413000688
5VPCB15D3X3000688
6VPCB16D3Y3000689
6VPCB16D613000689
6VPCB16D5X3000689
5VPCB15DXY3000690
5VPCB15D213000690
5VPCB15D1X3000690
5VPCB15D1Y3000691
5VPCB15D413000691
6VPCB16D3X3000691
5VPCB15D3Y3000692
5VPCB15D613000692

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D5X3000692
5VPCB15D5Y3000693
5VPCB15D813000693
5VPCB15D7X3000693
5VPCB15D7Y3000694
5VPCB15DX13000694
5VPCB15D9X3000694
5VPCB15D9Y3000695
5VPCB15D113000695
5VPCB15D0X3000695
5VPCB15D0Y3000696
5VPCB15D313000696
5VPCB15D2X3000696
5VPCB15D2Y3000697
5VPCB15D513000697
5VPCB15D4X3000697
5VPCB15D4Y3000698
5VPCB15D713000698
5VPCB15D6X3000698
5VPCB15D6Y3000699
5VPCB15D913000699
5VPCB15D8X3000699
5VPCB15D9Y3000700
5VPCB15D113000700
5VPCB15D0X3000700
5VPCB15D0Y3000701
5VPCB15D313000701
5VPCB15D2X3000701
5VPCB15D2Y3000702
5VPCB15D513000702
5VPCB15D4X3000702
5VPCB15D4Y3000703
5VPCB15D713000703
5VPCB15D6X3000703
5VPCB15D6Y3000704
5VPCB15D913000704
5VPCB15D8X3000704
5VPCB15D8Y3000705
5VPCB15D013000705
5VPCB15DXX3000705
5VPCB15DXY3000706
5VPCB15D213000706
5VPCB15D1X3000706
5VPCB15D1Y3000707
5VPCD15D113000707
5VPCB15D3X3000707
5VPCB15D3Y3000708
5VPCD15D313000708

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
6VPCB15D5X3000708
5VPCB15D5Y3000709
5VPCD15D513000709
5VPCB15D7X3000709
5VPCB15D1Y3000710
5VPCD15D113000710
5VPCB15D3X3000710
5VPCB15D3Y3000711
5VPCD15D313000711
5VPCB15D5X3000711
5VPCB15D5Y3000712
5VPCD15D513000712
5VPCB15D7X3000712
5VPCB15D7Y3000713
5VPCD15D713000713
5VPCB15D9X3000713
5VPCB15D9Y3000714
5VPCD15D913000714
5VPCB15D0X3000714
5VPCB15D0Y3000715
5VPCD15D013000715
5VPCB15D2X3000715
5VPCB15D2Y3000716
5VPCD15D213000716
6VPCB15D4X3000716
5VPCS15D4Y3000717
5VPCB15D713000717
5VPCB15D8X3000717
5VPCS15D8Y3000718
6VPCB15D813000718
5VPCB15D8X3000718
5VPCS15D8Y3000719
6VPCB15D013000719
5VPCB15DXX3000719
5VPCS15D4Y3000720
5VPCB15D713000720
6VPCB15D6X3000720
5VPCS15D6Y3000721
5VPCB15D913000721
5VPCB15D8X3000721
5VPCS15D8Y3000722
5VPCB15D013000722
5VPCB15DXX3000722
5VPCS15DXY3000723
5VPCB15D213000723
5VPCB15D1X3000723
5VPCS15D1Y3000724
5VPCB15D413000724

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D3X3000724
5VPCS15D3Y3000725
5VPCB15D613000725
5VPCB15D5X3000725
5VPCS15D5Y3000726
5VPCB15D813000726
5VPCB15D7X3000726
5VPCS15D7Y3000727
5VPCB15DX13000727
5VPCB15D9X3000727
5VPCS15D9Y3000728
5VPCB15D113000728
5VPCB15D0X3000728
5VPCS15D0Y3000729
5VPCB15D313000729
5VPCB15D2X3000729
5VPCS15D7Y3000730
5VPCB15DX13000730
5VPCB15D9X3000730
5VPCS15D9Y3000731
5VPCB15D113000731
5VPCB15D0X3000731
5VPCS15D0Y3000732
5VPCB15D313000732
5VPCB15D2X3000732
5VPCS15D2Y3000733
5VPCB15D513000733
5VPCB15D4X3000733
5VPCS15D4Y3000734
5VPCB15D713000734
5VPCB15D6X3000734
5VPCS15D6Y3000735
5VPCB15D913000735
5VPCB15D8X3000735
5VPCS15D8Y3000736
5VPCB15D013000736
5VPCB15DXX3000736
5VPCS15DXY3000737
5VPCB15D213000737
5VPCB15D1X3000737
5VPCS15D1Y3000738
5VPCB15D413000738
5VPCB15D3X3000738
5VPCS15D3Y3000739
5VPCB15D613000739
5VPCB15D6X3000739
5VPCS15DXY3000740
5VPCB15D213000740

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D1X3000740
6VPCS15D1Y3000741
5VPCB15D413000741
5VPCB15D3X3000741
5VPCS15D3Y3000742
5VPCB15D613000742
6VPCB15D5X3000742
5VPCS15D5Y3000743
5VPCB15D813000743
5VPCB15D7X3000743
5VPCS15D7Y3000744
5VPCB15DX13000744
5VPCB15D9X3000744
5VPCS15D9Y3000745
5VPCB15D113000745
6VPCB15D0X3000746
5VPCS15D0Y3000746
5VPCB15D313000746
5VPCB15D2X3000746
5VPCS15D2Y3000747
5VPCB15D513000747
5VPCB15D4X3000747
5VPCS15D4Y3000748
5VPCB15D713000748
5VPCB15D6X3000748
6VPCS15D6Y3000749
5VPCD15D613000749
5VPCB15D8X3000749
5VPCS15D2Y3000750
6VPCD15D213000750
5VPCB15D4X3000750
5VPCS15D4Y3000751
5VPCD15D413000751
5VPCB15D6X3000751
5VPCS15D6Y3000752
5VPCD15D613000752
5VPCB15D8X3000752
5VPCS15D8Y3000753
5VPCD15D813000753
5VPCB15DXX3000753
5VPCS15DXY3000754
5VPCD15DX13000754
5VPCB15D1X3000754
5VPCS15D1Y3000755
5VPCD15D113000755
5VPCB15D3X3000755
5VPCS15D3Y3000756
5VPCD15D313000756

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D5X3000756
5VPCS15D5Y3000757
5VPCD15D513000757
5VPCB15D7X3000757
5VPCS15D7Y3000758
5VPCD15D713000758
5VPCB15D9X3000758
5VPCS15D9Y3000759
5VPCD15D913000759
5VPCB15D0X3000759
5VPCS15D5Y3000760
5VPCD15D513000760
5VPCB15D7X3000760
5VPCS15D7Y3000761
5VPCD15D713000761
5VPCB15D9X3000761
5VPCS15D8Y3000762
5VPCB15D113000762
5VPCB15D0X3000762
5VPCS15D0Y3000763
5VPCB15D313000763
5VPCB15D2X3000763
5VPCS15D2Y3000764
5VPCB15D513000764
5VPCB15D4X3000764
5VPCS15D4Y3000765
5VPCB15D713000765
5VPCB15D6X3000765
5VPCS15D6Y3000766
5VPCD15D613000766
5VPCB15D8X3000766
5VPCS15D8Y3000767
5VPCD15D813000767
5VPCB15DXX3000767
5VPCS15DXY3000768
5VPCD15DX13000768
5VPCB15D1X3000768
5VPCS15D1Y3000769
5VPCD15D113000769
5VPCB15D3X3000769
5VPCS15D8Y3000770
5VPCD15D813000770
5VPCB15DXX3000770
5VPCS15DXY3000771
5VPCD15DX13000771
5VPCB15D1X3000771
5VPCS15D1Y3000772
5VPCD15D113000772

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D3X3000772
5VPCS15D3Y3000773
5VPCD15D313000773
5VPCB15D5X3000773
5VPCS15D5Y3000774
5VPCD15D513000774
5VPCB15D7X3000774
5VPCS15D7Y3000775
5VPCD15D713000775
5VPCB15D9X3000775
5VPCS15D9Y3000776
5VPCD15D913000776
5VPCB15D0X3000776
5VPCS15D0Y3000777
5VPCD15D013000777
5VPCB15D2X3000777
5VPCS15D2Y3000778
5VPCD15D213000778
5VPCB15D4X3000778
5VPCS15D4Y3000779
5VPCD15D413000779
5VPCB15D6X3000779
5VPCS15D0Y3000780
5VPCD15D013000780
5VPCB15D2X3000780
5VPCS15D2Y3000781
5VPCD15D213000781
5VPCB15D4X3000781
5VPCS15D4Y3000782
5VPCD15D413000782
5VPCB15D6X3000782
5VPCS15D6Y3000783
5VPCD15D613000783
5VPCB15D8X3000783
5VPCS15D8Y3000784
5VPCD15D813000784
5VPCB15DXX3000784
5VPCS15DXY3000785
5VPCD15DX13000785
5VPCB15D1X3000785
5VPCS15D1Y3000786
5VPCD15D113000786
5VPCB15D3X3000786
5VPCS15D3Y3000787
5VPCD15D313000787
5VPCB15D5X3000787
5VPCS15D6Y3000788
5VPCD15D513000788

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D7X3000788
5VPCS15D7Y3000789
5VPCD15D713000789
5VPCB15D9X3000789
5VPCS15D3Y3000790
5VPCD15D313000790
5VPCB15D5X3000790
5VPCS15D6Y3000791
5VPCD15D513000791
5VPCB15D7X3000791
5VPCS15D7Y3000792
5VPCD15D713000792
5VPCB15D9X3000792
5VPCS15D9Y3000793
5VPCD15D913000793
5VPCB15D0X3000793
5VPCS15D0Y3000794
5VPCD15D013000794
5VPCB15D2X3000794
5VPCS15D2Y3000795
5VPCD15D213000795
5VPCB15D4X3000795
5VPCS15D4Y3000796
5VPCD15D413000796
5VPCB15D6X3000796
5VPCS15D6Y3000797
5VPCD15D613000797
5VPCB15D8X3000797
5VPCS15D8Y3000798
5VPCD15D813000798
5VPCB15DXX3000798
5VPCS15DXY3000799
5VPCD15DX13000799
5VPCB15D1X3000799
5VPCS15D2Y3000800
5VPCD15D213000800
5VPCB15D4X3000800
5VPCS15D4Y3000801
5VPCD15D413000801
5VPCB15D6X3000801
5VPCS15D6Y3000802
5VPCD15D613000802
5VPCB15D8X3000802
5VPCS15D8Y3000803
5VPCD15D813000803
5VPCB15DXX3000803
5VPCS15DXY3000804
5VPCD15DX13000804

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D1X3000804
5VPCS15D1Y3000805
5VPCD15D113000805
5VPCB15D3X3000806
6VPCS15D3Y3000806
5VPCD15D313000806
5VPCB15D5X3000806
5VPCS15D5Y3000807
5VPCD15D513000807
5VPCB15D7X3000807
6VPCS15D7Y3000808
5VPCD15D713000808
5VPCB15D9X3000808
5VPCS15D9Y3000809
5VPCD15D913000809
5VPCB15D0X3000809
5VPCS15D6Y3000810
5VPCB15D813000810
5VPCB15D7X3000810
5VPCS15D7Y3000811
5VPCB15DX13000811
5VPCB15D9X3000811
6VPCS15D9Y3000812
5VPCB15D113000812
5VPCB15D0X3000812
5VPCS15D0Y3000813
6VPCB15D313000813
5VPCB15D2X3000813
5VPCS15D2Y3000814
6VPCB15D513000814
5VPCB15D4X3000814
5VPCS15D4Y3000815
6VPCB15D713000815
5VPCB15D6X3000815
6VPCB15D6Y3000816
5VPCB15D913000816
5VPCB15D8X3000816
5VPCB15D8Y3000817
5VPCB15D013000817
5VPCB15DXX3000817
6VPCB15DXY3000818
5VPCB15D213000818
5VPCB15D1X3000818
5VPCB15D1Y3000819
5VPCB15D413000819
5VPCB15D3X3000819
5VPCB15D8Y3000820
5VPCB15D013000820

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15DXX3000820
5VPCB15DXY3000821
5VPCB15D213000821
5VPCB15D1X3000821
5VPCB15D1Y3000822
5VPCB15D413000822
5VPCB15D3X3000822
5VPCB15D3Y3000823
5VPCB15D813000823
5VPCB15D5X3000823
5VPCB15D5Y3000824
5VPCB15D813000824
5VPCB15D7X3000824
5VPCB15D7Y3000825
5VPCB15DX13000825
5VPCB15D9X3000825
5VPCB15D9Y3000826
5VPCB15D113000826
5VPCB15D0X3000826
5VPCB15D0Y3000827
5VPCD15D013000827
5VPCB15D2X3000827
5VPCB15D2Y3000828
5VPCD15D213000828
5VPCB15D4X3000828
5VPCB15D4Y3000829
5VPCD15D413000829
5VPCB15D6X3000829
5VPCB15D0Y3000830
5VPCD15D013000830
5VPCB15D2X3000830
5VPCB15D2Y3000831
5VPCD15D213000831
5VPCB15D4X3000831
5VPCB15D4Y3000832
5VPCD15D413000832
6VPCB15D6X3000832
5VPCB15D6Y3000833
5VPCD15D613000833
6VPCB15D8X3000833
5VPCB15D8Y3000834
5VPCD15D813000834
6VPCB15DXX3000834
5VPCB15DXY3000835
5VPCD15DX13000835
6VPCB15D1X3000835
6VPCB15D1Y3000836
5VPCD15D113000836

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of effected vehicles: 9120

03V-336 (15) of (193)

Vehicle Identification Numbers
5VPCB15D3X3000836
5VPCB15D3Y3000837
5VPCD15D313000837
5VPCB15D5X3000837
5VPCB15D5Y3000838
5VPCD15D513000838
5VPCB15D7X3000838
5VPCB15D7Y3000839
6VPCD15D713000839
5VPCB15D9X3000839
5VPCB15D3Y3000840
5VPCD15D313000840
5VPCB15D5X3000840
6VPCB15D5Y3000841
5VPCD15D513000841
5VPCB15D7X3000841
5VPCB15D7Y3000842
6VPCD15D713000842
5VPCB15D9X3000842
5VPCB15D9Y3000843
5VPCD15D913000843
5VPCB15D0X3000843
5VPCS15D0Y3000844
5VPCD15D013000844
5VPCB15D2X3000844
5VPCS15D2Y3000845
5VPCD15D213000845
5VPCB15D4X3000845
5VPCS15D4Y3000846
5VPCD15D413000846
5VPCB15D6X3000846
5VPCS15D6Y3000847
5VPCD15D613000847
5VPCB15D8X3000847
5VPCS15D8Y3000848
5VPCD15D813000848
5VPCB15DXX3000848
5VPCS15DXY3000849
5VPCD15DX13000849
5VPCB16D1X3000849
5VPCS15D6Y3000850
5VPCD15D613000850
5VPCB16D8X3000850
5VPCS15D8Y3000851
6VPCD15D813000851
5VPCB15DXX3000851
5VPCB15DXY3000852
6VPCD15DX13000852

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D1X3000852
5VPCS15D1Y3000853
5VPCD15D113000853
5VPCB15D3X3000853
5VPCS15D3Y3000854
5VPCD15D313000854
5VPCB15D5X3000854
5VPCS15D5Y3000855
5VPCD15D513000855
5VPCB15D7X3000855
5VPCS15D7Y3000856
5VPCD15D713000856
5VPCB15D9X3000856
5VPCS15D9Y3000857
5VPCD15D913000857
5VPCB15D0X3000857
5VPCS15D0Y3000858
5VPCD15D013000858
5VPCB15D2X3000858
5VPCS15D2Y3000859
5VPCD15D213000859
5VPCB15D4X3000859
5VPCS15D9Y3000860
5VPCD15D913000860
5VPCB15D0X3000860
5VPCS15D0Y3000861
5VPCD15D013000861
5VPCB15D2X3000861
5VPCS15D2Y3000862
5VPCB15D613000862
5VPCB15D4X3000862
5VPCS15D4Y3000863
5VPCB15D713000863
5VPCB15D6X3000863
5VPCS15D6Y3000864
6VPCB15D913000864
5VPCB15D8X3000864
6VPCS15D8Y3000865
5VPCB15D013000865
5VPCB15DXX3000865
6VPCS15DXY3000866
5VPCB15D213000866
5VPCB15D1X3000866
5VPCS15D1Y3000867
6VPCB15D413000867
5VPCB15D3X3000867
5VPCS15D3Y3000868
5VPCB15D613000868

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D5X3000868
5VPCS15D5Y3000869
5VPCB15D813000869
5VPCB15D7X3000869
5VPCS15D1Y3000870
5VPCB15D413000870
5VPCB15D3X3000870
5VPCS15D3Y3000871
5VPCB15D613000871
5VPCB15D5X3000871
5VPCS15D5Y3000872
5VPCB15D813000872
5VPCB15D7X3000872
5VPCS15D7Y3000873
5VPCB15DX13000873
5VPCB15D9X3000873
5VPCS15D9Y3000874
5VPCB15D113000874
5VPCB15D0X3000874
5VPCS15D0Y3000875
5VPCB15D313000875
5VPCB15D2X3000875
5VPCS15D2Y3000876
5VPCB15D513000876
5VPCB15D4X3000876
5VPCS15D4Y3000877
5VPCB15D713000877
5VPCB15D6X3000877
5VPCS15D6Y3000878
5VPCB15D913000878
5VPCB15D8X3000878
5VPCS15D8Y3000879
5VPCB15D013000879
5VPCB15DXX3000879
5VPCS15D4Y3000880
5VPCB15D713000880
5VPCB15D6X3000880
5VPCS15D6Y3000881
5VPCB15D913000881
5VPCB15D8X3000881
5VPCS15D8Y3000882
5VPCB15D013000882
5VPCB15DXX3000882
5VPCS15DXY3000883
5VPCB15D213000883
5VPCB15D1X3000883
5VPCS15D1Y3000884
5VPCB15D413000884

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D3X3000884
5VPCS15D3Y3000885
5VPCB15D613000885
5VPCB15D5X3000885
5VPCS15D5Y3000886
5VPCB15D813000886
5VPCB15D7X3000886
5VPCS15D7Y3000887
5VPCB15DX13000887
5VPCB15D9X3000887
5VPCS15D9Y3000888
5VPCB15D113000888
5VPCB15D0X3000888
5VPCS15D0Y3000889
5VPCB15D313000889
5VPCB15D2X3000889
5VPCS15D7Y3000890
5VPCB15DX13000890
5VPCB15D9X3000890
5VPCS15D9Y3000891
5VPCB15D113000891
5VPCB15D0X3000891
5VPCS15D0Y3000892
5VPCB15D313000892
5VPCB15D2X3000892
5VPCS15D2Y3000893
5VPCB15D513000893
5VPCB15D4X3000893
5VPCS15D4Y3000894
5VPCB15D713000894
5VPCB15D6X3000894
5VPCS15D6Y3000895
5VPCB15D913000896
5VPCB15D8X3000895
5VPCS15D8Y3000896
5VPCB15D013000896
5VPCB15DXX3000896
5VPCS15DXY3000897
5VPCB15D213000897
5VPCB15D1X3000897
5VPCS15D1Y3000898
6VPCB15D413000898
5VPCB15D3X3000898
5VPCS15D3Y3000899
5VPCB15D613000899
5VPCB15D5X3000899
5VPCS15D6Y3000900
6VPCB15D913000900

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D8X3000900
5VPCS15D8Y3000901
5VPCB15D013000901
5VPCB15DXX3000901
5VPCS15DXY3000902
5VPCB15D213000902
5VPCB15D1X3000902
5VPCS15D1Y3000903
5VPCB15D413000903
5VPCB15D3X3000903
5VPCS15D3Y3000904
5VPCB15D613000904
5VPCB15D5X3000904
5VPCS15D5Y3000905
5VPCB15D813000905
5VPCB15D7X3000905
5VPCS15D7Y3000906
5VPCB15DX13000906
5VPCB15D9X3000906
5VPCS15D9Y3000907
5VPCB15D113000907
5VPCB15D0X3000907
5VPCS15D0Y3000908
5VPCB15D313000908
5VPCB15D2X3000908
5VPCS15D2Y3000909
5VPCB15D513000909
5VPCB15D4X3000909
5VPCS15D9Y3000910
5VPCB15D113000910
5VPCB15D0X3000910
5VPCS15D0Y3000911
5VPCB15D313000911
5VPCB15D2X3000911
5VPCS15D2Y3000912
5VPCB15D613000912
5VPCB15D4X3000912
5VPCS15D4Y3000913
5VPCB15D713000913
5VPCB15D6X3000913
5VPCS15D6Y3000914
5VPCB15D8X3000914
5VPCS15D8Y3000915
5VPCB15D013000915
5VPCB15DXX3000915
5VPCS15DXY3000916
5VPCB15D213000916
5VPCB15D1X3000916

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D1Y3000917
5VPCB15D413000917
5VPCB15D3X3000917
5VPCS15D9Y3000918
5VPCB15D613000918
5VPCB15D5X3000918
5VPCS15D5Y3000919
5VPCB15D813000919
5VPCB15D7X3000919
5VPCS15D1Y3000920
5VPCB15D413000920
5VPCB15D3X3000920
5VPCS15D3Y3000921
5VPCB15D613000921
5VPCB15D5X3000921
5VPCS15D5Y3000922
5VPCB15D813000922
5VPCB15D7X3000922
5VPCS15D7Y3000923
5VPCB15DX13000923
5VPCB15D9X3000923
5VPCS15D9Y3000924
5VPCB15D113000924
5VPCB15D0X3000924
5VPCS15D0Y3000925
5VPCB15D2X3000926
5VPCS15D2Y3000926
5VPCB15D4X3000926
5VPCS15D4Y3000927
5VPCB15D6X3000927
5VPCS15D6Y3000928
5VPCB15D8X3000928
5VPCS15D8Y3000929
5VPCB15DXX3000929
5VPCS15D4Y3000930
5VPCD15D413000930
5VPCB15D8X3000930
5VPCS15D6Y3000931
5VPCD15D613000931
5VPCB15D8X3000931
5VPCS15D8Y3000932
5VPCD15D813000932
5VPCB15DXX3000932
5VPCS15DXY3000933
5VPCD15DX13000933
5VPCB15D1X3000933
5VPCS15D1Y3000934
5VPCD16D113000934

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D3X3000934
5VPCS15D3Y3000935
5VPCD15D313000935
6VPCB15D5X3000935
5VPCS15D5Y3000936
6VPCD15D513000936
5VPCB15D7X3000936
5VPCS15D7Y3000937
5VPCD15D713000937
5VPCB15D9X3000937
5VPCS15D9Y3000938
5VPCD15D913000938
5VPCB15D0X3000938
5VPCS15D0Y3000939
5VPCD15D013000939
5VPCB15D2X3000939
5VPCS16D7Y3000940
5VPCD15D713000940
5VPCB15D9X3000940
6VPCS15D9Y3000941
5VPCD15D913000941
5VPCB16D0X3000941
6VPCS15D0Y3000942
6VPCD15D013000942
5VPCB15D2X3000942
5VPCS15D2Y3000943
5VPCD15D213000943
5VPCB15D4X3000943
6VPCS15D4Y3000944
5VPCD15D413000944
6VPCB15D6X3000944
5VPCS15D6Y3000945
6VPCD15D613000945
5VPCB15D8X3000945
5VPCB15D8Y3000946
5VPCD15D813000946
5VPCB15DXX3000946
5VPCB15DXY3000947
5VPCD15DX13000947
5VPCB15D1X3000947
5VPCB15D1Y3000948
5VPCD15D113000948
5VPCB15D3X3000948
5VPCB16D3Y3000949
5VPCD15D313000949
5VPCB15D6X3000949
5VPCB15DXY3000950
5VPCD15DX13000950

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D1X3000950
5VPCB15D1Y3000951
5VPCD15D113000951
5VPCB15D3X3000951
5VPCB15D3Y3000962
5VPCD15D313000952
5VPCB15D5X3000952
5VPCB15D5Y3000953
5VPCD15D513000953
5VPCB15D7X3000953
5VPCB15D7Y3000954
5VPCD15D713000954
5VPCB15D9X3000954
5VPCB15D9Y3000955
5VPCD15D913000955
5VPCB15D0X3000955
5VPCB15D0Y3000956
5VPCD15D013000956
5VPCB15D2X3000956
5VPCB15D2Y3000957
5VPCD15D213000957
5VPCB15D4X3000957
5VPCB15D4Y3000958
5VPCD15D413000958
5VPCB15D6X3000958
5VPCB15D6Y3000959
5VPCD15D613000959
5VPCB15D8X3000959
5VPCB15D2Y3000960
5VPCD15D213000960
5VPCB15D4X3000960
5VPCB15D4Y3000961
6VPCD15D413000961
5VPCB15D6X3000961
6VPCB15D6Y3000962
6VPCD15D613000962
5VPCB15D8X3000962
5VPCB15D8Y3000963
5VPCD15D813000963
6VPCB15DXX3000963
5VPCB15DXY3000964
5VPCD15DX13000964
6VPCB15D1X3000964
5VPCB15D1Y3000965
5VPCD15D113000965
6VPCB15D3X3000965
5VPCB15D3Y3000966
5VPCD15D313000966

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D5X3000966
5VPCB15D5Y3000967
5VPCD15D513000967
5VPCB15D7X3000967
6VPCB15D7Y3000968
5VPCD15D713000968
6VPCB15D8X3000968
5VPCB15D9Y3000969
5VPCD15D913000969
5VPCB15D0X3000969
5VPCB15D5Y3000970
5VPCD15D513000970
5VPCB15D7X3000970
6VPCB15D7Y3000971
5VPCD15D713000971
6VPCB15D9X3000971
5VPCB15D9Y3000972
6VPCD15D913000972
5VPCB15D0X3000972
6VPCB15D0Y3000973
5VPCD15D013000973
5VPCB15D2X3000973
5VPCB15D2Y3000974
5VPCB15D513000974
6VPCB15D4X3000974
6VPCB15D4Y3000975
5VPCB15D713000975
5VPCB15D6X3000975
5VPCB15D6Y3000976
5VPCB15D913000976
5VPCB15D8X3000976
5VPCB15D8Y3000977
5VPCB15D013000977
5VPCB15DXX3000977
5VPCB15DXY3000978
5VPCD15DX13000978
5VPCB15D1X3000978
5VPCB15D1Y3000979
5VPCD15D113000979
5VPCB15D3X3000979
5VPCB15D8Y3000980
5VPCD15D813000980
5VPCB15DXX3000980
5VPCB15DXY3000981
5VPCD15DX13000981
5VPCB15D1X3000981
5VPCB15D1Y3000982
5VPCD15D113000982

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D3X3000982
5VPCB15D3Y3000983
5VPCD15D313000983
5VPCB15D5X3000983
5VPCB15D5Y3000984
5VPCB15D813000984
5VPCB15D7X3000984
5VPCB15D7Y3000985
5VPCB15DX13000985
5VPCB15D9X3000985
5VPCB15D9Y3000986
5VPCB15D113000986
5VPCB15D0X3000986
5VPCB15D0Y3000987
5VPCB15D313000987
5VPCB15D2X3000987
5VPCB15D2Y3000988
5VPCB15D513000988
5VPCB15D4X3000988
5VPCB15D4Y3000989
5VPCB15D713000989
5VPCB15D6X3000989
5VPCB15D0Y3000990
5VPCB15D313000990
5VPCB15D2X3000990
5VPCB15D2Y3000991
5VPCB15D513000991
5VPCB15D4X3000991
5VPCB15D4Y3000992
5VPCB15D713000992
5VPCB15D6X3000992
5VPCB15D6Y3000993
5VPCB15D8X3000993
5VPCB15D8Y3000994
5VPCB15DXX3000994
5VPCB15DXY3000995
5VPCB15D1X3000995
5VPCB15D1Y3000996
5VPCB15D3X3000996
5VPCB15D3Y3000997
5VPCB15D5X3000997
5VPCB15D5Y3000998
5VPCB15D7X3000998
5VPCB15D7Y3000999
5VPCB15D9X3000999
5VPCB15D8Y3001000
5VPCB15DXX3001000
5VPCB15DXY3001001

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D213001001
6VPCB16D1X3001001
5VPCB15D1Y3001002
5VPCB15D413001002
6VPCB16D3X3001002
5VPCB15D3Y3001003
6VPCB16D613001003
5VPCB15D5X3001003
6VPCB16D6Y3001004
5VPCB15D7X3001004
5VPCB15D7Y3001005
5VPCB15D9X3001005
6VPCB15D9Y3001006
5VPCB15D0X3001006
6VPCB15D0Y3001007
5VPCB15D2X3001007
5VPCB15D2Y3001008
5VPCB16D4X3001008
6VPCB15D4Y3001009
5VPCB15D6X3001009
6VPCB15D0Y3001010
5VPCB15D2X3001010
5VPCB15D513001011
5VPCD15D213001011
5VPCB15D4X3001011
5VPCB15D713001012
5VPCD15D413001012
6VPCB16D8X3001012
5VPCB15D913001013
6VPCD15D613001013
5VPCB15D8X3001013
5VPCB15D013001014
5VPCD15D813001014
5VPCB15DXX3001014
5VPCB15D213001015
5VPCD15DX13001015
6VPCB16D1X3001016
5VPCB15D1Y3001016
5VPCB15D3X3001016
5VPCB15D3Y3001017
5VPCB15D5X3001017
5VPCB15D5Y3001018
5VPCB15D7X3001018
5VPCB15D7Y3001019
5VPCB15D9X3001019
5VPCB15D3Y3001020
5VPCB16D5X3001020
5VPCB15D5Y3001021

M.Y. 1999 through 2001 motorcycles assembled from 7-1-96 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D7X3001021
5VPCB15D7Y3001022
5VPCB15DX13001022
5VPCB15D9X3001022
5VPCB15D9Y3001023
5VPCB15D113001023
5VPCB15D0X3001023
5VPCB15D0Y3001024
5VPCB15D313001024
5VPCB15D2X3001024
5VPCB15D2Y3001025
5VPCB15D513001025
5VPCB15D4X3001025
5VPCB15D4Y3001026
5VPCB15D713001026
5VPCB15D6X3001026
5VPCB15D6Y3001027
5VPCB15D913001027
5VPCB15D8X3001027
5VPCB15D8Y3001028
5VPCB15D013001028
5VPCB15DXX3001028
5VPCB15DXY3001029
5VPCB15D213001029
5VPCB15D1X3001029
5VPCS15D6Y3001030
5VPCD15D613001030
5VPCB15D8X3001030
5VPCS15D8Y3001031
5VPCD15D813001031
5VPCB15DXX3001031
5VPCS15DXY3001032
5VPCD15DX13001032
5VPCB15D1X3001032
5VPCS15D1Y3001033
5VPCD15D113001033
5VPCB15D3X3001033
5VPCS15D3Y3001034
5VPCD15D313001034
5VPCB15D5X3001034
5VPCS15D5Y3001035
5VPCD15D513001035
5VPCB15D7X3001035
5VPCS15D7Y3001036
5VPCD15D713001036
5VPCB15D9X3001036
5VPCS15D9Y3001037
5VPCD15D913001037

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB16D0X3001037
5VPCS15D0Y3001038
5VPCD15D013001038
5VPCB15D2X3001038
5VPCS15D2Y3001039
5VPCD15D213001039
5VPCB15D4X3001039
5VPCS16D9Y3001040
5VPCD15D813001040
6VPCB15D0X3001040
5VPCS15D0Y3001041
5VPCD15D013001041
5VPCB15D2X3001041
5VPCS15D2Y3001042
5VPCD15D213001042
5VPCB15D4X3001042
5VPCS15D4Y3001043
6VPCD15D413001043
5VPCB15D6X3001043
5VPCS15D6Y3001044
6VPCD15D613001044
5VPCB15D8X3001044
5VPCS15D8Y3001045
5VPCD15D813001045
5VPCB15DXX3001045
5VPCS15DXY3001046
5VPCD15DX13001046
5VPCB15D1X3001046
6VPCS16D1Y3001047
5VPCD15D113001047
5VPCB15D3X3001047
5VPCS15D3Y3001048
5VPCD15D313001048
6VPCB16D6X3001048
5VPCS15D5Y3001049
6VPCD15D513001049
5VPCB15D7X3001049
6VPCS16D1Y3001050
5VPCD15D113001050
5VPCB15D3X3001050
5VPCS15D3Y3001051
5VPCD15D313001051
5VPCB15D5X3001051
5VPCS15D5Y3001052
5VPCD15D513001052
5VPCB15D7X3001052
5VPCS15D7Y3001053
5VPCD15D713001053

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D9X3001053
5VPCS15D9Y3001054
5VPCD15D913001054
5VPCB15D0X3001054
5VPCS15D0Y3001055
5VPCD15D013001055
5VPCB15D2X3001055
5VPCS15D2Y3001056
5VPCD15D213001056
5VPCB15D4X3001056
5VPCS15D4Y3001057
5VPCD15D413001057
5VPCB15D6X3001057
5VPCS15D6Y3001058
5VPCD15D613001058
5VPCB15D8X3001058
5VPCS15D8Y3001059
5VPCD15D813001059
5VPCB15DXX3001059
5VPCS15D4Y3001060
5VPCD15D413001060
5VPCB15D6X3001060
5VPCS15D6Y3001061
5VPCD15D613001061
5VPCB15D8X3001061
5VPCS15D8Y3001062
5VPCD15D813001062
5VPCB15DXX3001062
5VPCS15DXY3001063
5VPCD15DX13001063
5VPCB15D1X3001063
5VPCS15D1Y3001064
5VPCD15D113001064
5VPCB15D3X3001064
5VPCS15D3Y3001065
5VPCD15D313001065
5VPCB15D5X3001065
5VPCS15D5Y3001066
5VPCD15D513001066
5VPCB15D7X3001066
5VPCS15D7Y3001067
5VPCD15D713001067
5VPCB15D9X3001067
5VPCS15D9Y3001068
5VPCD15D913001068
5VPCB15D0X3001068
5VPCS15D0Y3001069
5VPCD15D013001069

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D2X3001069
5VPCS15D7Y3001070
5VPCD15D713001070
5VPCB15D9X3001070
5VPCS15D9Y3001071
5VPCD15D913001071
5VPCB15D0X3001071
5VPCS15D0Y3001072
5VPCD15D013001072
5VPCB15D2X3001072
5VPCS15D2Y3001073
5VPCD15D213001073
5VPCB15D4X3001073
5VPCS15D4Y3001074
5VPCB15D713001074
5VPCB15D6X3001074
5VPCS15D6Y3001075
5VPCB15D913001075
5VPCB15D8X3001075
5VPCS15D8Y3001076
5VPCB15D013001076
5VPCB15DXX3001076
5VPCS15DXY3001077
5VPCD15DX13001077
5VPCB15D1X3001077
5VPCS15D1Y3001078
5VPCD15D113001078
5VPCB15D3X3001078
5VPCS15D3Y3001079
5VPCD15D313001079
5VPCB15D5X3001079
5VPCS15DXY3001080
5VPCD15DX13001080
5VPCB15D1X3001080
5VPCS15D1Y3001081
5VPCD15D113001081
5VPCB15D3X3001081
5VPCS15D3Y3001082
5VPCD15D313001082
5VPCB15D6X3001082
5VPCS15D5Y3001083
5VPCD15D513001083
5VPCB15D7X3001083
5VPCS15D7Y3001084
5VPCD15D713001084
5VPCB15D9X3001084
5VPCS15D9Y3001085
5VPCD15D913001085

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D0X3001085
5VPCS15D0Y3001086
5VPCD15D013001086
5VPCB15D2X3001086
6VPCS15D2Y3001087
5VPCD15D213001087
5VPCB15D4X3001087
5VPCS15D4Y3001088
5VPCD15D413001088
5VPCB15D6X3001088
6VPCS15D6Y3001089
5VPCD15D613001089
5VPCB15D8X3001089
5VPCS15D2Y3001090
5VPCD15D213001090
5VPCB15D4X3001090
5VPCS15D4Y3001091
5VPCD15D413001091
5VPCB15D6X3001091
5VPCS15D6Y3001092
5VPCD15D613001092
5VPCB15D8X3001092
5VPCS15D8Y3001093
5VPCD15D813001093
6VPCB15DXX3001093
5VPCB15DXY3001094
5VPCD15DX13001094
5VPCB15D1X3001094
5VPCB15D1Y3001095
5VPCD15D113001095
5VPCB15D3X3001095
5VPCB15D3Y3001096
5VPCD15D313001096
5VPCB15D5X3001096
5VPCB15D5Y3001097
5VPCD15D513001097
5VPCB15D7X3001097
5VPCB15D7Y3001098
5VPCD15D713001098
5VPCB15D9X3001098
5VPCB15D9Y3001099
5VPCD15D913001099
5VPCB15D0X3001099
5VPCB15D1Y3001100
5VPCB15D3X3001100
5VPCB15D3Y3001101
5VPCB15D5X3001101
5VPCB15D5Y3001102

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D7X3001102
5VPCB15D7Y3001103
5VPCB15D9X3001103
5VPCB15D9Y3001104
5VPCB15D0X3001104
5VPCB15D0Y3001105
5VPCB15D2X3001105
5VPCB15D2Y3001106
5VPCD15D213001106
5VPCB15D4X3001106
5VPCB15D4Y3001107
5VPCD15D413001107
5VPCB15D6X3001107
5VPCB15D6Y3001108
6VPCD15D613001108
6VPCB15D8X3001108
5VPCB15D8Y3001109
5VPCD15D813001109
5VPCB15DXX3001109
5VPCB15D4Y3001110
5VPCB15D6X3001110
5VPCB15D6Y3001111
5VPCB15D8X3001111
5VPCB15D8Y3001112
5VPCB15DXX3001112
5VPCB15DXY3001113
5VPCD15DX13001113
5VPCB15D1X3001113
5VPCB15D1Y3001114
5VPCD15D113001114
5VPCB15D3X3001114
5VPCB15D3Y3001115
5VPCD15D313001115
5VPCB15D5X3001116
5VPCB15D5Y3001116
5VPCD15D513001116
5VPCB15D7X3001116
5VPCB15D7Y3001117
5VPCD15D713001117
5VPCB15D9X3001117
5VPCB15D9Y3001118
5VPCD15D913001118
5VPCB15D0X3001118
5VPCB15D0Y3001119
5VPCD15D013001119
5VPCB15D2X3001119
5VPCB15D7Y3001120
5VPCD15D713001120

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D9X3001120
5VPCB15D9Y3001121
5VPCD15D913001121
5VPCB15D0X3001121
5VPCB15D0Y3001122
5VPCB16D2X3001122
5VPCB15D2Y3001123
5VPCB15D4X3001123
5VPCB15D4Y3001124
5VPCB15D6X3001124
5VPCB15D6Y3001125
5VPCB15D8X3001125
5VPCB15D8Y3001126
6VPCB15DXX3001126
6VPCB15DXY3001127
5VPCB15D1X3001127
5VPCB15D1Y3001128
5VPCB15D3X3001128
5VPCB15D3Y3001129
5VPCB15D5X3001129
5VPCB15DXY3001130
5VPCB15D1X3001130
5VPCB15D1Y3001131
6VPCB16D3X3001131
5VPCB15D3Y3001132
5VPCD15D319001132
5VPCB15D5X3001132
5VPCB15D5Y3001133
5VPCD15D513001133
5VPCB15D7X3001133
5VPCB15D7Y3001134
5VPCD15D713001134
6VPCB15D9X3001134
5VPCB15D9Y3001135
5VPCD15D913001135
6VPCB15D0X3001135
5VPCB15D0Y3001136
5VPCD15D013001136
5VPCB15D2X3001136
5VPCB15D2Y3001137
6VPCD15D213001137
5VPCB15D4X3001137
6VPCB15D4Y3001138
5VPCD15D413001138
6VPCB15D6X3001138
5VPCB16D6Y3001139
5VPCD15D613001139
5VPCB15D6X3001139

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D2Y3001140
5VPCD15D213001140
5VPCB15D4X3001140
5VPCS15D4Y3001141
5VPCD15D413001141
5VPCB15D6X3001141
5VPCS15D6Y3001142
5VPCD15D613001142
5VPCB15D8X3001142
5VPCS15D8Y3001143
5VPCD15D813001143
5VPCB15DXX3001143
5VPCS15DXY3001144
5VPCD15DX13001144
5VPCB15D1X3001144
5VPCS15D1Y3001145
5VPCD15D113001145
5VPCB15D3X3001145
5VPCS15D3Y3001146
5VPCD15D313001146
5VPCB15D5X3001146
5VPCS15D5Y3001147
5VPCB15D7X3001147
5VPCS15D7Y3001148
5VPCB15D9X3001148
5VPCS15D9Y3001149
5VPCD15D913001149
5VPCB15D0X3001149
5VPCS15D5Y3001150
5VPCD15D613001150
5VPCB15D7X3001150
5VPCS15D7Y3001151
5VPCD15D713001151
5VPCB15D9X3001151
5VPCS15D9Y3001152
5VPCB15D0X3001152
5VPCS15D0Y3001153
5VPCB15D2X3001153
5VPCS15D2Y3001154
5VPCB15D4X3001154
5VPCS15D4Y3001155
5VPCB15D6X3001155
6VPCS16D6Y3001156
5VPCB15D8X3001156
6VPCS16D8Y3001157
5VPCB15DXX3001157
5VPCS16DXY3001158
5VPCB15D1X3001158

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D1Y3001159
5VPCB15D3X3001159
5VPCS15D8Y3001160
6VPCB15DXX3001160
5VPCS15DXY3001161
5VPCB15D1X3001161
5VPCS15D1Y3001162
5VPCB15D3X3001162
5VPCS15D3Y3001163
5VPCB15D5X3001163
5VPCS15D5Y3001164
5VPCB15D7X3001164
5VPCS15D7Y3001165
5VPCB15D9X3001166
5VPCS15D9Y3001166
5VPCB15D0X3001166
5VPCS15D0Y3001167
5VPCB15D2X3001167
5VPCS15D2Y3001168
5VPCB15D4X3001168
5VPCS15D4Y3001169
5VPCB15D6X3001169
5VPCS15D0Y3001170
5VPCB15D2X3001170
5VPCS15D2Y3001171
5VPCB15D4X3001171
5VPCS15D4Y3001172
5VPCB15D6X3001172
6VPCS15D6Y3001173
5VPCB15D8X3001173
5VPCS15D8Y3001174
5VPCB15DXX3001174
5VPCS15DXY3001175
5VPCB15D1X3001175
5VPCS15D1Y3001176
5VPCB15D3X3001176
5VPCS15D3Y3001177
5VPCB15D5X3001177
5VPCS15D5Y3001178
5VPCB15D7X3001178
5VPCS15D7Y3001179
6VPCB15D9X3001179
5VPCS15D3Y3001180
5VPCB15D5X3001180
5VPCS15D5Y3001181
5VPCB15D7X3001181
5VPCS15D7Y3001182
6VPCB15D9X3001182

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D9Y3001183
5VPCB15D0X3001183
5VPCS15D0Y3001184
5VPCB15D2X3001184
5VPCS15D2Y3001185
5VPCB15D4X3001185
5VPCS15D4Y3001186
5VPCB15D6X3001186
5VPCS15D6Y3001187
5VPCB15D8X3001187
5VPCS15D8Y3001188
5VPCB15DXX3001188
5VPCS15DXY3001189
5VPCB15D1X3001189
5VPCS15D8Y3001190
5VPCB15D8X3001190
5VPCS15D8Y3001191
5VPCB15DXX3001191
5VPCS15DXY3001192
5VPCB15D1X3001192
5VPCS15D1Y3001193
5VPCB15D3X3001193
5VPCS15D3Y3001194
5VPCB15D5X3001194
5VPCS15D5Y3001195
5VPCB15D7X3001196
5VPCS15D7Y3001196
5VPCB15D9X3001196
5VPCS15D9Y3001197
5VPCB15D0X3001197
5VPCS15D0Y3001198
5VPCB15D2X3001198
5VPCS15D2Y3001199
5VPCB15D4X3001199
5VPCS15D5Y3001200
5VPCB15D7X3001200
5VPCS15D7Y3001201
5VPCB15D9X3001201
5VPCS15D9Y3001202
5VPCB15D0X3001202
5VPCS15D0Y3001203
5VPCB15D2X3001203
5VPCS15D2Y3001204
5VPCB15D4X3001204
5VPCS15D4Y3001205
5VPCB15D713001206
5VPCB15D6X3001205
5VPCS15D6Y3001206

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D913001206
5VPCB15D6X3001206
5VPCS15D8Y3001207
5VPCD15D813001207
5VPCB15DXX3001207
5VPCS15DXY3001208
5VPCD15DX13001208
5VPCB15D1X3001208
5VPCS15D1Y3001209
5VPCD15D113001209
5VPCB15D3X3001209
5VPCS15D8Y3001210
5VPCD15D813001210
5VPCB15DXX3001210
5VPCS15DXY3001211
5VPCB15D1X3001211
5VPCS15D1Y3001212
5VPCB15D3X3001212
5VPCS15D3Y3001213
5VPCB15D5X3001213
5VPCS15D5Y3001214
5VPCB15D7X3001214
5VPCS15D7Y3001215
5VPCB15D9X3001215
5VPCS15D9Y3001216
5VPCB15D0X3001216
5VPCS15D0Y3001217
5VPCB15D2X3001217
5VPCS15D2Y3001218
5VPCB15D4X3001218
5VPCS15D4Y3001219
5VPCB15D6X3001219
5VPCS15D0Y3001220
5VPCB15D2X3001220
5VPCS15D2Y3001221
5VPCD15D213001221
5VPCB15D4X3001221
5VPCS15D4Y3001222
5VPCD15D413001222
5VPCB15D6X3001222
5VPCB15D6Y3001223
5VPCD15D613001223
6VPCB15D8X3001223
5VPCB15D8Y3001224
5VPCD15D813001224
5VPCB15DXX3001224
5VPCB15DXY3001225
5VPCD15DX13001225

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D1X3001225
5VPCB15D1Y3001226
5VPCD15D113001226
5VPCB15D3X3001226
5VPCB15D3Y3001227
5VPCD15D313001227
5VPCB15D5X3001227
5VPCB15D5Y3001228
5VPCD15D513001228
5VPCB15D7X3001228
5VPCB15D7Y3001229
5VPCD15D713001229
5VPCB15D9X3001229
5VPCB15D3Y3001230
5VPCD15D313001230
5VPCB15D5X3001230
5VPCB15D5Y3001231
5VPCD15D513001231
5VPCB15D7X3001231
5VPCB15D7Y3001232
5VPCD15D713001232
5VPCB15D9X3001232
5VPCB15D9Y3001233
5VPCD15D913001233
5VPCB15D0X3001233
5VPCB15D0Y3001234
5VPCB15D313001234
5VPCB15D2X3001234
5VPCB15D2Y3001235
5VPCB15D513001235
5VPCB15D4X3001235
5VPCB15D4Y3001236
5VPCB15D713001236
5VPCB15D8X3001236
5VPCB15D6Y3001237
5VPCB15D913001237
5VPCB15D8X3001237
5VPCB15D8Y3001238
5VPCB15D013001238
5VPCB15DXX3001238
5VPCB15DXY3001239
5VPCD15DX13001239
5VPCB15D1X3001239
5VPCB15D6Y3001240
5VPCB15D913001240
5VPCB15D8X3001240
5VPCB15D8Y3001241
5VPCB15D013001241

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15DXX3001241
5VPCB15DXY3001242
5VPCB15D213001242
5VPCB15D1X3001242
5VPCB15D1Y3001243
5VPCB15D413001243
5VPCB15D3X3001243
5VPCB15D3Y3001244
5VPCB15D613001244
5VPCB15D5X3001244
5VPCB15D5Y3001245
5VPCB15D813001245
5VPCB15D7X3001245
5VPCB15D7Y3001246
5VPCD15D713001246
5VPCB15D9X3001246
5VPCB15D9Y3001247
5VPCD15D913001247
5VPCB15D0X3001247
5VPCB16D0Y3001248
5VPCD15D013001248
5VPCB15D2X3001248
5VPCB16D2Y3001249
5VPCD15D213001249
5VPCB16D4X3001249
5VPCB15D9Y3001250
5VPCD15D913001250
5VPCB16D0X3001250
5VPCB15D0Y3001251
5VPCD16D013001251
5VPCB15D2X3001251
5VPCB15D2Y3001252
5VPCD16D213001252
5VPCB15D4X3001252
5VPCB16D4Y3001253
5VPCB15D713001253
5VPCB16D6X3001253
5VPCB15D6Y3001254
5VPCB15D913001254
5VPCB15D8X3001254
5VPCB15D8Y3001255
5VPCB15D013001255
5VPCB16DXX3001255
5VPCB15DXY3001256
5VPCB16D213001256
5VPCB15D1X3001256
5VPCB15D1Y3001257
5VPCS15D413001257

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D3X3001257
6VPCB16D3Y3001258
5VPCS15D613001258
5VPCB15D5X3001258
5VPCB16D5Y3001259
5VPCS15D813001259
5VPCB15D7X3001259
5VPCB15D1Y3001260
6VPCB16D3X3001260
5VPCB15D3Y3001261
5VPCB15D6X3001261
5VPCB15D5Y3001262
6VPCB16D7X3001262
5VPCB15D7Y3001263
5VPCB16D9X3001263
6VPCB15D9Y3001264
5VPCB15D0X3001264
5VPCB15D0Y3001265
5VPCB15D2X3001265
5VPCB15D2Y3001266
6VPCB16D4X3001266
5VPCB15D4Y3001267
6VPCB15D6X3001267
5VPCS15D6Y3001268
6VPCB16D8X3001268
6VPCS16D8Y3001269
5VPCB15DXX3001269
6VPCS16D4Y3001270
5VPCB15D6X3001270
5VPCS15D6Y3001271
5VPCB15D8X3001271
5VPCS15D8Y3001272
6VPCB16DXX3001272
5VPCS15DXY3001273
6VPCB15D1X3001273
5VPCB15D1Y3001274
5VPCB15D3X3001274
5VPCB15D3Y3001275
6VPCB15D5X3001275
5VPCB15D5Y3001276
6VPCB15D7X3001276
5VPCB15D7Y3001277
6VPCB15D9X3001277
5VPCB15D9Y3001278
6VPCB15D0X3001278
5VPCS15D0Y3001279
6VPCD15D013001279
5VPCB15D2X3001279

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of effected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D7Y3001280
5VPCD15D713001280
5VPCB15D9X3001280
5VPCS15D9Y3001281
5VPCD15D913001281
6VPCB15D0X3001281
5VPCS15D0Y3001282
6VPCD15D013001282
6VPCB15D2X3001282
5VPCS15D2Y3001283
5VPCD15D213001283
5VPCB15D4X3001283
5VPCS15D4Y3001284
5VPCD15D413001284
6VPCB15D6X3001284
5VPCS15D6Y3001285
5VPCD15D613001285
5VPCB15D8X3001285
6VPCS15D8Y3001286
5VPCD15D813001286
5VPCB15DXX3001286
5VPCS15DXY3001287
5VPCD15DX13001287
5VPCB15D1X3001287
5VPCS15D1Y3001288
5VPCD15D113001288
5VPCB15D3X3001288
5VPCS15D3Y3001289
5VPCD15D313001289
5VPCB15D5X3001289
5VPCS15DXY3001290
5VPCD15DX13001290
5VPCB15D1X3001290
5VPCS15D1Y3001291
6VPCD15D113001291
5VPCB15D3X3001291
6VPCS15D3Y3001292
5VPCD15D313001292
5VPCB15D5X3001292
5VPCS15D5Y3001293
5VPCD15D513001293
5VPCB15D7X3001293
6VPCS15D7Y3001294
5VPCD15D713001294
6VPCB15D9X3001294
5VPCS15D9Y3001295
5VPCD15D913001295
5VPCB15D0X3001295

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D0Y3001296
5VPCD15D013001296
5VPCB15D2X3001296
5VPCS15D2Y3001297
5VPCD15D213001297
5VPCB15D4X3001297
5VPCS15D4Y3001298
5VPCD15D413001298
5VPCB15D6X3001298
5VPCS15D6Y3001299
5VPCD15D613001299
5VPCB15D8X3001299
5VPCS15D9Y3001300
5VPCD15D913001300
5VPCB15D0X3001300
5VPCS15D0Y3001301
5VPCD15D013001301
5VPCB15D2X3001301
5VPCS15D2Y3001302
5VPCD15D213001302
5VPCB15D4X3001302
5VPCS15D4Y3001303
5VPCD15D413001303
5VPCB15D6X3001303
5VPCB15D6Y3001304
5VPCD15D613001304
5VPCB15D8X3001304
5VPCB15D8Y3001305
5VPCD15D813001305
5VPCB15DXX3001305
5VPCB15DXY3001306
5VPCD15DX13001306
5VPCB15D1X3001306
5VPCB15D1Y3001307
5VPCD15D113001307
5VPCB15D3X3001307
5VPCB15D3Y3001308
5VPCD15D313001308
5VPCB15D5X3001308
5VPCB15D5Y3001309
5VPCD15D513001309
5VPCB15D7X3001309
5VPCB15D1Y3001310
5VPCD15D113001310
5VPCB15D3X3001310
5VPCB15D3Y3001311
5VPCD15D313001311
5VPCB15D5X3001311

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D5Y3001312
5VPCD15D513001312
5VPCB15D7X3001312
5VPCB15D7Y3001313
5VPCD15D713001313
5VPCB15D9X3001313
5VPCB15D9Y3001314
5VPCD15D913001314
5VPCB15D0X3001314
5VPCB15D0Y3001315
5VPCD15D013001315
5VPCB15D2X3001315
5VPCB15D2Y3001316
5VPCD15D213001316
5VPCB15D4X3001316
5VPCB15D4Y3001317
5VPCD15D413001317
5VPCB15D6X3001317
5VPCB15D6Y3001318
5VPCD15D613001318
5VPCB15D8X3001318
5VPCB15D8Y3001319
5VPCD15D813001319
5VPCB15DXX3001319
5VPCB15D4Y3001320
5VPCD15D413001320
5VPCB15D6X3001320
5VPCB15D6Y3001321
5VPCD15D613001321
5VPCB15D8X3001321
5VPCB15D6Y3001322
5VPCD15D613001322
5VPCB15DXX3001322
5VPCB15DXY3001323
5VPCD15DX13001323
5VPCB15D1X3001323
5VPCB15D1Y3001324
5VPCD15D113001324
5VPCB15D3X3001324
5VPCB15D3Y3001325
5VPCD15D313001325
5VPCB15D5X3001325
5VPCB15D5Y3001326
5VPCD15D513001326
5VPCB15D7X3001326
5VPCB15D7Y3001327
5VPCD15D713001327
5VPCB15D9X3001327

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D9Y3001328
5VPCD15D913001328
5VPCB15D0X3001328
5VPCB15D0Y3001329
5VPCD15D013001329
5VPCB15D2X3001329
5VPCB15D7Y3001330
5VPCD15D713001330
5VPCB15D9X3001330
5VPCB15D9Y3001331
5VPCD15D913001331
5VPCB15D0X3001331
5VPCB15D0Y3001332
5VPCD15D013001332
5VPCB15D2X3001332
5VPCB15D2Y3001333
5VPCD15D213001333
5VPCB15D4X3001333
5VPCB15D4Y3001334
5VPCD15D413001334
5VPCB15D6X3001334
5VPCB15D6Y3001335
5VPCD15D613001335
5VPCB15D8X3001335
5VPCB15D8Y3001336
5VPCD15D813001336
5VPCB15DXX3001336
5VPCB15DXY3001337
5VPCD15DX13001337
5VPCB15D1X3001337
5VPCB15D1Y3001338
5VPCD15D113001338
5VPCB15D3X3001338
5VPCB15D3Y3001339
5VPCD15D313001339
5VPCB15D5X3001339
5VPCB15DXY3001340
5VPCD15DX13001340
5VPCB15D1X3001340
5VPCB15D1Y3001341
5VPCD15D113001341
5VPCB15D3X3001341
5VPCB15D3Y3001342
5VPCD15D313001342
5VPCB15D5X3001342
5VPCB15D5Y3001343
5VPCD15D513001343
5VPCB15D7X3001343

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D7Y3001344
5VPCD15D713001344
5VPCB15D9X3001344
5VPCB15D9Y3001345
5VPCD15D913001345
5VPCB15D0X3001345
5VPCB15D0Y3001346
5VPCD15D013001346
5VPCB15D2X3001346
5VPCB15D2Y3001347
5VPCD15D213001347
5VPCB15D4X3001347
5VPCB15D4Y3001348
5VPCD15D413001348
5VPCB15D6X3001348
5VPCB15D6Y3001349
5VPCD15D613001349
5VPCB15D8X3001349
5VPCB15D2Y3001350
5VPCD15D213001350
5VPCB15D4X3001350
5VPCB15D4Y3001351
5VPCD15D413001351
5VPCB15D6X3001351
5VPCB15D6Y3001352
5VPCD15D613001352
5VPCB15D8X3001352
5VPCB15D8Y3001353
5VPCD15D813001353
5VPCB15DXX3001353
5VPCS15DXY3001354
5VPCD15DX13001354
5VPCB15D1X3001354
5VPCS15D1Y3001355
5VPCD15D113001355
5VPCB15D3X3001355
5VPCS15D3Y3001356
5VPCD15D313001356
5VPCB15D5X3001356
5VPCS15D5Y3001357
5VPCD15D513001357
5VPCB15D7X3001357
5VPCS15D7Y3001358
5VPCB15D9X3001358
5VPCS15D9Y3001359
5VPCS15D113001359
5VPCB15D0X3001359
5VPCS15D6Y3001360

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D613001360
5VPCB15D7X3001360
5VPCS15D7Y3001361
5VPCS15DX13001361
5VPCB15D9X3001361
5VPCS15D9Y3001362
5VPCS15D113001362
5VPCB15D0X3001362
5VPCS15D0Y3001363
5VPCS15D313001363
5VPCB15D2X3001363
5VPCS15D2Y3001364
5VPCS15D513001364
5VPCB15D4X3001364
5VPCS15D4Y3001365
5VPCS15D713001365
5VPCB15D6X3001365
5VPCS15D6Y3001366
5VPCS15D913001366
5VPCB15D8X3001366
5VPCS15D8Y3001367
5VPCS15D013001367
5VPCB15DXX3001367
5VPCS15DXY3001368
5VPCS15D213001368
5VPCB15D1X3001368
5VPCS15D1Y3001369
5VPCS15D413001369
5VPCB15D3X3001369
5VPCS15D6Y3001370
5VPCS15D013001370
5VPCB15DXX3001370
5VPCS15DXY3001371
5VPCS15D213001371
5VPCB15D1X3001371
5VPCS15D1Y3001372
5VPCS15D413001372
5VPCB15D3X3001372
5VPCS15D3Y3001373
5VPCS15D613001373
5VPCB15D5X3001373
5VPCS15D5Y3001374
5VPCB15D7X3001374
5VPCS15D7Y3001375
5VPCB15D9X3001375
5VPCS15D8Y3001376
5VPCB15D0X3001376
5VPCS15D0Y3001377

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D2X3001377
5VPCS15D2Y3001378
6VPCB15D4X3001378
5VPCS15D4Y3001379
5VPCB15D6X3001379
6VPCS15D0Y3001380
5VPCB15D2X3001380
6VPCS15D2Y3001381
5VPCB15D4X3001381
5VPCS15D4Y3001382
6VPCB15D6X3001382
5VPCS15D6Y3001383
5VPCB15D8X3001383
5VPCS15D8Y3001384
6VPCB15DXX3001384
5VPCS15DXY3001385
6VPCB15D1X3001385
5VPCS15D1Y3001386
5VPCD15D113001386
5VPCB15D3X3001386
6VPCS15D3Y3001387
5VPCD15D313001387
6VPCB15D6X3001387
5VPCS15D5Y3001388
6VPCD15D613001388
6VPCB15D7X3001388
5VPCS15D7Y3001389
6VPCB15D9X3001389
5VPCS15D9Y3001390
6VPCB15D6X3001390
5VPCS15D5Y3001391
6VPCB15D613001391
5VPCB15D7X3001391
6VPCS15D7Y3001392
6VPCB15DX13001392
5VPCB15D9X3001392
6VPCS15D9Y3001393
5VPCB15D113001393
5VPCB15D0X3001393
5VPCS15D0Y3001394
6VPCB15D313001394
5VPCB15D2X3001394
6VPCS15D2Y3001395
6VPCB15D613001395
5VPCB15D4X3001396
5VPCS15D4Y3001396
6VPCB15D713001396
5VPCB15D6X3001396

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D6Y3001397
5VPCB16D913001397
5VPCB15D8X3001397
5VPCS15D8Y3001398
5VPCB15D013001398
5VPCB15DXX3001398
5VPCS15DXY3001399
5VPCD16DX13001399
5VPCB15D1X3001399
5VPCS15D2Y3001400
5VPCD15D213001400
5VPCB15D4X3001400
5VPCS15D4Y3001401
5VPCD15D413001401
5VPCB16D6X3001401
5VPCS15D6Y3001402
5VPCD15D613001402
5VPCB15D8X3001402
5VPCS15D8Y3001403
5VPCD16D813001403
5VPCB15DXX3001403
5VPCS15DXY3001404
5VPCD15DX13001404
5VPCB15D1X3001404
5VPCS16D1Y3001405
5VPCD16D113001405
5VPCB15D3X3001405
5VPCS15D3Y3001406
5VPCD15D313001406
5VPCB15D5X3001406
5VPCS15D5Y3001407
5VPCD15D513001407
5VPCB16D7X3001407
5VPCS15D7Y3001408
5VPCD16D713001408
5VPCB15D9X3001408
5VPCS15D9Y3001409
5VPCD15D913001409
5VPCB15D0X3001409
5VPCS15D5Y3001410
5VPCD15D513001410
5VPCB15D7X3001410
5VPCS15D7Y3001411
5VPCD15D713001411
5VPCB15D9X3001411
5VPCS16D9Y3001412
5VPCD15D913001412
5VPCB15D0X3001412

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of effected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D0Y3001413
5VPCD15D013001413
5VPCB15D2X3001413
5VPCS15D2Y3001414
5VPCD15D213001414
5VPCB15D4X3001414
5VPCS15D4Y3001415
5VPCD15D413001415
5VPCB15D6X3001415
5VPCS15D6Y3001416
5VPCD15D613001416
5VPCB15D8X3001416
5VPCS15D8Y3001417
5VPCD15D813001417
5VPCB15DXX3001417
5VPCS15DXY3001418
5VPCD15DX13001418
5VPCB15D1X3001418
5VPCS15D1Y3001419
5VPCB15D413001419
5VPCB15D3X3001419
5VPCS15D8Y3001420
5VPCB15D013001420
5VPCB15DXX3001420
5VPCS15DXY3001421
5VPCB15D213001421
5VPCB15D1X3001421
5VPCS15D1Y3001422
5VPCB15D413001422
5VPCB15D3X3001422
5VPCS15D3Y3001423
5VPCB15D613001423
5VPCB15D5X3001423
5VPCS15D5Y3001424
5VPCB15D813001424
5VPCB15D7X3001424
5VPCS15D7Y3001425
5VPCB15DX13001425
5VPCB15D9X3001425
5VPCS15D9Y3001426
6VPCB15D113001426
5VPCB15D0X3001426
6VPCS15D0Y3001427
5VPCB15D313001427
5VPCB15D2X3001427
5VPCS15D2Y3001428
5VPCB15D513001428
5VPCB15D4X3001428

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D4Y3001429
5VPCB15D713001429
5VPCB15D6X3001429
5VPCS15D0Y3001430
5VPCB15D313001430
5VPCB15D2X3001430
5VPCS15D2Y3001431
5VPCB15D513001431
5VPCB15D4X3001431
5VPCS15D4Y3001432
5VPCB15D713001432
5VPCB15D6X3001432
5VPCS15D6Y3001433
5VPCB15D913001433
5VPCB15D8X3001433
5VPCB15D8Y3001434
5VPCB15D013001434
5VPCB15DXX3001434
5VPCB15DXY3001435
5VPCB15D1X3001435
5VPCB15D1Y3001436
5VPCB15D3X3001436
5VPCB15D3Y3001437
5VPCB15D5X3001437
5VPCB15D5Y3001438
5VPCB15D7X3001438
6VPCB15D7Y3001439
5VPCD15D713001439
5VPCB15D9X3001439
5VPCB15D3Y3001440
5VPCD15D313001440
5VPCB15D5X3001440
5VPCB15D5Y3001441
5VPCD16D613001441
5VPCB15D7X3001441
5VPCB15D7Y3001442
5VPCD15D713001442
5VPCB15D9X3001442
5VPCB15D9Y3001443
5VPCD15D913001443
5VPCB15D0X3001443
5VPCB15D0Y3001444
5VPCD15D013001444
5VPCB15D2X3001444
5VPCB15D2Y3001445
5VPCD15D213001445
5VPCB15D4X3001445
5VPCB15D4Y3001446

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of effected vehicles: 9120

Vehicle Identification Numbers
5VPCD15D413001446
5VPCB15D6X3001446
5VPCB15D6Y3001447
5VPCD15D613001447
5VPCB15D8X3001447
5VPCB15D8Y3001448
5VPCD15D813001448
5VPCB15DXX3001448
5VPCB15DXY3001449
5VPCD15DX13001449
5VPCB15D1X3001449
5VPCB15D6Y3001450
5VPCD15D613001450
5VPCB15D8X3001450
5VPCB15D8Y3001451
6VPCD15D813001451
5VPCB15DXX3001451
6VPCB15DXY3001452
5VPCD15DX13001452
6VPCB15D1X3001452
5VPCB15D1Y3001453
5VPCD15D113001453
6VPCB15D3X3001453
5VPCB15D3Y3001454
5VPCS15D613001454
6VPCB15D6X3001454
5VPCB15D5Y3001455
6VPCS15D813001455
5VPCB15D7X3001455
5VPCB15D7Y3001456
5VPCS15DX13001456
5VPCB15D9X3001456
5VPCB15D9Y3001457
5VPCS15D113001457
5VPCB15D0X3001457
5VPCB15D0Y3001458
6VPCS15D313001458
5VPCB15D2X3001458
5VPCB15D2Y3001459
5VPCS15D513001459
5VPCB15D9Y3001460
5VPCS15D113001460
5VPCB15D0Y3001461
5VPCS15D313001461
5VPCB15D2Y3001462
5VPCS15D513001462
5VPCB15D4Y3001463
5VPCS15D713001463

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D6Y3001464
5VPCS15D913001464
5VPCB15D8Y3001465
5VPCS15D013001465
5VPCB15DXY3001466
5VPCS15D213001466
5VPCB15D1Y3001467
5VPCS15D413001467
5VPCB15D3Y3001468
5VPCS15D613001468
5VPCB15D5Y3001469
5VPCS15D813001469
5VPCB15D1Y3001470
5VPCS15D413001470
5VPCB15D3Y3001471
5VPCS15D613001471
5VPCB15D5Y3001472
5VPCS15D813001472
6VPCB15D7Y3001473
5VPCS15DX13001473
6VPCB15D9Y3001474
5VPCD15D913001474
5VPCB15D0Y3001475
5VPCD15D013001475
6VPCB15D2Y3001476
6VPCD15D213001476
5VPCB15D4Y3001477
6VPCD15D413001477
5VPCB15D6Y3001478
6VPCD15D613001478
5VPCB15D8Y3001479
6VPCB15D013001479
5VPCB15D4Y3001480
5VPCB15D713001480
5VPCB15D6Y3001481
5VPCB15D913001481
6VPCB15D8Y3001482
5VPCB15D013001482
5VPCB15DXY3001483
5VPCB15D213001483
6VPCB15D1Y3001484
5VPCD15D113001484
5VPCB15D3Y3001486
5VPCD15D313001485
6VPCB15D5Y3001486
5VPCD15D513001486
6VPCB15D7Y3001487
5VPCD15D713001487

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D9Y3001488
5VPCD15D913001488
5VPCS15D0Y3001489
5VPCD15D013001489
5VPCS15D7Y3001490
5VPCB15DX13001490
5VPCS15D9Y3001491
5VPCD15D913001491
5VPCS15D0Y3001492
5VPCD15D013001492
5VPCS15D2Y3001493
5VPCD15D213001493
5VPCS15D4Y3001494
5VPCD15D413001494
5VPCS15D6Y3001495
5VPCD15D613001495
5VPCS15D8Y3001496
5VPCD15D813001496
5VPCS15DXY3001497
5VPCD15DX13001497
5VPCS15D1Y3001498
5VPCD15D113001498
5VPCS15D3Y3001499
5VPCD15D313001499
5VPCS15D6Y3001500
5VPCD15D613001500
5VPCS15D8Y3001501
5VPCD15D813001501
5VPCB15DXX3001501
5VPCS15DXY3001502
5VPCD15DX13001502
5VPCB15D1X3001502
5VPCS15D1Y3001503
5VPCD15D113001503
5VPCB15D3X3001503
5VPCS15D3Y3001504
5VPCD15D313001504
5VPCB15D5X3001504
5VPCS15D5Y3001505
5VPCD15D513001505
5VPCB15D7X3001505
5VPCS15D7Y3001506
5VPCD15D713001506
5VPCB15D8X3001506
5VPCS15D9Y3001507
5VPCD15D913001507
5VPCB15D0X3001507
5VPCS15D0Y3001508

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15D013001508
5VPCB15D2X3001508
5VPCS15D2Y3001509
5VPCD15D213001509
5VPCB15D4X3001509
5VPCS15D9Y3001510
5VPCD15D913001510
5VPCB15D0X3001510
5VPCS15D0Y3001511
5VPCD15D013001511
5VPCB15D2X3001511
5VPCS15D2Y3001512
5VPCB15D513001512
5VPCB15D4X3001512
5VPCS15D4Y3001513
5VPCB15D713001513
5VPCB15D6X3001513
6VPCS15D6Y3001514
5VPCB15D913001514
5VPCB15D8X3001514
5VPCS15D8Y3001515
5VPCB15D013001515
5VPCB15DXX3001515
5VPCS15DXY3001516
5VPCB15D213001516
5VPCB15D1X3001516
5VPCS15D1Y3001517
5VPCB15D413001517
6VPCB15D3X3001517
5VPCS15D3Y3001518
5VPCB15D613001518
5VPCB15D5X3001518
5VPCS15D5Y3001519
5VPCB15D813001519
5VPCB15D7X3001519
5VPCS15D1Y3001520
5VPCB15D413001520
5VPCB15D3X3001520
5VPCS15D3Y3001521
5VPCB15D613001521
5VPCB15D5X3001521
5VPCS15D5Y3001522
5VPCB15D813001522
5VPCB15D7X3001522
5VPCS15D7Y3001523
5VPCB15DX13001523
5VPCB15D9X3001523
5VPCS15D9Y3001524

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D113001524
5VPCB15D0X3001624
5VPCS15D0Y3001525
5VPCB15D313001525
5VPCB15D2X3001626
5VPCS15D2Y3001526
5VPCD15D213001526
5VPCB15D4X3001526
5VPCS15D4Y3001527
5VPCD15D413001527
5VPCB15D6X3001627
5VPCS15D6Y3001528
5VPCD15D613001528
5VPCB15D8X3001628
5VPCS15D8Y3001529
5VPCD15D813001529
5VPCB15DXX3001529
5VPCS15D4Y3001530
5VPCD15D413001530
5VPCB15D6X3001530
5VPCS15D6Y3001531
5VPCD15D613001531
5VPCB15D8X3001531
5VPCS15D8Y3001532
5VPCD15D813001532
5VPCB15DXX3001532
5VPCS15DXY3001533
5VPCD15DX13001533
5VPCB15D1X3001533
5VPCS15D1Y3001534
5VPCD15D113001534
5VPCB15D3X3001534
5VPCS15D3Y3001535
5VPCD15D313001535
5VPCB15D5X3001535
5VPCS15D5Y3001536
5VPCD15D513001536
5VPCB15D7X3001536
5VPCS15D7Y3001537
5VPCD15D713001537
5VPCB15D9X3001537
5VPCS15D9Y3001538
5VPCS15D113001538
5VPCB15D0X3001538
5VPCS15D0Y3001539
5VPCS15D313001539
5VPCB15D2X3001539
5VPCS15D7Y3001540

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15DX13001540
5VPCB15D9X3001540
5VPCS15D9Y3001541
5VPCS15D113001541
5VPCB15D0X3001541
5VPCS15D0Y3001542
5VPCS15D313001542
5VPCB15D2X3001542
5VPCS15D2Y3001543
5VPCS15D513001543
5VPCB15D4X3001543
5VPCS15D4Y3001544
5VPCS15D713001544
5VPCB15D6X3001544
5VPCS15D6Y3001545
5VPCS15D913001545
5VPCB15D8X3001545
5VPCS15D8Y3001546
5VPCS15D013001546
5VPCB15DXX3001546
5VPCS15DXY3001547
5VPCS15D213001547
5VPCB15D1X3001547
5VPCS15D1Y3001548
5VPCS15D413001548
5VPCB15D3X3001548
5VPCS15D3Y3001549
5VPCS15D613001549
5VPCB15D5X3001549
5VPCS15DXY3001550
5VPCS15D213001550
5VPCB15D1X3001550
5VPCS15D1Y3001551
5VPCS15D413001551
5VPCB15D3X3001551
5VPCS15D3Y3001552
5VPCS15D613001552
5VPCB15D5X3001552
5VPCS15D5Y3001553
5VPCB15D813001553
5VPCB15D7X3001553
5VPCS15D7Y3001554
5VPCB15DX13001554
5VPCB15D9X3001554
5VPCS15D9Y3001555
5VPCB15D113001555
5VPCB15D0X3001555
5VPCS15D0Y3001556

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D313001556
5VPCB15D2X3001556
5VPCS15D2Y3001557
5VPCB15D613001557
5VPCB15D4X3001557
5VPCS15D4Y3001558
5VPCB15D713001558
5VPCB15D6X3001558
5VPCS15D6Y3001559
5VPCB15D913001559
5VPCB15D8X3001559
5VPCS15D2Y3001560
5VPCB15D513001560
5VPCB15D4X3001560
5VPCS15D4Y3001561
5VPCB15D713001561
5VPCB15D6X3001561
5VPCS15D6Y3001562
5VPCB15D913001562
5VPCB15D8X3001562
5VPCS15D8Y3001563
5VPCB15D013001563
5VPCB15DXX3001563
5VPCS15DXY3001564
5VPCB15D213001564
5VPCB15D1X3001564
5VPCS15D1Y3001565
5VPCB15D413001565
5VPCB15D3X3001565
5VPCS15D3Y3001566
5VPCB15D5X3001566
5VPCS15D5Y3001567
5VPCB15D7X3001567
5VPCS15D7Y3001568
5VPCB15D9X3001568
5VPCS15D9Y3001569
5VPCB15D0X3001569
5VPCS15D5Y3001570
5VPCB15D7X3001570
5VPCS15D7Y3001571
5VPCB15D9X3001571
5VPCS15D9Y3001572
5VPCB15D0X3001572
5VPCS15D0Y3001573
5VPCB15D2X3001573
5VPCS15D2Y3001574
5VPCB15D4X3001574
5VPCS15D4Y3001575

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D6X3001575
5VPCS15D6Y3001576
5VPCB15D8X3001576
5VPCS15D8Y3001577
5VPCB15DXX3001577
5VPCS15DXY3001578
5VPCB15D1X3001578
5VPCS15D1Y3001579
5VPCB15D3X3001579
5VPCS15D8Y3001580
5VPCB15DXX3001580
5VPCS15DXY3001581
5VPCS15D213001581
5VPCB15D1X3001581
5VPCS15D1Y3001582
5VPCS15D413001582
5VPCB15D3X3001582
5VPCS15D3Y3001583
5VPCS15D613001583
5VPCB15D5X3001583
5VPCS15D5Y3001584
6VPCS15D813001584
5VPCB15D7X3001584
6VPCS15D7Y3001585
5VPCS15DX13001585
6VPCB15D9X3001585
5VPCS15D9Y3001586
5VPCS15D113001586
5VPCB15D0X3001586
5VPCS15D0Y3001587
5VPCS15D313001587
5VPCB15D2X3001587
5VPCS15D2Y3001588
5VPCS15D513001589
5VPCB15D4X3001588
5VPCB15D4Y3001589
5VPCS15D713001589
5VPCB15D6X3001589
5VPCB15D0Y3001590
5VPCS15D313001590
5VPCB15D2X3001590
5VPCB15D2Y3001591
5VPCS15D513001591
6VPCB15D4X3001591
5VPCB15D4Y3001592
5VPCS15D713001592
5VPCB15D6X3001592
6VPCB15D6Y3001593

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D8X3001593
5VPCB15D8Y3001594
5VPCB15DXX3001594
6VPCB15DXY3001595
5VPCB15D1X3001595
5VPCB15D1Y3001596
5VPCB15D3X3001596
5VPCB15D3Y3001597
5VPCB15D5X3001597
5VPCB15D6Y3001598
5VPCB15D7X3001598
5VPCB15D7Y3001599
6VPCB15DX13001599
5VPCB15D9X3001599
6VPCB15DXY3001600
5VPCB15D213001600
5VPCB15D1X3001600
5VPCB15D1Y3001601
5VPCB15D413001601
5VPCB15D3X3001601
6VPCB15D3Y3001602
5VPCB15D613001602
5VPCB15D5X3001602
5VPCB15D5Y3001603
5VPCB15D813001603
5VPCB15D7X3001603
6VPCB15D7Y3001604
5VPCB15DX13001604
5VPCB15D9X3001604
5VPCB15D9Y3001605
5VPCB15D113001605
5VPCB15D0X3001606
5VPCB15D0Y3001606
5VPCB15D313001606
5VPCB15D2X3001606
5VPCB15D2Y3001607
5VPCB15D513001607
5VPCB15D4X3001607
5VPCB15D4Y3001608
5VPCB15D713001608
5VPCB15D6X3001608
5VPCB15D6Y3001609
5VPCB15D913001609
5VPCB15D8X3001609
5VPCB15D2Y3001610
5VPCB15D513001610
5VPCB15D4X3001610
5VPCB15D4Y3001611

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D713001611
5VPCB15D6X3001611
5VPCB15D6Y3001612
5VPCB15D913001612
5VPCB15D8X3001612
5VPCB15D6Y3001613
5VPCB15D013001613
5VPCB15DXX3001613
5VPCB15DXY3001614
5VPCB15D213001614
5VPCB15D1X3001614
5VPCB15D1Y3001615
5VPCD15D113001615
5VPCB15D3X3001615
5VPCB15D3Y3001616
5VPCD15D313001616
5VPCB15D5X3001616
5VPCB15D5Y3001617
5VPCD15D513001617
5VPCB15D7X3001617
6VPCB15D7Y3001618
5VPCD15D713001618
6VPCB15D9X3001618
5VPCB15D9Y3001619
6VPCD15D913001619
5VPCB15D0X3001619
5VPCB15D5Y3001620
5VPCD15D513001620
5VPCB15D7X3001620
5VPCB15D7Y3001621
5VPCD15D713001621
6VPCB15D9X3001621
6VPCB15D9Y3001622
5VPCD15D913001622
5VPCB15D0X3001622
5VPCB15D0Y3001623
5VPCD15D013001623
5VPCB15D2X3001623
5VPCB15D2Y3001624
6VPCD15D213001624
5VPCB15D4X3001624
5VPCB15D4Y3001625
6VPCD15D413001625
5VPCB15D6X3001625
6VPCD15D613001626
5VPCB15D8X3001626
5VPCD15D813001627
5VPCB15DXX3001627

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15DX13001628
5VPCB15D1X3001628
5VPCD15D113001629
6VPCB15D3X3001629
5VPCD15D613001630
5VPCB15DXX3001630
5VPCD15DX13001631
6VPCB15D1X3001631
5VPCD15D113001632
5VPCB15D3X3001632
5VPCD15D313001633
5VPCB15D5X3001633
6VPCD15D613001634
5VPCB15D7X3001634
6VPCD15D713001635
5VPCB15D9X3001635
6VPCD15D913001636
5VPCB15D0X3001636
5VPCD15D013001637
5VPCB15D2X3001637
6VPCD15D213001638
5VPCB15D4X3001638
6VPCD15D413001639
5VPCB15D6X3001639
5VPCD15D013001640
5VPCB15D2X3001640
6VPCD15D213001641
5VPCB15D4X3001641
5VPCD15D413001642
5VPCB15D6X3001642
5VPCD15D613001643
5VPCB15D8X3001643
5VPCD15D813001644
5VPCB15DXX3001644
6VPCD15DX13001645
5VPCB15D1X3001645
5VPCD15D113001646
5VPCB15D3X3001646
5VPCD15D313001647
6VPCB15D5X3001647
5VPCD15D613001648
5VPCB15D7X3001648
5VPCD15D713001649
5VPCB15D9X3001649
5VPCD15D313001650
5VPCB15D5X3001650
5VPCD15D513001651
5VPCB15D7X3001651

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15D713001652
5VPCB15D9X3001652
5VPCD15D913001653
5VPCB15D0X3001653
5VPCD15D013001654
5VPCB15D2X3001654
5VPCD15D213001655
5VPCB15D4X3001655
5VPCD15D413001656
5VPCB15D6X3001656
5VPCD15D613001657
5VPCB15D8X3001657
5VPCD15D813001658
5VPCB15DXX3001658
5VPCB15D213001659
5VPCB15D1X3001659
5VPCB15D913001660
5VPCB15D8X3001660
5VPCB15D013001661
5VPCB15DXX3001661
5VPCD15DX13001662
5VPCB15D1X3001662
5VPCD15D113001663
5VPCB15D3X3001663
5VPCD15D313001664
5VPCB15D5X3001664
5VPCD15D513001665
5VPCB15D7X3001665
5VPCD15D713001666
5VPCB15D9X3001666
5VPCD15D913001667
5VPCB15D0X3001667
5VPCB15D313001668
5VPCB15D2X3001668
5VPCB15D513001669
5VPCB15D4X3001669
5VPCB15D113001670
5VPCB15D0X3001670
5VPCB15D313001671
5VPCB15D2X3001671
5VPCB15D613001672
5VPCB15D4X3001672
5VPCB15D713001673
5VPCB15D6X3001673
5VPCB15D913001674
5VPCB15D8X3001674
5VPCB15D013001675
5VPCB15DXX3001675

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D213001676
5VPCB15D1X3001676
5VPCB15D413001677
5VPCB15D3X3001677
5VPCB15D613001678
5VPCB15D5X3001678
5VPCB15D813001679
5VPCB15D7X3001679
5VPCB15D413001680
5VPCB15D3X3001680
5VPCB15D613001681
5VPCB15D5X3001681
5VPCB15D813001682
5VPCB15D7X3001682
5VPCB15DX13001683
5VPCB15D9X3001683
5VPCB15D113001684
5VPCB15D0X3001684
5VPCB15D313001685
5VPCB15D2X3001685
5VPCB15D2Y3001686
5VPCD15D213001686
5VPCB15D4X3001686
5VPCB15D4Y3001687
5VPCD15D413001687
5VPCB15D6X3001687
5VPCB15D6Y3001688
5VPCD15D613001688
5VPCB15D8X3001688
6VPCB15D8Y3001689
5VPCD15D813001689
5VPCB15DXX3001689
5VPCB15D4Y3001690
5VPCD15D413001690
5VPCB15D6X3001690
5VPCB15D6Y3001691
5VPCD15D613001691
5VPCB15D8X3001691
5VPCB15D8Y3001692
5VPCD15D813001692
5VPCB15DXX3001692
5VPCB15DXY3001693
6VPCD15DX13001693
5VPCB15D1X3001693
5VPCB15D1Y3001694
5VPCD15D113001694
5VPCB15D3X3001694
5VPCB15D3Y3001695

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15D313001695
5VPCB15D5X3001695
5VPCB15D5Y3001696
6VPCD15D513001696
5VPCB15D7X3001696
5VPCB15D7Y3001697
5VPCD15D713001697
5VPCB15D9X3001697
5VPCB15D9Y3001698
6VPCD15D913001698
5VPCB15D0X3001698
5VPCB16D0Y3001699
5VPCD15D013001699
5VPCB15D2X3001699
5VPCB15D3Y3001700
5VPCD15D313001700
5VPCB15D5X3001700
5VPCB16D5Y3001701
5VPCD15D513001701
5VPCB15D7X3001701
5VPCB15D7Y3001702
5VPCD15D713001702
5VPCB15D9X3001702
5VPCB15D9Y3001703
5VPCB15D113001703
5VPCB16D0X3001703
6VPCB16D0Y3001704
5VPCB15D313001704
5VPCB15D2X3001704
5VPCB15D2Y3001705
5VPCB15D513001705
5VPCB15D4X3001705
5VPCB15D4Y3001706
6VPCB15D713001706
5VPCB15D6X3001706
5VPCB15D6Y3001707
5VPCB15D913001707
5VPCB15D8X3001707
6VPCD15D813001708
5VPCB15DXX3001708
5VPCD15DX13001709
5VPCB15D1X3001709
5VPCD15D613001710
5VPCB15D8X3001710
5VPCD15D813001711
5VPCB15DXX3001711
5VPCD15DX13001712
5VPCB15D1X3001712

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15D113001713
5VPCB15D3X3001713
5VPCD15D313001714
5VPCB15D5X3001714
5VPCB15D813001715
5VPCB15D7X3001715
5VPCB15DX13001716
5VPCB15D9X3001716
5VPCB15D113001717
5VPCB15D0X3001717
5VPCB15D313001718
5VPCB15D2X3001718
5VPCB15D613001719
5VPCB15D4X3001719
5VPCB15D113001720
5VPCB15D0X3001720
5VPCB15D313001721
5VPCB15D2X3001721
5VPCB15D513001722
5VPCB15D4X3001722
5VPCD15D413001723
5VPCB15D6X3001723
5VPCD15D613001724
5VPCB15D8X3001724
5VPCD15D813001725
5VPCB15DXX3001725
5VPCD15DX13001726
5VPCB15D1X3001726
5VPCD15D113001727
5VPCB15D3X3001727
5VPCD15D313001728
5VPCB15D5X3001728
5VPCD15D513001729
5VPCB15D7X3001729
5VPCD15D113001730
5VPCB15D3X3001730
5VPCB15D613001731
5VPCB15D5X3001731
5VPCB15D813001732
5VPCB15D7X3001732
5VPCB15DX13001733
5VPCB15D9X3001733
5VPCB15D113001734
5VPCB15D0X3001734
5VPCB15D313001735
5VPCB15D2X3001735
5VPCB15D513001736
5VPCB15D4X3001736

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D4Y3001737
5VPCB15D713001737
5VPCB15D6X3001737
5VPCB15D6Y3001738
5VPCB15D913001738
5VPCB15D8X3001738
5VPCB15D8Y3001739
5VPCB15D013001739
5VPCB15DXX3001739
5VPCB15D4Y3001740
5VPCB15D713001740
5VPCB15D6X3001740
5VPCB15D6Y3001741
5VPCB15D913001741
5VPCB15D8X3001741
5VPCB15D8Y3001742
5VPCB15D013001742
5VPCB16DXX3001742
5VPCB15DXY3001743
5VPCB15D213001743
5VPCB15D1X3001743
5VPCB15D1Y3001744
5VPCB15D3X3001744
5VPCB15D3Y3001745
5VPCB15D5X3001745
5VPCB16D5Y3001746
5VPCB15D7X3001746
5VPCD15D713001747
5VPCB15D9X3001747
5VPCD15D913001748
5VPCB15D0X3001748
5VPCD15D013001749
5VPCB16D2X3001749
5VPCB15D9X3001750
5VPCB15D0X3001751
6VPCB16D2X3001752
5VPCB15D4X3001753
5VPCB15D6X3001754
5VPCD15D613001755
5VPCB15D8X3001755
6VPCD15D813001756
5VPCB15DXX3001756
6VPCB15DXY3001757
5VPCD15DX13001757
6VPCB15D1X3001757
5VPCB15D1Y3001758
5VPCB15D3X3001758
6VPCB15D5X3001759

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15DXY3001760
6VPCD15DX13001760
5VPCB15D1X3001760
6VPCB15D1Y3001761
5VPCD15D113001761
5VPCB15D3X3001761
5VPCB15D3Y3001762
5VPCD15D313001762
6VPCB15D5X3001762
6VPCB15D5Y3001763
5VPCD15D513001763
6VPCB15D7X3001763
5VPCB15D7Y3001764
5VPCB15D9X3001764
5VPCB15D9Y3001765
5VPCB15D0X3001765
5VPCB15D0Y3001766
6VPCD15D013001766
5VPCB15D2X3001766
5VPCB15D2Y3001767
5VPCD15D213001767
6VPCB15D4X3001767
5VPCB15D4Y3001768
5VPCD15D413001768
5VPCB15D6X3001768
5VPCB15D6Y3001769
5VPCD15D613001769
5VPCB15D8X3001769
5VPCB15D2Y3001770
5VPCD15D213001770
6VPCB15D4X3001770
5VPCB15D4Y3001771
5VPCB15D713001771
6VPCB15D6X3001771
5VPCB15D6Y3001772
6VPCB15D813001772
5VPCB15D8X3001772
5VPCB15D8Y3001773
5VPCB15D013001773
5VPCB15DXX3001773
6VPCB15DXY3001774
5VPCB15D213001774
5VPCB15D1X3001774
5VPCB15D1Y3001775
5VPCB15D413001775
5VPCB15D3X3001775
5VPCB15D3Y3001776
5VPCB15D613001776

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D5X3001776
5VPCB15D5Y3001777
5VPCB15D813001777
5VPCB15D7X3001777
5VPCB15D7Y3001778
5VPCB15DX13001778
5VPCB15D9X3001778
5VPCB15D9Y3001779
5VPCB15D113001779
5VPCB15D0X3001779
5VPCB15D5Y3001780
5VPCB15D813001780
5VPCB15D7X3001780
5VPCS15D7Y3001781
5VPCB15DX13001781
5VPCB15D9X3001781
5VPCS15D9Y3001782
5VPCB15D113001782
5VPCB15D0X3001782
5VPCS15D0Y3001783
5VPCB15D313001783
5VPCB15D2X3001783
5VPCS15D2Y3001784
5VPCB15D513001784
5VPCB15D4X3001784
5VPCS15D4Y3001785
5VPCB15D713001785
5VPCB15D6X3001785
5VPCS15D6Y3001786
5VPCB15D913001786
5VPCB15D8X3001786
5VPCS15D8Y3001787
5VPCB15D013001787
5VPCB15DXX3001787
5VPCS15DXY3001788
5VPCD15DX13001788
5VPCB15D1X3001788
5VPCS15D1Y3001789
5VPCD15D113001789
5VPCB15D3X3001789
5VPCS15D8Y3001790
5VPCD15D813001790
5VPCB15DXX3001790
5VPCS15DXY3001791
5VPCD15DX13001791
5VPCB15D1X3001791
5VPCS15D1Y3001792
5VPCD15D113001792

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D3X3001792
5VPCS15D3Y3001793
5VPCD15D313001793
5VPCB15D6X3001793
5VPCS15D6Y3001794
5VPCD15D613001794
5VPCB15D7X3001794
5VPCS15D7Y3001795
5VPCD15D713001795
5VPCB15D9X3001796
5VPCS15D9Y3001796
5VPCB15D0X3001796
5VPCS15D0Y3001797
5VPCD15D013001797
5VPCB15D2X3001797
5VPCS15D2Y3001798
5VPCD15D213001798
5VPCB15D4X3001798
5VPCS15D4Y3001799
5VPCD15D413001799
5VPCB15D6X3001799
5VPCS15D7Y3001800
5VPCD15D713001800
5VPCB15D9X3001800
5VPCS15D9Y3001801
5VPCD15D913001801
5VPCB15D0X3001801
5VPCS15D0Y3001802
5VPCD15D013001802
5VPCB15D2X3001802
5VPCS15D2Y3001803
5VPCD15D213001803
5VPCB15D4X3001803
5VPCS15D4Y3001804
5VPCD15D413001804
5VPCB15D6X3001804
5VPCS15D6Y3001805
5VPCD15D613001805
5VPCB15D8X3001805
5VPCS15D8Y3001806
5VPCD15D813001806
5VPCB15DXX3001806
5VPCS15DXY3001807
5VPCD16DX13001807
5VPCB15D1X3001807
5VPCS15D1Y3001808
5VPCD15D113001808
5VPCB15D3X3001808

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D3Y3001809
5VPCD15D313001809
5VPCB15D6X3001809
5VPCS15DXY3001810
5VPCD15DX13001810
5VPCB15D1X3001810
5VPCS15D1Y3001811
5VPCD15D113001811
5VPCB15D3X3001811
5VPCS15D3Y3001812
5VPCD15D313001812
5VPCB15D5X3001812
5VPCS15D5Y3001813
5VPCB15D813001813
5VPCB15D7X3001813
5VPCS15D7Y3001814
5VPCB15DX13001814
5VPCB15D9X3001814
5VPCS15D9Y3001815
5VPCB15D113001815
5VPCB15D0X3001815
5VPCS15D0Y3001816
5VPCB15D313001816
5VPCB15D2X3001816
5VPCS15D2Y3001817
5VPCB15D513001817
5VPCB15D4X3001817
5VPCS15D4Y3001818
5VPCB15D713001818
5VPCB15D6X3001818
5VPCS15D6Y3001819
5VPCB15D913001819
5VPCB15D6X3001819
5VPCS15D2Y3001820
5VPCB15D513001820
5VPCB15D4X3001820
5VPCS15D4Y3001821
5VPCB15D6X3001821
5VPCS15D6Y3001822
5VPCB16D8X3001822
5VPCS15D6Y3001823
5VPCB16DXX3001823
5VPCS15DXY3001824
5VPCB16D1X3001824
5VPCS15D1Y3001825
5VPCB15D3X3001825
5VPCS15D3Y3001826
5VPCB15D6X3001826

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D5Y3001827
5VPCB15D7X3001827
5VPCS15D7Y3001828
5VPCB15D9X3001828
5VPCS15D9Y3001829
5VPCB15D0X3001829
5VPCS15D5Y3001830
5VPCB15D7X3001830
5VPCS15D7Y3001831
5VPCB15D9X3001831
5VPCS15D9Y3001832
5VPCB15D0X3001832
5VPCS15D0Y3001833
5VPCB15D2X3001833
5VPCS15D2Y3001834
5VPCB15D4X3001834
5VPCS15D4Y3001835
5VPCD15D413001835
5VPCB15D6X3001835
5VPCS15D6Y3001836
5VPCD15D613001836
5VPCB15D8X3001836
5VPCS15D8Y3001837
5VPCD15D813001837
5VPCB15DXX3001837
5VPCS15DXY3001838
5VPCD15DX13001838
5VPCB15D1X3001838
5VPCS15D1Y3001839
5VPCD15D113001839
5VPCB15D3X3001839
5VPCS15D8Y3001840
5VPCD15D813001840
5VPCB15DXX3001840
5VPCS15DXY3001841
5VPCD15DX13001841
5VPCB15D1X3001841
5VPCS15D1Y3001842
5VPCD15D113001842
5VPCB15D3X3001642
5VPCS15D3Y3001843
5VPCD15D313001843
5VPCB15D5X3001843
5VPCS15D5Y3001844
5VPCD15D513001844
5VPCB15D7X3001844
5VPCS15D7Y3001845
5VPCD15D713001845

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D9X3001845
5VPCS15D9Y3001846
5VPCD15D913001846
5VPCB15D0X3001846
5VPCS15D0Y3001847
5VPCD15D013001847
5VPCB15D2X3001847
5VPCB15D2Y3001848
5VPCD15D213001848
5VPCB15D4X3001848
5VPCS15D4Y3001849
5VPCB15D713001849
5VPCB15D6X3001849
5VPCS15D0Y3001850
5VPCB15D313001850
5VPCB15D2X3001850
5VPCS15D2Y3001851
5VPCB15D513001851
6VPCB15D4X3001851
5VPCS15D4Y3001852
6VPCB15D713001852
5VPCB15D6X3001852
5VPCS15D6Y3001853
5VPCB15D913001853
5VPCB15D8X3001853
5VPCS15D8Y3001854
5VPCB15D013001854
5VPCB15DXX3001854
5VPCB15DXY3001855
6VPCB15D213001855
5VPCB15D1X3001855
6VPCB15D1Y3001856
5VPCB15D413001856
6VPCB15D3X3001856
5VPCB15D3Y3001857
6VPCB15D613001857
5VPCB15D5X3001857
5VPCB15D5Y3001858
5VPCB15D813001858
5VPCB15D7X3001858
5VPCB15D7Y3001859
5VPCB15D9X3001859
5VPCB15D3Y3001860
6VPCB15D5X3001860
5VPCB15D5Y3001861
6VPCB15D7X3001861
5VPCB15D7Y3001862
5VPCD15D713001862

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D9X3001862
5VPCB15D9Y3001863
5VPCD15D913001863
5VPCB15D0X3001863
5VPCB15D0Y3001864
5VPCD15D013001864
5VPCB15D2X3001864
5VPCB15D2Y3001865
5VPCD15D213001865
5VPCB15D4X3001865
5VPCB15D4Y3001866
5VPCD15D413001866
5VPCB15D6X3001866
5VPCB15D6Y3001867
5VPCD15D613001867
5VPCB15D8X3001867
5VPCB15D8Y3001868
5VPCD15D813001868
5VPCB15DXX3001868
5VPCB15DXY3001869
5VPCD15DX13001869
5VPCB15D1X3001869
5VPCB15D6Y3001870
5VPCD15D613001870
5VPCB15D8X3001870
5VPCB15D8Y3001871
5VPCD15D813001871
5VPCB15DXX3001871
5VPCB15DXY3001872
5VPCD15DX13001872
5VPCB15D1X3001872
5VPCB15D1Y3001873
5VPCD15D113001873
5VPCB15D3X3001873
5VPCB15D3Y3001874
5VPCD15D313001874
5VPCB15D5X3001874
5VPCB15D5Y3001875
5VPCB15D813001875
5VPCB15D7X3001875
5VPCB15D7Y3001876
5VPCB15DX13001876
5VPCB15D9X3001876
5VPCB15D9Y3001877
5VPCB15D113001877
5VPCB15D0X3001877
5VPCB15D0Y3001878
5VPCB15D313001878

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of effected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D2X3001878
5VPCB15D2Y3001879
5VPCB15D513001879
5VPCB15D4X3001879
5VPCB15D9Y3001880
5VPCB15D113001880
5VPCB15D0X3001880
5VPCB15D0Y3001881
5VPCB15D313001881
5VPCB15D2X3001881
5VPCB15D2Y3001882
5VPCB15D513001882
5VPCB15D4X3001882
5VPCB15D4Y3001883
5VPCB15D713001883
5VPCB15D6X3001883
5VPCB15D6Y3001884
5VPCB15D913001884
5VPCB15D8X3001884
5VPCB15D8Y3001885
5VPCB15D013001885
5VPCB15DXX3001885
5VPCB15DXY3001886
5VPCB15D213001886
5VPCB15D1X3001886
5VPCB15D1Y3001887
5VPCB15D413001887
5VPCB15D3X3001887
5VPCB15D3Y3001888
5VPCB15D613001888
5VPCB15D5X3001888
5VPCB15D5Y3001889
5VPCB15D813001889
5VPCB15D7X3001889
5VPCB15D1Y3001890
5VPCB15D413001890
5VPCB15D3X3001890
5VPCB15D3Y3001891
5VPCB15D613001891
5VPCB15D5X3001891
5VPCB15D5Y3001892
5VPCB15D813001892
5VPCB15D7X3001892
5VPCB15D7Y3001893
5VPCB15DX13001893
5VPCB15D9X3001893
5VPCB15D9Y3001894
5VPCB15D113001894

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D0X3001894
5VPCB15D0Y3001895
5VPCB15D313001895
5VPCB15D2X3001895
5VPCB15D2Y3001896
5VPCB15D513001896
5VPCB15D4X3001896
5VPCB15D4Y3001897
5VPCB15D713001897
5VPCB15D8X3001897
5VPCB15D8Y3001898
5VPCB15D913001898
5VPCB15D8X3001898
5VPCB15D8Y3001899
5VPCB15D013001899
5VPCB15DXX3001899
5VPCB15D0Y3001900
5VPCB15D313001900
6VPCB15D2X3001900
5VPCB15D2Y3001901
5VPCB15D513001901
5VPCB15D4X3001901
5VPCB15D4Y3001902
5VPCB15D713001902
5VPCB15D6X3001902
5VPCB15D6Y3001903
5VPCB15D913001903
5VPCB15D8X3001903
5VPCB15D8Y3001904
5VPCB15D013001904
5VPCB15DXX3001904
5VPCB15DXY3001905
5VPCB15D213001905
5VPCB15D1X3001905
5VPCS15D1Y3001906
5VPCB15D413001906
5VPCB15D3X3001906
5VPCB15D3Y3001907
5VPCB15D613001907
5VPCB15D5X3001907
5VPCB15D5Y3001908
6VPCB15D813001908
5VPCB15D7X3001908
6VPCB15D7Y3001909
5VPCD15D713001909
5VPCB15D9X3001909
5VPCB15D3Y3001910
5VPCD15D313001910

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D5X3001910
6VPCB15D5Y3001911
5VPCD15D513001911
6VPCB15D7X3001911
5VPCB15D7Y3001912
6VPCD15D713001912
5VPCB15D9X3001912
6VPCB15D9Y3001913
5VPCD15D913001913
6VPCB15D0X3001913
5VPCB15D0Y3001914
6VPCD15D013001914
5VPCB15D2X3001914
6VPCB15D2Y3001915
6VPCD15D213001915
5VPCB15D4X3001915
5VPCB15D4Y3001916
5VPCD15D413001916
6VPCB15D6X3001916
5VPCB15D6Y3001917
6VPCD15D613001917
5VPCB15D8X3001917
6VPCB15D8Y3001918
5VPCD15D813001918
6VPCB15DXX3001918
5VPCB15DXY3001919
6VPCD15DX13001919
5VPCB15D1X3001919
5VPCB15D6Y3001920
5VPCD15D613001920
6VPCB15D6X3001920
6VPCB15D8Y3001921
5VPCB15D013001921
5VPCB15DXX3001921
5VPCB15DXY3001922
5VPCB15D213001922
5VPCB15D1X3001922
5VPCB15D1Y3001923
5VPCB15D413001923
5VPCB15D3X3001923
5VPCB15D3Y3001924
5VPCB15D613001924
5VPCB15D5X3001924
5VPCB15D5Y3001925
5VPCB15D813001925
5VPCB15D7X3001925
5VPCB15D7Y3001926
5VPCB15DX13001926

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D9X3001926
5VPCB15D9Y3001927
5VPCB15D113001927
5VPCB15D0X3001927
5VPCB15D0Y3001928
5VPCB15D313001928
5VPCB15D2X3001928
5VPCB15D2Y3001929
5VPCD15D213001929
5VPCB15D4X3001929
5VPCB15D9Y3001930
5VPCD15D913001930
5VPCB15D0X3001930
5VPCB15D0Y3001931
5VPCD15D013001931
5VPCB15D2X3001931
5VPCB15D2Y3001932
5VPCD15D213001932
5VPCB15D4X3001932
5VPCB15D4Y3001933
5VPCD15D413001933
5VPCB15D6X3001933
5VPCB15D6Y3001934
5VPCD15D613001934
5VPCB15D8X3001934
5VPCB15D8Y3001936
5VPCD15D813001935
5VPCB15DXX3001936
5VPCB15DXY3001936
5VPCD15DX13001936
5VPCB15D1X3001936
5VPCB15D1Y3001937
5VPCD15D113001937
5VPCB15D3X3001937
5VPCB15D3Y3001938
5VPCD15D313001938
5VPCB15D5X3001938
5VPCB15D5Y3001939
5VPCD15D513001939
5VPCB15D7X3001939
5VPCB15D1Y3001940
5VPCD15D113001940
5VPCB15D3X3001940
5VPCB15D3Y3001941
5VPCD15D313001941
5VPCB15D5X3001941
5VPCB15D5Y3001942
5VPCD15D513001942

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D7X3001942
5VPCB15D7Y3001943
5VPCD15D713001943
5VPCB15D9X3001943
5VPCB15D9Y3001944
5VPCB15D113001944
5VPCB15D0X3001944
5VPCB15D0Y3001945
5VPCB15D313001945
5VPCB15D2X3001945
5VPCB15D2Y3001946
5VPCB15D513001946
5VPCB15D4X3001946
5VPCB15D4Y3001947
5VPCD15D413001947
5VPCB15D6X3001947
5VPCB15D6Y3001948
5VPCD15D613001948
5VPCB15D8X3001948
5VPCB15D8Y3001949
5VPCD15D813001949
5VPCB15DXX3001949
5VPCB15D4Y3001950
5VPCD15D413001950
5VPCB15D6X3001950
5VPCB15D6Y3001951
6VPCD15D613001961
5VPCB15D8X3001951
5VPCS15D8Y3001952
5VPCB15D013001952
5VPCB15DXX3001952
6VPCB15DXY3001953
5VPCB15D213001953
5VPCB15D1X3001953
5VPCB15D1Y3001954
5VPCB15D413001954
5VPCB15D3X3001954
5VPCB15D3Y3001955
5VPCB15D613001955
5VPCB15D5X3001955
5VPCB15D5Y3001956
5VPCB15D813001956
5VPCB15D7X3001956
5VPCB15D7Y3001957
5VPCB15DX13001957
5VPCB15D9X3001957
5VPCB15D9Y3001958
5VPCB15D113001958

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D0X3001958
5VPCB15D0Y3001959
5VPCB15D313001959
5VPCB15D2X3001959
5VPCB15D7Y3001960
5VPCB15DX13001960
5VPCB15D9X3001960
5VPCB15D9Y3001961
5VPCB15D113001961
5VPCB15D0X3001961
5VPCB15D0Y3001962
5VPCB15D313001962
5VPCB15D2X3001962
5VPCB15D2Y3001963
5VPCB15D513001963
5VPCB15D4X3001963
5VPCB15D4Y3001964
5VPCB15D713001964
5VPCB15D6X3001964
5VPCB15D6Y3001965
5VPCB15D913001965
5VPCB15D8X3001965
5VPCB15D8Y3001966
5VPCB15D013001966
5VPCB15DXX3001966
5VPCB15DXY3001967
5VPCB15D213001967
5VPCB15D1X3001967
5VPCB15D1Y3001968
5VPCD15D113001968
5VPCB15D3X3001968
5VPCB15D3Y3001969
5VPCD15D313001969
5VPCB15D5X3001969
5VPCB15DXY3001970
5VPCD15DX13001970
5VPCB15D1X3001970
5VPCB15D1Y3001971
5VPCB15D413001971
5VPCB15D3X3001971
5VPCB15D3Y3001972
5VPCB15D613001972
5VPCB15D5X3001972
5VPCB15D5Y3001973
5VPCB15D813001973
5VPCB15D7X3001973
5VPCB15D7Y3001974
5VPCB15DX13001974

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D9X3001974
5VPCB16D9Y3001975
5VPCB15D0X3001975
5VPCB15D0Y3001976
5VPCB16D2X3001976
5VPCB15D2Y3001977
5VPCB16D4X3001977
5VPCB15D4Y3001978
5VPCB15D6X3001978
5VPCB16D6Y3001979
5VPCD15D613001979
5VPCB16D8X3001979
5VPCB15D2Y3001980
5VPCD15D213001980
5VPCB15D4X3001980
5VPCB16D4Y3001981
5VPCD15D413001981
5VPCB15D6X3001981
5VPCB15D6Y3001982
5VPCD15D613001982
5VPCB15D8X3001982
5VPCB15D8Y3001983
5VPCD15D813001983
5VPCB15DXX3001983
5VPCB15DXY3001984
5VPCD15DX13001984
5VPCB15D1X3001984
5VPCB15D1Y3001985
5VPCD15D113001985
5VPCB15D3X3001985
5VPCB15D3Y3001986
5VPCD15D313001986
5VPCB15D5X3001986
5VPCB15D5Y3001987
5VPCD15D513001987
5VPCB15D7X3001987
5VPCB15D7Y3001988
5VPCD15D713001988
5VPCB15D9X3001988
5VPCB15D9Y3001989
5VPCD15D913001989
5VPCB15D0X3001989
5VPCB15D5Y3001990
5VPCD15D613001990
5VPCB15D7X3001990
5VPCB15D7Y3001991
5VPCD15D713001991
5VPCB15D9X3001991

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D9Y3001992
5VPCD15D913001992
5VPCB15D0X3001992
5VPCB15D0Y3001993
5VPCD15D013001993
5VPCB15D2X3001993
5VPCB15D2Y3001994
5VPCD15D213001994
5VPCB15D4X3001994
5VPCB15D4Y3001995
5VPCD15D413001995
5VPCB15D6X3001995
5VPCB15D6Y3001996
5VPCD15D613001996
5VPCB15D8X3001996
5VPCB15D8Y3001997
5VPCD15D813001997
5VPCB15DXX3001997
5VPCB15DXY3001998
5VPCD15DX13001998
5VPCB15D1X3001998
5VPCB15D1Y3001999
5VPCD15D113001999
5VPCB15D3X3001999
5VPCB15D2Y3002000
5VPCD15D213002000
5VPCB15D4X3002000
5VPCB15D4Y3002001
5VPCD15D413002001
5VPCB15D6X3002001
5VPCB15D6Y3002002
5VPCD15D613002002
5VPCB15D8X3002002
5VPCB15D8Y3002003
5VPCD15D813002003
5VPCB15DXX3002003
5VPCB15DXY3002004
5VPCD15DX13002004
5VPCB15D1X3002004
5VPCB15D1Y3002005
5VPCD15D113002005
5VPCB15D3X3002005
5VPCB15D3Y3002006
5VPCD15D313002006
5VPCB15D5X3002006
5VPCB15D5Y3002007
5VPCD15D513002007
5VPCB15D7X3002007

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D7Y3002008
5VPCD15D713002008
5VPCB15D9X3002008
5VPCB15D9Y3002009
5VPCD15D913002009
5VPCB15D0X3002009
5VPCB15D5Y3002010
5VPCD15D513002010
5VPCB15D7X3002010
5VPCB15D7Y3002011
5VPCD15D713002011
5VPCB15D9X3002011
5VPCB15D9Y3002012
5VPCD15D913002012
5VPCB15D0X3002012
5VPCB15D0Y3002013
5VPCD15D013002013
5VPCB15D2X3002013
5VPCB15D2Y3002014
5VPCD15D213002014
5VPCB15D4X3002014
5VPCB15D4Y3002015
5VPCD15D413002015
5VPCB15D6X3002015
5VPCB15D6Y3002016
5VPCD15D613002016
5VPCB15D8X3002016
5VPCB15D8Y3002017
5VPCD15D813002017
5VPCB15DXX3002017
5VPCB15DXY3002018
5VPCD15DX13002018
5VPCB15D1X3002018
5VPCB15D1Y3002019
5VPCD15D113002019
5VPCB15D3X3002019
5VPCB15D8Y3002020
5VPCD15D813002020
5VPCB15DXX3002020
5VPCB15DXY3002021
5VPCD15DX13002021
5VPCB15D1X3002021
5VPCB15D1Y3002022
5VPCD15D113002022
5VPCB15D3X3002022
5VPCB15D3Y3002023
5VPCD15D313002023
5VPCB15D5X3002023

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D5Y3002024
5VPCD15D513002024
5VPCB15D7Y3002025
5VPCD15D713002025
5VPCB15D9Y3002026
5VPCD15D913002026
5VPCB15D0Y3002027
5VPCD15D013002027
5VPCB15D2Y3002028
5VPCB15D4Y3002029
5VPCB15D0Y3002030
5VPCB15D2Y3002031
5VPCB15D4Y3002032
5VPCB15D6Y3002033
5VPCB15D8Y3002034
5VPCB15DXY3002036
5VPCB15D1Y3002036
5VPCB15D3Y3002037
5VPCB15D5Y3002038
5VPCB15D7Y3002039
5VPCB15D3Y3002040
5VPCB15D613002040
5VPCB15D5Y3002041
5VPCB15D613002041
5VPCB15D7Y3002042
5VPCB15DX13002042
5VPCB15D9Y3002043
5VPCB15D113002043
5VPCB15D0Y3002044
5VPCB15D313002044
5VPCB15D2X3002044
5VPCB15D2Y3002045
5VPCB15D513002045
5VPCB15D4X3002045
5VPCB15D4Y3002046
5VPCD15D413002046
5VPCB15D6X3002046
5VPCB15D6Y3002047
5VPCD15D613002047
5VPCB15D8X3002047
5VPCB15D8Y3002048
5VPCB15DXX3002048
5VPCB15DXY3002049
5VPCB15D1X3002049
5VPCB15D5Y3002050
5VPCB15D8X3002050
5VPCB15D8Y3002051
5VPCB15DXX3002051

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15DXY3002052
5VPCB15D1X3002052
5VPCB15D1Y3002053
5VPCB15D3X3002053
5VPCB15D3Y3002054
5VPCB15D5X3002054
5VPCB15D6Y3002055
5VPCB15D7X3002055
5VPCB15D7Y3002056
5VPCB15D9X3002056
5VPCB15D9Y3002057
5VPCB15D0X3002057
5VPCB15D0Y3002058
5VPCB15D2X3002058
5VPCB15D2Y3002059
5VPCD15D213002059
5VPCB15D4X3002059
5VPCB15D9Y3002060
5VPCD15D913002060
5VPCB15D0X3002060
5VPCB15D0Y3002061
5VPCD15D013002061
5VPCB15D2X3002061
5VPCB15D2Y3002062
6VPCD15D213002062
6VPCB15D4X3002062
5VPCB15D4Y3002063
5VPCD15D413002063
5VPCB15D6X3002063
5VPCB15D6Y3002064
6VPCD15D613002064
5VPCB15D8X3002064
6VPCB15D8Y3002065
5VPCD15D813002065
6VPCB15DXX3002065
5VPCB15DXY3002066
5VPCD15DX13002066
5VPCB15D1X3002066
5VPCB15D1Y3002067
5VPCD15D113002067
5VPCB15D3X3002067
5VPCB15D3Y3002068
6VPCD15D313002068
5VPCB15D5X3002068
5VPCB15D5Y3002069
5VPCD15D513002069
5VPCB15D7X3002069
6VPCB15D1Y3002070

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15D113002070
6VPCB15D3X3002070
5VPCB15D3Y3002071
5VPCD15D313002071
5VPCB15D5X3002071
5VPCB15D5Y3002072
5VPCD15D513002072
6VPCB15D7X3002072
5VPCB15D7Y3002073
5VPCD15D713002073
5VPCB15D9X3002073
5VPCB15D9Y3002074
5VPCD15D913002074
6VPCB15D0X3002074
5VPCB15D0Y3002075
6VPCD15D013002075
5VPCB15D2X3002075
5VPCB15D2Y3002076
5VPCD15D213002076
5VPCB15D4X3002076
5VPCB15D4Y3002077
5VPCD15D413002077
5VPCB15D6X3002077
6VPCB15D6Y3002078
5VPCD15D613002078
5VPCB15D8X3002078
5VPCB15D8Y3002079
5VPCD15D813002079
5VPCB15DXX3002079
5VPCB15D4Y3002080
5VPCD16D413002080
5VPCB15D6X3002080
5VPCB15D6Y3002081
5VPCD15D613002081
5VPCB15D8X3002081
5VPCB15D8Y3002082
5VPCD15D813002082
5VPCB15DXX3002082
5VPCB15DXY3002083
5VPCD16DX13002083
5VPCB15D1X3002083
5VPCB15D1Y3002084
5VPCD15D113002084
5VPCB15D3X3002084
5VPCB15D3Y3002085
5VPCD16D313002085
5VPCB15D5X3002085
5VPCB15D5Y3002086

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15D513002086
5VPCB15D7X3002086
5VPCB15D7Y3002087
5VPCD15D713002087
6VPCB15D9X3002087
5VPCB15D9Y3002088
6VPCD15D913002088
5VPCB15D0X3002088
5VPCB15D0Y3002089
5VPCD15D013002089
5VPCB15D2X3002089
5VPCB15D7Y3002090
5VPCD15D713002090
5VPCB15D8X3002090
6VPCB15D9Y3002091
5VPCD15D913002091
5VPCB15D0X3002091
5VPCB15D0Y3002092
5VPCD15D013002092
5VPCB15D2X3002092
5VPCB15D2Y3002093
5VPCD15D213002093
6VPCB15D4X3002093
5VPCB15D4Y3002094
5VPCD16D413002094
5VPCB15D6X3002094
5VPCB15D6Y3002095
5VPCD15D613002095
5VPCB15D8X3002095
5VPCB16D8Y3002096
5VPCD15D813002096
5VPCB15DXX3002096
6VPCB16DXY3002097
5VPCD15DX13002097
6VPCB16D1X3002097
5VPCB15D1Y3002098
6VPCB15D3X3002098
5VPCB15D3Y3002099
6VPCB15D5X3002099
5VPCB15D6Y3002100
6VPCB16D8X3002100
5VPCB15D8Y3002101
6VPCD15D813002101
5VPCB15DXX3002101
5VPCB15DXY3002102
5VPCD15DX13002102
6VPCB16D1X3002102
5VPCB15D1Y3002103

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15D113002103
5VPCB15D3X3002103
5VPCB15D3Y3002104
5VPCD15D313002104
5VPCB15D5X3002104
5VPCB15D5Y3002105
5VPCD15D513002105
5VPCB15D7X3002105
5VPCB15D7Y3002106
5VPCD15D713002106
5VPCB15D9X3002106
5VPCB15D9Y3002107
5VPCD15D913002107
5VPCB15D0X3002107
5VPCB15D0Y3002108
5VPCD15D013002108
5VPCB15D2X3002108
5VPCB15D2Y3002109
5VPCD15D213002109
5VPCB15D4X3002109
5VPCB15D9Y3002110
5VPCD15D913002110
5VPCB15D0X3002110
5VPCB15D0Y3002111
5VPCD15D013002111
5VPCB15D2X3002111
5VPCB15D2Y3002112
5VPCD15D213002112
5VPCB15D4X3002112
5VPCB15D4Y3002113
5VPCD15D413002113
5VPCB15D6X3002113
5VPCB15D6Y3002114
5VPCD15D613002114
5VPCB15D8X3002114
5VPCB15D8Y3002115
5VPCD15D813002115
5VPCB15DXX3002115
5VPCB15DXY3002116
5VPCD15DX13002116
5VPCB15D1X3002116
5VPCB15D1Y3002117
5VPCD15D113002117
5VPCB15D3X3002117
5VPCB15D3Y3002118
5VPCD15D313002118
5VPCB15D5X3002118
5VPCB15D5Y3002119

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15D513002118
5VPCB15D7X3002119
5VPCB15D1Y3002120
5VPCD15D113002120
5VPCB15D3X3002120
5VPCB15D3Y3002121
5VPCD15D313002121
5VPCB15D5X3002121
5VPCB15D5Y3002122
5VPCD15D513002122
5VPCB15D7X3002122
5VPCB15D7Y3002123
5VPCD15D713002123
5VPCB15D9X3002123
5VPCB15D9Y3002124
5VPCD15D913002124
5VPCB15D0X3002124
5VPCB15D0Y3002125
5VPCD15D013002125
5VPCB15D2X3002125
5VPCB15D2Y3002126
5VPCD15D213002126
5VPCB15D4X3002126
5VPCB15D4Y3002127
5VPCD15D413002127
5VPCB15D6X3002127
5VPCB15D6Y3002128
5VPCD15D613002128
5VPCB15D8X3002128
5VPCB15D8Y3002129
5VPCD15D813002129
5VPCB15DXX3002129
5VPCB15D4Y3002130
5VPCD15D413002130
5VPCB15D6X3002130
5VPCB15D6Y3002131
5VPCD15D613002131
5VPCB15D8X3002131
5VPCB15D8Y3002132
5VPCD15D813002132
5VPCB15DXX3002132
5VPCB15DXY3002133
5VPCD15DX13002133
5VPCB15D1X3002133
5VPCB15D1Y3002134
5VPCD15D113002134
5VPCB15D3X3002134
5VPCB15D3Y3002135

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15D313002135
5VPCB15D5X3002135
5VPCB15D5Y3002136
5VPCD15D513002136
5VPCB15D7X3002136
5VPCB15D7Y3002137
5VPCD15D713002137
5VPCB15D9X3002137
5VPCB15D9Y3002138
5VPCD15D913002138
5VPCB15D0X3002138
5VPCB15D0Y3002139
5VPCD15D013002139
5VPCB15D2X3002139
5VPCB15D7Y3002140
5VPCD15D713002140
5VPCB15D9X3002140
5VPCB15D9Y3002141
5VPCD15D913002141
5VPCB15D0X3002141
5VPCB15D0Y3002142
5VPCD15D013002142
5VPCB15D2X3002142
5VPCB15D2Y3002143
5VPCD15D213002143
5VPCB15D4X3002143
5VPCB15D4Y3002144
5VPCD15D413002144
5VPCB15D6X3002144
5VPCB15D6Y3002145
5VPCD15D613002145
5VPCB15D8X3002145
5VPCB15D8Y3002146
5VPCD15D813002146
5VPCB15DXX3002146
5VPCB15DXY3002147
5VPCD15DX13002147
5VPCB15D1X3002147
5VPCB15D1Y3002148
5VPCD15D113002148
5VPCB15D3X3002148
5VPCB15D3Y3002149
5VPCD15D313002149
5VPCB15D6X3002149
5VPCB15DXY3002150
5VPCD15DX13002150
5VPCB15D1X3002150
5VPCB15D1Y3002151

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15D113002151
5VPCB15D3X3002151
6VPCB15D3Y3002152
5VPCD15D313002152
5VPCB15D6X3002152
5VPCB15D5Y3002153
5VPCD15D513002153
5VPCB15D7X3002153
5VPCB15D7Y3002154
5VPCD15D713002154
5VPCB15D9X3002154
5VPCB15D9Y3002155
6VPCD15D913002155
5VPCB15D0X3002155
5VPCB15D0Y3002156
5VPCD15D013002156
5VPCB15D2X3002156
5VPCB15D2Y3002157
5VPCD15D213002157
5VPCB15D4X3002157
5VPCB15D4Y3002158
5VPCD15D413002158
6VPCB15D6X3002158
5VPCB15D6Y3002159
6VPCD15D613002159
6VPCB15D8X3002159
5VPCB15D2Y3002160
5VPCD15D213002160
5VPCB15D4X3002160
5VPCB15D4Y3002161
5VPCD15D413002161
5VPCB15D6X3002161
6VPCB15D6Y3002162
5VPCD15D613002162
6VPCB15D8X3002162
5VPCB15D6Y3002163
6VPCD15D813002163
5VPCB15DXX3002163
5VPCB15DXY3002164
5VPCD15DX13002164
5VPCB15D1X3002164
5VPCB15D1Y3002165
6VPCD15D113002165
5VPCB15D3X3002165
5VPCB15D3Y3002166
5VPCD15D313002166
5VPCB15D5X3002166
5VPCB15D5Y3002167

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15D513002167
5VPCB15D7X3002167
5VPCB15D7Y3002168
5VPCD15D713002168
5VPCB15D9X3002168
5VPCB15D9Y3002169
5VPCD15D913002169
5VPCB15D0X3002169
5VPCB15D6Y3002170
5VPCD15D513002170
5VPCB15D7X3002170
5VPCB15D7Y3002171
5VPCD15D713002171
5VPCB15D9X3002171
5VPCB15D9Y3002172
5VPCD15D913002172
5VPCB15D0X3002172
5VPCB15D0Y3002173
5VPCD15D013002173
5VPCB15D2X3002173
5VPCB15D2Y3002174
5VPCD15D213002174
5VPCB15D4X3002174
5VPCB15D4Y3002175
5VPCD15D413002175
5VPCB15D6X3002175
5VPCB15D6Y3002176
5VPCD15D613002176
5VPCB15D8X3002176
5VPCB15D8Y3002177
5VPCD15D813002177
5VPCB15DXX3002177
5VPCB15DXY3002178
5VPCD15DX13002178
5VPCB15D1X3002178
5VPCB15D1Y3002179
5VPCD15D113002179
5VPCB15D3X3002179
5VPCB15D8Y3002180
5VPCD15D813002180
5VPCB15DXX3002180
5VPCB15DXY3002181
5VPCD15DX13002181
5VPCB15D1X3002181
5VPCB15D1Y3002182
5VPCD15D113002182
5VPCB15D3X3002182
5VPCB15D3Y3002183

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15D313002183
5VPCB15D5X3002183
5VPCB15D5Y3002184
5VPCD15D513002184
5VPCB15D7X3002184
5VPCB15D7Y3002185
5VPCD15D713002185
5VPCB15D9X3002185
5VPCB15D9Y3002186
5VPCD15D913002186
5VPCB15D0X3002186
5VPCB15D0Y3002187
5VPCD15D013002187
5VPCB15D2X3002187
5VPCB15D2Y3002188
5VPCD15D213002188
5VPCB15D4X3002188
5VPCB15D4Y3002189
5VPCD15D413002189
5VPCB15D6X3002189
5VPCB15D0Y3002190
5VPCD15D013002190
5VPCB15D2X3002190
5VPCB15D2Y3002191
5VPCD15D213002191
5VPCB15D4X3002191
5VPCB15D4Y3002192
5VPCD15D413002192
6VPCB16D6X3002192
5VPCB15D6Y3002193
6VPCD16D613002193
6VPCB15D8X3002193
5VPCB15D8Y3002194
5VPCD15D813002194
6VPCB16DXX3002194
5VPCB15DXY3002195
5VPCD15DX13002195
5VPCB15D1X3002195
5VPCB15D1Y3002196
6VPCD16D113002196
5VPCB15D3X3002196
5VPCB15D3Y3002197
5VPCD15D313002197
5VPCB15D5X3002197
5VPCB15D6Y3002198
5VPCD15D513002198
5VPCB15D7X3002198
5VPCB15D7Y3002199

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15D713002199
5VPCB15D9X3002199
5VPCB15DXY3002200
5VPCD15DX13002200
5VPCB15D1X3002200
5VPCB15D1Y3002201
5VPCD15D113002201
5VPCB15D3X3002201
5VPCB15D3Y3002202
5VPCD15D313002202
5VPCB15D5X3002202
5VPCB15D5Y3002203
5VPCD15D513002203
5VPCB15D7X3002203
5VPCB15D7Y3002204
5VPCD15D713002204
5VPCB15D9X3002204
5VPCB15D9Y3002205
5VPCD15D913002205
5VPCB15D0X3002205
5VPCB15D0Y3002206
5VPCD15D013002206
5VPCB15D2X3002206
5VPCB15D2Y3002207
5VPCD15D213002207
5VPCB15D4X3002207
5VPCB15D4Y3002208
5VPCD15D413002208
5VPCB15D6X3002208
5VPCB15D6Y3002209
5VPCD15D613002209
5VPCB15D8X3002209
5VPCB15D2Y3002210
5VPCD15D213002210
5VPCB15D4X3002210
5VPCB15D4Y3002211
5VPCD15D413002211
5VPCB15D6X3002211
5VPCB15D6Y3002212
5VPCD15D613002212
5VPCB15D8X3002212
5VPCB15D8Y3002213
5VPCD15D813002213
6VPCB15DXY3002214
5VPCD15DX13002214
6VPCB15D1Y3002215
5VPCD15D113002215
5VPCB15D3Y3002216

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
6VPCD15D313002216
5VPCB15D5Y3002217
5VPCD15D513002217
6VPCB16D7Y3002218
5VPCD15D713002218
5VPCB15D9Y3002219
5VPCD15D913002219
5VPCB15D5Y3002220
5VPCD15D513002220
5VPCB15D7Y3002221
5VPCD15D713002221
5VPCB15D9Y3002222
6VPCD15D913002222
5VPCB15D0Y3002223
6VPCD15D013002223
5VPCB15D2Y3002224
6VPCD15D213002224
5VPCB15D4Y3002225
5VPCD15D413002225
5VPCB15D6Y3002226
6VPCD15D613002226
5VPCB15D8Y3002227
5VPCD15D813002227
5VPCB15DXY3002228
5VPCD15DX13002228
5VPCB15D1Y3002229
5VPCD15D113002229
5VPCB15D8Y3002230
5VPCD15D813002230
5VPCB15DXY3002231
5VPCD15DX13002231
5VPCB15D1Y3002232
5VPCD15D113002232
5VPCB15D3Y3002233
5VPCD15D313002233
5VPCB15D5Y3002234
5VPCD15D513002234
5VPCB15D7Y3002235
5VPCD15D713002235
5VPCB15D9Y3002236
5VPCD16D913002236
5VPCB15D0Y3002237
5VPCD15D013002237
5VPCB15D2Y3002238
5VPCD15D213002238
5VPCB15D4Y3002239
5VPCD15D413002239
5VPCB15D0Y3002240

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15D013002240
6VPCB15D2Y3002241
5VPCD15D213002241
5VPCB15D4Y3002242
6VPCD15D413002242
5VPCB15D6Y3002243
5VPCD15D613002243
5VPCB15D8Y3002244
5VPCD15D613002244
5VPCB15DXY3002245
6VPCD15DX13002246
5VPCB15D1Y3002246
5VPCD15D113002246
6VPCB15D3Y3002247
5VPCD15D313002247
5VPCB15D5Y3002248
5VPCD15D513002248
5VPCB15D7Y3002249
5VPCD15D713002249
5VPCB15D3Y3002250
5VPCD15D313002250
5VPCB15D5Y3002251
5VPCD15D513002251
5VPCB16D7Y3002252
5VPCD15D713002252
5VPCB15D9Y3002253
5VPCD15D913002253
5VPCB15D0X3002253
5VPCB15D0Y3002254
5VPCD15D013002254
5VPCB15D2X3002254
5VPCB15D2Y3002255
6VPCD15D213002255
5VPCB15D4X3002255
5VPCB15D4Y3002256
6VPCD15D413002256
5VPCB15D6X3002256
5VPCB15D6Y3002257
5VPCD15D613002257
5VPCB15D8X3002257
5VPCB15D8Y3002258
5VPCD15D613002258
5VPCB15DXX3002258
5VPCB15DXY3002259
6VPCD15DX13002259
5VPCB15D1X3002259
5VPCB15D6Y3002260
5VPCD15D613002260

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D8X3002260
5VPCB15D8Y3002261
5VPCD15D813002261
5VPCB15DXX3002261
5VPCB15DXY3002262
5VPCD15DX13002262
5VPCB15D1X3002262
5VPCB15D1Y3002263
5VPCD15D113002263
5VPCB15D3X3002263
5VPCB15D3Y3002264
5VPCD15D313002264
5VPCB15D5X3002264
5VPCB16D6Y3002265
5VPCD15D513002265
5VPCB15D7X3002265
5VPCB15D7Y3002266
5VPCD15D713002266
5VPCB15D9X3002266
5VPCB15D9Y3002267
5VPCD15D913002267
5VPCB15D0X3002267
5VPCB15D0Y3002268
5VPCD15D013002268
5VPCB15D2X3002268
5VPCB15D2Y3002268
5VPCD15D213002269
5VPCB15D4X3002269
5VPCB15D9Y3002270
5VPCD15D913002270
5VPCB15D0X3002270
5VPCB15D0Y3002271
5VPCD15D013002271
5VPCB15D2X3002271
5VPCB15D2Y3002272
5VPCD15D213002272
5VPCB15D4X3002272
5VPCB15D4Y3002273
5VPCD15D413002273
5VPCB15D6X3002273
5VPCB16D6Y3002274
5VPCD15D613002274
5VPCB15D8X3002274
5VPCB16D8Y3002275
5VPCD15D813002275
5VPCB15DXX3002275
5VPCB15DXY3002276
5VPCD15DX13002276

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D1X3002276
5VPCB15D1Y3002277
5VPCD15D113002277
5VPCB15D3X3002277
5VPCB15D3Y3002278
5VPCD15D313002278
5VPCB15D5X3002278
5VPCB15D5Y3002279
5VPCD15D513002279
5VPCB15D7X3002279
5VPCB15D1Y3002280
5VPCD15D113002280
5VPCB15D3X3002280
5VPCB15D3Y3002281
5VPCD15D313002281
5VPCB15D5X3002281
5VPCB15D5Y3002282
5VPCD15D513002282
5VPCB15D7X3002282
5VPCB15D7Y3002283
5VPCD15D713002283
5VPCB15D9X3002283
5VPCB15D9Y3002284
5VPCD15D913002284
5VPCB15D0X3002284
5VPCB15D0Y3002285
5VPCD15D013002285
5VPCB15D2X3002285
5VPCB15D2Y3002286
5VPCD15D213002286
5VPCB15D4X3002286
5VPCB15D4Y3002287
5VPCD15D413002287
5VPCB15D6X3002287
5VPCB15D6Y3002288
5VPCD15D613002288
5VPCB15D8X3002288
5VPCB15D8Y3002289
5VPCD15D813002289
5VPCB15DXX3002289
5VPCB15D4Y3002290
5VPCD15D413002290
5VPCB15D6X3002290
5VPCB15D6Y3002291
5VPCD15D613002291
5VPCB15D8X3002291
5VPCB15D8Y3002292
5VPCD15D813002292

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15DXX3002292
5VPCB15DXY3002293
5VPCD15DX13002293
5VPCB15D1X3002293
5VPCB15D1Y3002294
5VPCD15D113002294
5VPCB15D3X3002294
5VPCB15D3Y3002295
5VPCD15D313002295
5VPCB15D5X3002295
5VPCB15D5Y3002296
5VPCD15D513002296
5VPCB15D7X3002296
5VPCB15D7Y3002297
5VPCD15D713002297
5VPCB15D9X3002297
5VPCB15D9Y3002298
5VPCD15D913002298
5VPCB15D0X3002298
5VPCB15D0Y3002299
5VPCD15D013002299
5VPCB15D2X3002299
5VPCB15D3Y3002300
5VPCD15D313002300
5VPCB15D5X3002300
5VPCB15D5Y3002301
5VPCD15D513002301
5VPCB15D7X3002301
5VPCB15D7Y3002302
5VPCD15D713002302
5VPCB15D9X3002302
5VPCB15D9Y3002303
5VPCD15D913002303
5VPCB15D0X3002303
5VPCB15D0Y3002304
5VPCD15D013002304
5VPCB15D2X3002304
5VPCB15D2Y3002305
5VPCD15D213002305
5VPCB15D4X3002305
5VPCB15D4Y3002306
5VPCD15D413002306
5VPCB15D6X3002306
5VPCB15D6Y3002307
5VPCD15D613002307
5VPCB15D8X3002307
5VPCB15D8Y3002308
5VPCD15D813002308

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15DXX3002308
5VPCB15DXY3002309
5VPCD15DX13002309
5VPCB15D1X3002309
5VPCB15D6Y3002310
5VPCD15D613002310
5VPCB15D8X3002310
5VPCB15D8Y3002311
5VPCD15D813002311
5VPCB15DXX3002311
5VPCB15DXY3002312
5VPCD15DX13002312
5VPCB15D1X3002312
5VPCB15D1Y3002313
5VPCD15D113002313
5VPCB15D3X3002313
5VPCB15D3Y3002314
5VPCD15D313002314
5VPCB15D5X3002314
5VPCB15D5Y3002316
5VPCD15D513002315
5VPCB15D7X3002315
5VPCB15D7Y3002316
5VPCD15D713002316
5VPCB15D9X3002316
5VPCB15D9Y3002317
5VPCD15D913002317
5VPCB15D0X3002317
5VPCB15D0Y3002318
5VPCD15D013002318
5VPCB15D2X3002318
5VPCB15D2Y3002319
5VPCD16D213002319
5VPCB15D4X3002319
5VPCB15D9Y3002320
5VPCD16D913002320
5VPCB15D0X3002320
5VPCB15D0Y3002321
5VPCD15D013002321
5VPCB15D2X3002321
5VPCB15D2Y3002322
5VPCD15D213002322
5VPCB15D4X3002322
5VPCB16D4Y3002323
5VPCD16D413002323
5VPCB15D6X3002323
5VPCB15D6Y3002324
5VPCD15D613002324

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D8X3002324
5VPCB15D8Y3002325
5VPCD15D813002325
5VPCB15DXX3002325
5VPCB15DXY3002326
6VPCD15DX13002326
5VPCB15D1X3002326
5VPCB15D1Y3002327
5VPCD15D113002327
6VPCB15D3X3002327
5VPCB15D3Y3002328
6VPCD15D313002328
5VPCB15D5X3002328
6VPCB15D5Y3002329
6VPCD15D513002329
5VPCB15D7X3002329
6VPCB15D1Y3002330
5VPCD15D113002330
5VPCB15D3X3002330
5VPCB15D3Y3002331
5VPCD15D313002331
5VPCB15D5X3002331
5VPCB16D6Y3002332
6VPCD15D513002332
5VPCB15D7X3002332
5VPCB15D7Y3002333
6VPCD15D713002333
5VPCB15D9X3002333
5VPCB15D9Y3002334
5VPCD15D913002334
5VPCB15D0X3002334
5VPCB16D0Y3002335
5VPCD15D013002335
6VPCB16D2X3002335
5VPCB16D2Y3002336
5VPCD15D213002336
5VPCB16D4X3002336
5VPCB15D4Y3002337
5VPCD16D413002337
5VPCB15D6X3002337
5VPCB16D6Y3002338
5VPCD15D613002338
5VPCB16D8X3002338
5VPCB15D8Y3002339
5VPCD15D813002339
5VPCB15DXX3002339
5VPCB15D4Y3002340
5VPCD15D413002340

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of effected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D6X3002340
5VPCB15D6Y3002341
5VPCD15D613002341
5VPCB15D8X3002341
5VPCB15D8Y3002342
5VPCD15D813002342
5VPCB15DXX3002342
5VPCB15DXY3002343
5VPCD15DX13002343
5VPCB15D1X3002343
5VPCB15D1Y3002344
5VPCD15D113002344
5VPCB15D3X3002344
5VPCB15D3Y3002345
5VPCD15D313002345
5VPCB15D5X3002345
5VPCB15D5Y3002346
5VPCD15D513002346
5VPCB15D7X3002346
5VPCB15D7Y3002347
5VPCD15D713002347
5VPCB15D9X3002347
5VPCB15D9Y3002348
5VPCD15D913002348
5VPCB15D0X3002348
5VPCB15D0Y3002349
5VPCD15D013002349
5VPCB15D2X3002349
5VPCB15D7Y3002350
5VPCD15D713002360
5VPCB15D9X3002350
5VPCB15D9Y3002351
5VPCD15D913002351
5VPCB15D0X3002351
5VPCB15D0Y3002352
5VPCD15D013002352
5VPCB15D2X3002352
5VPCB15D2Y3002353
5VPCD15D213002353
5VPCB15D4X3002353
5VPCB15D4Y3002354
5VPCD15D413002354
5VPCB15D6X3002354
5VPCB15D6Y3002355
5VPCD15D613002355
5VPCB15D8X3002355
5VPCB15D8Y3002356
5VPCD15D813002356

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15DXX3002356
5VPCB15DXY3002357
5VPCD15DX13002357
5VPCB15D1X3002357
5VPCB15D1Y3002358
5VPCD15D113002358
5VPCB15D3X3002358
5VPCB15D3Y3002359
5VPCD15D313002359
5VPCB15D5X3002359
5VPCB15DXY3002360
5VPCD15DX13002360
5VPCB15D1X3002360
5VPCB15D1Y3002361
5VPCD15D113002361
5VPCB15D3X3002361
5VPCB15D3Y3002362
5VPCD15D313002362
5VPCB15D5X3002362
5VPCB15D6Y3002363
5VPCD15D513002363
5VPCB15D7X3002363
5VPCB15D7Y3002364
5VPCD15D713002364
5VPCB15D8X3002364
5VPCB15D9Y3002365
5VPCD15D913002365
5VPCB15D0X3002365
5VPCB15D0Y3002366
5VPCD15D013002366
5VPCB15D2X3002366
5VPCB15D2Y3002367
5VPCD15D213002367
5VPCB15D4X3002367
5VPCB15D4Y3002368
5VPCD15D413002368
5VPCB15D6X3002368
5VPCB15D6Y3002369
5VPCD15D613002369
5VPCB15D8X3002369
5VPCB15D2Y3002370
5VPCD15D213002370
5VPCB15D4X3002370
5VPCB15D4Y3002371
5VPCD15D413002371
5VPCB15D6X3002371
5VPCB15D6Y3002372
5VPCD15D613002372

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB16D8X3002372
5VPCB15D8Y3002373
5VPCD16D813002373
5VPCB15DXX3002373
5VPCB16DXY3002374
5VPCD15DX13002374
5VPCB15D1X3002374
5VPCB15D1Y3002375
5VPCD15D113002375
5VPCB15D3X3002375
5VPCB16D3Y3002376
5VPCD15D313002376
5VPCB16D6X3002376
5VPCB15D5Y3002377
5VPCD15D513002377
5VPCB15D7X3002377
5VPCB16D7Y3002378
5VPCD15D713002378
5VPCB16D9X3002378
5VPCB15D9Y3002379
5VPCD15D913002379
5VPCB15D0X3002379
5VPCB16D5Y3002380
5VPCD15D513002380
5VPCB15D7X3002380
5VPCB15D7Y3002381
5VPCD15D713002381
5VPCB16D9X3002381
5VPCB15D9Y3002382
5VPCD16D913002382
5VPCB15D0X3002382
5VPCB15D0Y3002383
5VPCB15D313002383
5VPCB15D2X3002383
5VPCB15D2Y3002384
5VPCB15D513002384
5VPCB15D4X3002384
5VPCB15D4Y3002385
6VPCB16D713002385
5VPCB15D6X3002385
6VPCB15D6Y3002386
5VPCB15D913002386
5VPCB15D8X3002386
5VPCB15D8Y3002387
5VPCB15D013002387
5VPCB15DXX3002387
6VPCB15DXY3002388
5VPCB15D213002388

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D1X3002388
5VPCB15D1Y3002389
5VPCD15D113002389
5VPCB15D3X3002389
5VPCB15D8Y3002390
5VPCD15D813002390
5VPCB15DXX3002390
5VPCB15DXY3002391
5VPCD16DX13002391
5VPCB16D1X3002391
5VPCB15D1Y3002392
5VPCD15D113002392
5VPCB15D3X3002392
5VPCB15D3Y3002393
5VPCD15D313002393
5VPCB15D5X3002393
5VPCB15D5Y3002394
5VPCD16D513002394
5VPCB15D7X3002394
5VPCB15D7Y3002395
5VPCD15D713002395
5VPCB15D9X3002395
5VPCB15D9Y3002396
5VPCD15D913002396
5VPCB15D0X3002396
5VPCB16D0Y3002397
5VPCD15D013002397
5VPCB15D2X3002397
5VPCB15D2Y3002398
5VPCD15D213002396
5VPCB15D4X3002398
5VPCB15D4Y3002399
5VPCB15D713002399
5VPCB15D6X3002399
5VPCB15D7Y3002400
5VPCB15DX13002400
5VPCB15D9X3002400
5VPCB15D9Y3002401
5VPCB15D113002401
5VPCB15D0X3002401
5VPCB15D0Y3002402
5VPCD15D013002402
5VPCB15D2X3002402
5VPCB15D2Y3002403
5VPCD15D213002403
5VPCB15D4X3002403
5VPCB15D4Y3002404
5VPCD16D413002404

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D6X3002404
5VPCB15D6Y3002405
5VPCD15D613002405
6VPCB15D8X3002405
5VPCB15D8Y3002406
5VPCB15D013002406
5VPCB15DXX3002406
5VPCB15DXY3002407
5VPCB15D213002407
5VPCB15D1X3002407
5VPCB15D1Y3002408
5VPCB15D413002408
5VPCB15D3X3002408
5VPCB15D3Y3002409
5VPCB15D613002409
5VPCB15D5X3002409
5VPCB15DXY3002410
5VPCB15D213002410
5VPCB15D1X3002410
5VPCB15D1Y3002411
5VPCB15D413002411
6VPCB16D3X3002411
5VPCB15D3Y3002412
5VPCB15D613002412
5VPCB15D5X3002412
5VPCB15D6Y3002413
5VPCB15D813002413
5VPCB15D7X3002413
5VPCB15D7Y3002414
5VPCB16DX13002414
6VPCB16D9X3002414
5VPCB15D9Y3002415
5VPCB15D113002415
5VPCB15D0X3002415
5VPCB15D0Y3002416
5VPCB15D313002416
5VPCB15D2X3002416
6VPCB15D2Y3002417
5VPCB15D513002417
6VPCB16D4X3002417
5VPCB15D4Y3002418
5VPCB15D713002418
5VPCB15D6X3002418
5VPCB15D6Y3002419
5VPCB15D913002419
5VPCB15D8X3002419
5VPCB15D2Y3002420
5VPCB15D513002420

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D4X3002420
5VPCB15D4Y3002421
5VPCB15D713002421
5VPCB15D6X3002421
5VPCB15D6Y3002422
5VPCB15D913002422
5VPCB15D8X3002422
5VPCB15D8Y3002423
5VPCB15D013002423
5VPCB15DXX3002423
5VPCB15DXY3002424
5VPCB15D213002424
5VPCB15D1X3002424
5VPCB15D1Y3002425
5VPCB15D413002425
5VPCB15D3X3002425
6VPCB15D3Y3002426
5VPCB15D613002426
5VPCB15D5X3002426
5VPCB15D5Y3002427
5VPCB15D813002427
5VPCB15D7X3002427
5VPCB15D7Y3002428
5VPCB15DX13002428
5VPCB15D9X3002428
5VPCB15D9Y3002429
5VPCB15D113002429
5VPCB15D0X3002429
5VPCB15D5Y3002430
5VPCB15D613002430
5VPCB15D7X3002430
5VPCB15D7Y3002431
5VPCB15DX13002431
6VPCB15D9X3002431
6VPCB15D9Y3002432
5VPCB15D113002432
5VPCB15D0X3002432
5VPCB15D0Y3002433
5VPCB15D313002433
5VPCB15D2X3002433
5VPCB15D2Y3002434
5VPCB15D513002434
5VPCB15D4X3002434
6VPCB15D4Y3002435
6VPCB15D713002435
5VPCB15D6X3002435
5VPCB15D6Y3002436
5VPCB15D913002436

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D8X3002436
5VPCB15D8Y3002437
5VPCB15D013002437
5VPCB15DXX3002437
5VPCB15DXY3002436
5VPCB15D213002438
5VPCB15D1X3002438
5VPCB15D1Y3002439
5VPCB15D413002439
5VPCB15D3X3002439
5VPCB15D8Y3002440
5VPCB15D013002440
5VPCB15DXX3002440
5VPCB15DXY3002441
5VPCB15D213002441
5VPCB15D1X3002441
5VPCB15D1Y3002442
5VPCB15D413002442
5VPCB15D3X3002442
5VPCB15D3Y3002443
5VPCB15D813002443
5VPCB15D5X3002443
5VPCB15D5Y3002444
5VPCB15D813002444
5VPCB15D7X3002444
5VPCB15D7Y3002445
5VPCB15DX13002445
5VPCB15D9X3002445
5VPCB15D9Y3002446
5VPCB15D113002446
5VPCB15D0X3002446
5VPCB15D0Y3002447
5VPCB15D313002447
5VPCB15D2X3002447
5VPCB15D2Y3002448
5VPCB15D613002448
5VPCB15D4X3002448
5VPCB15D4Y3002449
5VPCB15D713002449
5VPCB15D8X3002448
5VPCB15D0Y3002450
5VPCB15D313002450
5VPCB15D2X3002450
5VPCB15D2Y3002451
5VPCB15D513002451
5VPCB15D4X3002451
5VPCB15D4Y3002452
5VPCD15D413002452

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D6X3002452
5VPCB15D6Y3002453
5VPCD15D613002453
5VPCB15D8X3002453
5VPCB15D8Y3002454
5VPCD15D813002454
5VPCB15DXX3002454
5VPCB15DXY3002455
5VPCD15DX13002455
5VPCB15D1X3002455
5VPCB15D1Y3002456
5VPCD15D113002456
5VPCB15D3X3002456
5VPCB15D3Y3002457
5VPCD15D313002457
5VPCB15D5X3002457
5VPCB15D5Y3002458
5VPCD15D513002458
5VPCB15D7X3002458
5VPCB15D7Y3002459
5VPCD15D713002459
5VPCB15D9X3002459
5VPCB15D3Y3002460
5VPCB15D613002460
5VPCB15D5X3002460
5VPCB15D5Y3002461
5VPCB15D813002461
5VPCB15D7X3002461
5VPCB15D7Y3002462
5VPCB15DX13002462
5VPCB15D9X3002462
5VPCB15D9Y3002463
5VPCB15D113002463
5VPCB15D0X3002463
5VPCB15D0Y3002464
5VPCB15D313002464
5VPCB15D2X3002464
5VPCB15D2Y3002465
5VPCB15D513002465
5VPCB15D4X3002465
5VPCB15D4Y3002466
5VPCB15D713002466
5VPCB15D6X3002466
5VPCB15D6Y3002467
5VPCB15D913002467
5VPCB15D8X3002467
5VPCB15D8Y3002468
5VPCB15D013002468

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of effected vehicles: 9120

Vehicle Identification Numbers
5VPCB15DXX3002468
5VPCB15DXY3002469
5VPCB16D213002469
6VPCB15D1X3002469
5VPCB15D6Y3002470
5VPCB15D913002470
5VPCB15D8X3002470
5VPCB15D8Y3002471
5VPCB16D013002471
5VPCB15DXX3002471
5VPCB15DXY3002472
5VPCB15D213002472
5VPCB16D1X3002472
5VPCB15D1Y3002473
5VPCB16D413002473
5VPCB15D3X3002473
5VPCB15D3Y3002474
5VPCB15D613002474
5VPCB15D5X3002474
5VPCB15D5Y3002475
5VPCB15D813002475
5VPCB15D7X3002475
5VPCB15D7Y3002476
5VPCB15DX13002476
5VPCB15D9X3002476
5VPCB15D9Y3002477
5VPCD15D913002477
5VPCB15D0X3002477
5VPCB15D0Y3002478
5VPCD15D013002478
5VPCB15D2X3002478
5VPCB15D2Y3002479
5VPCD15D213002479
5VPCB15D4X3002479
5VPCB15D9Y3002480
5VPCD15D913002480
5VPCB15D0X3002480
5VPCB15D0Y3002481
5VPCB15D313002481
5VPCB15D2X3002481
5VPCB16D2Y3002482
6VPCB15D613002482
6VPCB15D4X3002482
5VPCB15D4Y3002483
6VPCB15D713002483
5VPCB15D6X3002483
5VPCB16D6Y3002484
5VPCB15D913002484

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D8X3002484
5VPCB15D8Y3002485
5VPCB15D013002486
5VPCB15DXX3002485
5VPCB16DXY3002486
5VPCB15D213002486
5VPCB15D1X3002486
5VPCB15D1Y3002487
5VPCB15D413002487
5VPCB15D3X3002487
5VPCB15D3Y3002488
5VPCD15D313002488
5VPCB15D6X3002488
5VPCB15D5Y3002489
6VPCD16D513002488
5VPCB15D7X3002489
5VPCB15D1Y3002490
5VPCD15D113002490
6VPCB16D3X3002490
5VPCB15D3Y3002491
5VPCD15D313002491
5VPCB15D5X3002491
5VPCB15D5Y3002492
5VPCD15D513002492
6VPCB16D7X3002492
5VPCB15D7Y3002493
5VPCD15D713002493
6VPCB16D9X3002493
5VPCB15D9Y3002494
6VPCD15D913002494
5VPCB15D0X3002494
6VPCB16D0Y3002496
5VPCD15D013002495
5VPCB15D2X3002495
5VPCB15D2Y3002496
5VPCD15D213002496
5VPCB15D4X3002496
5VPCB15D4Y3002497
5VPCD15D413002497
5VPCB15D6X3002497
6VPCB16D6Y3002498
5VPCD15D613002498
6VPCB15D8X3002496
5VPCB15D8Y3002499
5VPCD15D813002499
5VPCB15DXX3002499
5VPCB15D0Y3002500
5VPCD15D013002500

03V-336 (134) of (193)

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D2X3002500
5VPCB15D2Y3002501
5VPCD15D213002501
5VPCB15D4X3002501
5VPCB15D4Y3002502
5VPCD15D413002502
5VPCB15D6X3002502
5VPCB15D6Y3002503
5VPCD15D613002503
5VPCB15D8X3002503
5VPCB15D8Y3002504
5VPCD15D813002504
5VPCB15DXX3002504
5VPCB15DXY3002505
5VPCD15DX13002505
5VPCB15D1Y3002506
5VPCD15D113002506
5VPCB15D3Y3002507
5VPCD15D313002507
5VPCB15D5Y3002508
5VPCD15D513002508
5VPCB15D7Y3002509
5VPCD15D713002509
5VPCB15D3Y3002510
5VPCD15D313002510
5VPCB15D5Y3002511
5VPCD15D613002511
5VPCB15D7Y3002512
5VPCD15D713002512
5VPCB15D9Y3002513
5VPCD15D913002513
5VPCB15D0Y3002514
5VPCD15D013002514
5VPCB15D2Y3002515
5VPCD15D213002515
5VPCB15D4Y3002516
5VPCD15D413002516
5VPCB15D6Y3002517
5VPCB15D913002517
5VPCB15D8Y3002518
5VPCB15D013002518
5VPCB15DXY3002519
5VPCB15D213002519
5VPCB15D6Y3002520
5VPCB15D913002520
5VPCB15D8Y3002521
5VPCB15D013002521
5VPCB15DXY3002522

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D213002522
5VPCB15D1Y3002523
5VPCB15D413002523
5VPCB15D3Y3002524
5VPCD15D313002524
5VPCB15D5Y3002525
5VPCD15D513002525
5VPCB15D7Y3002526
5VPCD15D713002526
5VPCB15D9Y3002527
5VPCD15D913002527
5VPCB15D0Y3002528
5VPCD15D013002528
5VPCB15D2Y3002529
5VPCD15D213002529
5VPCB15D9Y3002530
5VPCD15D913002530
5VPCB15D0X3002530
5VPCB15D0Y3002531
5VPCD15D013002531
5VPCB15D2X3002531
5VPCB15D2Y3002532
5VPCD15D213002532
5VPCB15D4X3002532
5VPCB15D4Y3002533
5VPCD15D413002533
5VPCB15D6X3002533
5VPCB15D8Y3002534
5VPCB15D813002534
5VPCB15D8X3002534
5VPCB15D8Y3002535
5VPCB15D013002535
5VPCB15DXX3002535
5VPCB15DXY3002536
5VPCB15D213002536
5VPCB15D1X3002536
5VPCB15D1Y3002537
5VPCB15D413002537
5VPCB15D3X3002537
5VPCB15D3Y3002538
5VPCB15D613002538
5VPCB15D5X3002538
5VPCB15D5Y3002539
5VPCB15D813002539
5VPCB15D7X3002539
5VPCB15D1Y3002540
5VPCB15D413002540
5VPCB15D3X3002540

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D3Y3002541
5VPCB15D613002541
5VPCB15D5X3002541
5VPCB15D5Y3002542
5VPCB15D813002542
5VPCB15D7X3002542
5VPCB15D7Y3002543
5VPCB15DX13002543
5VPCB15D9X3002543
5VPCB15D9Y3002544
5VPCB15D113002544
5VPCB15D0X3002544
5VPCB15D0Y3002545
5VPCB15D313002545
5VPCB15D2X3002545
5VPCB15D2Y3002546
5VPCB15D513002546
5VPCB15D4X3002546
5VPCB15D4Y3002547
5VPCB15D713002547
5VPCB15D6X3002547
5VPCB15D6Y3002548
5VPCD15D613002548
5VPCB15D8X3002548
5VPCB15D8Y3002549
5VPCD15D813002549
5VPCB15DXX3002549
5VPCB15D4Y3002550
5VPCD15D413002550
5VPCB15D6X3002550
5VPCB15D6Y3002551
5VPCD15D613002551
5VPCB15D8X3002551
5VPCB15D8Y3002552
5VPCD15D813002552
5VPCB15DXX3002552
5VPCB15DXY3002553
5VPCD15DX13002553
5VPCB15D1X3002553
5VPCB15D1Y3002554
5VPCD15D113002554
5VPCB15D3X3002554
5VPCB15D3Y3002555
5VPCD15D313002555
5VPCB15D5X3002555
5VPCB15D5Y3002556
5VPCD15D513002556
5VPCB15D7X3002556

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D7Y3002557
5VPCD15D713002557
5VPCB15D9X3002557
5VPCB15D9Y3002558
5VPCD15D913002558
5VPCB15D0X3002558
5VPCB15D0Y3002559
5VPCD15D013002559
5VPCB15D2X3002559
5VPCB15D7Y3002560
5VPCD15D713002560
5VPCB15D9Y3002561
5VPCD15D913002561
5VPCB15D0Y3002562
5VPCD15D013002562
5VPCB15D2Y3002563
5VPCB16D613002563
5VPCB15D4Y3002564
5VPCB15D713002564
5VPCB15D8Y3002565
5VPCB15D913002565
5VPCB15D8Y3002566
5VPCB15D013002566
5VPCB15DXY3002567
5VPCB15D213002567
5VPCB16D1Y3002568
5VPCB15D413002568
5VPCB15D3Y3002569
5VPCB15D613002569
5VPCB16DXY3002570
5VPCB15D213002570
5VPCB15D1Y3002571
5VPCD15D113002571
5VPCB15D3Y3002572
5VPCD15D313002572
5VPCB16D5Y3002573
5VPCD15D513002573
5VPCB15D7Y3002574
5VPCD15D713002574
5VPCB15D9Y3002575
5VPCD15D913002575
5VPCB15D0X3002575
5VPCB15D0Y3002576
5VPCB15D313002576
6VPCB15D2X3002576
5VPCB15D2Y3002577
6VPCB15D513002577
5VPCB15D4X3002577

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D4Y3002578
5VPCB15D713002578
5VPCB15D6X3002578
5VPCB15D6Y3002579
5VPCB15D913002579
5VPCB15D8X3002579
5VPCB15D2Y3002580
5VPCB15D513002580
5VPCB15D4X3002580
5VPCB15D4Y3002581
5VPCD15D413002581
5VPCB15D6X3002581
5VPCB15D6Y3002582
5VPCD15D613002582
5VPCB15D8X3002582
5VPCB15D8Y3002583
5VPCD15D813002583
5VPCB15DXX3002583
5VPCB15DXY3002584
5VPCD15DX13002584
5VPCB15D1X3002584
5VPCB15D1Y3002585
5VPCD15D113002585
5VPCB15D3X3002585
5VPCB15D3Y3002586
5VPCD15D313002586
5VPCB15D6X3002586
5VPCB15D6Y3002587
5VPCD15D513002587
5VPCB15D7X3002587
5VPCB15D7Y3002588
5VPCD15D713002588
5VPCB15D9X3002588
5VPCB15D9Y3002589
5VPCD15D913002589
5VPCB15D0X3002589
5VPCB15D5Y3002590
5VPCB15D813002590
5VPCB15D7X3002590
5VPCB15D7Y3002591
5VPCB15DX13002591
5VPCB15D9X3002591
5VPCB15D9Y3002592
5VPCB15D113002592
5VPCB15D0X3002592
5VPCB15D0Y3002593
5VPCB15D313002593
5VPCB15D2X3002593

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D2Y3002594
5VPCB15D513002594
5VPCB15D4X3002594
5VPCB15D4Y3002595
5VPCB15D713002595
5VPCB15D6X3002595
5VPCB15D6Y3002596
5VPCB15D913002596
5VPCB15D8X3002596
5VPCB15D8Y3002597
5VPCB15D013002597
5VPCB15DXX3002597
5VPCB15DXY3002598
5VPCB15D213002598
5VPCB15D1X3002598
5VPCB15D1Y3002599
5VPCB15D413002599
5VPCB15D3X3002599
5VPCB15D4Y3002600
5VPCB15D713002600
5VPCB15D6X3002600
5VPCB15D6Y3002601
5VPCB15D913002601
5VPCB15D8X3002601
5VPCB15D8Y3002602
5VPCB15D013002602
5VPCB15DXX3002602
5VPCB15DXY3002603
5VPCB15D213002603
5VPCB15D1X3002603
5VPCB15D1Y3002604
5VPCB15D413002604
5VPCB15D3X3002604
5VPCB15D3Y3002605
5VPCB15D613002605
5VPCB15D5X3002605
5VPCB15D5Y3002606
5VPCB15D813002606
5VPCB15D7X3002606
5VPCB15D7Y3002607
5VPCB15DX13002607
5VPCB15D9X3002607
5VPCB15D9Y3002608
5VPCB15D113002608
5VPCB15D0X3002608
5VPCB15D0Y3002609
5VPCB15D313002609
5VPCB15D2X3002609

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D7Y3002610
5VPCB15DX13002610
5VPCB15D9X3002610
5VPCB15D9Y3002611
5VPCD15D913002611
5VPCB15D0X3002611
5VPCB15D0Y3002612
5VPCD15D013002612
5VPCB15D2X3002612
5VPCB15D2Y3002613
5VPCD15D213002613
5VPCB15D4X3002613
5VPCB15D4Y3002614
5VPCD15D413002614
5VPCB15D6X3002614
5VPCB15D6Y3002615
5VPCD15D613002615
5VPCB15D8X3002615
5VPCB15D8Y3002616
5VPCD15D813002616
5VPCB15DXX3002616
5VPCB15DXY3002617
5VPCD15DX13002617
5VPCB15D1X3002617
5VPCB15D1Y3002618
5VPCD15D113002618
5VPCB15D3X3002618
5VPCB15D3Y3002619
5VPCD15D313002619
5VPCB15D5X3002619
5VPCB15DXY3002620
5VPCD15DX13002620
5VPCB15D1X3002620
5VPCB15D1Y3002621
5VPCD15D113002621
5VPCB15D3X3002621
5VPCB15D3Y3002622
5VPCB15D613002622
5VPCB15D5X3002622
5VPCB15D5Y3002623
5VPCB15D813002623
5VPCB15D7X3002623
5VPCB15D7Y3002624
5VPCB15DX13002624
5VPCB15D9X3002624
5VPCB15D9Y3002625
5VPCD15D913002625
5VPCB15D0X3002625

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D0Y3002626
5VPCD15D013002626
5VPCB15D2X3002626
5VPCB15D2Y3002627
5VPCD15D213002627
5VPCB15D4X3002627
5VPCB15D4Y3002628
5VPCD15D413002628
5VPCB15D6X3002628
5VPCB15D6Y3002629
5VPCD15D613002629
5VPCB15D8X3002629
5VPCB15D2Y3002630
5VPCD15D213002630
6VPCB15D4X3002630
5VPCB15D4Y3002631
5VPCD16D413002631
5VPCB15D6X3002631
5VPCB15D6Y3002632
5VPCD15D613002632
6VPCB15D8X3002632
5VPCB15D8Y3002633
6VPCD16D813002633
5VPCB15DXX3002633
5VPCB16DXY3002634
5VPCD15DX13002634
5VPCB15D1X3002634
5VPCB15D1Y3002635
5VPCD15D113002635
5VPCB16D3X3002635
5VPCB15D3Y3002636
5VPCD15D313002636
5VPCB15D5X3002636
5VPCB15D5Y3002637
5VPCD15D513002637
5VPCB15D7X3002637
5VPCB15D7Y3002638
6VPCD15D713002638
5VPCB15D9X3002638
5VPCB15D9Y3002639
6VPCD15D913002639
5VPCB15D0X3002639
5VPCB15D5Y3002640
5VPCB15D813002640
6VPCB15D7X3002640
5VPCB15D7Y3002641
5VPCB15DX13002641
6VPCB15D9X3002641

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D9Y3002642
5VPCB15D113002642
5VPCB15D0X3002642
5VPCB15D0Y3002643
5VPCB15D313002643
5VPCB15D2X3002643
5VPCB15D2Y3002644
5VPCB15D513002644
5VPCB15D4X3002644
5VPCB15D4Y3002645
5VPCB15D713002645
5VPCB15D6X3002645
5VPCB15D6Y3002646
5VPCD15D613002646
5VPCB15D8X3002646
5VPCB15D8Y3002647
5VPCD15D813002647
5VPCB15DXX3002647
5VPCB15DXY3002648
5VPCD15DX13002648
5VPCB15D1X3002648
5VPCB15D1Y3002649
5VPCD15D113002649
5VPCB15D3X3002649
5VPCB15D8Y3002650
5VPCD15D813002650
5VPCB15DXX3002650
5VPCB15DXY3002651
5VPCD15DX13002651
5VPCB15D1X3002651
5VPCB15D1Y3002652
5VPCD15D113002652
5VPCB15D3X3002652
5VPCB15D3Y3002653
5VPCD15D313002653
5VPCB15D5X3002653
5VPCB15D6Y3002654
5VPCD15D513002654
5VPCB15D7X3002654
5VPCB15D7Y3002655
5VPCD15D713002655
5VPCB15D9X3002655
5VPCB15D9Y3002656
5VPCD15D913002656
5VPCB15D0X3002656
5VPCB15D0Y3002657
5VPCD15D013002657
5VPCB15D2X3002657

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15D213002658
5VPCB15D4X3002658
5VPCD15D413002659
5VPCB15D6X3002659
5VPCS15D0Y3002660
5VPCD15D013002660
5VPCB15D2X3002660
5VPCS15D2Y3002661
5VPCB15D513002661
5VPCB15D4X3002661
5VPCS15D4Y3002662
5VPCB15D713002662
5VPCB15D6X3002662
5VPCS15D6Y3002663
5VPCB15D913002663
5VPCB15D8X3002663
5VPCS15D8Y3002664
5VPCB15D013002664
5VPCB15DXX3002664
5VPCS15DXY3002665
5VPCB15D213002665
5VPCB15D1X3002665
5VPCS15D1Y3002666
5VPCB15D413002666
5VPCB15D3X3002666
5VPCS15D3Y3002667
5VPCB15D613002667
5VPCB15D5X3002667
5VPCS15D5Y3002668
5VPCD15D613002668
5VPCB15D7X3002668
5VPCS15D7Y3002669
5VPCD15D713002669
5VPCB15D9X3002669
5VPCS15D3Y3002670
5VPCD15D313002670
5VPCB15D5X3002670
5VPCS15D6Y3002671
5VPCD15D613002671
5VPCB15D7X3002671
5VPCS15D7Y3002672
5VPCB15DX13002672
5VPCB15D9X3002672
5VPCS15D9Y3002673
5VPCB15D113002673
5VPCB15D0X3002673
5VPCS15D0Y3002674
5VPCB15D313002674

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D2X3002674
5VPCS15D2Y3002675
5VPCB15D513002675
5VPCB15D4X3002675
5VPCS15D4Y3002676
5VPCB15D713002676
5VPCB15D6X3002676
5VPCD15D813002677
6VPCB15D8X3002677
5VPCS15D8Y3002678
5VPCD15D813002678
5VPCB15DXX3002678
5VPCS15DXY3002679
6VPCD15DX13002679
5VPCB15D1X3002679
5VPCS15D6Y3002680
5VPCD15D613002680
5VPCB15D8X3002680
5VPCS15D8Y3002681
5VPCD15D813002681
5VPCB15DXX3002681
5VPCS15DXY3002682
5VPCD15DX13002682
5VPCB15D1X3002682
5VPCS15D1Y3002683
5VPCD15D113002683
5VPCB15D3X3002683
5VPCS15D3Y3002684
6VPCD15D313002684
5VPCB15D5X3002684
6VPCS15D5Y3002685
5VPCD15D513002685
6VPCB15D7X3002685
5VPCS15D7Y3002686
5VPCB15DX13002686
5VPCB15D9X3002686
6VPCS15D9Y3002687
5VPCB15D113002687
5VPCB15D0X3002687
5VPCS15D0Y3002688
5VPCB15D313002688
5VPCB15D2X3002688
5VPCS15D2Y3002689
5VPCB15D513002689
6VPCB15D4X3002689
5VPCS15D9Y3002690
6VPCB15D113002690
5VPCB15D0X3002690

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D0Y3002691
5VPCD15D013002691
5VPCB15D2X3002691
5VPCD15D213002692
5VPCB15D4X3002692
5VPCB15D713002693
5VPCB15D6X3002693
5VPCB15D913002694
5VPCB15D8X3002694
5VPCB15D013002695
5VPCB15DXX3002695
5VPCD15DX13002696
5VPCB15D1X3002696
5VPCD15D113002697
5VPCB15D3X3002697
5VPCD15D313002698
5VPCB15D5X3002698
5VPCB15D813002699
5VPCB15D7X3002699
5VPCB15D013002700
5VPCB15DXX3002700
6VPCB15D213002701
5VPCB15D1X3002701
6VPCB15D413002702
5VPCB15D3X3002702
5VPCB15D613002703
6VPCB15D6X3002703
5VPCB15D813002704
6VPCB15D7X3002704
5VPCD15D713002705
5VPCB15D9X3002705
5VPCD15D913002706
5VPCB15D0X3002706
5VPCD15D013002707
5VPCB15D2X3002707
6VPCS16D2Y3002708
5VPCD15D213002708
6VPCB16D4X3002708
5VPCS15D4Y3002709
6VPCD15D413002709
5VPCB15D6X3002709
5VPCD15D013002710
5VPCB15D2X3002710
5VPCS15D2Y3002711
5VPCD15D213002711
5VPCB16D4X3002711
5VPCD15D413002712
5VPCB15D6X3002712

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D913002713
5VPCB15D8X3002713
5VPCS15D8Y3002714
5VPCB15D013002714
5VPCB15DXX3002714
5VPCS15DXY3002715
5VPCB15D213002715
5VPCB15D1X3002716
5VPCS15D1Y3002716
5VPCB15D413002716
5VPCB15D3X3002716
5VPCS15D3Y3002717
5VPCB15D613002717
5VPCB15D5X3002717
5VPCS15D5Y3002718
5VPCB15D813002718
5VPCB15D7X3002718
5VPCS15D7Y3002719
5VPCB15DX13002719
5VPCB15D9X3002719
5VPCB15D613002720
5VPCB15D5X3002720
5VPCB15D813002721
5VPCB15D7X3002721
5VPCD15D713002722
5VPCB15D9X3002722
5VPCD15D913002723
5VPCB15D0X3002723
5VPCD15D013002724
5VPCB15D2X3002724
5VPCD15D213002725
5VPCB15D4X3002725
5VPCB15D4Y3002726
5VPCD15D413002726
5VPCB15D6X3002726
5VPCB15D913002727
5VPCB15D8X3002727
5VPCB15D013002728
5VPCB15DXX3002728
5VPCB15D213002729
5VPCB15D1X3002729
5VPCB15D913002730
5VPCB15D8X3002730
5VPCB15D013002731
5VPCB15DXX3002731
5VPCB15D213002732
5VPCB15D1X3002732
5VPCB15D413002733

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D3X3002733
5VPCB15D613002734
5VPCB15D5X3002734
5VPCB15D813002735
5VPCB15D7X3002735
5VPCD15D713002736
5VPCB15D9X3002736
5VPCD15D913002737
5VPCB15D0X3002737
5VPCD15D013002738
5VPCB15D2X3002738
5VPCB15D513002739
5VPCB15D4X3002739
5VPCB15D113002740
5VPCB15D0X3002740
5VPCS15D0Y3002741
5VPCB15D313002741
5VPCB15D2X3002741
5VPCB15D513002742
5VPCB15D4X3002742
5VPCB15D713002743
5VPCB15D6X3002743
5VPCB15D913002744
5VPCB15D8X3002744
5VPCB15D013002745
5VPCB15DXX3002745
5VPCB15D213002746
5VPCB15D1X3002746
5VPCB15D413002747
5VPCB15D3X3002747
5VPCB15D613002748
5VPCB15D5X3002748
5VPCB15D813002749
5VPCB15D7X3002749
5VPCB15D413002750
5VPCB15D3X3002750
5VPCB15D613002751
5VPCB15D5X3002751
5VPCB16D813002752
5VPCB16D7X3002752
5VPCB15DX13002753
5VPCB15D9X3002753
5VPCB16D113002754
5VPCB15D0X3002754
5VPCB16D313002755
5VPCB15D2X3002755
5VPCB15D513002756
5VPCB15D4X3002756

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D713002757
5VPCB15D6X3002757
5VPCB15D913002758
5VPCB15D8X3002758
5VPCB15D013002759
5VPCB15DXX3002759
5VPCD15D413002760
5VPCB15D6X3002760
5VPCD15D613002761
5VPCB15D8X3002761
5VPCD15D813002762
5VPCB15DXX3002762
5VPCD15DX13002763
5VPCB15D1X3002763
5VPCD15D113002764
5VPCB15D3X3002764
5VPCD15D313002765
5VPCB15D5X3002765
5VPCD15D513002766
5VPCB15D7X3002766
5VPCD15D713002767
5VPCB15D9X3002767
5VPCD15D913002768
5VPCB15D0X3002768
5VPCD15D013002769
5VPCB15D2X3002769
5VPCD15D713002770
5VPCB15D9X3002770
5VPCD15D913002771
5VPCB15D0X3002771
5VPCD15D013002772
5VPCB15D2X3002772
5VPCB15D513002773
5VPCB15D4X3002773
5VPCB15D713002774
5VPCB15D6X3002774
5VPCB15D913002775
5VPCB15D8X3002775
5VPCB15D013002776
5VPCB15DXX3002776
5VPCS15D213002777
5VPCB15D1X3002777
5VPCS15D413002778
5VPCB15D3X3002778
5VPCS15D613002779
5VPCB15D5X3002779
5VPCS15D213002780
5VPCB15D1X3002780

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D413002781
5VPCB15D3X3002781
5VPCS15D613002782
5VPCB15D5X3002782
5VPCS15D813002783
5VPCB15D7X3002783
5VPCS15DX13002784
5VPCB15D9X3002784
5VPCS15D113002785
5VPCB15D0X3002785
5VPCS15D313002786
5VPCB15D2X3002786
5VPCS15D513002787
5VPCB15D4X3002787
5VPCS15D713002788
5VPCB15D6X3002788
5VPCS15D913002789
5VPCB15D8X3002789
5VPCB15D4X3002790
5VPCB15D6X3002791
5VPCB15D8X3002792
5VPCB15DXX3002793
5VPCD15DX13002794
5VPCB15D1X3002794
5VPCD15D113002795
5VPCB15D3X3002795
5VPCD15D313002796
5VPCB15D5X3002796
5VPCD15D513002797
5VPCB15D7X3002797
5VPCD15D713002798
5VPCB15D9X3002798
5VPCD15D913002799
5VPCB15D0X3002799
5VPCD15D113002800
5VPCB15D3X3002800
5VPCD15D313002801
5VPCB15D5X3002801
5VPCS15D5Y3002802
5VPCD15D613002802
5VPCB15D7X3002802
5VPCS15D7Y3002803
5VPCD15D713002803
5VPCB15D9X3002803
5VPCS15D9Y3002804
5VPCD15D913002804
5VPCB15D0X3002804
5VPCS15D0Y3002805

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15D013002805
5VPCB15D2X3002805
5VPCS15D2Y3002806
5VPCD15D213002806
5VPCB15D4X3002806
5VPCS15D4Y3002807
5VPCD15D413002807
5VPCB15D6X3002807
5VPCS15D6Y3002808
5VPCD15D613002808
5VPCB15D8X3002808
5VPCS15D8Y3002809
5VPCD15D813002809
5VPCB15DXX3002809
5VPCS15D4Y3002810
5VPCD15D413002810
5VPCB15D6X3002810
5VPCS15D6Y3002811
5VPCD15D613002811
5VPCB15D8X3002811
5VPCS15D8Y3002812
5VPCD15D813002812
5VPCB15DXX3002812
5VPCS15DXY3002813
5VPCD15DX13002813
5VPCB15D1X3002813
5VPCS15D1Y3002814
5VPCD15D113002814
5VPCB15D3X3002814
5VPCS15D3Y3002815
5VPCD15D313002815
5VPCB15D5X3002815
5VPCS15D5Y3002816
5VPCD15D613002816
5VPCB15D7X3002816
5VPCS15D7Y3002817
5VPCD15D713002817
5VPCB15D9X3002817
5VPCS15D9Y3002818
5VPCD15D913002818
5VPCB15D0X3002818
5VPCS15D0Y3002819
5VPCD15D013002819
5VPCB15D2X3002819
5VPCS15D7Y3002820
5VPCD15D713002820
5VPCB15D9X3002820
5VPCS15D9Y3002821

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15D913002821
5VPCB15D0X3002821
5VPCS15D0Y3002822
5VPCD15D013002822
5VPCB15D2X3002822
5VPCS15D2Y3002823
5VPCD15D213002823
5VPCB15D4X3002823
5VPCS15D4Y3002824
5VPCB15D6X3002824
5VPCS15D6Y3002825
5VPCB15D8X3002825
5VPCS15D8Y3002826
5VPCB15DXX3002826
5VPCS15DXY3002827
5VPCB15D213002827
5VPCB15D1X3002827
5VPCS15D1Y3002828
5VPCB15D413002828
5VPCB15D3X3002828
5VPCS15D3Y3002829
5VPCB15D613002829
5VPCB15D5X3002829
5VPCB15D213002830
5VPCB15D1X3002830
5VPCB15D413002831
5VPCB15D3X3002831
5VPCB15D613002832
5VPCB15D5X3002832
5VPCB15D813002833
5VPCB15D7X3002833
5VPCB15DX13002834
5VPCB15D9X3002834
5VPCB15D113002835
5VPCB15D0X3002835
5VPCB15D313002836
5VPCB15D2X3002836
5VPCB15D513002837
5VPCB15D4X3002837
5VPCB15D713002838
5VPCB15D6X3002838
5VPCB15D913002839
5VPCB15D8X3002839
5VPCB15D513002840
5VPCB15D4X3002840
5VPCB15D713002841
5VPCB15D6X3002841
5VPCB15D913002842

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D8X3002842
6VPCB15D013002843
5VPCB15DXX3002843
5VPCB15D213002844
5VPCB15D1X3002844
5VPCB15D413002845
5VPCB15D3X3002845
5VPCB15D613002846
5VPCB15D5X3002846
6VPCB15D813002847
5VPCB15D7X3002847
5VPCB15DX13002848
5VPCB15D9X3002848
5VPCB15D113002849
5VPCB15D0X3002849
5VPCB15D813002850
5VPCB15D7X3002850
5VPCB15D9X3002851
5VPCB16D0X3002852
5VPCB15D2X3002853
5VPCB15D4X3002854
5VPCB16D6X3002855
5VPCB15D8X3002856
5VPCB15DXX3002857
5VPCB15D213002858
5VPCB15D1X3002858
5VPCB15D413002859
5VPCB15D3X3002859
5VPCB15D013002860
5VPCB15DXX3002860
5VPCB15D213002861
5VPCB15D1X3002861
5VPCB15D413002862
5VPCB15D3X3002862
5VPCB15D613002863
5VPCB15D5X3002863
5VPCB15D613002864
5VPCB15D7X3002864
5VPCB15DX13002865
5VPCB15D9X3002865
5VPCB16D113002866
5VPCB15D0X3002866
5VPCB15D313002867
5VPCB15D2X3002867
5VPCB15D513002868
5VPCB15D4X3002868
5VPCB15D713002869
5VPCB15D6X3002869

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D313002870
5VPCB16D2X3002870
5VPCB15D513002871
5VPCB15D4X3002871
5VPCB16D713002872
5VPCB15D6X3002872
5VPCB16D913002873
5VPCB15D8X3002873
5VPCB15D013002874
5VPCB15DXX3002874
5VPCB15D213002875
5VPCB15D1X3002875
5VPCB15D413002876
5VPCB15D3X3002876
5VPCB15D613002877
5VPCB15D5X3002877
5VPCB15D813002878
5VPCB15D7X3002878
5VPCB15DX13002879
5VPCB15D9X3002879
5VPCB15D613002880
5VPCB15D5X3002880
5VPCB15D813002881
5VPCB16D7X3002881
5VPCB15DX13002882
5VPCB16D9X3002882
5VPCB15D113002883
5VPCB15D0X3002883
5VPCB15D313002884
5VPCB15D2X3002884
5VPCB15D513002885
5VPCB15D4X3002885
5VPCB15D713002886
5VPCB15D6X3002886
5VPCB15D913002887
5VPCB15D8X3002887
5VPCB15D013002888
5VPCB15DXX3002888
5VPCB15D213002889
5VPCB15D1X3002889
5VPCB15D913002890
5VPCB15D8X3002890
5VPCB15D013002891
5VPCB15DXX3002891
5VPCB16D213002892
5VPCB15D1X3002892
5VPCB15D413002893
5VPCB15D3X3002893

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D613002894
5VPCB15D5X3002894
5VPCB15D813002895
5VPCB15D7X3002895
5VPCB15DX13002896
5VPCB15D9X3002896
5VPCB15D113002897
5VPCB15D0X3002897
5VPCB15D313002898
5VPCB15D2X3002898
5VPCB15D513002899
5VPCB15D4X3002899
5VPCB15D813002900
5VPCB15D7X3002900
5VPCB15DX13002901
5VPCB15D9X3002901
5VPCB15D113002902
5VPCB15D0X3002902
5VPCB15D313002903
5VPCB15D2X3002903
5VPCB15D513002904
5VPCB15D4X3002904
5VPCB15D713002905
5VPCB15D6X3002905
5VPCB15D913002906
5VPCB15D8X3002906
5VPCB15D013002907
5VPCB15DXX3002907
5VPCB15D213002908
5VPCB15D1X3002908
5VPCD15D113002909
5VPCB15D3X3002909
5VPCD15D813002910
5VPCB15DXX3002910
5VPCD15DX13002911
5VPCB15D1X3002911
5VPCB15D413002912
5VPCB15D3X3002912
5VPCB15D613002913
5VPCB15D5X3002913
5VPCB15D813002914
5VPCB15D7X3002914
5VPCB15DX13002915
5VPCB15D9X3002915
5VPCB15D113002916
5VPCB15D0X3002916
5VPCB15D313002917
5VPCB15D2X3002917

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D513002916
5VPCB15D4X3002916
6VPCB15D713002919
5VPCB15D6X3002919
5VPCB15D313002920
5VPCB15D2X3002920
6VPCB15D513002921
6VPCB15D4X3002921
5VPCB15D713002922
5VPCB15D6X3002922
5VPCB15D913002923
5VPCB15D8X3002923
5VPCB15D013002924
5VPCB15DXX3002924
5VPCB15D213002925
5VPCB15D1X3002925
5VPCB15D413002926
5VPCB15D3X3002926
5VPCB15D613002927
5VPCB15D5X3002927
5VPCB15D813002928
5VPCB15D7X3002928
5VPCB15DX13002929
5VPCB15D9X3002929
5VPCB15D3Y3002930
6VPCB15D613002930
5VPCB15D5X3002930
6VPCB15D5Y3002931
5VPCB15D813002931
5VPCB15D7X3002931
5VPCB15D7Y3002932
5VPCB15DX13002932
5VPCB15D9X3002932
5VPCB15D9Y3002933
5VPCB15D0X3002933
5VPCS15D0Y3002934
5VPCB15D2X3002934
5VPCB15D4X3002935
5VPCB15D6X3002936
5VPCB15D6Y3002937
6VPCB15D8X3002937
5VPCB15D8Y3002938
5VPCB15DXX3002938
6VPCB15DXY3002939
5VPCB15D1X3002939
5VPCB15D6Y3002940
5VPCB15D8X3002940
5VPCB15D8Y3002941

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15DXX3002941
5VPCB15DXY3002942
5VPCB15D1X3002942
6VPCB15D1Y3002943
5VPCB15D3X3002943
6VPCB15D3Y3002944
5VPCB15D5X3002944
5VPCB15D5Y3002945
5VPCB15D7X3002945
6VPCB15D7Y3002946
5VPCB15D9X3002946
6VPCB15D9Y3002947
5VPCB15D0X3002947
6VPCB15D0Y3002948
5VPCB15D2X3002948
5VPCB15D2Y3002949
5VPCB15D4X3002949
5VPCB15D9Y3002950
5VPCB15D0X3002950
6VPCB15D0Y3002951
5VPCB15D2X3002951
5VPCB15D2Y3002952
5VPCB15D4X3002952
5VPCB15D4Y3002953
5VPCB15D6X3002953
5VPCB15D6Y3002954
5VPCB15D8X3002954
5VPCB15D8Y3002955
5VPCB15DXX3002955
5VPCB15DXY3002956
6VPCB15D1X3002956
5VPCB15D1Y3002957
5VPCB15D3X3002957
5VPCB15D3Y3002958
5VPCB15D5X3002958
5VPCB15D5Y3002959
5VPCB15D7X3002959
5VPCB15D1Y3002960
5VPCB15D3X3002960
5VPCB15D3Y3002961
6VPCB15D5X3002961
6VPCB15D6Y3002962
5VPCB15D7X3002962
5VPCB15D7Y3002963
5VPCB15D9X3002963
6VPCB15D9Y3002964
5VPCB15D0X3002964
5VPCB15D0Y3002965

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D2X3002985
5VPCB15D2Y3002986
5VPCB15D4X3002986
5VPCB15D4Y3002987
5VPCB15D6X3002987
5VPCB15D6Y3002988
5VPCB15D8X3002988
5VPCB15D8Y3002989
5VPCB15DXX3002988
5VPCB15D4Y3002970
5VPCB15D6X3002970
5VPCB15D6Y3002971
5VPCB15D8X3002971
5VPCB15D8Y3002972
5VPCB15DXX3002972
5VPCB15DXY3002973
5VPCB15D1X3002973
5VPCB15D1Y3002974
5VPCB16D3X3002974
5VPCB15D3Y3002975
5VPCB15D5X3002975
5VPCB15D5Y3002976
5VPCB15D7X3002976
5VPCB15D7Y3002977
5VPCB15D9X3002977
5VPCB16D9Y3002978
5VPCB16D0X3002978
5VPCB15D0Y3002979
5VPCB15D2X3002979
5VPCB15D7Y3002980
5VPCB15D8X3002980
5VPCB15D9Y3002981
5VPCB15D0X3002981
5VPCB15D0Y3002982
5VPCB15D2X3002982
5VPCB16D2Y3002983
5VPCB15D4X3002983
5VPCB16D4Y3002984
5VPCB15D6X3002984
5VPCB15D6Y3002985
5VPCB15D8X3002985
5VPCB15D8Y3002986
5VPCB15DXX3002986
5VPCB15DXY3002987
5VPCB15D1X3002987
5VPCB16D1Y3002988
5VPCB15D3X3002988
5VPCB15D6X3002989

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D1X3002990
5VPCB15D3X3002991
5VPCB15D5X3002992
5VPCB15D7X3002993
5VPCB15D9X3002994
5VPCB15D0X3002995
5VPCB15D2X3002996
5VPCB15D4X3002997
5VPCB15D6X3002998
5VPCB15D8X3002999
5VPCB15D9X3003000
5VPCB15D0X3003001
5VPCB15D2X3003002
5VPCB15D4X3003003
5VPCB15D6X3003004
5VPCB15D8X3003006
6VPCB15DXX3003006
5VPCB15D1X3003007
5VPCB15D3X3003008
5VPCB15D5X3003009
6VPCB15D1X3003010
5VPCB15D3X3003011
5VPCB15D5X3003012
5VPCB15D7X3003013
5VPCB15D9X3003014
6VPCB15D0X3003015
5VPCB15D2X3003016
6VPCB15D4X3003017
5VPCB15D6X3003018
6VPCB15D8X3003019
5VPCB15D4X3003020
6VPCB15D6X3003021
5VPCB15D8X3003022
5VPCB15DXX3003023
5VPCB15D1X3003024
5VPCB15D3X3003025
6VPCB15D5X3003026
5VPCB15D7X3003027
5VPCB15D9X3003028
5VPCB15D0X3003029
6VPCB15D7X3003030
5VPCB15D9X3003031
5VPCB15D0X3003032
5VPCB15D2X3003033
6VPCB15D4X3003034
5VPCB15D6X3003035
5VPCB15D8X3003036
5VPCB15DXX3003037

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D1X3003038
5VPCB15D3X3003039
6VPCB15DXX3003040
5VPCB15D1X3003041
5VPCB15D3X3003042
5VPCB15D5X3003043
6VPCB15D7X3003044
5VPCB15D9X3003045
5VPCB15D0X3003046
6VPCB15D2X3003047
5VPCB15D4X3003048
5VPCB15D6X3003049
5VPCB15D2X3003050
6VPCB15D4X3003061
5VPCB15D6X3003052
6VPCB15D8X3003063
5VPCB15DXX3003054
6VPCB16D1X3003066
5VPCB15D3X3003056
5VPCB15D5X3003057
5VPCB15D7X3003058
5VPCB15D9X3003059
5VPCB15D5X3003060
5VPCB15D7X3003061
5VPCB15D9X3003062
5VPCB16D0X3003063
5VPCB15D2X3003064
5VPCB15D4X3003065
5VPCB15D6X3003066
5VPCB15D8X3003067
5VPCB16DXX3003068
5VPCB15D1X3003069
5VPCB15D6X3003070
5VPCB15DXX3003071
5VPCB15D1X3003072
6VPCB16D3X3003073
5VPCB15D5X3003074
5VPCB15D7X3003075
5VPCB15D9X3003076
5VPCB15D0X3003077
5VPCB16D2X3003078
5VPCB15D4X3003079
5VPCB15D0X3003080
6VPCB16D2X3003081
5VPCB15D4X3003082
5VPCB16D6X3003083
5VPCB15D8X3003084
6VPCB16DXX3003085

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D1X3003086
5VPCB15D3X3003087
5VPCB15D5X3003088
5VPCB15D7X3003089
5VPCB15D3X3003090
5VPCB15D5X3003091
5VPCB15D7X3003092
5VPCB15D9X3003093
5VPCB15D0X3003094
5VPCB15D2X3003095
5VPCB15D4X3003096
5VPCB15D6X3003097
5VPCB15D6Y3003098
5VPCB15D8X3003098
5VPCB15D8Y3003099
5VPCB15DXX3003099
5VPCB15D0Y3003100
5VPCB15D2X3003100
5VPCB15D2Y3003101
5VPCB15D4X3003101
5VPCB15D4Y3003102
5VPCB15D6X3003102
5VPCB15D6Y3003103
5VPCB15D8X3003103
5VPCB15D8Y3003104
5VPCB15DXX3003104
5VPCB15DXY3003105
5VPCB15D1X3003105
5VPCB15D1Y3003106
5VPCB15D3X3003106
5VPCB15D3Y3003107
5VPCB15D5X3003107
5VPCB15D5Y3003108
5VPCB15D7X3003108
5VPCS15D7Y3003109
5VPCB15D9X3003109
5VPCS15D3Y3003110
5VPCB15D5X3003110
5VPCS15D5Y3003111
5VPCB15D7X3003111
5VPCS15D7Y3003112
5VPCB15D9X3003112
5VPCS15D9Y3003113
5VPCB15D0X3003113
5VPCS15D0Y3003114
5VPCB15D2X3003114
5VPCS15D2Y3003115
5VPCB15D4X3003115

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D4Y3003116
5VPCB15D6X3003116
5VPCS15D6Y3003117
5VPCB15D8X3003117
5VPCS15D8Y3003118
5VPCB15DXX3003118
5VPCS15DXY3003119
5VPCB15D1X3003119
5VPCS15D6Y3003120
5VPCB15D8X3003120
5VPCS15D8Y3003121
5VPCB15DXX3003121
5VPCS15DXY3003122
5VPCB15D1X3003122
5VPCS15D1Y3003123
5VPCB15D3X3003123
5VPCS15D3Y3003124
5VPCB15D5X3003124
5VPCS15D6Y3003125
5VPCB15D7X3003125
5VPCS15D7Y3003126
5VPCB15D9X3003126
5VPCS15D9Y3003127
5VPCB15D0X3003127
5VPCS15D0Y3003128
5VPCB15D2X3003128
5VPCS15D2Y3003129
5VPCB15D4X3003129
5VPCS15D9Y3003130
5VPCB15D0X3003130
5VPCB15D0Y3003131
5VPCB15D2X3003131
5VPCB15D2Y3003132
5VPCB15D4X3003132
5VPCB15D4Y3003133
5VPCB15D6X3003133
5VPCB15D6Y3003134
5VPCB15D8X3003134
5VPCB15D8Y3003135
5VPCB15DXX3003135
5VPCB15DXY3003136
5VPCB15D1X3003136
5VPCB15D1Y3003137
5VPCB15D3X3003137
5VPCB15D3Y3003138
5VPCB15D5X3003138
5VPCB15D5Y3003139
5VPCB15D7X3003139

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D1Y3003140
5VPCB15D3X3003140
5VPCB15D3Y3003141
5VPCB15D5X3003141
5VPCB15D5Y3003142
5VPCB15D7X3003142
5VPCB15D7Y3003143
5VPCB15D9X3003143
5VPCB15D9Y3003144
5VPCB15D0X3003144
5VPCB15D0Y3003145
5VPCB15D2X3003145
5VPCB15D2Y3003146
5VPCB15D4X3003146
5VPCB15D4Y3003147
5VPCB15D6X3003147
5VPCB15D6Y3003148
5VPCB15D8X3003148
5VPCB15D8Y3003149
5VPCB15DXX3003149
5VPCS15D4Y3003150
5VPCB15D6X3003150
5VPCS15D6Y3003151
5VPCB15D8X3003151
5VPCS15D8Y3003152
5VPCB15DXX3003152
5VPCS15DXY3003153
5VPCB15D1X3003153
5VPCS15D1Y3003154
5VPCB15D3X3003154
5VPCS15D3Y3003155
5VPCB15D5X3003155
5VPCB15D5Y3003156
5VPCB15D7X3003156
5VPCB15D7Y3003157
5VPCB15D9X3003157
5VPCB15D9Y3003158
5VPCB15D0X3003158
5VPCB15D0Y3003159
5VPCB15D2X3003159
5VPCB15D7Y3003160
5VPCB15D9X3003160
5VPCB15D9Y3003161
5VPCB15D0X3003161
5VPCB15D0Y3003162
5VPCB15D2X3003162
5VPCB15D2Y3003163
5VPCB15D4X3003163

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D4Y3003164
5VPCB15D6X3003164
5VPCB15D6Y3003165
5VPCB15D8X3003165
5VPCB15D8Y3003166
5VPCB15DXX3003166
5VPCB15DXY3003167
5VPCB15D1X3003167
5VPCB15D1Y3003168
5VPCB15D3X3003168
5VPCB15D3Y3003169
5VPCB15D5X3003169
5VPCS15DXY3003170
5VPCB15D1X3003170
5VPCS15D1Y3003171
5VPCB15D3X3003171
5VPCS15D3Y3003172
5VPCB15D5X3003172
5VPCS15D5Y3003173
5VPCB15D7X3003173
5VPCS15D7Y3003174
5VPCB15D9X3003174
5VPCS15D9Y3003175
6VPCB15D0X3003176
5VPCS15D0Y3003176
5VPCB15D2X3003176
5VPCS15D2Y3003177
5VPCB15D4X3003177
6VPCS15D4Y3003178
5VPCB15D6X3003178
5VPCS15D6Y3003179
5VPCB15D8X3003179
5VPCS15D2Y3003180
6VPCB15D4X3003180
5VPCS15D4Y3003181
5VPCB15D6X3003181
5VPCS15D6Y3003182
6VPCB15D8X3003182
5VPCS15D8Y3003183
5VPCB15DXX3003183
5VPCS15DXY3003184
6VPCB15D1X3003184
5VPCS15D1Y3003185
5VPCB15D3X3003186
5VPCS15D3Y3003186
6VPCB15D5X3003186
5VPCS15D5Y3003187
5VPCB15D7X3003187

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D7Y3003188
6VPCB15D9X3003188
5VPCS15D9Y3003189
5VPCB15D0X3003189
5VPCS15D6Y3003190
6VPCB15D7X3003190
5VPCS15D7Y3003191
6VPCB15D9X3003191
6VPCS15D9Y3003192
5VPCB15D0X3003192
5VPCS15D0Y3003193
6VPCB15D2X3003193
5VPCS15D2Y3003194
5VPCB15D4X3003194
5VPCS15D4Y3003195
5VPCB15D6X3003195
5VPCS15D6Y3003196
5VPCB15D8X3003196
5VPCS15D8Y3003197
5VPCB15DXX3003197
5VPCS15DXY3003198
5VPCB15D1X3003198
6VPCS15D1Y3003199
5VPCB15D3X3003199
6VPCS15D4Y3003200
6VPCB15D6X3003200
5VPCB15D6Y3003201
6VPCB15D8X3003201
5VPCB15D8Y3003202
6VPCB15DXX3003202
5VPCB15DXY3003203
5VPCB15D1X3003203
5VPCB15D1Y3003204
5VPCB15D3X3003204
5VPCB15D3Y3003205
5VPCB15D5X3003205
5VPCB15D6Y3003206
5VPCB15D7X3003206
5VPCB15D7Y3003207
5VPCB15D8X3003207
6VPCB15D9Y3003208
5VPCB15D0X3003208
6VPCB15D0Y3003209
5VPCB15D2X3003209
5VPCB15D7Y3003210
6VPCB15D9X3003210
5VPCS15D9Y3003211
5VPCB15D0X3003211

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D0Y3003212
5VPCB15D2X3003212
5VPCS15D2Y3003213
5VPCB15D4X3003213
5VPCS15D4Y3003214
5VPCB15D6X3003214
5VPCS15D6Y3003215
5VPCB15D8X3003215
5VPCS15D8Y3003216
5VPCB15DXX3003216
5VPCS15DXY3003217
5VPCB15D1X3003217
5VPCS15D1Y3003218
5VPCB15D3X3003218
5VPCS15D3Y3003219
5VPCB15D5X3003219
5VPCS15DXY3003220
5VPCB15D1X3003220
5VPCS15D1Y3003221
5VPCB15D3X3003221
5VPCS15D3Y3003222
5VPCB15D5X3003222
5VPCS15D5Y3003223
5VPCB15D7X3003223
5VPCS15D7Y3003224
5VPCB15D9X3003224
5VPCB15D9Y3003225
5VPCB15D0X3003225
5VPCB15D0Y3003226
5VPCB15D2X3003226
5VPCB15D2Y3003227
5VPCB15D4X3003227
5VPCB15D4Y3003228
5VPCB15D6X3003228
5VPCB15D6Y3003229
5VPCB15D8X3003229
5VPCB15D2Y3003230
5VPCB15D4X3003230
5VPCB15D4Y3003231
5VPCB15D6X3003231
5VPCB15D6Y3003232
5VPCB15D8X3003232
5VPCB15D8Y3003233
5VPCB15DXX3003233
5VPCB15DXY3003234
5VPCB15D1X3003234
5VPCS15D1Y3003235
5VPCB15D3X3003235

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D3Y3003236
5VPCB15D6X3003236
5VPCS15D5Y3003237
5VPCB15D7X3003237
5VPCS15D7Y3003238
5VPCB15D9X3003238
5VPCB15D9Y3003239
5VPCB15D0X3003239
5VPCB15D5Y3003240
5VPCB15D7X3003240
5VPCB15D7Y3003241
5VPCB15D9X3003241
5VPCB15D9Y3003242
5VPCB15D0X3003242
5VPCB15D0Y3003243
5VPCB15D2X3003243
5VPCB15D2Y3003244
5VPCB15D4X3003244
5VPCB15D4Y3003245
5VPCB15D6X3003245
5VPCB15D6Y3003246
5VPCB15D8X3003246
5VPCB15D8Y3003247
5VPCB15DXX3003247
5VPCB15DXY3003248
5VPCB15D1X3003248
5VPCB15D1Y3003249
5VPCB15D3X3003249
5VPCB15D8Y3003250
5VPCB15DXX3003250
5VPCB15DXY3003251
5VPCB15D1X3003251
5VPCB15D1Y3003252
5VPCB15D3X3003252
5VPCB15D3Y3003253
5VPCB15D6X3003253
5VPCB15D5Y3003254
5VPCB15D7X3003254
5VPCB15D7Y3003255
5VPCB15D9X3003256
5VPCB15D9Y3003256
5VPCB15D0X3003256
5VPCB15D0Y3003257
5VPCB15D2X3003257
5VPCB15D2Y3003258
5VPCB15D4X3003258
5VPCB15D4Y3003259
5VPCB15D6X3003259

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D0Y3003260
5VPCB15D2X3003260
5VPCS15D2Y3003261
5VPCB15D4X3003261
5VPCS15D4Y3003262
5VPCB15D6X3003262
5VPCS15D6Y3003263
5VPCB15D8X3003263
5VPCS15D8Y3003264
5VPCB15DXX3003264
5VPCS15DXY3003265
5VPCB15D1X3003265
5VPCS15D1Y3003266
5VPCB15D3X3003266
5VPCS15D3Y3003267
5VPCB15D5X3003267
5VPCS15D5Y3003268
5VPCB15D7X3003268
5VPCS15D7Y3003269
5VPCB15D9X3003269
5VPCS15D3Y3003270
5VPCB15D5X3003270
5VPCS15D6Y3003271
5VPCB15D7X3003271
5VPCS15D7Y3003272
5VPCB15D9X3003272
5VPCS15D9Y3003273
5VPCB15D0X3003273
5VPCS15D0Y3003274
5VPCB15D2X3003274
5VPCS15D2Y3003275
5VPCB15D4X3003275
5VPCS15D4Y3003276
5VPCB15D6X3003276
5VPCS15D6Y3003277
5VPCB15D8X3003277
5VPCS15D8Y3003278
5VPCB15DXX3003278
5VPCS15DXY3003279
5VPCB15D1X3003279
5VPCS15D6Y3003280
5VPCB15D8X3003280
5VPCS15D6Y3003281
5VPCB15DXX3003281
5VPCS15DXY3003262
5VPCB15D1X3003282
5VPCS15D1Y3003283
5VPCB15D3X3003283

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D3Y3003284
5VPCB15D5X3003284
5VPCS15D5Y3003285
5VPCB15D7X3003285
5VPCS15D7Y3003286
5VPCB15D9X3003286
5VPCS15D9Y3003287
5VPCB15D0X3003287
5VPCS15D0Y3003288
5VPCB15D2X3003288
5VPCS15D2Y3003289
5VPCB15D4X3003289
5VPCS15D9Y3003290
5VPCB15D0X3003290
5VPCS15D0Y3003291
5VPCB15D2X3003291
5VPCB15D2Y3003292
5VPCB15D4X3003292
5VPCB15D4Y3003293
5VPCB15D6X3003293
5VPCB15D6Y3003294
5VPCB15D8X3003294
5VPCB15D8Y3003295
5VPCB15DXX3003295
5VPCB15DXY3003296
5VPCB15D1X3003296
5VPCB15D1Y3003297
5VPCB15D3X3003297
5VPCB15D3Y3003298
5VPCB15D5X3003298
5VPCB15D5Y3003299
5VPCB15D7X3003299
6VPCB15D8Y3003300
5VPCB15DXX3003300
5VPCB15DXY3003301
5VPCB15D1X3003301
5VPCB15D1Y3003302
5VPCB15D3X3003302
5VPCB15D3Y3003303
5VPCB15D5X3003303
5VPCB15D5Y3003304
5VPCB15D7X3003304
5VPCB15D7Y3003305
5VPCB15D9X3003305
5VPCB15D9Y3003306
5VPCB15D0X3003306
5VPCB15D0Y3003307
5VPCB15D2X3003307

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D2Y3003308
5VPCB15D4X3003308
5VPCB15D4Y3003309
5VPCB15D6X3003309
5VPCB15D0Y3003310
5VPCB15D2X3003310
5VPCB15D2Y3003311
5VPCB15D4X3003311
5VPCB15D4Y3003312
5VPCB15D6X3003312
5VPCS15D8Y3003313
5VPCB15D8X3003313
5VPCS15D8Y3003314
6VPCB15DXX3003314
5VPCS15DXY3003315
5VPCB15D1X3003315
5VPCS15D1Y3003316
5VPCB15D3X3003316
5VPCS15D3Y3003317
5VPCB15D5X3003317
5VPCS15D5Y3003318
5VPCB15D7X3003318
5VPCS15D7Y3003319
5VPCB15D9X3003319
5VPCS15D3Y3003320
5VPCB15D5X3003320
5VPCS15D5Y3003321
5VPCB15D7X3003321
5VPCS15D7Y3003322
5VPCB15D9X3003322
5VPCS15D9Y3003323
5VPCB15D0X3003323
5VPCS15D0Y3003324
5VPCB15D2X3003324
5VPCS15D2Y3003325
5VPCB15D4X3003325
5VPCB15D4Y3003326
5VPCB15D6X3003326
5VPCB15D6Y3003327
5VPCB15D8X3003327
5VPCB15D8Y3003328
5VPCB15DXX3003328
5VPCB15DXY3003329
5VPCB15D1X3003329
5VPCB15D6Y3003330
5VPCB15D8X3003330
5VPCB15D8Y3003331
5VPCB15DXX3003331

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15DXY3003332
5VPCB15D1X3003332
5VPCB15D1Y3003333
5VPCB15D3X3003333
5VPCB15D3Y3003334
5VPCB15D5X3003334
5VPCB15D5Y3003335
5VPCB15D7X3003335
5VPCS15D7Y3003336
5VPCB15D9X3003336
5VPCS15D9Y3003337
5VPCB15D0X3003337
5VPCS15D0Y3003338
5VPCB15D2X3003338
5VPCS15D2Y3003339
5VPCB15D4X3003339
5VPCS15D9Y3003340
5VPCB15D0X3003340
5VPCS15D0Y3003341
5VPCB15D2X3003341
5VPCS15D2Y3003342
5VPCB15D4X3003342
5VPCS15D4Y3003343
5VPCB15D6X3003343
5VPCS15D6Y3003344
5VPCB15D8X3003344
5VPCS15D8Y3003345
5VPCB15DXX3003345
5VPCS15DXY3003346
5VPCB15D1X3003346
5VPCS15D1Y3003347
5VPCB15D3X3003347
5VPCS15D3Y3003348
5VPCB15D5X3003348
5VPCS15D5Y3003349
5VPCB15D7X3003349
5VPCS15D1Y3003350
5VPCB15D3X3003350
5VPCS15D3Y3003351
5VPCB15D5X3003351
5VPCS15D5Y3003352
5VPCB15D7X3003352
5VPCS15D7Y3003353
5VPCB15D9X3003353
5VPCS15D9Y3003354
5VPCB15D0X3003354
5VPCS15D0Y3003355
5VPCB15D2X3003355

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15D2Y3003356
5VPCB15D4X3003356
5VPCS15D4Y3003357
5VPCB15D6X3003357
5VPCS15D6Y3003358
5VPCB15D8X3003358
5VPCS15D8Y3003359
5VPCB15DXX3003359
5VPCS15D4Y3003360
5VPCB15D6X3003360
5VPCS15D6Y3003361
5VPCB15D8X3003361
5VPCS15D8Y3003362
5VPCB15DXX3003362
5VPCS15DXY3003363
5VPCB15D1X3003363
5VPCS15D1Y3003364
5VPCB15D3X3003364
5VPCS15D3Y3003365
5VPCB15D5X3003365
5VPCS15D5Y3003366
5VPCB15D7X3003366
5VPCS15D7Y3003367
5VPCB15D9X3003367
5VPCS15D9Y3003368
5VPCB15D0X3003368
5VPCS15D0Y3003369
5VPCB15D2X3003369
5VPCS15D7Y3003370
5VPCB15D9X3003370
5VPCS15D9Y3003371
5VPCB15D0X3003371
5VPCB15D2X3003372
5VPCB15D4X3003373
5VPCB15D6X3003374
5VPCB15D8X3003375
5VPCB15DXX3003376
5VPCB15D1X3003377
5VPCB15D3X3003378
5VPCB15D5X3003379
5VPCB15D1X3003380
5VPCB15D3X3003381
5VPCB15D5X3003382
5VPCB15D7X3003383
5VPCB15D9X3003384
5VPCB15D0X3003385
5VPCB15D2X3003386
5VPCB15D4X3003387

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D6X3003386
5VPCB15D8X3003389
5VPCB15D4X3003390
5VPCB15D6X3003391
5VPCB15D8X3003392
5VPCB15DXX3003393
5VPCB15D1X3003394
5VPCB15D3X3003395
5VPCB15D5X3003396
5VPCB15D7X3003397
5VPCB15D9X3003398
5VPCB15D0X3003399
5VPCB15D3X3003400
5VPCB15D6X3003401
5VPCB15D7X3003402
5VPCB15D9X3003403
5VPCB15D0X3003404
5VPCB15D2X3003405
5VPCB15D4X3003406
5VPCB15D6X3003407
5VPCB15D8X3003408
5VPCB15DXX3003409
5VPCB15D6X3003410
5VPCB15D8X3003411
5VPCB15DXX3003412
5VPCB15D1X3003413
5VPCB15D3X3003414
5VPCB15D5X3003415
5VPCB15D7X3003416
5VPCB15D9X3003417
5VPCB15D0X3003418
5VPCB15D2X3003419
5VPCB15D9X3003420
5VPCB15D0X3003421
5VPCB15D2X3003422
5VPCB15D4X3003423
5VPCB15D6X3003424
5VPCB15D8X3003425
5VPCB15DXX3003426
5VPCB15D1X3003427
5VPCB15D3X3003428
5VPCB15D5X3003429
5VPCB15D1X3003430
5VPCB15D3X3003431
5VPCB15D5X3003432
5VPCB15D7X3003433
5VPCB15D9X3003434
5VPCB15D0X3003435

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D2X3003436
5VPCB15D4X3003437
5VPCB15D6X3003438
5VPCB15D8X3003439
5VPCB15D4X3003440
5VPCB15D6X3003441
5VPCB15D8X3003442
5VPCB15DXX3003443
5VPCB15D1X3003444
5VPCB15D3X3003445
5VPCB15D5X3003446
5VPCB15D7X3003447
5VPCB15D9X3003448
5VPCB15D0X3003449
5VPCB15D7X3003450
5VPCB15D9X3003451
5VPCB15D0X3003452
5VPCB15D2X3003453
5VPCB15D4X3003454
5VPCB15D6X3003455
6VPCB15D8X3003456
5VPCB15DXX3003457
5VPCB15D1X3003458
5VPCB15D3X3003459
5VPCB15DXX3003460
5VPCB15D1X3003461
5VPCB15D3X3003462
5VPCB15D5X3003463
5VPCB15D7X3003464
6VPCB15D9X3003465
5VPCB15D0X3003466
5VPCB15D2X3003467
5VPCB15D4X3003468
5VPCB15D6X3003469
6VPCB15D2X3003470
5VPCB15D4X3003471
5VPCB15D6X3003472
5VPCB15D8X3003473
5VPCB15DXX3003474
5VPCB15D1X3003475
5VPCB15D3X3003476
5VPCB15D5X3003477
5VPCB15D7X3003478
5VPCB15D9X3003479
5VPCB15D5X3003480
5VPCB15D7X3003481
5VPCB15D9X3003482
5VPCB15D0X3003483

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D2X3003484
5VPCB15D4X3003485
5VPCB15D6X3003486
5VPCB15D8X3003487
5VPCB15DXX3003488
5VPCB15D1X3003489
5VPCB15D8X3003490
5VPCB15DXX3003491
5VPCB15D1X3003492
5VPCB15D3X3003493
5VPCB15D5X3003494
5VPCB15D7X3003495
5VPCB15D9X3003496
5VPCB15D0X3003497
5VPCB15D2X3003498
5VPCB15D4X3003499
5VPCB15D7X3003500
5VPCB15D9X3003501
5VPCB15D0X3003502
5VPCB15D2X3003603
5VPCB15D4X3003504
5VPCB15D6X3003505
5VPCB15D8X3003506
5VPCB15DXX3003507
5VPCB15D1X3003508
5VPCB15D3X3003509
5VPCB15DXX3003510
5VPCB15D1X3003511
5VPCB15D3X3003512
5VPCB15D5X3003513
5VPCB15D7X3003514
5VPCB15D9X3003515
5VPCB15D0X3003516
5VPCB15D2X3003517
5VPCB15D4X3003518
5VPCB15D6X3003519
5VPCB15D2X3003520
5VPCB15D4X3003521
5VPCB15D6X3003522
5VPCB15D8X3003523
5VPCB15DXX3003524
5VPCB15D1X3003525
5VPCB15D3X3003526
5VPCB15D5X3003527
5VPCB15D7X3003528
5VPCB15D9X3003529
5VPCB15D5X3003530
5VPCB15D7X3003531

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D9X3003532
5VPCB15D0X3003533
5VPCB15D2X3003534
5VPCB15D4X3003535
5VPCB15D6X3003536
5VPCB15D8X3003537
5VPCB15DXX3003538
5VPCB15D1X3003539
5VPCB15D8X3003540
5VPCB15DXX3003541
5VPCB15D1X3003542
5VPCB15D3X3003543
5VPCB15D5X3003544
5VPCB15D7X3003545
5VPCB15D9X3003546
5VPCB15D0X3003547
5VPCB15D2X3003548
5VPCB15D4X3003549
5VPCB15D0X3003550
5VPCB15D2X3003551
5VPCB15D4X3003552
5VPCB15D6X3003553
5VPCB15D8X3003554
5VPCB15DXX3003555
5VPCB15D1X3003556
5VPCB15D3X3003557
5VPCB15D5X3003558
5VPCB15D7X3003559
5VPCB15D3X3003560
5VPCB15D5X3003561
5VPCB15D7X3003562
5VPCB15D9X3003563
5VPCB15D0X3003564
5VPCB15D2X3003565
5VPCB15D4X3003566
5VPCB15D6X3003567
5VPCB15D8X3003568
5VPCB15DXX3003569
5VPCB15D6X3003570
5VPCB15D8X3003571
5VPCB15DXX3003572
5VPCB15D1X3003573
5VPCB15D3X3003574
5VPCB15D2X3003596
5VPCB15D4X3003597
5VPCB15D6X3003598
5VPCB15D8X3003599
5VPCB15D0X3003600

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15D2X3003601
5VPCB15D4X3003602
5VPCB15L413000343
5VPCB16L613000344
5VPCB15L613000345
5VPCB15LX13000346
5VPCB15L113000347
5VPCB15L313000348
5VPCB15L213000356
5VPCS15L313000365
5VPCS15L513000366
5VPCS16L713000367
5VPCS15L913000368
5VPCS15L613000375
5VPCS15L813000376
5VPCB15LX13000377
5VPCB15L113000378
5VPCD15L013000379
5VPCD15L713000380
5VPCD15L613000385
5VPCD16L813000386
5VPCD15LX13000387
5VPCD15L713000413
5VPCD15L913000414
5VPCD15L013000415
5VPCB16L813000426
5VPCD15L713000427
5VPCD15L913000428
5VPCD16L013000429
5VPCD15L713000430
5VPCB15LX13000914
5VPCB15L413000925
5VPCB15L613000926
5VPCB16L813000927
5VPCB15LX13000928
5VPCB16L113000929
5VPCB15LX13000993
5VPCB16L113000994
5VPCB15L313000995
5VPCB16L513000996
5VPCB15L713000997
5VPCB15L913000998
5VPCB15L013000999
5VPCB15L113001000
5VPCB15L913001004
5VPCB15L013001005
5VPCB15L213001006
5VPCB16L413001007

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15L613001008
5VPCB15L813001009
5VPCB15L413001010
5VPCB15L613001016
5VPCB15L713001017
5VPCB15L913001018
5VPCB15L013001019
5VPCB15L713001020
5VPCB15L913001021
5VPCB15L413001122
5VPCB15L613001123
5VPCB15L813001124
5VPCB15LX13001125
5VPCB15L113001126
5VPCB15L313001127
5VPCB15L513001128
5VPCB15L713001129
5VPCB15L313001130
5VPCB15L513001131
5VPCD15L713001156
5VPCD15L913001157
5VPCD15L013001158
5VPCD15L213001159
5VPCD15L913001160
5VPCD15L013001161
5VPCD15L213001162
5VPCD15L413001163
5VPCD15L613001164
5VPCD15L813001165
5VPCD15LX13001166
5VPCD15L113001167
5VPCD15L313001168
5VPCD15L513001169
5VPCD15L113001170
5VPCD15L313001171
5VPCD15L513001172
5VPCD15L713001173
5VPCD15L913001174
5VPCD15L013001175
5VPCD15L213001176
5VPCD15L413001177
5VPCD15L613001178
5VPCD15L813001179
5VPCD15L413001180
5VPCD15L613001181
5VPCD15L813001182
5VPCD15LX13001183
5VPCD15L113001184

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15L313001185
5VPCD15L513001186
5VPCD15L713001187
5VPCD15L913001188
5VPCD15L013001189
5VPCB15LX13001190
5VPCB15L113001191
5VPCB15L313001192
5VPCB15L513001193
5VPCB15L713001194
5VPCD15L613001374
5VPCD15L813001375
5VPCD15LX13001376
5VPCD15L113001377
5VPCD15L313001378
5VPCD15L513001379
5VPCD15L113001380
5VPCD15L313001381
5VPCD15L513001382
5VPCD15L713001383
5VPCD16L813001384
5VPCD15L013001385
5VPCB15L5X3001459
5VPCB15L1X3001460
5VPCB15L3X3001461
5VPCB15L5X3001462
5VPCB16L7X3001463
5VPCB15L9X3001464
5VPCB16L0X3001465
5VPCB16L2X3001466
5VPCB15L4X3001467
5VPCB15L6X3001468
5VPCB15L8X3001469
5VPCB15L4X3001470
5VPCB15L6X3001471
5VPCB15L8X3001472
5VPCB15LXX3001473
5VPCB15L1X3001474
5VPCB15L3X3001475
5VPCB16L5X3001476
5VPCB15L7X3001477
5VPCB15L9X3001478
5VPCB15L0X3001479
5VPCB15L7X3001480
5VPCB15L9X3001481
5VPCB16L0X3001482
5VPCB15L2X3001483
5VPCB15L4X3001484

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15L8X3001485
5VPCB15L8X3001486
5VPCB15LXX3001487
5VPCB15L1X3001488
5VPCB15L3X3001489
5VPCB15LXX3001490
5VPCB15L1X3001491
5VPCB15L3X3001492
5VPCB15L5X3001493
5VPCB15L7X3001494
5VPCB15L9X3001495
5VPCB15L0X3001496
5VPCB15L2X3001497
5VPCB15L4X3001498
5VPCB15L6X3001499
5VPCB15L9X3001500
5VPCB15L713001566
5VPCB15L913001567
5VPCB15L013001568
5VPCB15L213001569
5VPCB15L913001570
5VPCB15L013001571
5VPCB16L213001672
5VPCB15L413001573
5VPCB16L613001674
5VPCB15L813001575
5VPCB16LX13001576
5VPCB15L113001577
5VPCB16L313001678
5VPCB15L513001579
5VPCB15L113001680
5VPCB15LX13001593
5VPCB15L113001594
5VPCB15L313001595
5VPCB16L613001696
5VPCB15L713001597
5VPCB15L913001598
5VPCS15L7Y3001626
5VPCS16L9Y3001627
5VPCS15L0Y3001628
5VPCS15L2Y3001629
5VPCS16L9Y3001630
5VPCS15L0Y3001631
5VPCS15L2Y3001632
5VPCS15L4Y3001633
5VPCS15L6Y3001634
5VPCS15L8Y3001635
5VPCS15LXY3001636

03V-336 (185) of (193)

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCS15L1Y3001637
5VPCS15L3Y3001638
5VPCS15L5Y3001639
5VPCS16L1Y3001640
5VPCS15L3Y3001641
5VPCS15L5Y3001642
5VPCS15L7Y3001643
5VPCS15L9Y3001644
5VPCS15L0Y3001645
5VPCS15L2Y3001646
5VPCS15L4Y3001647
5VPCS16L6Y3001648
5VPCS15L8Y3001649
5VPCS16L4Y3001650
5VPCS15L6Y3001651
5VPCS15L8Y3001652
5VPCS15LXY3001653
5VPCS15L1Y3001654
5VPCS15L3Y3001655
5VPCS15L5Y3001656
5VPCS15L7Y3001657
5VPCS15L9Y3001658
5VPCS15L0Y3001659
5VPCS15L7Y3001660
5VPCS15L9Y3001661
5VPCS16L0Y3001662
5VPCS15L2Y3001663
5VPCS15L4Y3001664
5VPCS15L6Y3001665
5VPCS15L8Y3001666
5VPCS16LXY3001667
5VPCS15L1Y3001668
5VPCS15L3Y3001669
5VPCS16LXY3001670
5VPCS15L1Y3001671
5VPCS15L3Y3001672
5VPCS15L5Y3001673
5VPCS15L7Y3001674
5VPCS15L9Y3001675
5VPCS16L0Y3001676
5VPCS15L2Y3001677
5VPCS15L4Y3001678
5VPCS15L6Y3001679
5VPCS16L2Y3001680
5VPCS15L4Y3001681
5VPCS15L6Y3001682
5VPCS15L8Y3001683
5VPCS16LXY3001684

M.Y. 1999 through 2001 motorcycles assembled from 7-1-99 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15L1Y3001685
6VPCB15L9Y3001708
5VPCB15L0Y3001709
6VPCB15L7Y3001710
5VPCB15L9Y3001711
6VPCB15L0Y3001712
5VPCB15L2Y3001713
5VPCB15L4Y3001714
5VPCB15L6Y3001715
5VPCB15L8Y3001716
5VPCB15LXY3001717
6VPCB15L1Y3001718
5VPCB15L3Y3001719
6VPCB15LXY3001720
5VPCB15L1Y3001721
5VPCB15L3Y3001722
5VPCB15L5Y3001723
5VPCB15L7Y3001724
5VPCB15L9Y3001725
5VPCB15L0Y3001726
5VPCB15L2Y3001727
5VPCB15L4Y3001728
5VPCB15L6Y3001729
5VPCB15L2Y3001730
5VPCB15L4Y3001731
6VPCB15L6Y3001732
5VPCB15L8Y3001733
5VPCB15LXY3001734
5VPCB15L1Y3001735
5VPCB15L3Y3001736
5VPCB15L8Y3001747
6VPCB15LXY3001748
5VPCB15L1Y3001749
5VPCB15L8Y3001750
5VPCB15LXY3001751
5VPCB15L1Y3001752
5VPCB15L3Y3001753
5VPCB16L5Y3001754
5VPCB15L7Y3001755
5VPCB15L9Y3001756
5VPCD15L213001758
5VPCB16L4Y3001759
5VPCD15L413001759
5VPCD16L813001764
5VPCD15LX13001765
5VPCD15LX13001796
5VPCD15L513001821
5VPCD15L713001822

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCD15L913001823
5VPCD15L013001824
5VPCD16L213001825
5VPCD15L413001826
5VPCD16L613001827
5VPCD15L813001828
5VPCD15LX13001829
5VPCD15L813001859
5VPCD15L413001860
5VPCD15L613001861
5VPCS15L213001975
5VPCS15L413001976
5VPCS15L613001977
5VPCS16L813001978
5VPCB15L8X3002024
5VPCB16LXX3002026
5VPCB15L1X3002026
5VPCB15L3X3002027
5VPCB15L5X3002028
5VPCB15L7X3002029
5VPCB15L3X3002030
5VPCB15L5X3002031
5VPCB15L7X3002032
5VPCB15L9X3002033
5VPCB15L0X3002034
5VPCB15L2X3002035
5VPCB15L4X3002036
5VPCB15L6X3002037
5VPCB15L8X3002038
5VPCB15LXX3002039
5VPCB15L6X3002040
5VPCB15L8X3002041
5VPCB15LXX3002042
5VPCB15L1X3002043
5VPCB15L0X3002213
5VPCB15L2X3002214
5VPCB15L4X3002215
5VPCB15L6X3002216
5VPCB15L8X3002217
5VPCB15LXX3002218
5VPCB15L1X3002219
5VPCB15L8X3002220
5VPCB15LXX3002221
5VPCB15L1X3002222
5VPCB15L3X3002223
5VPCB15L6X3002224
5VPCB15L7X3002225
5VPCB15L9X3002226

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15L0X3002227
5VPCB15L2X3002228
5VPCB15L4X3002229
5VPCB15L0X3002230
5VPCB15L2X3002231
5VPCB15L4X3002232
5VPCB15L6X3002233
5VPCB15L6X3002234
5VPCB15LXX3002235
5VPCB15L1X3002236
5VPCB15L3X3002237
5VPCB15L5X3002238
5VPCB15L7X3002239
5VPCB15L3X3002240
5VPCB15L5X3002241
5VPCB15L7X3002242
5VPCB15L9X3002243
5VPCB15L0X3002244
5VPCB15L2X3002245
5VPCB15L4X3002246
5VPCB15L6X3002247
5VPCB15L8X3002248
5VPCB15LXX3002249
5VPCB15L6X3002250
5VPCB15L8X3002251
5VPCB15LXX3002252
5VPCB15L2X3002505
5VPCB15L4X3002506
5VPCB15L6X3002507
5VPCB15L8X3002508
5VPCB15LXX3002509
5VPCB15L6X3002510
5VPCB15L8X3002511
5VPCB15LXX3002512
5VPCB15L1X3002513
5VPCB15L3X3002514
5VPCB15L5X3002515
5VPCB15L7X3002516
5VPCB15L9X3002517
5VPCB15L0X3002518
5VPCB15L2X3002519
5VPCB15L9X3002520
5VPCB15L0X3002521
5VPCB15L2X3002522
5VPCB15L4X3002523
5VPCB15L6X3002524
5VPCB15L8X3002525
5VPCB15LXX3002526

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15L1X3002527
5VPCB15L3X3002528
5VPCB15L5X3002529
5VPCB16LXX3002560
5VPCB15L1X3002561
5VPCB16L3X3002562
5VPCB15L5X3002563
5VPCB15L7X3002564
5VPCB15L9X3002565
5VPCB16L0X3002566
5VPCB15L2X3002567
5VPCB15L4X3002568
5VPCB15L6X3002569
5VPCB15L2X3002570
5VPCB15L4X3002571
5VPCB15L6X3002572
5VPCB15L8X3002573
5VPCB15LXX3002574
6VPCB15L3Y3002658
5VPCS15L5Y3002659
5VPCS15L3Y3002692
5VPCS15L5Y3002693
5VPCS15L7Y3002694
5VPCS15L9Y3002695
5VPCS15L0Y3002696
5VPCS15L2Y3002697
5VPCS15L4Y3002698
5VPCS15L6Y3002699
5VPCS15L2Y3002702
5VPCS15L4Y3002703
5VPCS15L6Y3002704
5VPCS15L8Y3002705
5VPCS15LXY3002706
6VPCS15L1Y3002707
5VPCS15L1Y3002710
6VPCS15L5Y3002712
5VPCS15L7Y3002713
6VPCS15L4Y3002720
5VPCS15L6Y3002721
5VPCS15L8Y3002722
5VPCS15LXY3002723
5VPCS15L1Y3002724
5VPCS15L3Y3002725
5VPCB15L7Y3002727
5VPCB15L9Y3002728
5VPCB15L0Y3002729
5VPCB15L7Y3002730
5VPCB15L9Y3002731

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15L0Y3002732
5VPCB15L2Y3002733
5VPCB15L4Y3002734
5VPCB15L6Y3002736
5VPCS15L8Y3002736
5VPCS15LXY3002737
5VPCS15L1Y3002738
5VPCS15L3Y3002739
5VPCS15LXY3002740
5VPCB15L3Y3002742
5VPCS15L5Y3002743
5VPCS15L7Y3002744
5VPCS15L9Y3002745
5VPCS15L0Y3002746
5VPCS15L2Y3002747
5VPCB15L4Y3002748
5VPCS15L6Y3002749
5VPCS15L2Y3002750
5VPCS15L4Y3002751
5VPCS15L6Y3002752
5VPCS15L8Y3002753
5VPCS15LXY3002754
5VPCS15L1Y3002755
5VPCS15L3Y3002756
5VPCS15L5Y3002757
5VPCS15L7Y3002758
5VPCS15L9Y3002759
5VPCS15L5Y3002760
5VPCS15L7Y3002761
5VPCS15L9Y3002762
5VPCS15L0Y3002763
5VPCS15L2Y3002764
5VPCS15L4Y3002765
5VPCS15L6Y3002766
5VPCS15L8Y3002767
5VPCS15LXY3002768
5VPCS15L1Y3002769
5VPCS15L8Y3002770
5VPCB15LXY3002771
5VPCB15L1Y3002772
5VPCB15L3Y3002773
5VPCB15L5Y3002774
5VPCB15L7Y3002775
5VPCB15L9Y3002776
5VPCB15L0Y3002777
5VPCB15L2Y3002778
5VPCB15L4Y3002779
5VPCB15L0Y3002780

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15L2Y3002781
5VPCB15L4Y3002782
5VPCB15L6Y3002783
5VPCS16L613002790
5VPCS15L813002791
5VPCS16LX13002792
5VPCS15L113002793
5VPCD15L513002824
5VPCD15L713002825
5VPCD15L913002826
5VPCD15L613002851
5VPCD15LX13002852
5VPCD15L113002853
5VPCD15L313002854
5VPCD15L513002855
5VPCD15L713002856
5VPCD15L913002857
5VPCB15L9Y3003040
5VPCB15L0Y3003041
5VPCB15L2Y3003042
5VPCB15L4Y3003043
5VPCB15L6Y3003044
5VPCB15L8Y3003045
5VPCB15LXY3003046
5VPCB15L1Y3003047
5VPCB15L3Y3003048
5VPCB15L5Y3003049
5VPCB15L1Y3003050
5VPCB15L3Y3003051
5VPCB15L5Y3003052
5VPCB15L7Y3003053
5VPCB15L9Y3003054
5VPCB15L0Y3003055
5VPCB15L2Y3003056
5VPCB15L4Y3003057
5VPCB15L6Y3003058
5VPCB15L8Y3003059
5VPCB15L4Y3003060
5VPCB15L6Y3003061
5VPCB15L8Y3003062
5VPCB15LXY3003063
5VPCB15L1Y3003064
5VPCB15L3Y3003065
5VPCB15L5Y3003066
5VPCB15L7Y3003067
5VPCB15L9Y3003068
5VPCB15L0Y3003069
5VPCB15L7Y3003070

M.Y. 1999 through 2001 motorcycles assembled from 7-1-98 through 7-25-01
Number of affected vehicles: 9120

Vehicle Identification Numbers
5VPCB15L9Y3003071
5VPCB15L0Y3003072
5VPCB15L2Y3003073
5VPCB15L4Y3003074
5VPCB15L6Y3003075
5VPCB15L8Y3003076
5VPCB15LXY3003077
5VPCB15L1Y3003078
5VPCB16L3Y3003079
5VPCB15LXY3003080
5VPCB15L1Y3003081
5VPCB15L3Y3003082
5VPCB15L5Y3003083
5VPCB15L7Y3003084
5VPCB15L9Y3003085
5VPCB16L0Y3003086
5VPCB15L2Y3003087
5VPCS16L4Y3003088
5VPCS15L6Y3003089
5VPCB16L2Y3003090
5VPCS15L4Y3003091
5VPCS15L6Y3003092
5VPCS15L8Y3003093
5VPCS15LXY3003094
5VPCS15L1Y3003095
5VPCS15L3Y3003096
5VPCS15L5Y3003097
5VPCB15L6X3003575
5VPCB15L8X3003576
5VPCB15LXX3003577
5VPCB15L1X3003578
5VPCB15L3X3003579
5VPCB15LXX3003580
5VPCB15L1X3003581
5VPCB15L3X3003582
5VPCB15L5X3003583
5VPCB15L7X3003584
5VPCB15L9X3003585
5VPCB15L0X3003586
5VPCB15L2X3003587
5VPCB15L4X3003588
5VPCB15L8X3003589
5VPCB15L2X3003590
5VPCB15L4X3003591
5VPCB15L6X3003592
5VPCB15L8X3003593
5VPCB15LXX3003594
5VPCB15L1X3003595