www.nhtsa.gov

This report, updated monthly, is designed to provide you with a summary of active NHTSA Defect Investigations. The investigations listed below are grouped according to type of investigation (Preliminary Evaluation, Engineering Analysis, Recall Query, and Defect/Recall Petition) and identify the products under investigation, the alleged problem, and the investigation status. For up-to-date details on specific investigations, you can enter its Action # in the Quick Search box at: http://www-odi.nhtsa.dot.gov/cars/problems/defect/defectsearch.cfm

If you're having any safety problem with your vehicle, whether or not identified on the list below, please Contact Us today!

July 2015

MONTHLY DEFECT INVESTIGATION REPORT
ENGINEERING ANALYSIS

Action#	MMY	Subject	Date Opened	Date Closed
EA11-005	2004-2005 Mini Cooper	Loss of Power Steering Assist	04-MAY-2011	
EA12-007	1992-2012 MCI D & E Series Buses with Steerable Tag Axle	MCI Driveshaft Safety Loop Failures	13-SEP-2012	
EA14-002	2011-2013 Kia Sorento	Spontaneous Sunroof Breakage	12-MAY-2014	
EA14-004	2008 Honda Accord 4-door	Inadvertent Side Air Bag Deployment	29-JUL-2014	
EA15-001	Various MY 2001-2011 models with Takata air bag inflators	Air Bag Inflator Rupture	24-FEB-2015	
EA15-002	MY2011-13 Fiesta, MY2013 Fusion, Lincoln MKZ	Door Latch Failure	27-FEB-2015	
EA15-003	Nissan Versa Sedan and Versa Note, MY 2013 - 2015	Pedal Operation Interference	01-APR-2015	

MONTHLY DEFECT INVESTIGATION REPORT
PRELIMINARY EVALUATIONS

Action#	MMY	Subject	Date Opened	Date Closed
PE14-020	2014 Freightliner Business Class M2	CNG Fuel System Integrity	07-JUL-2014	
PE14-030	2010-12 Ford Fusion, Lincoln MKZ and 2010-11 Mercury Milan	Loss of electric power assisted steering	02-OCT-2014	
PE14-033	2013 Honda Accord	Electric Power Steering Failure	04-NOV-2014	
PE15-001	2013 Nissan Rogue	Improper Frontal Air Bag Deployment	12-JAN-2015	
PE15-003	MY 2015 Jeep Cherokee	Engine compartment fire	13-JAN-2015	
PE15-005	MY 2014 Stallion 900 Tour Bus	Loss of Windshield Wiper Function	27-FEB-2015	
PE15-006	2014 Autocar ACX/Heil Half/Pack Freedom CNG Refuse Truck	CNG Fuel Container Rupture During A Fire	27-FEB-2015	
PE15-007	2008-2014 LCI RV Three Step Electric Powered Entry Steps	LCI RV Entry Step Failures	27-FEB-2015	
PE15-008	2004 - current Pierce Fire trucks with the TAK-4 suspension	Front suspension ball joint failure	27-FEB-2015	

PE15-009	2012 -2013 Mitsubishi FUSO FEC 52, FEC72 and FEC92 trucks	Extended Stopping Distance	23-MAR-2015	
PE15-010	2012 Volkswagen Passat and CC	Air Bag Clockspring Failure	24-MAR-2015	
PE15-011	2012 Winnebago Sightseer	Entry Step Failures	06-APR-2015	
PE15-012	2012 Subaru Impreza	Passenger Front Air Bag Suppression	10-APR-2015	15-JUL-2015
PE15-013	MY 2012 - 2013 Navistar Prostar Trucks	Accelerator Pedal Fails to Return	17-APR-2015	
PE15-014	2012-14 GL1800	Inconsistent Throttle Response	20-APR-2015	
PE15-015	2015 XG500 and XG750	Inconsistent Throttle Response	20-APR-2015	
PE15-016	2015 Slingshot SL	Sudden Wheel Failure	20-APR-2015	
PE15-017	2015 Ford Explorer Police Interceptor	Front Brake Hose Failure	29-APR-2015	
PE15-018	MY 2013 & 2014 Montana Trailers	Emergency Exit Obstruction	01-MAY-2015	21-JUL-2015
PE15-019	2008 - 2010 Nissan Versa	Front Coil Spring Fracture	13-MAY-2015	
PE15-020	2014 Ford Edge w/Sport Trim 22 inch alloy wheels	Wheel Separation	20-MAY-2015	
PE15-021	MY 2014 Jeep Grand Cherokee	Crash Imminent Braking Malfunction	01-JUN-2015	
PE15-022	2007-2008 Mazda CX-9	Front Suspension Ball Joint Separation	09-JUN-2015	
PE15-023	Fontaine Ultra LT 2011-2014	5th Wheel malfunction	09-JUN-2015	
PE15-024	2013 Dodge Dart	Brake Power Assist Failure	18-JUN-2015	
PE15-025	2007-2012 Jeep Wrangler (left hand drive)	Air Bag Clockspring Wiring Failure	19-JUN-2015	
PE15-026	2011-2012 Ford F-150 equipped with 3.5L GTDI engines	Brake Vacuum Pump Failure	22-JUN-2015	
PE15-027	ARC hybrid air bag inflators	Air Bag Inflator Rupture	13-JUL-2015	

MONTHLY DEFECT INVESTIGATION REPORT
RECALL QUERY

Action#	MMY	Subject	Date Opened	Date Closed
RQ14-001	2002-2003 Jeep Liberty and 2002-2004 Jeep Grand Cherokee	Inadvertent Airbag Deployment	29-MAY-14	
RQ14-004	2012 - 2013 Forest River RVs	Trailer tire may contact floor	10-SEP-14	09-JUL-15
RQ14-005	2011-2012 Ford F-250/350/450/550 with 6.7L Diesel Engines	Exhaust Gas Temperature Sensor	13-JAN-15	
RQ15-001	2013-2014 Various Nissan & Infiniti Models (see list below)	Occupant Classification System Failure	18-MAR-15	
RQ15-002	2006-2014 S2000 and 5500-Series Wheelchair Lifts	School bus wheelchair lift collapse	18-MAR-15	
RQ15-003	2011-2014 Jeep Grand Cherokee and Dodge Durango	Headliner Fires	01-MAY-15	
RQ15-004	MY 2013-2015 Chrysler/Dodge/Jeep/Ram with RA3 or RA4 radios	Software security vulnerability	24-JUL-15	

MONTHLY DEFECT INVESTIGATION REPORT

PETITIONS				
Action#	**MMY**	**Subject**	**Date Opened**	**Date Closed**
DP09-006	2005 - 07 MODEL YEAR BLUE BIRD WANDERLODGE M450 MOTOR HOME	ALLEGED INADEQUATE CAMPAIGN REMEDY	30-NOV-2009	
DP12-004	MY 2005-2010 Nissan Frontier/Xterra/Frontier	Transmission Failure (ATF contamination)	11-JUN-2012	
DP14-001	MY 2008 Chevrolet Impala	Passenger Air Bag OCS Algorithm	22-JUL-2014	
DP14-004	2007-2014 Chrysler light vehicles equipped with TIPM-7	Totally Integrated Power Module Failure	25-SEP-2014	24-JUL-2015
DP15-001	2008 - 2011 Ford Escape, Mercury Mariner	Electric power steering assist failure	01-APR-2015	
DP15-002	2003-2005 Ford Crown Victoria and Mercury Grand Marquis	Loss of headlamp/exterior lighting	01-APR-2015	
DP15-003	2005 Chrysler Crossfire with Convertible Top	Convertible Top Back Glass Separation	17-APR-2015	
DP15-004	2010 Chevrolet Tahoe	Rollover Side Curtain Air Bags	11-JUN-2015	
DP15-005	2009 Lexus ES350	Low-speed surging	09-JUL-2015	

PRELIMINARY EVALUATION (PE)

Initial phase of a NHTSA investigation, a PE is prompted after a review of consumer complaints and/or manufacturer service bulletins suggest a safety defect may exist. The results of a PE determine whether the investigation will be upgraded to an Engineering Analysis or closed. Most PEs are resolved within four months.

ENGINEERING ANALYSIS (EA)

Second and final phase of a NHTSA investigation, an EA is undertaken if data from a PE indicate further examination of a potential safety defect is warranted. The results of an EA determine whether a safety recall should be initiated or the investigation should be closed. Most EAs are resolved within one year.

RECALL QUERY (RQ)

NHTSA monitors recalls to ensure that the scope, completion rate, and remedy are adequate. If recall adequacy comes into question, an RQ is opened to determine if the scope of the recall should be expanded or an adjustment in existing remedies is required.

DEFECT OR RECALL PETITION (DP OR RP)

NHTSA may be petitioned to investigate an alleged safety defect or whether a manufacturer has successfully carried out the requirements of a recall. If the petition is granted, NHTSA opens an appropriate investigation. If the petition is denied, the reasons for denial are published in the Federal Register.

If you have a safety concern or want to learn more...

4 WAYS TO CONTACT US

VISIT:

- www.safercar.gov

CALL:

- 1-888-327-4236

FAX:

- 202-493-2833 (Download complaint form , fill out and fax).

WRITE:

- National Highway Traffic Safety Administration
  Office of Defects Investigations/CRD NVS-216
  1200 New Jersey Ave SE
  Washington, DC 20590