MACK TRUCKS, INC.

QUARTERLY REPORT DEFECT NOTIFICATION CAMPAIGNS
QUARTER ENDING DECEMBER 19, 2002

PERIOD	CAMPAIGN			CUSTOMER NOTIFICATION	NUMBER OF VEHICLES					VEHICLES UNREACHABLE DUE TO			
	NHTSA NUMBER	MACK CAMPAIGN NUMBER	TITLE	START/END	VEHICLES INVOLVED	REMEDIED PRIOR TO SALE	VEHICLES INSPECTED	CORRECTED	NOT NEEDING CORRECTION	SCRAPPED	EXPORTED	THEFT	NOTICE UNDELIVERED
6	01V-44-207	265	Drag Links - 24-DL	07/13/2001	4116		2311	2311		2	336	1	7
6	01V-44-107	266	TRW Tie Rod Ends - 24-DL	07/13/2001	1378		735	735			77		3
5	01V-189.004	267	Haldex Relay Valves	11/16/2001	6298		6056	6056		1	1137	2	79
6	01V-301	268	Front Axle Springs	12/29/2001	461		405	405			12		
5	01V-140-005	270	Tie Rod Ends	12/17/2001	10818		5731	5731		7	984	1	55
3	01V-389	271	Aux Shaft Nut	03/22/2002	6028		3992	3992		1	1007	1	19
3	02V-019	272	Hi Pressure P/S Hose	03/21/2002	853		489	489			113		
3	02V-061.002	273	Chalmers Tower Rpr Bkt	04/22/2002	215		42	42			97		
2	02V-018.006	274	ABS Modulator Valve	08/13/2002	83		55	55			19		1
1	02V-156	275	AWD Headlight Height	10/04/2002	40						2		
0	02V-037.006	276	Meritor Ball Sockets	12/27/02	2734		0	0			151		
0	02V-269	277	Park Brake Hill Hold		544						11		
2	02V-216	278	P/S Hoses	06/20/2002	690	592	77	77			6		

1202rfns.xls
1202SC US quarterly
DM
01/30/2003