Mitubishi Motor Sales
Quarterly Campaign Report
Federal Regulation 573.6

Qtr Ending: 3/31/02

MMSA Recall Number	Par. (b)(1) NHTSA Recall Number	Par. (b)(2) Owner Notification Date Began	Par. (b)(2) Owner Notification Date Completed	Par. (b)(3) Total No. of Vehicles Involved	Par. (b)(4) Vehicles Inspected and Repaired	Par. (b)(4) Vehicles Inspected Not Needing Repair	Par. (b)(5) Unreachable Vehicles: Vehicles Exported	Vehicles Stolen	Vehicles Scrapped	Notification Undeliverable	Sold or Traded	Total Unreachable
SR-00-005 Front Brake Hose	00V-228	9/20/00	09/20/00	344	152	0	0	2	23	20	5	44
	Remodification Completed on 11/25/02											
*SR-00-007 Crankshaft Pulley Bolt	00V-311	10/31/00	10/31/00	82,000	45,780	0	2	14	377	10,925	1,117	12,435
	Remodification Completed on 8/29/02											
*SR-01-002 Crankshaft Pulley Bolt	00V-311	1/15/01	1/15/01	128,000	76,556	0	294	79	216	20,178	2,319	23,086
	Remodification Completed on 9/23/02											
SR-01-003 Hydraulic Brake Booster	01V-254	10/1/01	11/8/01	38,020	33,240	0	1	4	6	1,175	137	1,323
SR-01-009 Power Steering Oil Feed Tube	01V-288.001	11/21/01	11/21/01	28,803	16,814	0	0	2	16	1,218	136	1,369
SR-01-010 Crankshaft Pulley Bolt	01V-340.001	11/28/01	11/28/01	18,830	10,383	0	0	4	63	2,887	173	3,127
	Remodification Completed on 10/21/02											
SR-02-001 Wiring Harness	02V-100	5/13/02	5/13/02	3,885	3,886	0	0	0	1	68	0 0	69
SR-02-002 Front Harness	02V-147	7/8/02	7/8/02	3,378	1,925	0	0	0	0	107	0	107
SR-02-003 Transfer Case	02V-143.001	12/9/02	12/18/02	16,224	3,559	0	4	2	21	1,780	289	2,096
SR-03-001 Throttle Valve	03V-028	1/29/03	1/29/03	31,000	21,709	0	0	0	0	0	0	0

Added Together

*Please add SR-00-007 and SR-01-002 together to calculate the results for 00V-311