Form Approved: O.M.B. No. 2-27-0028

U.S. Department of Transportation
National Highway Traffic Safety Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT
1-888-327-4236
www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 234	
Date Received 10-AUG-2000	Od_or ____ ____ rt_dt ____ ____ od_rt ____ ____ up_ltr ____ ____
	Reference No. 867364

[redacted]

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date___/___/___

VEHICLE INFORMATION

Vehicle Ident. No. (VIN.) (Located at bottom of windshield on driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
	FIRESTONE	WILDERNESS AT	1900	

Purchase Date	Dealer's Name	Engine Size (CID/CC/L	☐ Turbo
☒ New ☐ Used	City_____ State_____ Zip Code_____	No Cylinders	☐ Diesel ☐ Gas ☐ Fuel Injection

Transmission Type	Antilock Brakes	Restraint System	Cruise Control	Drive Train	Vehicle Type	Body Style
☐ Manual ☐ Automatic	☐ Yes ☒ No	☐ 3-Point Belt ☐ Driverside Airbag ☐ Passengerside Airbag ☐ Motorbelt ☐ 2-Point Belt	☐ Yes ☒ No	☐ Front ☐ Rear ☐ 4-Wheel	☐ Car ☐ Van ☐ Minivan ☐ Other_____ ☐ Sport Utl ☐ Truck ☐ Motorcycle	☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other_____

FAILED COMPONENT(S)/PART(S) INFORMATION

Component	Part Name(s)	Location	Failed Part(s)
02740000	TIRES: TREAD	☐ Left ☐ Right ☐ Front ☐ Rear	☐ Original ☐ Replacement

No of Failures	Dates) of Failure(s) / Mileage at Failure(s) / Vehicle Speed at Failure(s)	Failed Part(s) Available?	NHTSA Previously Contacted?
	01-JAN-2000 65	☐ Yes ☐ No	☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash	Fire	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police
☐ Yes ☒ No	☐ Yes ☒ No	1	1		☐ Yes ☒ No

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

FIRESTONE TIRE ORIGINAL EQUIPMENT ON A 97 MOUNTAINEER P235/75R15 DOT: VDHL1PY147. WHILE DRIVING 60-65MPH THE TREAD ON THE LEFT REAR TIRE SEPERATED CAUSING THE VEHICLE TO ROLLOVER. THE PASSENGER WAS EJECTED FROM THE VEHICLE AND KILLED. THE DRIVER SUSTAINED INJURIES. VEHICLE REGISTERED TO: ERIK KENT

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.