MACK TRUCKS, INC.

QUARTERLY REPORT DEFECT NOTIFICATION CAMPAIGNS
QUARTER ENDING DECEMBER 19, 2002

PERIOD	CAMPAIGN			CUSTOMER NOTIFICATION	NUMBER OF VEHICLES					VEHICLES UNREACHABLE DUE TO			
	NHTSA NUMBER	MACK CAMPAIGN NUMBER	TITLE	STARTED	VEHICLES INVOLVED	REMEDIED PRIOR TO SALE	VEHICLES INSPECTED	CORRECTED	NOT NEEDED CORRECTION	SCRAPPED	EXPORTED	THEFT	NOTICE UNDELIVERED
6	01V-44-207	265	Drag Links - 24-DL	07/13/2001	4116		2311	2311		2	336	1	7
6	01V-44-107	266	TRW Tie Rod Ends - 24-DL	07/13/2001	1379		735	735			77		3
5	01V-189.004	267	Haldex Relay Valves	11/16/2001	5295		5056	5056		1	1137	2	79
5	01V-301	269	Front Axle Springs	12/26/2001	481		406	406			12		
5	01V-140-005	270	Tie Rod Ends	12/17/2001	10919		5731	5731		7	984	1	56
3	01V-359	271	Aux Shaft Nut	03/22/2002	6028		5992	5992		1	1007	1	19
3	02V-019	272	Hi Pressure P/S Hose	03/21/2002	583		489	489			113		
3	02V-061.002	273	Chalmers Tower Rpr Bkt	04/22/2002	213		42	42			97		
2	02V-016.006	274	ABS Modulator Valve	06/13/2002	93		56	56			18		1
1	02V-168	275	AWD Headlight Height	10/04/2002	40						2		
0	02V-037.009	276	Mirror Ball Sockets	12/27/02	2734		0	0			151		
0	02V-289	277	Park Brake Hill Hold		544						11		
2	02V-216	278	P/S Hoses	06/20/2002	660	582	77	77			6		

1202nhtsa.xls
12cmsC LB quarterly
DM
01/30/2003