MACK TRUCKS, INC.

QUARTERLY REPORT DEFECT NOTIFICATION CAMPAIGNS
QUARTER ENDING DECEMBER 19, 2002

PERIOD	CAMPAIGN			CUSTOMER NOTIFICATION	NUMBER OF VEHICLES					VEHICLES UNREACHABLE DUE TO			
	NHTSA NUMBER	MACK CAMPAIGN NUMBER	TITLE	START/END	VEHICLES INVOLVED	REMEDIED PRIOR TO SALE	VEHICLES INSPECTED	CORRECTED	NOT NEEDING CORRECTION	SCRAPPED	EXPORTED	THEFT	NOTICE UNDELIVERED
6	01V-44-207	265	Drag Links - 24-DL	07/13/2001	4116		2311	2311		2	336	1	7
6	01V-44-107	268	TRW Tie Rod Ends - 24-DL	07/13/2001	1379		735	735			77		3
5	01V-189.004	267	Haldex Relay Valves	11/16/2001	8296		6058	6058		1	1137	2	79
5	01V-301	269	Front Axle Springs	12/26/2001	481		405	405			12		
6	01V-140-008	270	Tie Rod Ends	12/17/2001	10818		5731	5731		7	984	1	58
3	01V-369	271	Aux Shaft Nut	03/22/2002	6628		3892	3892		1	1007	1	19
3	02V-019	272	Hi Pressure P/S Hose	03/21/2002	863		489	489			113		
3	02V-061.002	273	Chalmers Tower Rpr Bkt	04/22/2002	213		42	42			87		
2	02V-018.008	274	ABS Modulator Valve	06/13/2002	93		55	55			19		1
1	02V-158	275	AWD Headlight Height	10/04/2002	40						2		
0	02V-037.008	276	Monitor Ball Sockets	12/27/02	2734		0	0			161		
0	02V-269	277	Park Brake Hill Hold		844						11		
2	02V-218	278	P/S Hoses	06/20/2002	690	592	77	77			8		

1202nhts.xls
1202SC US quarterly
DM
01/30/2003