MITSUBISHI MOTORS

Mitsubishi Motors North America, Inc.
6400 Katella Avenue
Cypress, CA 90630
Telephone: 714-372-6000
www.mitsubishicars.com

JUL 22 2009
RECEIVED

July 20, 2009

Kathleen DeMeter, Esq.
Director, Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave. SE
Washington, D.C. 20590

Dear Ms. DeMeter:

Subject: Quarterly Campaign Progress Report – 2nd Quarter 2009

Attached is the Quarterly Campaign Progress Report prepared in accordance with Federal Regulation 573.6 for the calendar quarter April 1 through June 30, 2009 (2nd Quarter 2008).

If you have any questions concerning this report, please do not hesitate to contact me directly during normal business hours.

Sincerely,

Sharon Kaplan

Sharon Kaplan
Sr. Specialist, Technical Compliance
Mitsubishi Motors North America, Inc.
Telephone: (714) 372-6148
Fax: (714) 934-4202
E-mail: skkaplan@mmsa.com

cc: Kelly Schuler (Email)

Enclosure

MMNA 2nd Quarter 2009
Campaign Progress Report

NHTSA Recall Number	MMNA Recall Number	Campign Name	Owner Notification Start	Owner Notification End	Total Number of Vehicles Involved	Number Vehicles inspected and Repaired	Number Vehicles inspected not needing Repair	Vehicles Exported	Vehicles Stolen	Vehicles Scrapped	Notification Undeliverable	Sold or Traded	Quarters Reported
08V022	SR-08-001	Endeavor Seat Belt	17-Mar-08	17-Mar-08	7,340	5,488	NA	0	0	28	392	78	6
08V094	SR-08-002	Outlander Floor Harness	7-Apr-08	7-Apr-08	5,400	5,189	NA	0	0	16	157	196	6
08V139	SR-08-003	Endeavor Shift Interlock	7-Jul-08	7-Jul-08	112,405	56,126	NA	0	0	546	4,185	660	4
08V276	SR-08-004	Galant Shift Interlock	2-Sep-08	2-Sep-08	69,926	25,239	NA	0	0	787	4,025	306	4
08V454	SR-08-005	Fuel Tank Bracket	30-Sep-08	30-Sep-08	45,988	721	22,063	0	0	339	1,600	250	4
08V680	SR-09-001	Outlander Stop Lamp Switch	24-Feb-09	24-Feb-09	19,852	11,366	NA	0	0	46	627	67	2
09V077	SR-09-002	Lancer/Outlander Brake Booster Check Valve	5-May-09	5-May-09	48,844	23,757	NA	0	0	104	1,887	118	1