Vehicle Safety Recall Quarterly Report Information[1]

Required per 49 CFR Part 573.6

Report Date: 10 JUL 2000 Calendar Quarter: 2ND QTR - 2000

Safety Recall Quarterly Report from 2 JUNE 2000 through 6/30/00

Manufacturer: TRIUMPH MOTORCYCLES (AMER) LTD

Report Author: SHELL BARR Phone: (770) 631-9500

Recall Subject: TT600 SPRAG-TO-ROTOR BOLTS

1. NHTSA Safety Recall Campaign Number: 00V-158

   Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 01221199

2. (a) The date notification to purchasers began: 2 JUNE 2000

   (b) The date notification of purchasers was completed: N/A.

3. The Total Number of Vehicles Involved: 763
   The total number of vehicles involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

4. (a) Total Number Inspected & Remedied: 23
   Total number of vehicles which were inspected and/or otherwise repaired or remedied.

   (b) Total Number Inspected & NOT REQUIRING REMEDY: N/A
   Total number of vehicles involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Vehicles Determined to be Unreachable

Total Number Exported: N/A

Total Number Stolen: N/A

Total Number Scrapped: N/A

Total Number Unable to Notify: 3

Total Number Otherwise Unreachable: N/A.

Describe Other: _____

---

[1]Any Questions please contact Mrs. Kelly Schuler or Mr. Jon White at (202) 366-5227 or by FAX at (202) 366-7882.

Vehicle Safety Recall Quarterly Report Information[1]

Required per 49 CFR Part 573.6

Report Date: 3 OCT 2000 Calendar Quarter: 3RD QUAR - 2000

Safety Recall Quarterly Report from 2 JUN 2000 through SEP 2000

Manufacturer: TRIUMPH MOTORCYCLES (AMER) LTD

Report Author: STEVE BELL Phone: 779 631-9500

Recall Subject: T602 SPEED-TO-ROTOR BOLTS

1. NHTSA Safety Recall Campaign Number: 00V-158

   Also, for completeness if your company has assigned a code number to this campaign, please provide your code: 021199

2. (a) The date notification to purchasers began: 2 JUNE 2000

   (b) The date notification of purchasers was completed: SAME

3. The Total Number of Vehicles Involved: 763
   The total number of vehicles involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and dealer outside beyond the immediate control of the manufacturer/importer).

4. (a) Total Number Inspected & Remedied: 274
   Total number of vehicles which were inspected and/or otherwise repaired or remedied.

   (b) Total Number Inspected & NOT REQUIRING REMEDY: N/A
   Total number of vehicles involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Vehicles Determined to be Unreachable:

Total Number Exported: N/A

Total Number Stolen: N/A

Total Number Scrapped: N/A

Total Number Unable to Notify: 3

Total Number Otherwise Unreachable: N/A

Describe Other: _____

[1]Any Questions please contact Mrs. Kelly Schuler or Mr. Jon White at (202) 366-5227 or by FAX at (202) 366-7882.

Vehicle Safety Recall Quarterly Report Information[1]

Required per 49 CFR Part 573.6

Report Date: 4 JAN '01 Calendar Quarter: 4TH QTR 2000

Safety Recall Quarterly Report from _____ through _____

Manufacturer: TRIUMPH MOTORCYCLES (AMER) LTD.

Report Author: SHELL BARR Phone: (770) 631-9500 x 3320

Recall Subject: TT 600 SPRAG-TO-ROTOR BOLTS

1. NHTSA Safety Recall Campaign Number: 00V-158

   Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 01221199

2. (a) The date notification to purchasers began: 2 JUNE 2000

   (b) The date notification of purchasers was completed: SAME

3. The Total Number of Vehicles Involved: 763
   The total number of vehicles involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

4. (a) Total Number Inspected & Remedied: 382
   Total number of vehicles which were inspected and/or otherwise repaired or remedied.

   (b) Total Number Inspected & NOT REQUIRING REMEDY: N/A
   Total number of vehicles involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Vehicles Determined to be Unreachable

Total Number Exported: N/A

Total Number Stolen: N/A

Total Number Scrapped: N/A

Total Number Unable to Notify: 3

Total Number Otherwise Unreachable: N/A

Describe Other: _____

---

[1]Any Questions please contact Mrs. Kelly Schuler or Mr. Jon White at (202) 366-5227 or by FAX at (202) 366-7882.

Vehicle Safety Recall Quarterly Report Information[1]

Required per 49 CFR Part 573.6

Report Date: 4 APR 2001 **Calender Quarter:** 1ST QTR - 2001

Safety Recall Quarterly Report from 6/2/00 **through** 3-31-01

Manufacturer: TRIUMPH MOTORCYCLE (AMER) LTD

Report Author: SHELL BAER **Phone:** (678) 854-2010 x 2060

Recall Subject: TT600 SPRAG TO ROTOR BOLTS

1. **NHTSA Safety Recall Campaign Number:** DOV-158

   Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 01221199

2. **(a) The date notification to purchasers began:** 2 JUNE 2000

   (b) The date notification of purchasers was completed: SAME

3. **The Total Number of Vehicles Involved:** 763
   The total number of vehicles involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

4. **(a) Total Number Inspected & Remedied:** 470
   Total number of vehicles which were inspected and/or otherwise repaired or remedied.

   (b) Total Number Inspected & NOT REQUIRING REMEDY: N/A
   Total number of vehicles involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Vehicles Determined to be Unreachable

Total Number Exported: N/A

Total Number Stolen: N/A

Total Number Scrapped: N/A

Total Number Unable to Notify: 3

Total Number Otherwise Unreachable: N/A

Describe Other: _____

[1]Any Questions please contact Mrs. Kelly Schuler or Mr. Jon White at (202) 366-5227 or by FAX at (202) 366-7882.

Vehicle Safety Recall Quarterly Report Information[1]

Report Date: 10 July 2001 Calendar Quarter: 2nd Qtr - 2001

Safety Recall Quarterly Report from 4/00 through 6/31/01

Manufacturer: Triumph Motorcycles (Amer.) Ltd.

Report Author: Shell Baer Phone: 1 678-854-2010

Recall Subject: TT600 Speak-to-Rotor Bolts

1. NHTSA Safety Recall Campaign Number: ODV-158

   Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 01221159

2. (a) The date notification to purchasers began: 2 June 2000

   (b) The date notification of purchasers was completed: Sept

3. The Total Number of Vehicles Involved: 763
   The total number of vehicles involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

4. (a) Total Number Inspected & Remedied: 498
   Total number of vehicles which were inspected and/or otherwise repaired or remedied.

   (b) Total Number Inspected & NOT REQUIRING REMEDY: N/A
   Total number of vehicles involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Vehicles Determined to be Unreachable:

Total Number Exported: N/A

Total Number Stolen: N/A

Total Number Scrapped: N/A

Total Number Unable to Notify: 3

Total Number Otherwise Unreachable: N/A

Describe Other: _____

---

[1]Any Questions please contact Mrs. Kelly Schuler or Mr. Jon White at (202) 366-5227 or by FAX at (202) 366-7882.

Vehicle Safety Recall Quarterly Report Information[1]

Required per 49 CFR Part 573.6

Report Date: 2 Oct '01 Calendar Quarter: 3RD QTR - '01

Safety Recall Quarterly Report from 6-2000 through 9-2001

Manufacturer: TRIUMPH MOTORCYCLES (AMER) LTD

Report Author: SHELL BARR Phone: 1 678-854-2010

Recall Subject: TT600 SPRAG-TO-ROTOR BOLTS

1. NHTSA Safety Recall Campaign Number: 00V-15B

   Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 01221199

2. (a) The date notification to purchasers began: 2 JUNE 2000

   (b) The date notification of purchasers was completed: SAME

3. The Total Number of Vehicles Involved: 763
   The total number of vehicles involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

4. (a) Total Number Inspected & Remedied: 513
   Total number of vehicles which were inspected and/or otherwise repaired or remedied.

   (b) Total Number Inspected & NOT REQUIRING REMEDY: -0-
   Total number of vehicles involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Vehicles Determined to be Unreachable

Total Number Exported: N/A

Total Number Stolen: N/A

Total Number Scrapped: N/A

Total Number Unable to Notify: 3

Total Number Otherwise Unreachable: N/A

Describe Other: _____

[1]Any Questions please contact Mrs. Kelly Schuler or Mr. Jon White at (202) 366-5227 or by FAX at (202) 366-7882.

Vehicle Safety Recall Quarterly Report Information[1]

Required per 49 CFR Part 573.6

Report Date: 4 JAN 2002 Calendar Quarter: 4TH QTR -2001

Safety Recall Quarterly Report from 6-2000 through 12-2001

Manufacturer: TRIUMPH MOTORCYCLES (AMER) LTD

Report Author: SHELL BAER Phone: 678 854-2010 X 2060

Recall Subject: T100 SPEAK-TO-ROTOR BOLTS

1. NHTSA Safety Recall Campaign Number: 00V-158

   Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 01221195

2. (a) The date notification to purchasers began: 2 JUNE 2000

   (b) The date notification of purchasers was completed: SAME

3. The Total Number of Vehicles Involved: 763
   The total number of vehicles involved in the subject campaign (including all those sold or distributed to purchasers, dealers, distributors, and dealer outlets beyond the importation control of the manufacturer/importer).

4. (a) Total Number Inspected & Remedied: 513
   Total number of vehicles which were inspected and/or otherwise repaired or remedied.

   (b) Total Number Inspected & NOT REQUIRING REMEDY: 0
   Total number of vehicles involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Vehicles Determined to be Unreachable

Total Number Exported: N/A

Total Number Stolen: N/A

Total Number Scrapped: N/A

Total Number Unable to Notify: 3

Total Number Otherwise Unreachable: N/A

Describe Other: _____

[1]Any Questions please contact Mrs. Kelly Schuler or Mr. Jon White at (202) 366-5227 or by FAX at (202) 366-7882.

Vehicle Safety Recall Quarterly Report Information[1]

Required per 49 CFR Part 573.6

Report Date: 1 APR 2002 Calendar Quarter: 1ST QTR - 2002

Safety Recall Quarterly Report from 6-2000 through 3-2002

Manufacturer: TRIUMPH MOTORCYCLES (AMER) LTD.

Report Author: SHELL BARR Phone: 678 854-2010 x 2060

Recall Subject: T600 SPRAG TO - ROTOR BOLT

1. NHTSA Safety Recall Campaign Number: 00V-158

   Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 01221199

2. (a) The date notification to purchasers began: 2 JUNE 2000

   (b) The date notification of purchasers was completed: SAME

3. The Total Number of Vehicles Involved: 763
   The total number of vehicles involved in the subject campaign (including all those sold or distributed to purchasers, dealers, distributors, and dealer vehicles beyond the immediate control of the manufacturer/importer).

4. (a) Total Number Inspected & Remedied: 517 +4
   Total number of vehicles which were inspected and/or otherwise repaired or remedied.

   (b) Total Number Inspected & NOT REQUIRING REMEDY: 0
   Total number of vehicles involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Vehicles Determined to be Unreachable

Total Number Exported: N/A

Total Number Stolen: N/A

Total Number Scrapped: N/A

Total Number Unable to Notify: 3

Total Number Otherwise Unreachable: N/A

Describe Other:

---

[1]Any Questions please contact Mrs. Kelly Schuler or Mr. Jon White at (202) 366-5227 or by FAX at (202) 366-7882.

Vehicle Safety Recall Quarterly Report Information[1]

Required per 49 CFR Part 573.6

Report Date: 2 JULY 2002 Calendar Quarter: 2ND QTR - 02

Safety Recall Quarterly Report from 6-2000 through 6-2002

Manufacturer: TRIUMPH MOTORCYCLES (AMER.) LTD

Report Author: SHELL BELL Phone: 1 678-854-2010

Recall Subject: T100 SPRING TO ROTOR BOLTS

1. NHTSA Safety Recall Campaign Number: 00V-158

   Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 01221199

2. (a) The date notification to purchasers began: 2 JUNE 2000

   (b) The date notification of purchasers was completed: SAME

3. The Total Number of Vehicles Involved: 763
   The total number of vehicles involved in the subject campaign (including all those sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

4. (a) Total Number Inspected & Remedied: 524
   Total number of vehicles which were inspected and/or otherwise repaired or remedied.

   (b) Total Number Inspected & NOT REQUIRING REMEDY: 0
   Total number of vehicles involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Vehicles Determined to be Unreachable

Total Number Exported: N/A

Total Number Stolen: N/A

Total Number Scrapped: N/A

Total Number Unable to Notify: 3

Total Number Otherwise Unreachable: N/A

Describe Other:

[1]Any Questions please contact Mrs. Kelly Schuler or Mr. Jon White at (202) 366-5227 or by FAX at (202) 366-7882.