VOLVO

00V-246. 306

573.6 (b) (1) NHTSA Recall Campaign No. Not Available

VOLVO TRUCKS NORTH AMERICA, INC. RECALL NO. RVXX0004

Title of Recall: TRW Steering Assist Cylinder Ball Socket

573.6 (b) (2) Notification Date:

Began: 11-13-2000

Completed: 11-16-2000

573.6 (b) (3) Number of Vehicles involved in the Notification: 730

	REPORTING QUARTER					
	DEC00 1	2	3	4	5	6
573.6 (b) (4) Correction:						
Inspected and repaired:	59					
Inspected and no repair required:	39					
573.5 (b) (5) Unreachable due to:						
Export	76					
Theft	0					
Scrapped	0					
Address Unknown	0					
Other	0					
TOTAL	250					

VOLVO

573.6 (b) (1) NHTSA Recall Campaign No. 00V-246.306

VOLVO TRUCKS NORTH AMERICA, INC. RECALL NO. RVXX0004

Title of Recall: TRW Steering Assist Cylinder Ball Socket

573.6 (b) (2) Notification Date:

Began: 11-13-2000

Completed: 11-16-2000

573.6 (b) (3) Number of Vehicles Involved in the Notification: 730

REPORTING QUARTER

	DEC00 1	MAR01 2	3	4	5	6
573.6 (b) (4) Correction:						
Inspected and repaired:	59	227				
Inspected and no repair required:	39	84				
573.5 (b) (5) Unreachable due to:						
Export	75	76				
Theft	0	0				
Scrapped	0	3				
Address Unknown	0	0				
Other	0	0				
TOTAL	250	390				

VOLVO

573.6 (b) (1) NHTSA Recall Campaign No. 00V-246.306

VOLVO TRUCKS NORTH AMERICA, INC. RECALL NO. RVXX0004

Title of Recall: TRW Steering Assist Cylinder Ball Socket

573.6 (b) (2) Notification Date:

Began: 11-13-2000

Completed: 11-16-2000

573.6 (b) (3) Number of Vehicles Involved in the Notification: 730

	REPORTING QUARTER					
	DEC00 1	MAR01 2	JUN01 3	4	5	6
573.6 (b) (4) Correction:						
Inspected and repaired:	59	227	296			
Inspected and no repair required:	39	84	103			
573.5 (b) (5) Unreachable due to:						
Export	75	78	76			
Theft	0	0	0			
Scrapped	0	3	3			
Address Unknown	0	0	0			
Other	0	0	1			
TOTAL	250	390	479			

VOLVO

573.6 (b) (1) NHTSA Recall Campaign No. 00V-246.306

VOLVO TRUCKS NORTH AMERICA, INC. RECALL NO. RVXX0004

Title of Recall: TRW Steering Assist Cylinder Ball Socket

573.6 (b) (2) Notification Date:

Began: 11-13-2000

Completed: 11-16-2000

573.6 (b) (3) Number of Vehicles Involved in the Notification: 730

	REPORTING QUARTER					
	DEC00 1	MAR01 2	JUN01 3	SEP 01 4	5	6
573.6 (b) (4) Correction:						
Inspected and repaired:	59	227	296	332		
Inspected and no repair required:	39	84	103	116		
573.5 (b) (5) Unreachable due to:						
Export	76	76	76	76		
Theft	0	0	0	0		
Scrapped	0	3	3	3		
Address Unknown	0	0	0	0		
Other	0	0	1	1		
TOTAL	250	390	479	528		

VOLVO

573.6 (b) (1) NHTSA Recall Campaign No. 00V-246.306

VOLVO TRUCKS NORTH AMERICA, INC. RECALL NO. RVXX0004

Title of Recall: TRW Steering Assist Cylinder Ball Socket

573.6 (b) (2) Notification Date:

Began: 11-13-2000

Completed: 11-16-2000

573.6 (b) (3) Number of Vehicles Involved in the Notification: 730

	REPORTING QUARTER					
	DEC00 1	MAR01 2	JUN01 3	SEP 01 4	DEC01 5	6
573.6 (b) (4) Correction:						
Inspected and repaired:	59	227	296	332	344	
Inspected and no repair required:	39	84	103	116	120	
573.5 (b) (5) Unreachable due to:						
Export	76	76	76	76	76	
Theft	0	0	0	0	0	
Scrapped	0	3	3	3	3	
Address Unknown	0	0	0	0	0	
Other	0	0	1	1	1	
TOTAL	250	[illegible]	479	528	544	

I:\LEGAL\STAFF\CHUCK\RECALL\NHTSA.DOC

VOLVO

573.6 (b) (1) NHTSA Recall Campaign No. 00V-246.306

VOLVO TRUCKS NORTH AMERICA, INC. RECALL NO. RVXX0004

Title of Recall: TRW Steering Assist Cylinder Ball Socket

573.6 (b) (2) Notification Date:

Began: 11-13-2000

Completed: 11-16-2000

573.6 (b) (3) Number of Vehicles Involved in the Notification: 730

	REPORTING QUARTER					
	DEC00 1	MAR01 2	JUN01 3	SEP 01 4	DEC01 5	MAR02 6
573.6 (b) (4) Correction:						
Inspected and repaired:	59	227	296	332	344	355
Inspected and no repair required:	39	84	103	116	120	132
573.5 (b) (5) Unreachable due to:						
Export	76	76	76	76	76	76
Theft	0	0	0	0	0	0
Scrapped	0	3	3	3	3	3
Address Unknown	0	0	0	0	0	0
Other	0	0	1	1	1	0
TOTAL	250	390	479	528	544	566