MACK TRUCKS, INC.

QUARTERLY REPORT DEFECT NOTIFICATION CAMPAIGNS
QUARTER ENDING DECEMBER 21, 2000

PERIOD	CAMPAIGN			CUSTOMER NOTIFICATION	NUMBER OF VEHICLES					VEHICLES UNREACHABLE DUE TO			
	NHTSA NUMBER	MACK CAMPAIGN NUMBER	TITLE	STARTEND	VEHICLES INVOLVED	PERMITTED PRIOR TO SALE	VEHICLES INSPECTED	CORRECTED	NOT NEEDING CORRECTION	SCRAPPED	EXPORTED	THEFT	NOTICE UNDELIVERED
7	99V-014	257	Front Axle Wheel Bearings	04/23/1999	6025		5083	5081			984	2	19
3	00V-024	258	CX Headlamp Label	03/16/2000	761		205	204			116	1	1
2	00V-019.00	259	Fontaine Fifth Wheel	06/22/2000	43		5	5					1
1	00V-232.00	260	Bendix ABS ECU	01/12/2001	651								
1	00V-230.00	264	Felsted Throttle Pedal Spring	12/13/2000	49252	3386	1751	1744		6	4303	1	2
1	00V-246-00	262	TRW Tie Rod Ends	12/13/2000	6244		56	56			562		1
1	00V-308	263	MS200-Steering Gear Torque	11/27/2000	34		2	2					

1200ahts.xls
1200SC US quarterly
DM
02/07/2001

MACK TRUCKS, INC.

QUARTERLY REPORT DEFECT NOTIFICATION CAMPAIGNS
QUARTER ENDING MARCH 27, 2001

PERIOD	CAMPAIGN			CUSTOMER NOTIFICATION	NUMBER OF VEHICLES					VEHICLES UNREACHABLE DUE TO			
	[illegible]	MACK CAMPAIGN NUMBER	TITLE	STARTED	VEHICLES INVOLVED	REMEDIED PRIOR TO SALE	VEHICLES INSPECTED	CORRECTED	NOT NEEDING CORRECTION	SCRAPPED	EXPORTED	THEFT	NOTICE UNDELIVERED
5	99V-014	257	Front Axle Wheel Bearings	04/23/1999	5025		5138	5138			864	2	19
4	00V-024	258	CX Headlamp Label	03/15/2000	761		248	248			116	1	1
3	00V-019.00	259	Fontaine Fifth Wheel	05/22/2000	43		5	5			0		1
2	00V-232.00	260	Bendix ABS ECU	01/12/2001	651		6	6			0		
2	00V-230.00	261	Folded Throttle Pedal Spring	12/13/2000	49252	3368	10162	10149		12	4316	2	2
2	00V-246-00	262	TRW Tie Rod Ends	12/13/2000	8244		1659	1659		1	692		1
2	00V-266	263	MS300-Steering Gear Torque	11/27/2000	34		14	14					

[illegible]
[illegible] US quarterly
[illegible]
04/[illegible]

MACK TRUCKS, INC.

QUARTERLY REPORT DEFECT NOTIFICATION CAMPAIGNS
QUARTER ENDING JUNE 30, 2001

PERIOD	CAMPAIGN			CUSTOMER NOTIFICATION	NUMBER OF VEHICLES					VEHICLES UNREACHABLE DUE TO			
	NHTSA NUMBER	MACK CAMPAIGN NUMBER	TITLE	STARTED	VEHICLES INVOLVED	REMEDIED PRIOR TO SALE	VEHICLES INSPECTED	CORRECTED	NOT NEEDING CORRECTION	SCRAPPED	EXPORTED	THEFT	NOTICE UNDELIVERED
5	00V-024	258	CX Headlamp Label	03/16/2000	761		298	298			118	1	1
4	00V-019.00	259	Fontaine Fifth Wheel	06/22/2000	43		5	5			0		1
3	00V-232.00	260	Bendix ABS ECU	01/12/2001	551		63	63			0		
3	00V-230.00	261	Felsted Throttle Pedal Sprit___	12/13/2000	49252	3388	22118	22118		12	4323	2	2
3	00V-246-00	262	TRW Tie Rod Ends	12/13/2000	6244		3139	3139		1	682		1
3	00V-308	263	MS200-Steering Gear Torq	11/27/2000	34		17	17					

MACK TRUCKS, INC.

QUARTERLY REPORT DEFECT NOTIFICATION CAMPAIGNS
QUARTER ENDING SEPTEMBER 25, 2001

PERIOD	CAMPAIGN: MVSA NUMBER	CAMPAIGN: MACK CAMPAIGN NUMBER	CAMPAIGN: TITLE	CUSTOMER NOTIFICATION: SCHEDULED	NUMBER OF VEHICLES: VEHICLES INVOLVED	NUMBER OF VEHICLES: REMEDIED PRIOR TO SALE	NUMBER OF VEHICLES: VEHICLES INSPECTED	NUMBER OF VEHICLES: CORRECTED	NUMBER OF VEHICLES: NOT NEEDING CORRECTION	VEHICLES UNREACHABLE DUE TO: SCRAPPED	VEHICLES UNREACHABLE DUE TO: EXPORTED	VEHICLES UNREACHABLE DUE TO: THEFT	VEHICLES UNREACHABLE DUE TO: NOTICE UNDELIVERED
6	00V-024	259	CX Headlamp Label	03/16/2000	781		323	323			116	1	1
5	00V-019.00	259	Fontaine Fifth Wheel	08/22/2000	43		5	5			0		1
4	00V-232.00	260	Bendix ABS ECU	01/12/2004	681		105	105			0		
4	00V-239.00	261	Fabient Throttle Pedal Spring	12/13/2000	49252	3386	25478	25478		12	4523	2	2
4	00V-348-09	262	TRW Tie Rod Ends	12/13/2000	6244		3577	3577		1	662		1
4	00V-309	263	MS200-Steering Gear Torque	11/27/2000	34		18	18					
2	01V-003	264	Power Steering Hoses	04/26/2000	69		25	25			18		
1	01V-44-207	265	Drag Links - 24-DL	07/13/2001	4116		783	783		2	336	1	2
1	01V-44-107	266	TRW Tie Rod Ends - 24-DL	07/13/2001	1379		242	242			77		

MACK TRUCKS, INC.

QUARTERLY REPORT DEFECT NOTIFICATION CAMPAIGNS
QUARTER ENDING DECEMBER 31, 2001

PERIOD	CAMPAIGN			CUSTOMER NOTIFICATION	NUMBER OF VEHICLES					VEHICLES UNREACHABLE DUE TO			
	MTRA NUMBER	MACK CAMPAIGN NUMBER	TITLE	DATE	VEHICLES INVOLVED	ESTIMATED PARTS TO SELL	VEHICLES INSPECTED	CORRECTED	NOT REQUIRED CORRECTION	TOWED/TRD	EXPORTED	THEFT	REFUSE UNREPAIRED
7	00V-024	299	CX Headlamp Label	03/15/2000	791		335	334		1	116		1
6	00V-019.00	298	Fontaine Fifth Wheel	08/22/2000	43		8	8			0		1
6	00V-092.00	289	Bendix ABS ECU	01/13/2001	981		147	147			0		
6	00V-230.00	291	Painted Throttle Pedal Spring	12/18/2000	48202	3386	27144	27129		13	4330	3	4
6	00V-046-00	292	TRW Tie Rod Ends	12/13/2000	8214		3740	3738		2	652		1
6	00V-368	293	M6700-Steering Gear Torque	11/27/2000	34		19	19					
5	01V-088	294	Power Steering Hoses	04/26/2000	55		28	28			16		
2	01V-44-207	288	Drag Links - 24-OX.	07/13/2001	4116		1299	1296		2	336	1	3
2	01V-44-107	286	TRW Tie Rod Ends - 24-OX.	07/13/2001	1379		374	374			77		1
1	01V-180.00	287	Haldex Relay Valves	11/16/2001	5295		8	8		1	1138	1	
1	01V-391	289	Front Axle Springs	12/28/2001	461		2	2			15		
1	01V-140-00	276	Tie Rod Ends	12/17/2001	3929		318	316		2	791		2

[illegible]
[illegible] quarterly
[illegible]
[illegible]

MACK TRUCKS, INC.

QUARTERLY REPORT DEFECT NOTIFICATION CAMPAIGNS
QUARTER ENDING MARCH 29, 2002

PERIOD	CAMPAIGN: NHTSA NUMBER	CAMPAIGN: MACK CAMPAIGN NUMBER	CAMPAIGN: TITLE	CUSTOMER NOTIFICATION: STARTING	NUMBER OF VEHICLES: VEHICLES INVOLVED	NUMBER OF VEHICLES: REMAINING PRIOR TO MAR	NUMBER OF VEHICLES: VEHICLES REPAIRED	NUMBER OF VEHICLES: REMAINING	NUMBER OF VEHICLES: NOT REQUIRING CORRECTION	VEHICLES UNREACHABLE DUE TO: REFUSED	VEHICLES UNREACHABLE DUE TO: REPORTED	VEHICLES UNREACHABLE DUE TO: SCRAP	VEHICLES UNREACHABLE DUE TO: SOURCE UNEXPLAINED
6	00V-232.00	260	Bendix ABS ECU	01/12/2001	651		170	170			0		
6	00V-230.00	261	Falstaf Throttle Pedal Spring	12/13/2000	48552	3368	29148	28128		14	4330	3	4
6	00V-246.00	262	TRW Tie Rod Ends	12/13/2000	6944		3784	3782		2	662		1
6	00V-344	263	MEXCO-Steering Gear Torque	11/22/2000	34		19	19					
4	01V-063	264	Power Steering Hoses	04/25/2000	85		28	26			18		
3	01V-44-207	265	Drag Links - 24-DL	07/13/2001	4118		1835	1832		2	336	1	3
3	01V-44-197	266	TRW Tie Rod Ends - 24-DL	07/13/2001	1370		684	684			77		1
2	01V-160.00	267	Haldex Relay Valves	11/16/2001	6266		2273	2270		1	1136	2	
2	01V-301	269	Front Axle Springs	12/20/2001	461		194	194			16		
2	01V-140-00	270	Tie Rod Ends	12/17/2001	5665		1648	1643		5	798		3
0	01V-386	271	Axle Shaft Nut	03/22/2002	6828		1	1			1604		
0	02V-019	272	Hi Pressure PS Hose	03/21/2002	863						113		
0	02V-064.00	273	Chainless Tower Rpr Bkt	04/22/2002	213						97		

MACK TRUCKS, INC.

QUARTERLY REPORT DEFECT NOTIFICATION CAMPAIGNS
QUARTER ENDING JUNE 25, 2002

PERIOD	CAMPAIGN			CUSTOMER NOTIFICATION	NUMBER OF VEHICLES					VEHICLES UNREACHABLE DUE TO			
	MYTRA NUMBER	MACK CAMPAIGN NUMBER	TITLE	STARTED	VEHICLES INVOLVED	REMOVED PRIOR TO SALE	VEHICLES INSPECTED	CORRECTED	NOT NEEDING CORRECTION	SCRAPPED	EXPORTED	THEFT	NOTICE UNDELIVERED
7	00V-232.00	260	Bendix ABS ECU	01/12/2001	661		226	226			0		
7	00V-250.00	261	Felsted Throttle Pedal Spring	12/13/2000	46252	5386	30859	30841		14	4330	4	25
7	00V-246-~~003~~ 005	262	TRW Tie Rod Ends	12/13/2000	6244		3758	3756		2	662		1
7	00V-306	263	MS200-Steering Gear Torque	11/27/2000	34		26	26					
6	01V-083	264	Power Steering Hoses	04/26/2000	58		30	30			16		
4	01V-44-207	265	Drag Links - 24-DL	07/13/2001	4116		2135	2132		2	336	1	6
4	01V-44-107	266	TRW Tie Rod Ends - 24-DL	07/13/2001	1379		887	887			77		2
3	01V-189.00	267	Haldex Relay Valves	11/16/2001	5296		4219	4216		1	1133	2	
3	01V-001	269	Front Axle Springs	12/28/2001	461		349	349			13		
3	01V-140-00	270	Tie Rod Ends	12/17/2001	5665		4667	4652		8	790		6
1	01V-368	271	Aux Shaft Nut	03/22/2002	6626		2415	2414		1	1004		
1	02V-019	272	Hi Pressure P/S Hose	03/21/2002	663		316	316			113		
1	02V-061.00 2	273	Chelsea Tower Rpr Bkt	04/22/2002	213		11	11			97		
0	02V-016.00	274	ABS Modulator Valve	06/13/2002	93						19		