[redacted] JUS[redacted] [redacted] [redacted] [redacted] WA[redacted]Y [redacted]E [redacted] [redacted] [redacted] [redacted] [redacted] [redacted] [redacted] [redacted]

MICROFILM B134546 INPUT DT 07/16/87 VIN 1JCCF 071911 IN SERVICE DT 09/05/86 COPS IN SERV DT C 86
L A 05245 INPUT TIME 07:20 MODEL 87FC REPAIR DT 07/15/87 SELLING DLR SAME Y
INVOICE NO 19709 REPAIR ORDER 54 55 FAB MILEAGE 09935 PAINT O
RESUB INVOICE COPS INVOICE DT 11/30/84

INCIDENT A FAPV MESSAGE: 7100 INVOICE ADJUSTED UP [redacted] $10.00
INC TEXT: HARD TO START CHOKE LINKAGE BINDING [redacted]ICATE CHOKE LINKAGE
WARR TYPE: 12 EXPENSE CD: 71 INC CD: 1230 [redacted] CD: 999

OPER CD: 0012 OPER TEXT: LUBE CHOKE L. HRS: 00.2 AMOUNT: 7.40
INCIDENT A TOTAL 7.40

INCIDENT B FAPV MESSAGE: 7100 INVOICE ADJUSTED UP OVER $10.00
INC TEXT: OIL LEAK VALVE COVER WARPED RR VALVE COVER AND REPLACE
WARR TYPE: 12 EXPENSE CD: 71 INC CD: 1143 SUPP CD: 999

OPER CD: 1282 OPER TEXT: HRS: 01.5 AMOUNT: 55.50

PART NO: 8983503347 PART TEXT: COVER QTY: 01 AMOUNT: 60.32

ADJUSTMENT: INCIDENT B ERROR 4040 PART/OPERATION 8983503347 ORIGINAL VALUE 35.44 ADJUSTED VALUE 60.32 FIELD NUMBER 00
INCIDENT B TOTAL 115.82

TOTAL INVOICE AMOUNT 123.22

MICROFILM B134546

FS AF — IN MOTORS SALES CORPORATION
WAR — TY INVOICE—REPAIR ORDER

206 — 53

Submit invoice within 21 days from RO date. Late submission may result in claim denial
Follow inquiry procedure in WAM if applicable

Eng. Trans. Dealship

Service part or all condemning item or equipment at time of repair or record

Date: Month / Day / Year

Mileage when serviced: Kms / Miles

Claim RO Count slip No.

OWNER NAME AND AD
Domenic Rea
302 Simondsville Ave.
Johnston, RI

VIN: 2C.C.C.K.3.8.5.1.F.0.7.1.3.5.8.6

DELIVERY DATE JOB / FIRST USE DATE: 11/28/86

WARR IN SERVICE: 12/9/0 — REPAIR DATE: 1/14/87 — PARTS SOLD: ☐ — ZONE: — SELLING DEALER: X

DEALER

Dealer Information: Claims which are not processed will be returned to dealership

38 0163 3000
FA POLLI MTR SLS
1 V CRANSTON RI
CRANSTON RI 02 .10

RESUBMISSION OF CLAIM NO: 0 — SYSTEM GENERATED NUMBER: 1.90203

ALL CLAIMED CLAIMS ARE SUBJECT TO AUDIT

| PART NO | PART DESCRIPTION | QTY | DEALER NET | WARR C | WARR P | LABOR CALCULATIONS | TIME | AMOUNT |
|---|---|---|---|---|---|---|---|---|
| A 92.83.00 88.1 | VALVE COVER | 1 | 11.94 | 23.37 | | A 1997 Labor | 0.3 | 9.00 |
| | | | | | | A 1282 | 1.5 | 45.00 |

OIL LEAK AT REAR OF ENGINE.
STEAM CLEAN ENGINE.
VALVE COVER. NOT SEATED PROPERLY BECAUSE OF WARPAGE.
REPLACE VALVE COVER.

TECHNICAL DESCRIPTION AND CORRECTION

DESIRE - MALFUNCTION - FAULT AND CORRECTION

SUBLET
SUBLET

RELIGIBLE

ZUK000

This is to certify that the services described were performed on my vehicle at no charge to the owner, using genuine AMC manufacturer parts and specified repair procedures. Also attached reports are not complete without any part(s) supporting which were part of warranty repair(s) in accordance with AMC's Warranty Policy.

Dennis L. Lalonde — 1/16/87
CENTER SIGNATURE — DATE

$ 23.37 TOTAL PARTS
$ 54.00 TOTAL LABOR
$ 77.37 TOTAL CREDIT

WARRANTY DEPT. COPY

'76 Am Motors Sales Corporation

WARR / INVOICE — REPAIR ORDER

DEALER 5835

'16 4306 4900

GENE PUSE AND JP REM
1080 MANCHESTER RD
MANCHESTER MO 63011

OWNER NAME AND ADDRESS: Pat Murphy

VIN: 2CCCK3B57EB311466

WARRANTY COVERAGE: 1/12 DEDUCTIBLE: 0

| MILES | REPAIR DATE | DEL. DATE | 1ST DAY | PAINT CODE | 2 TONE |
|---|---|---|---|---|---|
| 065911 | 071218 | 021248 | | | ☐ |

REDUBMISSION OF INVOICE NO:

INVOICE NUMBER: 120425

| | PART NO | QTY | PART DESCRIPTION | DEALER NET UNIT PRICE | WARRANTY PRICE UNIT | WARRANTY PRICE EXTENDED | NOT |
|---|---|---|---|---|---|---|---|
| A | 8992350139B | 1 | Valve K.I.T | 23.50 | | 30.55 | |
| A | 8993317 | 1 | gasket/fm | 2.84 | | 3.69 | |
| A | SUBTOTAL | | | | | 34.24 | |
| B | | | | | | | |
| B | SUBTOTAL | | | | | | |
| C | | | | | | | |
| C | SUBTOTAL | | | | | | |

DIAGNOSIS: 1143 — CONDITION, CAUSE AND CORRECTION: Engine oil leak. Oil leaking past valve cover mating surface on cylinder heads valve cover warped. Replace valve cover.

DIAGNOSIS: 6230 — CONDITION, CAUSE AND CORRECTION: AC system under load (jacked up and off) Evaporator housing drain hose kinked. Route & secure. Evaporator housing base for proper drainage.

DIAGNOSIS: — CONDITION, CAUSE AND CORRECTION:

LABOR CALCULATIONS

| | OPR NO | TIME | AMOUNT |
|---|---|---|---|
| A | 1282 | 1.5 | 63.00 |
| A | SUBTOTAL | | 63.00 |
| B | 0062 | .2 | 8.40 |
| B | SUBTOTAL | | 8.40 |
| C | | | |
| C | SUBTOTAL | | |

This is to certify that the warranty described was performed on this vehicle, at no charge to the customer, using genuine AMC/Jeep/Renault parts and recorded repair procedures. Also, that all repairs will be performed with any exception. Supporting shop records and parts if requested, are available for inspection by representative of AMC.

DEALER SIGNATURE: Kathy Pierce — DATE: 7-23-86

I hereby authorize the repair work to be done along with the necessary material and agree to pay all charges for work and material. I also agree that Motors Sales Corporation is not responsible for loss or damage to property or vehicle in case of fire, theft or any other cause beyond its control.

CUSTOMER'S SIGNATURE — DATE

| TOTAL PARTS | TOTAL LABOR | TOTAL CREDIT |
|---|---|---|
| GRAND 34.24 | 71.40 | 105.64 |

Submit invoice within 30 days from R.O. date
Late submission may result in invoice denial
For a inquiry procedure in 'WAM' if applicable

WARRANTY DEPT. COPY

In Canada: American Motors Canada Inc. In Latin America and Caribbean countries: American Motors Inter-American Corporation.

Not responsible for loss or damage to property or vehicle in case of fire, theft or any other cause beyond.

ALL CREDITED CHARGES ARE SUBJECT TO AUDIT

STAPLE RELATED ATTACHMENTS TO BACK OF THIS FORM

DO NOT FOLD OR STAPLE

442639

WARRANTY VOICE

Contract Form Claim Number

'0'0 0 189 03

26 1567 3000

NELSON A. HOLMES
# 17 OLLA
EAST AURORA
03.1

Ord. Source Dir. Inst. Other

Installation Date

Engine Code and No. 408C02

R.O. No. 4852

Mileage when Installed

Always fill out this section for service part, accessory or special equipment part failure

R.O. Claim No. or Counterfeit No.

M D Y

Date Installed or Sold

Mileage when Installed

James Brady
555 Leydecker Rd
West Seneca, NY 14224

2CCCA3856FB706152
72685

Mfrs 11005 Rx Dx 7 886 Paint Code

Type Tune 0 Sailing Dir. Same as servicing dir. Y

Debit/Credit

| | | | | Labor Calculations | | |
|---|---|---|---|---|---|---|
| A | Description: Engine is leaking oil | 1143 | 7 | Opr. No. | Time | Amount |
| | Correction: Valve cover is out of shape | | | 1282 | 1.5 | 45.00 |
| | Replaced valve cover | 45.00 | | | | |
| | | 34.24 | | | | |
| B | Description: Engine Stalls | 1232 | 7 | 1101 | 1.6 | 48.00 |
| | Correction: Overhauled Carb | Carter | 614 | | | |
| | | 48.00 | | | | |
| | | 6.99 | | | | |

ILLEGIBLE

| | Part Number | Qty | War Price Unit | War Price Total | Description | P. Ref. | Part Number | Qty | War Price Unit | War Price Total | Description | P. Ref. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| A | 8983501398 | 1 | | 30.55 | cover | | | | | | | |
| A | 8193317 | 1 | | 3.69 | sealer | | | | | | | |
| B | 8134232 | 1 | | 6.99 | Carb Kit | | | | | | | |

Micro Reference No.

Approved

Claim Code

Total Claim Denied 93.00 $
42.03
13.03 GRAND

ALL APPROVED CLAIMS ARE SUBJECT TO AUDIT

Robert Voss

7/8/86

WARRANTY INVOICE MUST BE LEGIBLE

1442639

000404

AMERICAN MOTORS SALES CORP.

# WARRANTY INVOICE — REPAIR ORDER

85 Eagle

643881

DEALER

30 4190 8400

GLENDALE AMC JEEP R
1260 S BRAND AVE
GLENDALE CA 91204
UBERGE C

OWNER NAME AND ADDRESS

Robert Meeker
P.O. Box 10016
Big Bear Lake 92315

VEHICLE

2CCLCK3852F107264441

WARRANTY COVERAGE 1/12 DEDUCTIBLE $0

MILES 07000 REPAIR DATE 7-27-87 DEC. DATE 7-27-87 DAY 2

RESUBMISSION OF INVOICE NO.

INVOICE NUMBER 048224

BO Lot Labor adjustment (see TSB bulletin MCA 0 ; exempt MCA 0)

DIAGNOSIS AUTHORIZATION DATE 07000 07/11/87d 11001185

| | PART NO | QTY | PART DESCRIPTION | DEALER NET UNIT PRICE | WARRANTY PRICE UNIT | WARRANTY PRICE EXTENDED | INIT |
|---|---|---|---|---|---|---|---|
| A | #8883088348 | 1 | Cover | 17.10 | 17.10 | 23.38 | |
| A | 8806876 | 1 | Clamp | 1.00 | 1.00 | 1.50 | |
| A | SUBTOTAL | | | | | 2388 | |
| B | | | | | | | |
| B | SUBTOTAL | | | | | | |
| C | | | | | | | |
| C | SUBTOTAL | | | | | | |

TIME OPER. NO. AUTHORIZATION NUMBER
1.1 43
DESCRIPTIVE EXPLANATION CAUSE AND CORRECTION
ck for oil leak valve cover leaking RH valve cover, drill shelf cord mod Repl. I/C

TIME OPER. NO. AUTHORIZATION NUMBER
1.5
DESCRIPTIVE EXPLANATION CAUSE AND CORRECTION
Adjust carburetor Check choke vacuum hose & passages Check & adjust idle mixture & speed Check PCV valve & hose

TIME OPER. NO. AUTHORIZATION NUMBER

DESCRIPTIVE EXPLANATION CAUSE AND CORRECTION

| | LABOR CALL | RATE | AMOUNT |
|---|---|---|---|
| A | 1289 | 1.5 | 5100 |
| A | SUBTOTAL | | 5100 |
| B | 1748 | 0.7 | 2380 |
| B | SUBTOTAL | | 2380 |
| C | | | |
| C | SUBTOTAL | | |

07000 905

This is to certify that the services described were performed on this vehicle at no charge to the owner, using genuine and unmodified parts and specified repair procedures. The above owner was informed and agreed with my decision. Supporting shop records and parts invoices are retained for a period of 1 year.

DEALER SIGNATURE 7-28-87 DATE

I hereby authorize the repair(s) and the necessary road test(s) and agree to pay for all repairs not covered by this warranty. I understand that a lien may be placed on my vehicle for repairs not paid for.

CUSTOMER'S SIGNATURE DATE

TOTAL PARTS GRAND 2388 TOTAL LABOR 7480 TAX CHARGES 98.83

Submit invoice within 30 days from R.O. date. Submission may result in invoice deduction. Follow inquiry procedure in WAM-I appendix.

In Canada: American Motors Canada Inc. for Latin America and Caribbean: American Motors Pan American Corporation.

Not responsible for loss or damage to car in case of fire, theft or any other cause.

WARRANTY DEPT. COPY

ST. ADJUSTED WARRANTY INVC 0502

MICROFILM A436181 INPUT DT 07/24/86 VIN 2CCCK387A. 12392 IN SERVICE DT 05/19/86 COPS IN SERV DT 05/
DEALER 06863 INPUT TIME 10:16 MODEL 38KC REPAIR DT 07/01/86 SELLING DLR SAME Y
INVOICE NO 20505 REPAIR ORDER TRUSHELL FAB MILEAGE 01285 PAINT D
RESUB INVOICE 19727 COPS INVOICE DT 02/12/85

INCIDENT A FAPV MESSAGE: 9000 OK TO PAY - NO ADJUSTMENTS
INC TEXT: OIL LEAK VALVE COVER WARPED AND LEAKING R AND R VALVE COVER AND ROAD TEST
WARR TYPE: 12 EXPENSE CD: 11 INC CD: 1143 SUPP CD:

OPER CD: 1282 OPER TEXT: HRS: 01.5 AMOUNT: 42.00

| PART NO: | PART TEXT: | QTY: | AMOUNT: |
|---|---|---|---|
| 8983501398 | VALVE COVER | 01 | 30.55 |
| 0008993317 | ATV | 01 | 1.69 |
| 0003227850 | MINI CLAMP | 01 | 0.23 |
| 8982200287 | OIL | 01 | 1.63 |
| 0008995564 | FREON | 06 | 15.78 |
| 0008993862 | DEGREASER | 01 | 3.48 |

INCIDENT A TOTAL 97.36

INCIDENT B FAPV MESSAGE: 9000 OK TO PAY - NO ADJUSTMENTS
INC TEXT: DOME LITE INOP BULB BROKEN REPLACE BULB BURNED OUT
WARR TYPE: 12 EXPENSE CD: 11 INC CD: 8197 SUPP CD:

OPER CD: 8011 OPER TEXT: HRS: 00.3 AMOUNT: 8.40

PART NO: 0004488457 PART TEXT: BULB QTY: 01 AMOUNT: 1.59

INCIDENT B TOTAL 9.99

INCIDENT C FAPV MESSAGE: 9100 OK TO PAY - SYSTEM ADJUSTED PARTS & LABOR
INC TEXT: PARK BRAKE TOO LOOSE OUT OF ADJUSTMENT ADJUSTED REAR BRAKES
WARR TYPE: 12 EXPENSE CD: 13 INC CD: 381L SUPP CD:

OPER CD: 3757 OPER TEXT: HRS: 00.2 AMOUNT: 5.60

ADJUSTMENT: INCIDENT A ERROR 4040 PART/OPERATION 0008993317 ORIGINAL VAL 3.71 ADJUSTED VALUE 3.69 FIELD NUMBER 00

ADJUSTMENT: INCIDENT A ERROR 4040 PART/OPERATION 0008993862 ORIGINAL VALUE 3.51 ADJUSTED VALUE 3.48 FIELD NUMBER 00

INCIDENT C TOTAL 5.60

TOTAL INVOICE AMOUNT 112.95

MICROFILM A436181

22 130

AMERICAN MOTORS SALES CORPORATION
**WARRANTY INVOICE—REPAIR ORDER**

LICENSE NO. [illegible] · PHONE NO. [illegible] · VEHICLE NO. — · YEAR/MODEL 1981 · ENGINE/TRANSMISSION —

OWNER NAME AND ADDRESS: [illegible handwriting]

MODEL NO. [illegible] · FAB NO.

VIN: [illegible]

DELIVERY DATE OR FIRST USE DATE: [illegible] · WARR. COV. [illegible] · DEDUCTIBLE $ [illegible]

MILES [illegible] · REPAIR DATE [illegible] · PAINT CODE · 2 TONE · SELLING DEALER · RESUBMISSION OF CLAIM NO. · CLAIM SUFFIX

DEALER

Dealer information. Claims which are not imprinted will be returned to dealership.

38 506 [illegible]

| PART NO. | PART DESCRIPTION | QTY | DEALER NET | WARR. PRICE |
|---|---|---|---|---|
| [illegible] | [illegible] | 1 | [illegible] | |
| [illegible] | [illegible] | 2 | [illegible] | |

ILLEGIBLE

VEHICLE CONDITION, CAUSE AND CORRECTION: [illegible handwriting]

T/C [illegible] · SUPPLIER CODE [illegible] · SUPPLIER NAME —

DESCRIBE CONDITION, CAUSE AND CORRECTION: [illegible handwriting]

T/C 1143 · SUPPLIER CODE [illegible] · SUPPLIER NAME

DESCRIBE CONDITION, CAUSE AND CORRECTION

C

T/C · SUPPLIER CODE · SUPPLIER NAME

| OPR. NO. | TIME | AMOUNT |
|---|---|---|
| 1139 | 0.9 | [illegible] |
| [illegible] | 0.6 | [illegible] |
| 1137 | 0.5 | [illegible] |
| [illegible] | [illegible] | [illegible] |
| SUBLET | | |
| SUBLET | | |

$ [illegible] TOTAL PARTS · $ 111.65 TOTAL LABOR · $ [illegible] TOTAL CREDIT

DEALER SIGNATURE · DATE

CUSTOMER'S SIGNATURE · DATE

WARRANTY DEPT. COPY

ALL CHECKED CLAIMS ARE SUBJECT TO AUDIT

# GM MOTORS SALES CORPORATION
## WARRANTY INVOICE—REPAIR ORDER

PHONE WHEN R | DATE 85/05 | P.O. I.D. AC I.D. | MODEL YEAR 85/Auto | 31 | '16

Subm...ions within 21 days from R.O. date. Late Submission may result in claim denial. ✓ Have inquiry procedures in WAM if applicable

Fault Code Yes

Service port or on comp. (owning/operator) (dispersed) information record

Date of original or last service

Mileage when installed or last serviced

Oper., R.O., Courtesy

OWNER NAME AND ADDRESS
F. Jaber
76 LANGE dr.
MANAHAWKIN, NJ

MODEL NO. K87X

VIN 1J4CF87E7FT160555

DELIVERY DATE OR FIRST USE DATE 09/11/85

WARR COV 12-12 DEDUCTIBLE $ 0

MILES 5909 | REPAIR DATE 02/25/85 | PAINT CODE | SELLING DEALER | REIMBURSEMENT OF CLAIM NO | CLAIM NUMBER 19-JF-85 05601

DEALER
Dealer Information. Claims which are not imprinted with the returned to dealership.
405311
ISLAND MOTORS INC
610 E BAY AVENUE
MANAHAWKIN NJ 08050

GENERAL REPAIR OPERATIONS

| PART NO. | PART DESCRIPTION | QTY | DEALER NET | WARR PRICE | NET |
|---|---|---|---|---|---|
| 8998501998 | Cover | 1 | 2250 | 3015 | N |
| 3837057 | Seal | 2 | .80 | .66 | N |
| 8993317 | Gasket/MS | 1 | 2.84 | 769 | N |
| | | | | 3490 | |

DISCARD

INTERFILE

DESCRIBE CONDITION, CAUSE AND CORRECTION
Valve Cover Leaking
Bad Sealing Compound
Reseal Valve Cover
PT

TC 1.98 SUPPLIER CODE SUPPLIER NAME

DESCRIBE CONDITION, CAUSE AND CORRECTION
Radio Plays on Left Side Only
Remove + Replace Radio For Repairs
B

TC 86.91 SUPPLIER CODE 7691 SUPPLIER NAME Mitsubishi

DESCRIBE CONDITION, CAUSE AND CORRECTION
C

TC SUPPLIER CODE SUPPLIER NAME

LABOR CALCULATIONS

| OPR | OPR NO | TIME | AMOUNT |
|---|---|---|---|
| A | 1282 | 1.3 | 37.95 |
| B | 8719 | 0.5 | 17.51 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| SUBLET | | | 42.20 |
| SUBLET | | | |

This is to certify that the services described were performed on my vehicle, at my request and that the parts listed were used and charged for. All warranty parts are held intact for inspection.

$ 34.90 TOTAL PARTS | $ 97.66 TOTAL LABOR | $ 132.56 TOTAL CHARGE

DEALER SIGNATURE | DATE | CUSTOMER'S SIGNATURE | DATE

WARRANTY DEPT. COPY

All warranties stated herein are in Lieu of all other warranties, expressed or implied, including any implied warranty of merchantability or fitness, and no agent or representative of dealer is authorized to assume for dealer any liability in connection with any GM vehicle except as set forth herein. Chevrolet Motor Division, Inc. in Lieu America and Caribbean Islands. In Canada Motors Insurance Corporation

WARRANTY INVOICE — REPAIR ORDER

4091207

Submit Invoice within 30 days from R.O. date. Late submission may result in claim denial. Follow inquiry procedure in WMM if applicable.

CLAIM NUMBER: 050.07

Service part or air conditioning / special equipment installation record

Date installed or last serviced

Mileage when installed or last serviced

Claim R.O. Controller No. 29361

John Behrens
4535 Cinderbed Dr.
Tax, T

1JCCF87A3FT171033

06255 071585

DEALER

PREPAIR DATE: 02/11/86

PART CODE

2 TONE

SELLING DEALER

ENG / TRANS CODE / NO

CROSS REFERENCE RETAIL REPAIR ORDER NO

| Code | Part No. | Qty | Part Description | Warranty Price Unit | Warranty Price Extended | Rev | Description | Labor Calculations Opn No. | Time | Amount | Rev |
|---|---|---|---|---|---|---|---|---|---|---|---|
| A | 8993317 | 1 | RTU | 2.84 | 3.65 | | 1143 Check for fluid leak Reseal valve cover | A | 1282 | 1.5 | 45.00 |
| | | | | | | | 6446 Check for water leak around dash. Reseal front cowl panel | B | 6999 | 0.9 | 27.00 |

ILLEGIBLE

000409

| | Total Parts | Total Labor | Total Price |
|---|---|---|---|
| A | $ 3.65 | $ 45.00 | $ 48.65 |
| B | $ | $ 27.00 | $ 27.00 |
| C | $ | $ | $ |
| GRAND | $ 3.65 | $ 72.00 | $ 75.65 |

Customer's Signature

2-19-86

Date

WARRANTY DEPT. COPY

Motors Sales Corporation

WARRANTY INVOICE — REPAIR ORDER

51550

86CS-7

John Paulson
1309 Richmond
Sant Cruz

1JCCF87A8FT171142

11919 061485

10225.86

DEALER

30 [illegible]

GARRIAGE AJR
2181 N OXNARD BLVD
OXNARD CA 93030
100165 0

CLAIM NUMBER 06426

FAILURE

1992

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| A | 8933002893 | 1 | Value CVR | 2193 | | 2850 | 14.43 | 7/1 | A | 1999 | 56.25 |
| A | 8993317 | 1 | Sealant | 2.84 | | 3.69 | Oil Leak | | | | |
| A | 3203078 | 1 | Clamps | .86 | | 1.11 | Value Covers leaking | | | | |
| | | | | | | | Installed new Value Covers & Resealed | | | | |

000440

ELIGIBLE

Ok.

| | | | |
|---|---|---|---|
| A | 33.30 | 56.25 | 89.55 |
| B | | | |
| C | | | |
| GRAND | 33.30 | 56.25 | 89.55 |

WARRANTY DEPT. COPY

[redacted]

**AMERICAN MOTORS SALES CORPORATION**
**WARRANTY INVOICE—REPAIR ORDER**

30 929

Submit invoice within 21 days from R.O. date. Late submission may result in claim denial. Follow inquiry procedure in WAM if applicable.

Eng/Trans. Code/No.: ROH# 14117

OWNER NAME AND ADDRESS: Larry Lloyd — Grand Rapids

VIN: 2CCCK7852FB701403

DELIVERY DATE OR FIRST USE DATE: 9/6/84 — WARR COV: 1/12 — DEDUCTIBLE $

MILES: 5869 — REPAIR DATE: 8/17/88 — PAINT CODE — 2 TONE — SELLING DEALER: N

DEALER
Dealer information [illegible] are not imprinted will be returned to dealership

16 5606 3200
SWANSON AMC JEEP
193 N PARK JAMA AVE
GRAND RAPIDS MN
010107 C 6 744

RESUBMISSION OF CLAIM NO: — CLAIM NUMBER: 24601

| | PART NO | PART DESCRIPTION | QTY | DEALER NET | WARR PRICE |
|---|---|---|---|---|---|
| A | 8993503343 | cover | 1 | 2726 | 3549 |
| B | 8993502508 | seal | 1 | 334 | 434 |
| B | 8130815 | seal | 1 | 857 | 1141 |
| C | [illegible] | [illegible] | 1 | 15 | 20 |

DESCRIBE CONDITION, CAUSE AND CORRECTION:

A: oil leak RH side w/A [illegible] replace drive cover [illegible] [illegible] coil 1/4 transfer case — TC 1143 — CO 71

B: oil leak — RR flange replace [illegible] drive shaft seal & flange seal — TC 2204 — CO 71

C: TC 2427 — CO 71

| | OPR NO | TIME | AMOUNT |
|---|---|---|---|
| A | 2282 | 1.5 | 48.00 |
| B | 2293 | .4 | 12.80 |
| B | 2197 | .3 | 9.60 |
| C | 2278 | .4 | 12.80 |

TOTAL PARTS $ 41.69 — TOTAL LABOR $ 83.20 — TOTAL CREDIT $ 124.89

DEALER SIGNATURE — DATE 9-2-87

ILLEGIBLE

ALL CREDITED CLAIMS ARE SUBJECT TO AUDIT

STAPLE REQUIRED ATTACHMENTS TO BACK TOP LEFT CORNER

WARRANTY DEPT. COPY

Jim Morris Sales Corporation

# ...ITY INVOICE — REPAIR ORDER

POW 229 | 854-013 | BS Eagle | GM | 4822

Submission of claims 30 days from R.O. date may result in claim denial. Follow inquiry procedure in WAIT applicable.

CLAIM NUMBER: 28 0041

REPUBLICATION OF CLAIM NO.

Date of sale or lease

Mileage when installed at last service

Claim R.O. Ownership No.

Albert Westlake
236 So 4th Ave
Brighton Co 80601

2CCCK3879FB711895

10075 | 090186

REPAIR DATE: 08 28 87 | PRINT CODE | 2 TONE | DELIVERY DEALER

ENG / TRANS CODE NO. | CHOSE REMOVED REPL. REPAIR ORDER NO.

ZONE AUTHORIZED SIGNATURE | DATE

| PART NO. | QTY | PART DESCRIPTION | SUBLINE | UNIT | EXTENDED | LABOR OPERATION | OP. NO. | TIME | AMOUNT | NOT |
|---|---|---|---|---|---|---|---|---|---|---|
| 8983503343 | 1 | Valve assy | 8726 | | 35.00 | 1.43 | | | | |
| 479402 | 1 | Clamp | 81 | | 10.00 | Check eng. oil leaks | | | | |
| | | | | | | rep & value correct | A | 1.00 | 1.5 | 57.00 |
| | | | | | | | | | 110.40 | |

ALL DEALER CLAIMS ARE SUBJECT TO AUDIT

DEALER SIGNATURE | DATE

Albert F. Westlake
CUSTOMER SIGNATURE | DATE

| | TOTAL PARTS | TOTAL LABOR | TOTAL CREDIT |
|---|---|---|---|
| A | $ | $ | $ |
| B | $ | $ | $ |
| C | $ | $ | $ |
| D | $ | $ | $ |
| GRAND | $ 3649 | $ 5700 | $ 9349 |

WARRANTY DEPT. COPY

In Canada American Motors Canada Inc. In Mexico American and Caribbean Branch American Motors Pan American Corporation

STATUS ACCEPTED WARRANTY INVOICE 16

MICRO B375918 INPUT DT 10/19/87 VIN 2CCCK3879F 7 IN SERVICE DT 10/18/86 COPS IN SERV DT 10/18/
DEALER 00464 INPUT TIME 16:15 MODEL 38KC REPAIR DT 10/06/87 SELLING DLR SAME Y
INVOICE NO 29216 REPAIR ORDER 4889518 FAB 5709497 MILEAGE 11710 PAINT 0
RESUB INVOICE COPS INVOICE DT 12/04/84

INCIDENT A FAPV MESSAGE: 5200 TIC/SRT EXCEEDS VALUE
INC TEXT: ENGINE MISSES ROTOR BURNT REPLACE CAP AND ROTOR
WARR TYPE: 12 EXPENSE CD: 71 INC CD: 1714 SUPP CD: 999

OPER CD: 1421 OPER TEXT: HRS: 00.3 AMOUNT: 14.40

PART NO: 0003230457 PART TEXT: CAP QTY: 01 AMOUNT: 9.15
0003230821 ROTOR 01 1.47

INCIDENT A TOTAL 25.02

INCIDENT B FAPV MESSAGE: 5200 TIC/SRT EXCEEDS VALUE
INC TEXT: ENGINE LEAKS OIL VALVE COVER WARPED AND LEAKING REPLACE VALVE COVER WITH NEW STYLE
WARR TYPE: 12 EXPENSE CD: 71 INC CD: 1143 SUPP CD:

OPER CD: 1282 OPER TEXT: HRS: 01.5 AMOUNT: 72.00
0102 00.2 9.60

PART NO: 8983503343 PART TEXT: VALVE COVER QTY: 01 AMOUNT: 3[illegible].44
0008993317 RTV 01 3.91

INCIDENT B TOTAL 120.95

INCIDENT C FAPV MESSAGE: 5200 TIC/SRT EXCEEDS VALUE
INC TEXT: ENG ILDES ROUGH PERFORM IS NOTE 34E AND REPLACE DEFECTIVE CHOKE COIL SHORTED
WARR TYPE: 12 EXPENSE CD: 71 INC CD: 1241 SUPP CD: 999

OPER CD: 0108 OPER TEXT: HRS: 00.8 AMOUNT: 38.40
0105 00.5 24.00

PART NO: 0008133455 PART TEXT: HOUSING QTY: 01 AMOUNT: 27.56

INCIDENT C TOTAL 89.96

TOTAL INVOICE AMOUNT 235.93

000413

MICROFILM B375918

FB AMER MOTORS SALES CORPORATION
WARRA INVOICE—REPAIR ORDER

1985

2333

DEALER

Deal ... 10-85 are not ... Twin ... Ownership

28 4840 8800

FISHER MOTORS INC
BOX 1606
MINOT ND 58701
040188 R

Craig Voight
Box 752
New Rockford ND 58356

LJC U.B. 7.8.2 X F.T. 0.53.1.9.1

1/12

Zone Use

1206184

11.894 082889

X

RESUBMISSION CLAIM NO

RO# 91375

CLAIM NUMBER 268.02

ZONE AUTHORIZED SIGNATURE

| Line | Part No | Part Description | Qty | Dealer Net | Vendor Price | Net | Description | Line | Amount |
|---|---|---|---|---|---|---|---|---|---|
| A | 324212.1 | V. Cover | 1 | 20.44 | 26.57 | | Oil leak | A | 1063 1.0 28.00 |
| A | 324173.1 | V.C. Gold | 1 | 5.10 | 6.63 | | Valve cover cracked. Replace valve cover | | |

1143

CO 71

ILLEGIBLE

000414

ALL CREDIT CLAIMS ARE SUBJECT TO AUDIT

STATE REQUIRED ATTACHMENTS TO BACK TOP LEFT CORNER

Bill Nicholson 9/3/85

SIGNATURE

$33.30 TOTAL PARTS

$28.00 TOTAL LABOR

$61.30 TOTAL CREDIT

109

WARRANTY DEPT. COPY

WAR#

# INVOICE—REPAIR ORDER

2851 4

OWNER NAME AND ADDRESS
Jameja Milewski
2151 Ray Lane
Krakow, WI 54162

078.3
MODEL NO

FAN NO

VIN
1 J C U B 7 8 2 X F T 1 7 1 3 2 1 1

DELIVERY DATE OR FIRST USE DATE 10/01/85

WARR COV 1/12
DEDUCTIBLE $

SALES 154.38

REPAIR DATE 09/11/85

PAINT CODE

2 TONE

SELLING DEALER X

DEALER

Dealer Information. Claims which are not completed will be returned to dealership.

16 534 8
S AND L MOTORS Inc
HWY 32 ROUTE 3
PULASKI WI 54162
110104 0

RESUBMISSION OR CLAIM NO

CLAIM NUMBER
R770.11

633

| LINE | PART NO | PART DESCRIPTION | QTY | DEALER NET | WARR PRICE | REF # |
|---|---|---|---|---|---|---|
| A | 000324.21.21 | Cover | 1 | 20.97 | 21.26 | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| B | 000899.93.17 | Gasket/10013 | 2 | 5.68 | 7.38 | |
| | | | | | 3.69 | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

Valve covers were warped and leaking.

Replace valve covers (4 cyl.)

TIC 143 SUPPLIER CODE — SUPPLIER NAME

OD N. Troyd

Cylinder head was cracked

Resealed with gasket in a tube.

TIC 1000 SUPPLIER CODE — SUPPLIER NAME

OD N. Dixie Lake Oil Lap "A"

Rear view mirror was loose.

Adjust base of rear view mirror.

TIC 5315 SUPPLIER CODE 999 SUPPLIER NAME

OD 13

| LINE | OPN NO | LABOR CALCULATIONS TIME | AMOUNT |
|---|---|---|---|
| A | 1063 | 1.0 | 24.50 |
| B | 0015 | 0.5 | 12.25 |
| C | 5249 | 0.3 | 7.35 |
| | | | |
| | | | |
| SUBLET | | | |
| SUBLET | | | |

ALL CREDITED CLAIMS ARE SUBJECT TO AUDIT

This is to certify that the services described were performed in the manner as set forth in the manufacturer's warranty policy and that the statements made herein are true and correct to the best of my knowledge.

Julie Zemicki 11-6-85
DEALER'S SIGNATURE DATE

$ 34.64 TOTAL PARTS
$ 44.10 TOTAL LABOR
$ 78.74 TOTAL CREDIT

Signature On file
SIGNATURE

11-11-85

WARRANTY DEPT. COPY

...ERN ...OTORS SALES CORPORATION
...ANTY INVOICE—REPAIR ORDER

LICENSE NO | PHONE NO | PHONE WHEN READY 1 46 0 0 8 | CAR MODEL | P.S. II A.C. | ENGINE/TRANSMISSION | 28984

...Invoice within 21 days from R.O. date. Late ...ation ... result in claim denial ...ion inquiry procedure in WAM if applicable

Service part or an condition/repair of equipment ...ation record

Date retained or test serviced

Mileage when installed or test serviced

Claim, R.O. Counterpoint

OWNER NAME AND ADDRESS
Lee Chalinsky
1201 E. MacArthur
Wichita, Ks.

MODEL NO

FAB NO

VIN 1 J C L L B 7 8 1 2 F T 1 4 6 9 4 2

WARR COV 1-12

DELIVERY DATE OR FIRST USE DATE 05 24 85

DEDUCTIBLE $

MILES 1 7 8 1 4 | REPAIR DATE M D 01 14 86 | PAINT CODE | 2 TONE | SELLING DEALER

DEALER
Dealer Information. Claims which are not imprinted will be returned to dealership.
28 1506 2000

DAVIS MOORE INC
6315 E KELLOGG
WICHITA KS 67218
070385 MARK ...

RESUBMISSION OF CLAIM NO. | 02003

| PART NO. | PART DESCRIPTION | QTY | DEALER NET | WARR PRICE | RET P |
|---|---|---|---|---|---|
| | | | | | |

DESCRIBE CONDITION CAUSE AND CORRECTION
Eng. oil leak at head area
not sealed correctly -
R+R w/cur + reseal

TIC 1143 | SUPPLIER CODE | SUPPLIER NAME

DESCRIBE CONDITION CAUSE AND CORRECTION
Rattle at L lwr dachon
accel - lwr a/c vent base -
Tighten L a/c vent

TIC 731 | SUPPLIER CODE | SUPPLIER NAME

DESCRIBE CONDITION CAUSE AND CORRECTION

TIC | SUPPLIER CODE | SUPPLIER NAME

LABOR CALCULATIONS

| ABC | OPR NO | TIME | AMOUNT |
|---|---|---|---|
| A | 1063 | 10 | 24.00 |
| B | 6719 | 2 | 6.80 |
| | SUBLET | | |
| | SUBLET | | |

$ | TOTAL PARTS | 40.80 TOTAL LABOR | 40.80 TOTAL CREDIT

CUSTOMER'S SIGNATURE | DATE

WARRANTY DEPT. COPY

ALL CREDITED CLAIMS ARE SUBJECT TO AUDIT

ILLEGIBLE

UNCALC

This is to certify that the services described were performed on this vehicle, in the charge to the owner, using genuine AMC/Jeep/Renault parts and specified repair procedures. Also above repairs are not connected with any accident. Supporting shop service and parts if applicable are available for inspection by representatives of AMC.

DEALER SIGNATURE | DATE 1-20-86

Schedule American Motors Canada, Inc. 3a Lights America and Canadian Islands American Motors Pan American Corporation

Motors Sales Corporation

WA[illegible]TY INVOICE — REPAIR ORDER LGD637 782 31oc [illegible] 85 R 503 51347

DEALER

24 4932 [illegible]
ROBERTS MOTORS INC
[illegible] AUBURN WAY N
AUBURN WA 98002
Location J

CUSTOMER NUMBER 01308

ZONE USE

William Nelson
2853 NW 69
Seattle 98117

1 JCUB7814 FT081217

7038 2285

11386

ZONE AUTHORIZED SIGNATURE

73

1.9.91 1143

Has oil Leak Possible valve cover 001 8 0.3 11.40

Tighten oil plug & 10 Valve cover & oil sender

Left Rain Drip is Loose

Has Rust in in the Left Rain Gutter

(10) Bring in 1-27-86 2-3 Days

Left Side Hood is discolored has over spray all over see Rich

A 11.40
B
C
GRAND 11.40

Geo K Lingel 1-16-86 J William Nelson

WARRANTY DEPT. COPY

SIMPLE REQUIRED ALIGNMENTS TO BACK TOP LEFT CORNER

ALL CREDITED CLAIMS ARE SUBJECT TO AUDIT

US ACCEPTED WARRANTY CE 16906

US ACCEPTED WARRANTY CE 16906

MICROFILM A381262 INPUT DT 06/18/86 VIN 1JCUMB7A1F1167668 IN SERVICE DT 05/19/86 COPS IN SERV DT 05/19/86
DEALER 00137 INPUT TIME 08:13 MODEL 87MV REPAIR DT 06/16/86 SELLING DLR SAME Y
INVOICE NO 16906 REPAIR ORDER 6304650 FAB J452967 MILEAGE 02856 PAINT O
RESUB INVOICE COPS INVOICE DT 05/30/85

INCIDENT A FAPV MESSAGE: 9000 OK TO PAY - NO ADJUSTMENTS
INC TEXT: OIL LEAK VLV COVER WARPED RENEW VLV CVR
WARR TYPE: 12 EXPENSE CD: 11 INC CD: 1143 SUPP CD:

OPER CD: 1329 OPER TEXT:

PART NO: 0003242121 PART TEXT:
0008595317
8982200043
0003237765

HRS: 01.0 AMOUNT: 36.00

QTY: 01 AMOUNT: 28.51
01 3.69
01 3.25
01 1.39

INCIDENT A TOTAL 73.04

INCIDENT B FAPV MESSAGE: 9000 OK TO PAY - NO ADJUSTMENTS
INC TEXT: RT REAR TAIL LAMP INOP LAMP ASSY SHORTD RENEW LAMP
WARR TYPE: 12 EXPENSE CD: 11 INC CD: 8124 SUPP CD:

OPER CD: 8083 OPER TEXT:

PART NO: 0005758254 PART TEXT:

HRS: 00.4 AMOUNT: 14.40

QTY: 01 AMOUNT: 33.19

INCIDENT B TOTAL 47.59

TOTAL INVOICE AMOUNT 120.63

MICROFILM A381262

Pa Am... Motors Sales Corporation

WAR... Y INVOICE – REPAIR ORDER

742 1985

4392

Kim Hillhouse
2840 Vergoss
Terre Haute, Ind.

12 1985

26 4997 2000

DIETRICH BUICK A J
PO BOX 1740
TERRE HAUTE, IN 47808
070106 C

CLAIM NUMBER: 24024

RESULT OF CLAIM

ZONE USE

1JCUM87A2FT184267

5636 092885

082584 K

ZONE AUTHORIZED SIGNATURE

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| A | 575.2010 | 1 | boot | 2.93 | 11 | 2361 Shifter boot cracked – R & R shifter boot. | A 0024 | .4 | 11.20 |
| | | | | | 11 | 1232613 Ford Idler rough and rund poor – install loose vacuum hose and tighten down | B 1748 | .7 | 19.60 |
| | | | | | 11 | 1143. Oil leak – Valve cover "seeping", tighten down valve cover bolts. | C 0013 | .3 | 8.40 |

2.4

11.20
19.60
8.40

14.13
19.60
8.40
42.13

Vicki L Harlan 8/28/85

WARRANTY DEPT. COPY

STATE REQUIRED ATTACHMENTS TO BACK TOP LEFT CORNER

AS REQUIRED AND ARE SUBJECT TO AUDIT

000419

FORD MOTORS SALES CORPORATION
WARRANTY INVOICE—REPAIR ORDER 41:30

Submit invoice within 21 days from R.O. date. Late submission may result in claim denial. For low inquiry procedure in WASM if applicable.

Eng/Trans. Code/No

Service per... or as limit... has engine oil changed... replaced... checked

Date installed or last serviced

Mileage when installed or last serviced

Claim, R.O. Coverage No.

OWNER NAME AND ADDRESS
Gregory Hughes
331 Central Ave
Billings MT

MODEL NO

FAB NO

VIN 1LRCM1=85E1FT03589

DELIVERY DATE OR FIRST USE DATE 11/23/84

WARR COV 1-1/2

DEDUCTIBLE $

MILES 10254

REPAIR DATE 11/29/84

PAINT CODE

☐ 2 TONE

SELLING DEALER

RESUBMISSION OF CLAIM NO

CLAIM NUMBER 02905

13? 49

DEALER

Dealer Information. Claims which are not imprinted will be returned to dealership

24 4704 3000!

ARNLUND AUTO SALES
2504 PHYLLIS LANE
BILLINGS MT 59102
180184 J

ALL CREDITED CLAIMS ARE SUBJECT TO AUDIT

STAPLE REQUIRED ATTACHMENTS TO BACK TOP LEFT CORNER

| LOC | PART NO | PART DESCRIPTION | QTY | DEALER NET | WARR PRICE | RET P |
|---|---|---|---|---|---|---|
| | | | | | | |
| | | | | O-RIDE | FOR | |
| | | | | LABOR | | |

DESCRIBE CONDITION CAUSE AND CORRECTION

Replaced valve
cover
Gasket 23 installed
Left Awaiting
Part Difference

OP 143 SUPPLIER CODE SUPPLIER NAME

OP 11

DESCRIBE CONDITION CAUSE AND CORRECTION

OP SUPPLIER CODE SUPPLIER NAME

OP

DESCRIBE CONDITION CAUSE AND CORRECTION

OP SUPPLIER CODE SUPPLIER NAME

OP

| LOC | OPR NO | LABOR CALCULATIONS TIME | AMOUNT |
|---|---|---|---|
| A | 1999 | .04 | 1.80 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | SUBLET | | |
| | SUBLET | | |

This is to certify that the services described were performed on this vehicle at no charge to the owner using genuine FMC/Motorcraft parts and that I/we have read the cautions on the above repairs are not connected with the accident. Authorized signature required for all repairs performed on customer's vehicle.

Phyllis Shotwell 12/8/84
DEALER SIGNATURE DATE

$ TOTAL PARTS

$ 1.80 TOTAL LABOR

$ 1.80 TOTAL CREDIT

CUSTOMER SIGNATURE DATE

WARRANTY DEPT. COPY

F8 AI ...N MOTORS SALES CORPORATION
WAR... ...TY INVOICE—REPAIR ORDER

487-52 150 84 Scram

37 12

Submit invoice within 21 days from R.O. date. Late submission may result in claim denial. Follow inquiry procedure in WAM if applicable.
Eng/Trans Code No.

Zone Use

OWNER NAME AND ADDRESS
Paul Merrill
749 State Fair Blvd
Syr NY 13209

88XX

1JCUF88E9ET0 3 1699

1/12

DEALER
Dealer Information. Claims which are not imprinted will be returned to dealership
5004 [illegible]

RETRO AND JEEP
BOX 1070
SYRACUSE NY 13[illegible]

RESUBMISSION OF CLAIM NO. 70183 [illegible] CLAIM NUMBER 14304

DELIVERY DATE OR FIRST USE DATE 8 1 84 DEDUCTIBLE $

MILES 8324 PAID 52085 X

ZONE AUTHORIZED SIGNATURE DATE

| ASSC | PART NO | PART DESCRIPTION | QTY | DEALER NET | WARR PRICE | RET P |
|---|---|---|---|---|---|---|
| C | 8993317 | GASKET | 1 | 2.84 | 3.69 | |
| A | 5764195 | HOSE | 1 | 3.86 | 5.02 | X |
| 1 | 3203277 | CLAMPS | 2 | 1.86 | 2.42 | X |
| | 8993850 | ANTIFREEZE | 1 | 4.85 | 6.31 | |

71

DESCRIPTION
Vehicle leaking oil and antifreeze
Pressure test cooling system
replace heater hose

TIC 6122 SUPPLIER CODE SUPPLIER NAME
CD

DESCRIPTION CAUSE AND CORRECTION
Screws laying in skid plate
Check no screws found that belonged to vehicle

TIC SUPPLIER CODE SUPPLIER NAME
CD

Vehicle leaking oil - Rescal Valve cover

71 -1143

LABOR CALCULATIONS

| | OPR NO | TIME | AMOUNT |
|---|---|---|---|
| A | 1005 | .5 | 13.00 |
| | ~~1999~~ 0063 | .3 | 7.80 |
| B | | | |
| C | 1282 | 1.5 | 39.00 |

ILLEGIBLE

184000

ALL CREDITED CLAIMS ARE SUBJECT TO AUDIT

STAPLE REQUIRED ATTACHMENTS TO BACK TOP LEFT CORNER

John Dobreski 52385
DEALER SIGNATURE

TOTAL PARTS 1744 TOTAL LABOR 5980 TOTAL CREDIT 77.24

WARRANTY DEPT. COPY

11753

# WARRA[illegible] INVOICE

Dealer must notify Claims Processors, Location within 90 days from the date of submission if disposition or payment of claim not received. Returned claims must be sent back within 90 days or will be subject to rejection.

Gre[illegible] Carlile
110 [illegible]
[illegible]ville CA

1JC [illegible] 030 ET 017 994

11 16 83 1/12

362

30 5542 1728

ROY BALDWIN MOTORS
PO BOX 40
SANTA CRUZ CA [illegible]

R.O. No. 10240

Miles 1425 Repair Date 12 [illegible] 83

**A**

Description: Oil [illegible] at rear of engine — 1149 Incident

Correction: Install missing grommet in rocker cover

Cleaned off oil and road tested Rechecked OK

Labor 13.28 — Parts .71

| Opr. No. | Time | Amount |
|---|---|---|
| 1999 | [illegible]4 | 13.28 |

**B**

Description: Incident

Correction: Supplier Name

Labor

Parts

| PART NUMBER List Causal Part No. | QTY | WAR. PRICE UNIT | WAR. PRICE TOTAL | DESCRIPTION | P. REV. |
|---|---|---|---|---|---|
| 3237765 | - | .71 | .71 | grommet | |

13 28
71
19 99

ALL APPROVED CLAIMS ARE SUBJECT TO AUDIT

Bill Baldwin — Date 1.4.84

Dealer Authorized Signature

In Canada, American Motors Canada, Inc. In Puerto Rico and U.S. Virgin Islands, American Motors Pan American Corporation

WARRANTY DEPT. COPY

1111753

00042

Ican Motors Sales Corporation

WARRANTY INVOICE — REPAIR ORDER

2R4536 464711 8507 113 87XX 18

480 3

24 5900 8400

LINCOLN

CLAIM NUMBER 05510

RESUBMISSION OF CLAIM NO

ZONE USE

SCOTT LYONS
900 No 56
LINCOLN NEBR

1JCCF87EOFT068753

3741 32786

21887

ZONE AUTHORIZED SIGNATURE DATE

CROSS REFERENCE RETAIL REPAIR ORDER NO

STAPLE REQUIRED ATTACHMENTS TO BACK TOP LEFT CORNER

ALL CREDITED CLAIMS ARE SUBJECT TO AUDIT

| | PART NO | QTY | PART DESCRIPTION | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | #65 Heater Fan Noise on turns or Hills Part Ordered Hog. | | | | |
| B | 8993317 | 1 | gskt | 2.95 | 3.84 | 7 1141 Leak Under Valve Cover Replace R+R valve cover - clean + reseal | B | 1282 | 1.5 | 51.00 |
| C | 5752010 | 1 | Boot | 2.25 | 2.93 | 7 3824 Tame Shift Boot Cracked R+R floor shift boot | C | 3465 | .4 | 13.60 |

000423

| | | TOTAL LABOR | TOTAL CREDIT |
|---|---|---|---|
| A | 3.84 | 51.00 | $ 54.84 |
| B | 2.93 | 13.60 | $ 16.53 |
| GRAND | 6.77 | 64.60 | $ 71.37 |

2/26/87

WARRANTY DEPT. COPY

FBA ...an Motors Sales Corporation

WARRANTY INVOICE — REPAIR ORDER

MMA499879-377 .49 10/84 CS-7 Waiting 24795.

Submit invoice within ... days from ... Late submission may result in ... Follow ... procedure in WAIT ...

CLAIM NUMBER: 09111

RESUBMISSION OF CLAIM NO:

ZONE USE

Janet Dezendorf
P.O. Box 767
Kihi Hi

87XX

1JCCF87A6FT054322

06685 063086

30 0465 3830

...UTTER A J N MAUI
... MAIN ST
... MAUI HI

REPAIR DATE: 032587

X

ZONE AUTHORIZED SIGNATURE

| | PART NO | QTY | PART DESCRIPTION | DATE | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| A | 8993317 | 1 | Form A Gasket | 5.68 | ~~3.69~~ | ~~1.38~~ 3.85 | 7/ 1.14.1 | A | 12.82 | 1.5 | 46.45 |

CK Oil Leak
Valve Cover leak
Reseal valve cover

T1040

CK Brakes - drags
when first start

ILLEGIBLE

EXPEDITE
CUSTOMER WAITING

STAPLE REQUIRED ATTACHMENTS TO BACK TOP LEFT CORNER

ALL CREDITED CLAIMS ARE SUBJECT TO AUDIT

| | | | |
|---|---|---|---|
| A | 7.38 | 46.45 | 55.83 |
| B | | | |
| | 7.38 | 46.45 | 55.83 |

Danny Vaur

Janet M. Dezendorf

T

WARRANTY DEPT. COPY

WARRANTY INVOICE — REPAIR ORDER

1985 GT

66533

26 0413

OWNER NAME AND ADDRESS
Roland Urspach
415 East Main
Lexington, Ohio

4307

8587

1FACP87AZFL181094
VIN

WARRANTY COVERAGE 1/12 DEDUCTIBLE

DOLLAR VALUE AUTHORIZED $ NOT TO EXCEED S.G.V. $ EXCEEDS S.G.V. ☐

REGION AUTHORIZED SIGNATURE DATE

| MILES | REPAIR DATE M D | DEL. DATE OR FIRST USE DATE M D Y | PAINT CODE | 2 TONE | RESUBMISSION OF INVOICE NO | INVOICE NUMBER |
|---|---|---|---|---|---|---|
| 9150 | 032387 | 0716 86 | | ☐ | | 8501 |

| A | PART NO | QTY | PART DESCRIPTION | DEALER NET UNIT PRICE | WARRANTY PRICE UNIT | WARRANTY PRICE EXTENDED |
|---|---|---|---|---|---|---|
| | 8983503343 | 1 | Cover | 20.97 | | 27.26 |
| | 3237765 | 2 | Grommet | 1.54 | 1.00 | 2.00 |
| | 3203077 | 1 | Clamp | 1.06 | | 1.38 |
| | 8982200287 | 1 | Oil | 1.30 | | 1.69 |
| A | SUBTOTAL | | | | | 32.33 |
| | 8134232 | 1 | Kit | 5.60 | | 7.28 |
| | 8983549 | 1 | Cleaner | 2.10 | | 2.73 |
| B | SUBTOTAL | | | | | 10.01 |
| C | | | | | | |
| C | SUBTOT | | | | | |

$33.00

ILLEGIBLE

W1 DEDUCTIBLE AUTHORIZATION NUMBER
1141
SUP CODE SUPPLEMENT NAME
DESCRIBE CONDITION, CAUSE AND CORRECTION
Valve Cover Leaking.
Valve Cover warped
Replace valve Cover.

W2 DEDUCTIBLE AUTHORIZATION NUMBER
1232 674 Carter
SUP CODE SUPPLEMENT NAME
DESCRIBE CONDITION, CAUSE AND CORRECTION
Engine idle orig. rich &
vibrate. Diagnose Computer
and adjust. Road test.

W3 DEDUCTIBLE AUTHORIZATION NUMBER
T.C.
SUP CODE SUPPLEMENT NAME
DESCRIBE CONDITION, CAUSE AND CORRECTION

| A | LABOR CALCULATIONS OPR NO | TIME | ALLOWANCE |
|---|---|---|---|
| | 0113 | 1.3 | 36.40 |
| A | SUBTOTAL | | |
| B | 1101 | 1.6 | 44.80 |
| | 0129 | .3 | 8.40 |
| B | SUBTOTAL | | 53.20 |
| C | | | |
| C | SUBTOTAL | | |

I certify the repairs on this unit were performed in this vehicle at my facility and that all parts and labor charged for were used and performed in accordance with Service Bulletins and Policy and Procedure Manuals.

Lynn Taylor
DEALER SIGNATURE

3/26/87
DATE

| TOTAL PARTS | TOTAL LABOR | TOTAL SALE |
|---|---|---|
| PAID $ 43.34 | $ 87.60 | $ 131.94 |

WARRANTY DEPT. COPY

STAPLE REQUIRED ATTACHMENTS TO EACH TOP LEFT CORNER

ALL CHECKED INVOICES ARE SUBJECT TO AUDIT

[redacted] Motor [redacted] Co[redacted]tion [redacted]

WA[illegible]Y INVOICE — REPAIR ORDER 901-

PL 0 47208

James Jewell

DEALER

22 4015 [illegible]

CRENVELGE MOTOR SLS
413 W MAIN
FREDRICKSBURG TX 78824
060105 J

CLAIM NUMBER: 06801

RESUBMISSION OF CLAIM NO.

ZONE USE

1 J C C F 8 7 9 1 5 1 7 1 3

9 4 9 2 0 4 0 5 8 6

REPAIR DATE: 03 09 87

ZONE AUTHORIZED SIGNATURE — DATE

| | PART NO. | QTY | PART DESCRIPTION | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| A | 8993317 | 1 | Sealer | 2.96 | 3.85 | 3.85 | no 1 14 1 | = | A | 1282 | 1.5 | 42.00 |

Correct engine oil leak. Seal valve cover. Sealer skips.

ILLEGIBLE

000426

STAPLE REQUIRED ATTACHMENTS TO BACK TOP LEFT CORNER

ALL CREDITED CLAIMS ARE SUBJECT TO AUDIT

Robert A. Crenvelge 3-09-87 — DEALER SIGNATURE — DATE

James Jewell 3-09-87 — CUSTOMER SIGNATURE — DATE

| | TOTAL PARTS | TOTAL LABOR | TOTAL CREDIT |
|---|---|---|---|
| A | $3.85 | $ 42.00 | $45.85 |
| B | $ | $ | $ |
| C | $ | $ | $ |
| GRAND | $3.85 | $ 42.00 | $45.85 |

WARRANTY DEPT. COPY

F8 Ame Motors Sales Corporation

WARRANTY INVOICE – REPAIR ORDER KOT 081

508941

DEALER

30 7883

KAUAI AUTO CENTER
P O BOX 1066
LIHUE HI 96736

JOHN GLASSNER
P.O BOX 212
KOLOA HI 96756

1JCCJ15N2FT103821

2158 121185

CLAIM NUMBER 06202

RESUBMISSION OF CLAIM NO

ZONE USE

REPAIR DATE 03/03/86

ENG TRANS CODE NO

CROSS REFERENCE RETAIL REPAIR ORDER NO

ZONE AUTHORIZED SIGNATURE DATE

| | PART NO | QTY | PART DESCRIPTION | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| A | 8993317 | 2 | SEALANT | 278 | 361 | 7.22 | 1141 | ENG OIL LEAK – RESEAL VALVE COVER | A | 1063 | 1.5 | 4800 |
| A | 32001 | 1 | CLAMP | 32 | 42 | 42 | | | | | | |
| B | 1370910 | 1 | INSULATOR | 1179 | 1533 | 1533 | | | | | | |
| | | | | | | | 2191 | CLUNK OVER BUMPS PIPE TRANS MOUNT BROKEN | B | 2015 | 0.6 | 19.20 |
| | | | | | | | 8868 | LIGHTER INOP Repair wire TO LIGHTER (Open) | C | 0085 | 0.5 | 1600 |

000427

ILLEGIBLE

4625

| | | | |
|---|---|---|---|
| A | 7.64 | 4800 | 55.64 |
| B | 15.33 | 19.20 | 34.53 |
| | | 16.00 | 16.00 |
| GRAND | 22.97 | 83.20 | 106.17 |

DEALER SIGNATURE

3/3/86

WARRANTY DEPT. COPY

STAPLE REQUIRED ATTACHMENTS TO BACK TOP LEFT CORNER

ALL CREDITED CLAIMS ARE SUBJECT TO AUDIT

# WARRANTY INVOICE—REPAIR ORDER

076 [illegible] 634 D'WAY

DEALER 6858

Submission within 21 days from R.O. date. Late submission may result in claim denial. Follow inquiry procedure in WAM II applicable.

Dealer Information Claims which are not imprinted will be returned to dealership

10 7588 3800
BRAUN ARC JEEP REN
011 N ORANGE AVE
ORLANDO FL 32801
[illegible]

Staple required attachments to back top left corner

Service part of ... (including special equipment installation) on record

Date vehicle entered or last serviced

Mileage when entered or last serviced

Claim RO Coverage No

Labor/Time Code No: 501C31

OWNER NAME AND ADDRESS
ROBERT MORICK
105 E GREEN TREE
LAKE MARY, FL. 32746

MODEL NO: 85 1ST

FAB NO

VIN: VJCCJ1SN8FT118243

DELIVERY DATE OR FIRST USE DATE: 08114 85T

WARR COV: 1/2

DEDUCTIBLE $

MILES: 10841

REPAIR DATE: 02141863

PAINT CODE: ☐ 2 TONE

SELLING DEALER: Y

REBUBMISSION OF CLAIM NO

CLAIM NUMBER: 078.03

3-12-86
DATE

| PART NO | PART DESCRIPTION | QTY | DEALER NET | WARR PRICE | NET P |
|---|---|---|---|---|---|
| 8773717 | Regulator | 1 | 100.20 | IX | |
| C 8983501398 | V/Cover | 1 | 23.50 | 30.55 | |
| C 8993317 | PTV | 1 | 2.84 | 3.69 | |
| 8576198 | Servo | 1 | 74.58 | 96.95 | |

DEALER CONDITION CAUSE AND CORRECTION
REPAIR RATTLING NOISE UNDER VEHICLE WHEN W. REVERSE
#17 TAIL PIPE RATTLING ON LEAF SPRING. CO. EXHAUST SYSTEM, INST, ALIGN, & TIGHTEN TO CLEAR SPRING.

INC 1971 SUPPLIER CODE SUPPLIER NAME
CO 71

DEALER CONDITION CAUSE AND CORRECTION
REPAIR INOP CRUISE CONTROL
#17 CABLE SEPERATED IN SERVO. CO. MOTOR SERVO REPLACE.

INC 8763 SUPPLIER CODE SUPPLIER NAME
CO 77

DEALER CONDITION CAUSE AND CORRECTION
REPAIR ENGINE OIL LEAK
#12 COVER WARPED, LEAKING. CO. COVER CYL HEAD REPLACE.

INC 1141 SUPPLIER CODE SUPPLIER NAME
CO 71

LABOR CALCULATIONS

| ADC | OPR NO | TIME | AMOUNT |
|---|---|---|---|
| A | 1824 | .3 | 9.60 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| B | 8241 | .5 | 16.00 |
| | 8759 | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| C | 1282 | 1.5 | 48.00 |
| | | | |
| | | | |
| | | | |
| | SUBLET | | |
| | SUBLET | | |

0004828

ALL CREDITED CLAIMS ARE SUBJECT TO AUDIT

This is to certify that the services described were performed on this vehicle at no charge to the owner using genuine AMC/Jeep/Renault parts and specified repair procedures. Also above repairs are not connected with any accident. Supporting shop records and parts removed are available for inspection by representatives of AMC.

DEALER SIGNATURE

DATE

$ 131.19 TOTAL PARTS

$ 7360.^ TOTAL LABOR

$ 204.79 TOTAL CREDIT

CUSTOMER'S SIGNATURE

DATE

In Canada: American Motors Canada Inc. In Latin America and Caribbean Nations: American Motors Pan American Corporation

WARRANTY DEPT. COPY

# WARRANTY INVOICE—REPAIR ORDER

Submit within 21 days from RO date. Late submission may result in claim denial. Follow inquiry procedure in WAM II applicable.

Eng/Trans Code No: 50K24

Zone No: Central Florida

Service Contract No:

Date Installed / Miles Serviced:

Mileage Miles Read:

Claim RO / Credit Memo No:

Joe Gullone
1447 Cardinal Ct
Winter Park FL 32789

MODEL NO: 185.15

FAB NO:

VIN: 1J4CCJ.15N5FT.105305

DELIVERY DATE OR FIRST USE DATE: 04/03/85

WARR COV: 1-12

DEDUCTIBLE $:

MILES: 109181

REPAIR DATE: 03/26/86

PAINT CODE: ☐ 2 TONE

SELLING DEALER: 8

RESUBMISSION OF CLAIM NO:

CLAIM NUMBER: 106109

DEALER: 03 1701

Dealer Information. Claims which are not imprinted will be returned to dealership.

10 7588 3800
BRAUN AMC JEEP RRM
911 N ORANGE AVE
ORLANDO FL 32801
0101d4 C

| PART NO | PART DESCRIPTION | QTY | DEALER NET | WARR PRICE | RET P |
|---|---|---|---|---|---|
| 8983039B | W/Cover | 1 | 23.50 | 32.55 | |
| 8993317 | R.T.V | 1 | 2.84 | 3.69 | |

Repair Oil Leak at Valve Cover

#1 COVER SLIGHTLY WARPED. CO. COVER CYL HEAD REPLACE.

TC: 1141 SUPPLIER CODE: SUPPLIER NAME:
CO: 71
DESCRIBE CONDITION CAUSE AND CORRECTION

TC: SUPPLIER CODE: SUPPLIER NAME:
CO:
DESCRIBE CONDITION CAUSE AND CORRECTION

TC: SUPPLIER CODE: SUPPLIER NAME:
CO:

| | OPN NO | TIME | AMOUNT |
|---|---|---|---|
| A | 1063 | 1.5 | 48.00 |
| | | | |
| SUBLET | | | |
| SUBLET | | | |

LABOR CALCULATIONS

$34.24 TOTAL PARTS — 48.00 TOTAL LABOR — $82.24 TOTAL CREDIT

This is to certify that the services described were performed on this vehicle at no charge to the owner using genuine AMC/Jeep/Renault parts and specified repair procedures. Also above vehicle was not involved in any accident. Supporting shop records and parts, if any, available for inspection by representatives of AMC.

DEALER SIGNATURE — DATE

CUSTOMER'S SIGNATURE — DATE

ALL CREDITED CLAIMS ARE SUBJECT TO AUDIT

STAPLE MOUNTED ATTACHMENTS TO BACK TOP LEFT CORNER

000429

In Canada: American Motors Canada Inc. In Latin America and Caribbean Islands: American Motors Pan American Corporation

WARRANTY DEPT. COPY

...ican Motors Sales Corporation
W... NTY INVOICE — REPAIR ORDER

332.30 86 26 1/38 4092

Johnny Robertson Cherokee
1200 ... 26TR
G/ville Fl 32601
JCCJ1 ... FT005578
4150 083085

4522

ZONE USE

ZONE AUTHORIZED SIGNATURE

10 7265 26.00
Richard Kelley AMC Jeep Renault
3525 NW 97th Blvd
Gainesville, Fl 32606
.092881 C.

020556

A 8993317 1 dealer P 284 369 369 1141 #19

Rear Main Seal
~~[illegible]~~
11 - R&R VALVE COVER GASKET A 063 1.5 39.00

000430

ILLEGIBLE

3.69 39.00 42.69

42.69

WARRANTY DEPT. COPY

1/85

6/85

NUMBER 06

'ATUS ACCEPTED WARRANTY :CE 32504

.ICROFILM A651692 INPUT DT 11/21/86 VIN 2CCA...79FB712853 IN SERVICE DT 09/21/86 COPS IN SERV DT 09/21/86
DEALER 04502 INPUT TIME 08:18 MODEL 38KC REPAIR DT 11/17/86 SELLING DLR SAME Y
INVOICE NO 32504 REPAIR ORDER 32103 FAB MILEAGE 03029 PAINT O
RESUB INVOICE COPS INVOICE DT 02/26/85

INCIDENT A FAPV MESSAGE: 9000 OK TO PAY - NO ADJUSTMENTS
INC TEXT: HORN VERY WEAK, REPL LOW TONE HORN, INOP.
WARR TYPE: 12 EXPENSE CD: 11 INC CD: 8211 SUPP CD: 846

OPER CD: 8076 OPER TEXT: HRS: 00.3 AMOUNT: 11.70

PART NO: 0003741286 PART TEXT: HORN QTY: 01 AMOUNT: 13.44

INCIDENT A TOTAL 25.14

INCIDENT B FAPV MESSAGE: 9000 OK TO PAY - NO ADJUSTMENTS
INC TEXT: OIL LEAK, REPL VALVE COVER WITH NEW TYPE TO CORRECT.
WARR TYPE: 12 EXPENSE CD: 11 INC CD: 1141 SUPP CD:

OPER CD: 1282 OPER TEXT: HRS: 01.5 AMOUNT 58.50

PART NO: 8983503343 PART TEXT: VALVE COVER QTY: 01 AMOUNT: 26.21

INCILENT B TOTAL 84.71

INCIDENT C FAPV MESSAGE: 9000 OK TO PAY - NO ADJUSTMENTS
INC TEXT: WATER LEAK INTO REAR COMPARTMENT. WATER TEST, REPL LIFTGATE SEAL, LOST SHAPE.
WARR TYPE: 12 EXPENSE CD: 11 INC CD: 6551 SUPP CD:

OPER CD: 6722 OPER TEXT: HRS: 00.2 AMOUNT: 7.80
6045 00.3 11.70

PART NO: 0003742795 PART TEXT: SEALER QTY: 01 AMOUNT: 30.86

INCIDENT C TOTAL 50.36

TOTAL INVOICE AMOUNT 160.21

000431

MICROFILM A651692

0/00

2/86

MICROFILM A650962 INPUT DT 11/21/86 VIN 2C[illegible]875TB708864 IN SERVICE DT 09/08/86 COPS IN SERV DT [illegible]/08/86
DEALER 00478 INPUT TIME 11:09 MODEL 38KC REPAIR DT 11/20/86 SELLING DLR SAME Y
INVOICE NO 32504 REPAIR ORDER 6378890 FAB MILEAGE 04132 PAINT O
RESUB INVOICE COPS INVOICE DT 11/26/84

INCIDENT A FAPV MESSAGE: 9000 OK TO PAY - NO ADJUSTMENTS
INC TEXT: NOISE FT. LT. WHEEL WHEN TURNING SHARP LEFT ROAD TEST REPL L.F. OUTER C.J. BOOT + JOINT
WARR TYPE: 12 EXPENSE CD: 11 INC CD: 2861 SUPP CD:

| | | | | | |
|---|---|---|---|---|---|
| OPER CD: 0129 | OPER TEXT: | HRS: | 00.3 | AMOUNT: | 10.05 |
| 2177 | | | 00.5 | | 16.75 |
| OPER CD: 2175 | OPER TEXT: | HRS: | 00.4 | AMOUNT: | 13.40 |
| PART NO: 0008132441 | PART TEXT: F. JOINT KIT | QTY: | 01 | AMOUNT: | 160.16 |
| 8983500976 | BOOT KIT | | 01 | | 10.05 |

INCIDENT A TOTAL 210.41

INCIDENT B FAPV MESSAGE: 9000 OK TO PAY - NO ADJUSTMENTS
INC TEXT: WHEN FIRST START CAR + PUT IN GEAR THERE'S VIBRATION IN REAR AXJ IDLE SPEEDS ALIGN EXHAU
WARR TYPE: 12 EXPENSE CD: 11 INC CD: 1232 SUPP CD: 614

| | | | | | |
|---|---|---|---|---|---|
| OPER CD: 1748 | OPER TEXT: | HRS: | 00.4 | AMOUNT: | 13.40 |
| 1824 | | | 00.3 | | 10.05 |

INCIDENT B TOTAL 23.45

INCIDENT C FAPV MESSAGE: 9000 OK TO PAY - NO ADJUSTMENTS
INC TEXT: ENG OIL LEAK REPL VALVE COVER GSK
WARR TYPE: 12 EXPENSE CD: 11 INC CD: 1141 SUPP CD:

| | | | | | |
|---|---|---|---|---|---|
| OPER CD: 1282 | OPER TEXT: | HRS: | 01.5 | AMOUNT: | 50.25 |
| PART NO: 0008993317 | PART TEXT: SEALANT | QTY: | 01 | AMOUNT: | 3.69 |

INCIDENT C TOTAL 53.94

TOTAL INVOICE AMOUNT 287.80

000432

MICROFILM A650962

8/25/86

1/05/85

STATUS ADJUSTED

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| MICROFILM | A649674 | INPUT DT | 11/20/86 | VIN | 2C4CK3875FB711554 | IN SERVICE DT | 08/25/86 | COPS IN SERV DT | 08/25/86 |
| DEALER | 05508 | INPUT TIME | 13:25 | MODEL | 38KC | REPAIR DT | 11/19/86 | SELLING DLR SAME | Y |
| INVOICE NO | 32412 | REPAIR ORDER | 107770 | FAB | | MILEAGE | 08026 | PAINT | 0 |
| RESUB INVOICE | | | | | | | | COPS INVOICE DT | 01/05/85 |

INCIDENT A FAPV MESSAGE: 9000 OK TO PAY - NO ADJUSTMENTS
INC TEXT: ENG KNOCKING-TIMMING SPEEDS RETARTED. SET TIMMING TO SPECS
WARR TYPE: 12 EXPENSE CD: 11 INC CD: 1711 SUPP CD:

| | | | | | |
|---|---|---|---|---|---|
| OPER CD: 1893 | OPER TEXT: | HRS: | 00.2 | AMOUNT: | 7.40 |
| | | INCIDENT A TOTAL | | | 7.40 |

INCIDENT B FAPV MESSAGE: 9000 OK TO PAY - NO ADJUSTMENTS
INC TEXT: REAR DEFROSTER GRID INOP-REPAIR 1 DEFROSTER GRID ON REAR WINDOW
WARR TYPE: 12 EXPENSE CD: 11 INC CD: 5452 SUPP CD:

| | | | | | |
|---|---|---|---|---|---|
| OPER CD: 8160 | OPER TEXT: | HRS: | 00.5 | AMOUNT: | 18.50 |
| PART NO: 0008123332 | PART TEXT: REPAIR KIT | QTY: | 01 | AMOUNT: | 23.95 |
| | | INCIDENT B TOTAL | | | 42.45 |

INCIDENT C FAPV MESSAGE: 9100 OK TO PAY - SYSTEM ADJUSTED PARTS & LABOR
INC TEXT: VALVE COVER LEAKING OIL- R AND R TO REPL WITH NEW STYLE VALVE COVER AND RESEAL.
WARR TYPE: 12 EXPENSE CD: 11 INC CD: 1141 SUPP CD:

| | | | | | |
|---|---|---|---|---|---|
| OPER CD: 0113 | OPER TEXT: | HRS: | 01.3 | AMOUNT: | 48.10 |
| PART NO: 8983503343 | PART TEXT: VALVE COVER | QTY: | 01 | AMOUNT: | 26.21 |
| 0004006502 | CLAMPS | | 04 | | 4.44 |

ADJUSTMENT: INCIDENT C ERROR 4040 PART/OPERATION 8983503343 ORIGINAL VALUE 39.31 ADJUSTED VALUE 26.21 FIELD NUMBER 0

| | | | |
|---|---|---|---|
| INCIDENT C TOTAL | | | 78.75 |
| TOTAL INVOICE AMOUNT | | | 128.60 |

000433

MICROFILM A649674

[redacted] ATUS ACCEPTED [redacted] WARRANT )ICE 33627

/23/85

/31/85

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| ,CROFILM | A671674 | INPUT DT | 12/02/86 | VIN 2C[illegible]856FB715806 | IN SERVICE DT | 12/23/85 | COPS IN SERV DT 12/23/85 |
| DEALER | 00450 | INPUT TIME | 14:38 | MODEL 38KC | REPAIR DT | 11/24/86 | SELLING DLR SAME Y |
| INVOICE NO | 33627 | REPAIR ORDER | 4394692 | FAB | MILEAGE | 11047 | PAINT O |
| RESUB INVOICE | | | | | | | COPS INVOICE DT 05/31/85 |

INCIDENT A FAPV MESSAGE: 8100 DEALER BEYOND CREDIT LIMIT
INC TEXT: REP ENGINE OIL LEAK-REPL V-COVER PER IS NOTE 1E
WARR TYPE: 12 EXPENSE CD: 71 INC CD: 1141 SUPP CD:

| | | | | | |
|---|---|---|---|---|---|
| OPER CD: 1999 | OPER TEXT: ST | | HRS: 01.7 | AMOUNT: | 57.80 |
| PART NO: 8983503343 | PART TEXT: COVER | | QTY: 01 | AMOUNT: | 26.21 |
| | | | INCIDENT A TOTAL | | 84.01 |

INCIDENT B FAPV MESSAGE: 8100 DEALER BEYOND CREDIT LIMIT
INC TEXT: REP COOLANT LEAK-REPL LEKAING WATER PUMP
WARR TYPE: 12 EXPENSE CD: 71 INC CD: 1111 SUPP CD:

| | | | | | |
|---|---|---|---|---|---|
| OPER CD: 1059 | OPER TEXT: | | HRS: 01.1 | AMOUNT: | 37.40 |
| PART NO: 8982775046 | PART TEXT: PUMP | | QTY: 01 | AMOUNT: | 22.36 |
| 0008993850 | COOLANT | | 01 | | 6.50 |
| 0000000000 | CLAMP | | 01 | | 0.44 |
| | | | INCIDENT B TOTAL | | 66.70 |

TOTAL INVOICE AMOUNT 150.71

000434

MICROFILM A671674

78 Ame [illegible] Motors Sales Corporation

WARRANTY

# INVOICE — REPAIR ORDER

557940

B.91 Tacke H

2CCCK38S4FB709678

8,973    111785

DEALER 18 90 01

26 0133

KENSON AND JP RAH
2210 GREENUP AVE
ASHLAND KY 41101

Claim Number: 33306

6428

12.11.48.4

| | Part No. | Qty | Part Description | | Unit | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| A | 599-2317 | 1 | Sealer | 284 | 3.69 | | A | 1212 | 1.5 | 40.50 |

71 / 1.41

Eng oil leak.
Valve Cover Leaking.
Resealed Valve Cover.

71 / 8445

| B | 5085 | .5 | 13.50 |
|---|---|---|---|

Dome Light Not working
cl. wiring. Repaired wiring.

ILLEGIBLE

000435

| | | | |
|---|---|---|---|
| A | 3.69 | 40.50 | 44.19 |
| B | | 13.50 | 13.50 |
| C | | | |
| GRAND | [illegible] | 54.00 | 57.69 |

[illegible signature] 11/28/86

WARRANTY DEPT. COPY

AMERICAN MOTOR SALES CORPORATION
WARRANTY INVOICE—REPAIR ORDER NSV247 7-7729 Cherokee. 23577

DEALER

Consuelo Stacy
301 5 St N W
Kasson Minn

78.

0801301

28 0091 3000

ROCHESTER AMC JP REN
600 37TH ST NE
ROCHESTER MN 55901
03II=5 C

Zone Use

1.3.C.4.8.7.8.4.1.F.T.0.6.1.5.7.0.1
12-12

11.15.84

11.89.6. 06.24.85

ZONE AUTHORIZED SIGNATURE | PART DESCR | DATE

8.9.5.6.0.0.0.5.9.6 arm 1 8A 1065

Rear Wiper Washer hose comes off arm
Hose too Short
Replace Arm assy
8553
7.11

Brakes pulsate W Applied
Nec to resurface rotors
fit - Rt and left
3276
7.11

Oil Leak at Engine
Reseal Valve cover
1141
7.11

| | | |
|---|---|---|
| A8080 | 02 | 6.00 |
| B3742 | 1.2 | 36.00 |
| C1063 | 1.0 | 30.00 |

17.7.03

ILLEGIBLE

IN DEALERSHIP AUTHORIZATION 32
Repair Authorization
TROUBLE
POLICY AUTHORIZATION
Dealer Owner AMSC Total Repair

Samuel DeSoy 6-24-85
Date

000436

Janette Tanner 6/28/85

10.65 | 72.00 TOTAL LABOR | 82.65 TOTAL CREDIT

WARRANTY DEPT COPY

23 780

CAN MOTORS SALES CORPORATION
WA NTY INVOICE—REPAIR ORDER GEG-961 6-1015 621 Chero

T+A Serv
600 S. Charlotte
S.F. SD 57103

78

DEALER

DUKE TUFTY CO
2317 S MINNESOTA
SIOUX FALLS SD 57101

2908

I.J.C.U.B.7.8.1.6.E.T.0.9.4.9.9.0

DELIVERY DATE OR SERVICE DATE 6.21.0.94

MILES 0.1.1.9.3 REPAIR TIME 0.60.6.8.5

RESUBMISSION OF CLAIM NO

CLAIM NUMBER 1570

ZONE AUTHORIZED SIGNATURE

| PART NO | PART DESCRIPTION | QTY | DEALER NET | | | LABOR CALCULATIONS OPR NO | TIME | AMOUNT |
|---|---|---|---|---|---|---|---|---|
| ~~89835-P-317~~ | ~~[illegible]~~ | ~~1~~ | ~~1107~~ | ~~1437~~ | Repair rattle in rear test drive several times to locate rattle under cover on right rear stem to repair | | | |
| 89835-P-871 | wheel | 1 | 4799 | 62.27 | Install S.D.P. steering wheel Replaced steering wheel, was cracked | B 3126 | .4 | 8.40 |
| | | | | | 3636 71 | C 1063 | 1.0 | 21.00 |
| | | | | | Repair oil leak R+R valve cover + reseal | | | |
| | | | | | 1141 71 | | | |

000437

ILLEGIBLE

$62.27 TOTAL PARTS $29.40 TOTAL LABOR $91.67 TOTAL CREDIT

Anita Massey

WARRANTY DEPT. COPY

Roy Bjornbo 6/24/85

TL 8.14

ALL CREDITED CLAIMS ARE SUBJECT TO AUDIT

PR AMC N MOTORS SALES CORPORATION
WARR / INVOICE—REPAIR ORDER 27408

2332 2

Submit invoice within 21 days from R.O. date. Late submission may result in claim denial. Future inquiry procedure in WAM II applicable

Eng Trans Code/No 412U19

OWNER NAME AND ADD
Rob Kleier
2106 North Haven Road
Claremore, Ok 74017

78XX
MODEL NO

FAB NO

1 J C U B 7 8 1 2 F T 0 1 7 2 9 2
VIN

DELIVERY DATE OR FIRST USE DATE 02/01/85

WARR COV 12/12

PRODUCT LEVEL 0

MILES 6139

REPAIR DAT 06/07/85

PAINT CODE

SELLING DEALER X

DEALER

Dealer Information. Claims which are not imprinted will be returned to dealership.

28 0627 0000

METRO MOTORS INC
2815 E 11TH
TULSA OK 74104
000168 J

RESUBMISSION OF CLAIM NO

CLAIM NUMBER 16213

ALL CREDITED CLAIMS ARE SUBJECT TO AUDIT

| LOC | PART NO | PART DESCRIPTION | QTY | DEALER NET | WARR PRICE | CAUSE AND CORRECTION | LOC | LABOR OPN NO | LABOR TIME | LABOR AMOUNT |
|---|---|---|---|---|---|---|---|---|---|---|
| A | 8 55 6 0 0 90 3 0 | switch | 1 | 6.39 | 8.31 | Defroster goes on and off, short in switch, R&R rear defroster switch<br>8256 SUPPLIER CODE 999 SUPPLIER NAME Unknown<br>CD | A | 8732 | .4 | 11 60 |
| B | 8 93 6 0 00 4 0 0 | relay | 1 | 6.85 | 8.91 | Rear wiper inoperative, relay shorted, R&R tailgate panel to replace rear wiper relay<br>8225 SUPPLIER CODE 999 SUPPLIER NAME Unknown<br>CD 44 D-101 #12713 | B | 8999 | .5 | 14 50 |
| C | 0 00 8 9 9 3 3 17 | gasket | 1 | 2.84 | 3.69 | Valve cover gasket leaking, reseal valve cover<br>1141 SUPPLIER CODE 999 SUPPLIER NAME Unknown<br>CD | C | 1063 | 1.0 | 29 00 |
| | | | | | | | | SUBLET | | |
| | | | | | | | | SUBLET | | |

5/25

ILLEGIBLE

000428

To the best of my knowledge, all the services listed on this repair order have been performed and all parts listed have been used in the repair of the owner's vehicle. Genuine AMC/Jeep Renault parts and new or remanufactured parts equivalent to genuine parts were used in the repair of the owner's vehicle. Subject to the terms and conditions and parts and labor warranties in the Owner's Warranty Information booklet, I represent that the repairs listed on this repair order have been performed and parts used in accordance with the applicable Chrysler Canada Ltd. or Motor Parts Canada Inc. Warranty.

Bill Thomas 06/11/85
DEALER SIGNATURE DATE

$ 20.91 TOTAL PARTS
$ 55.10 TOTAL LABOR
$ 76.01 TOTAL CREDIT

Robert W. Kleier 06/06/85
CUSTOMER'S SIGNATURE DATE

WARRANTY DEPT. COPY

...AN MOTORS SALES CORPORATION
W...ANTY INVOICE—REPAIR ORDER GEX 485 9.4 958 85 [illegible]

2 832

Bryan Bethle 7.8
2901 E 22nd
SFSD

DEALER

2100

DUKE TUFTY CO
2317 S MINNESOTA
SIOUX FALLS SD 57101

11JCUB7.81XET094989
1/12

Zone Use

ENTRY DATE 8/18/84

MILES 11.1.6.4.6 | 6/17/85 | PAINT CODE | SERVICE DEALER 0

RESUBMISSION OF CLAIM NO

CLAIM NUMBER 16902

ZONE AUTHORIZED SIGNATURE

| | PART NO | PART DESCRIPTION | QTY | DEAL | WARRANTY |
|---|---|---|---|---|---|
| | ~~8.76.300 1.9.5P~~ | ~~MCA~~ | ~~1~~ | | |
| C | 8993.31.1 | Sealer | 1 | 284 | 369 |
| B | | Kit | | | |

Paint doesn't match on Cowl PRO

Stumble on Left turn
Idle rough pointing PRO
[illegible] top of cars
[illegible] INSTALL
[illegible] TO [illegible]
RESPECT CARB TO [illegible]
CO 24 1.220

~~Install Sup Steering wheel~~
~~[illegible] Steering Wheel~~
[illegible] AIR [illegible] LOAD
[illegible] + [illegible]

1141
CO 71

| | OPR NO | TIME | AMOUNT |
|---|---|---|---|
| B | 1100 | 1.7 | 35.70 |
| | D1031 | | |
| C | 1063 | 1.0 | 21.00 |

SUBLET

$ 3.69 TOTAL PARTS | $ 56.70 TOTAL LABOR | $ 60.39 TOTAL CREDIT

ALL CREDITED CLAIMS ARE SUBJECT TO AUDIT

000439

ILLEGIBLE

[signature] 6/26/85

TL 8 14

WARRANTY DEPT. COPY

[redacted] MI[redacted] SA[redacted]ORI[redacted]ION[redacted] 16P 03

WA[redacted]NTY INVOICE—REPAIR ORDER 28597 Hu 7/4/85 Jeep

Jeep Ot
12 Maplewood
Northport NY

DEALER

30 5735 4000

ATLANTIC A J R
[illegible]
W ISLIP NY 11718

Zone Use

ZONE AUTHORIZED SIGNATURE DATE

1JCUB7839F+012897

62-15 85

5350 6625 85

CLAIM NUMBER 17934

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| A 8956000912 | Horn | 1.834 | 104 | Horn inop | A 8076 | 0.3 | 12.00 |
| 8956001134 | Horn | 1.834 | 104 | Replace horns | | | |
| | | | | 8.211 1.844 | | | |
| B 8993317 | R+V | 1.284 | 369 | Chail leak | B 1063 | 1.0 | 40.00 |
| | | | | Nec to reseal V/C (lefside) | | | |
| | | | | 1143 11 1141 | | | |
| C 8983501024 | Pump | 1.355 | 462 | Jeep very sluggish | C 1892 | 0.2 | 8.00 |
| 8983501013 | Gst | 1.767 | 997 | Ck + reset timing | 1868 | 1.0 | 40.00 |
| | | | | Replace acc pump on cart | 0129 | 0.3 | 12.00 |
| | | | | 1244 11 | | | |

ILLEGIBLE

ALL CREDITED CLAIMS ARE SUBJECT TO AUDIT

800440

6/28/85

39.96 | 112.00 | 151.96

PART | TOTAL LABOR | TOTAL CREDIT

WARRANTY DEPT COPY

438 13

American Motors Sales Corporation

WARRANTY INVOICE – REPAIR ORDER

ARG 944 216 35 85 Ger

Lyb Wandering
RR 1
Elgin MN 55932

1JCUC7846FT161273

09931 06/11/85

060386

DEALER

28 0091 3000

ROCHESTER AMC JP REM
800 SYTH ST NE
ROCHESTER MN 55901

CLAIM NUMBER 15302

| PART NO. | QTY | PART DESCRIPTION | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| 8923317 | 1 | [illegible] | 2.4 | 369 | 1141 | | A | 1063 | 1.0 | 30.00 |

71 Engine leaks oil
Nec to reseal Valve
Cover

000441

ILLEGIBLE

3.69 30.00 33.69

This is to certify that the services described were performed on this vehicle at no charge to the owner, using genuine AMC/Jeep/Renault parts and specified repair procedures. Also, all our repairs are not covered with any accident. Supporting shop records and parts, if required, are available for inspection by representatives of AMC.*

Ginny Douglas 6/6/86
DEALER SIGNATURE DATE

CUSTOMER SIGNATURE

* In Canada: American Motors Canada Inc. In Latin American and Caribbean Islands American Motors Pan American Corporation

WARRANTY DEPT COPY

Motors Sales Corporation

Y INVOICE — REPAIR ORDER

45752

Jerry Chellgren
4113 13th Ave Nw
Rochester MN 55401

78

DEALER

28 1568 2400

ROE ANC JEEP CO
881 CONCORD ST
W CONCORD MN 55900
030198 C

CLAIM NUMBER 1.6001

ZONE USE

1JCUC 7840FT171829

18113 7360 062185

06.03.86

| | PART NO | QTY | PART DESCRIPTION | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| A | 8983502798 | 1 | Seal | 5.18 | 6.73 | 6.73 | 2206 | 71 | Oil Leaking from front out put Shaft Seal Bad Seal Replace Seal | A | 2205 | 0.7 | 16.80 |
| | | | | | | | | | | | 2196 | 0.6 | 14.40 |
| | | | | | | | | | | | 2197 | 0.1 | 2.40 |
| B | 8983502798 | 1 | Seal | 5.18 | 6.73 | 6.73 | 2204 | 71 | Oil Leaking from Bar out put Shaft Bad Seal Replace Seal | B | 2238 | 0.6 | 14.40 |
| | | | | | | | | | | | 2196 | 0.6 | 14.40 |
| | | | | | | | | | | | 2197 | 0.1 | 2.40 |
| C | Sealant | 1 | RTV | 4.29 | 6.00 | 6.00 | 1141 | 71 | Oil Leaking from cylinder head cover Bad Seal Reseal Cover | C | 1063 | 1.0 | 24.00 |

000442

| | | | |
|---|---|---|---|
| A | $ 6.73 | $ 33.60 | $ 40.33 |
| B | $ 6.73 | $ 31.20 | $ 37.93 |
| C | $ 6.00 | $ 24.00 | $ 30.00 |
| GRAND | 19.46 | 88.80 | $ 108.26 |

Merle R. Mandel 6/4/86

WARRANTY DEPT. COPY

S1 ACCEPTED WARRANTY [illegible]04

MICROFILM A395168 INPUT DT 06/25/86 VIN 1JCUC7[illegible]1179059 IN SERVICE DT 09/09/85 COPS IN SERV DT 09/0[illegible]85
DEALER 07620 INPUT TIME 15:04 MODEL 78CU REPAIR DT 06/24/86 SELLING DLR SAME Y
INVOICE NO 17604 REPAIR ORDER 84241 FAB 0061856 MILEAGE 11098 PAINT M
RESUB INVOICE COPS INVOICE DT 06/20/85

INCIDENT A FAPV MESSAGE: 9000 OK TO PAY - NO ADJUSTMENTS
INC TEXT: OIL LEAK ENG BY CVR CYL HEAD GSKT R AND R CVR CYL HEAD CLEAN AND REPLACE GASKET
WARR TYPE: 12 EXPENSE CD: 71 INC CD: 1141 SUPP CD:

| | | | | | |
|---|---|---|---|---|---|
| OPER CD: 1063 | OPER TEXT: | | HRS: 01.0 | AMOUNT: | 34.00 |
| PART NO: 0003241731 | PART TEXT: GASKET | | QTY: 01 | AMOUNT: | 7.11 |
| 0008993317 | SEALER | | 01 | | 3.69 |
| | | INCIDENT A TOTAL | | | 44.80 |

INCIDENT B FAPV MESSAGE: 9000 OK TO PAY - NO ADJUSTMENTS
INC TEXT: OIL LEAK ON TRANS BY LOWER PAN GSKT R AND R PAN ON TRAN AND RPLCEGASKET
WARR TYPE: 12 EXPENSE CD: 71 INC CD: 2382 SUPP CD:

| | | | | | |
|---|---|---|---|---|---|
| OPER CD: 2224 | OPER TEXT: | | HRS: 00.6 | AMOUNT: | 20.40 |
| PART NO: 0008136660 | PART TEXT: GASKET | | QTY: 01 | AMOUNT: | 2.39 |
| 0008993865 | DEXTRON | | 01 | | 1.66 |
| | | INCIDENT B TOTAL | | | 24.45 |

TOTAL INVOICE AMOUNT 69.25

000443

MICROFILM A395168

AMERICAN MOTORS SALES CORPORATION

# WARRANTY INVOICE—REPAIR ORDER

2/ 199

Submit invoice within 21 days from R O date Late submission may result in claim denial
For low inquiry procedure in WAM it applicable

Leg/Trans Code/No

Service part or ... transmission or equipment ... received

Date sustained unit serviced

Mileage when ... unit serviced

Claim RO ... No

OWNER NAME AND ... SS
Rick Anderson
434 Hancock
Lander, Wyoming 82520

FAB NO

1 J C U L 7 7 2 9 F T 0 6 6 7 2

VIN

DELIVERY DATE / FIRST USE DAT 03 13 85

WAR COV

DEDUCTIBLE $

MILES 10864

REPAIR DATE 10 19 85

PAINT CODE

2 TONE

SELLING DEALER N

DEALER

(Dealer ... information Claim ... which are not ... will be returned to dealership

24 7500 0880
WIND RIVER VW INC
PO BOX F HWY 287
LANDER WY 82520
CODE C

R.O. 10935

RESUBMISSION OF CLAIM NO

CLAIM NUMBER 319-03

STAPLE REQUIRED ATTACHMENTS TO BACK TOP LEFT CORNER

ALL CREDITED CLAIMS ARE SUBJECT TO AUDIT

| ADD. | PART NO. | PART DESCRIPTION | QTY | DEALER NET | WARR PRICE | REF P |
|---|---|---|---|---|---|---|
| A | 3241731 | Gasket | 1 | 5.23 | 6.80 | |
| A | 3242121 | Cover | 1 | 20.97 | 27.26 | |

ILLEGIBLE

000444

DESCRIBE CONDITION CAUSE AND CORRECTION

Valve cover leaking from crack in upper right center of valve cover. Replace cover and gasket.

1141 SUPPLIER CODE --- SUPPLIER NAME ----

CO

DESCRIBE CONDITION CAUSE AND CORRECTION

IN SUPPLIER CODE SUPPLIER NAME

CO

DESCRIBE CONDITION CAUSE AND CORRECTION

SUPPLIER CODE SUPPLIER NAME

CO

| CD | LABOR CALCULATIONS OPR NO | TIME | AMOUNT |
|---|---|---|---|
| A | 1063 | 1.00 | 25.50 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | SUBLET | | |
| | SUBLET | | |

This is to certify that the services described above were performed in ... charge to the owner using genuine AMC/Jeep/Renault parts and ... All warranty repairs and adjustments made by any authorized Service ... were performed in accordance with ... given by the manufacturer above.

DEALER/AUTHORIZED SIGNATURE

11/15/85
DATE

In Canada American Motors Canada Inc. or Jeep International Ltd. where applicable

$ 34.06 TOTAL PARTS

$ 25.50 TOTAL LABOR

$ 59.56 TOTAL CREDIT

CUSTOMER'S SIGNATURE

DATE

WARRANTY DEPT. COPY

FARMAN MOTORS SALES CORPORATION
WARRANTY INVOICE—REPAIR ORDER

198 8

DEALER Tom.

RACINE A
6940 W WASHINGTON
RACINE WI 53406
640186 C

Zone Use

CLAIM NUMBER 89716

ZONE AUTHORIZED SIGNATURE

| | PART NO | PART DESCRIPTION | QTY | | |
|---|---|---|---|---|---|
| A | 3241669 | SEAL | 1 | 3.81 | 4.95 |
| A | 3241731 | GSKT | 1 | 5.23 | 6.80 |
| A | 4607123 | BOLTS | 6 | 3.60 | 4.68 |
| A | 89822002 87 | OIL | 1 | 1.89 | 2.46 |
| B | 89550023 40 | WINDOW | 1 | 32.82 | 42.67 |
| B | 89550023 41 | WINDOW | 1 | 32.82 | 42.67 |

S.O.P. Rear Main Leaking
R+R TRANS + TRANS CASE
REPLACE REAR MAIN SEAL IN ENGINE
LEAKING OIL
1026 663 SEAL STRIPPER
71

S.O.P. Right + Left Wing Windows Leaking
R+R BOTH WINGS WITH NEW
LEAKS WATER
66.15
71

S.O.P. Valve Cover Gasket
R+R VALVE COVER - REPLACE WITH NEW SEALANT
LEAKING OIL
1141
71

| | | | |
|---|---|---|---|
| A | 1817 | 2.9 | 104.40 |
| ~~A~~ | ~~2760~~ | ~~1.4~~ | |
| ~~B~~ | ~~5308~~ | | |
| B | 0999 | | 50.00 |
| C | 1063 | 1.0 | 36.00 |
| | ~~[illegible]~~ | ~~[illegible]~~ | ~~50.00~~ |

$ 10423 TOTAL PARTS
$ 19040 TOTAL LABOR
$ 29463 TOTAL CREDIT

ALL CREDITED CLAIMS ARE SUBJECT TO AUDIT

ILLEGIBLE

000445

WARRANTY DEPT. COPY

F8 Ame Motors Sales Corporation
# WARRANTY INVOICE—REPAIR ORDER

LICENSE NO: HZ4-908 | PHONE NO: 581-3157 | 85/Cherokee

047

22 4769 DEALER 3420

Submit invoice within 21 days from R.O. date. Late submission may result in claim denial. Follow inquiry procedure in WAM if applicable.

CLAIM NUMBER: 3 4 4 2 3 | RESUBMISSION OF CLAIM NO: 2 8 1 1 1

OWNER NAME AND ADDRESS: Shoes Too, 1717 San Pedro, Albuquerque, NM 87110

MODEL: 8 5 7 3

FAB NO: 0 0 1 7 2 9 9

1 J C U 7 7 1 5 F F 1 0 1 5 9 0

7 8 8 1 05 16 85

REPAIR DATE: 10 03 85 | PAINT CODE | 2 TONE | SELLING DEALER: 3

ENG-TRANS CODE NO | CROSS REFERENCE RETAIL REPAIR ORDER NO

| | PART NO | QTY | PART DESCRIPTION | DEALER NET UNIT PRICE | WARRANTY PRICE UNIT | WARRANTY PRICE EXTENDED | REF P |
|---|---|---|---|---|---|---|---|
| A | 3241731 | 1 | Gasket | | | 6.63 | |
| B | 8836000970 | 1 | Valve,Ch | | | 3.45 | |

WT 1/1 | SELECTIBLE | AUTHORIZATION NUMBER

1 1 4 1 | SUP CODE | SUPPLIER NAME

DESCRIPTION CONDITION CAUSE AND CORRECTION: Check for oil leak,RER valve cover and reseal-Gasket still leaking-had to replace.

WT | SELECTIBLE | AUTHORIZATION NUMBER

6 1 7 | SUP CODE | SUPPLIER NAME

DESCRIPTION CONDITION CAUSE AND CORRECTION: Check for water leak,Valve for rear washer was leaking,Had to replace rear washer valve.

WT | SELECTIBLE | AUTHORIZATION NUMBER

SUP CODE | SUPPLIER NAME

DESCRIPTION CONDITION CAUSE AND CORRECTION

| | OPR NO | TIME | AMOUNT | TEXT |
|---|---|---|---|---|
| A | 1065 | 1.0 | 34.00 | |
| | 1063 | | | |
| B | 8126 | 0.3 | 10.20 | |

000446

STAPLE REQUIRED ATTACHMENTS TO BACK TOP LEFT CORNER

ALL CREDITED CLAIMS ARE SUBJECT TO AUDIT

DEALER SIGNATURE | DATE 10/4/85

CUSTOMER SIGNATURE

A | TOTAL PARTS | TOTAL LABOR | TOTAL CREDIT

B

C

GRAND 10.03 | 44.23 | 54.26

WARRANTY DEPT. COPY

Motors Sales Corporation
WARR. Y INVOICE REPAIR ORDER

51317

Harry Francis Lotterman
1655 W Linden
Mesa, Az 5202

7777

30 7693 6000

MESA ANG JEEP INC
1350 W MAIN ST
MESA AZ 85201

31.466

1 5 C U L 7 7 2 9 F T 109331

11181 050385 82256.3

103085

11

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| A 3242854 | 1 | v/c gasket | 2.94 | 2.94 | 3.81 | 1141 engine oil leak v/c gaskets leak replace v/c gasket | A 1063 | 1.0 | 28.00 |
| B 8952001141 | 1 | hose P/S | 12.12 | 12.12 | 15.74 | 11 | B 1425 | 0.6 | 16.80 |
| B 8993342 | 1 | fluid | 2.16 | 2.16 | 2.81 | 3661 Power steering leak High Pressure hose faulty replace high Pressure hose [illegible] system | B ~~1977~~ 093 | 0.3 | 8.40 |
| C 8992564 | 3 | freon | 1.96 | 1.96 | 2.54 | 13 1386 A/C blows warm air Loose fitting at Comp Repair evacuate & Recharge | C 6066 | 0.8 | 22.40 |

| | | |
|---|---|---|
| 3.81 | 28.00 | 31.81 |
| 18.57 | 25.20 | 43.77 |
| 25~~[illegible]~~ | 22.40 | 24.94 |
| 24.92 | 75.60 | 100.52 |

Herbert H Snyder 11/27/85

WARRANTY DEPT COPY

N110

000447

000448

ATTACHMENT VIII

# DOMESTIC PART SALES

## Non-Metallic Cover

| REF | YEAR | JAN | FEB | MAR | APR | MAY | JUN | JUL | AUG | SEP | OCT | NOV | DEC |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| A. | 1981-85 | (See note.) | | | | | | | | | | | |
| | 1986 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| | 1987 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| B. | 1984-85 | (See note) | | | | | | | | | | | |
| | 1986 | 56 | 42 | 30 | 32 | 31 | 53 | 46 | 31 | 32 | 3 | 0 | 1 |
| | 1987 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| C. | 1985 | | | - | - | | | | | | - | 0 | 0 |
| | 1986 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 30 | 108 | 54 | 106 |
| | 1987 | 127 | 122 | 136 | 122 | 124 | 240 | 137 | 43 | 73 | 143 | 128 | 143 |
| D. | 1985 | | | - | | - | - | - | - | - | 0 | 0 | 0 |
| | 1986 | 0 | 0 | 0 | 0 | 134 | 142 | 42 | 24 | 33 | 19 | 10 | 12 |
| | 1987 | 15 | 16 | 19 | 35 | 20 | 28 | 45 | 24 | 25 | 26 | 19 | 19 |
| E. | 1984-85 | (See note) | | | | | | | | | | | |
| | 1986 | 3022 | 2207 | 2154 | 2567 | 2433 | 1304 | 269 | 31 | 3 | 3 | 0 | 0 |
| | 1987 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| F. | 1986 | | | - | | | | | | | 0 | 0 | 1 |
| | 1987 | 0 | 3 | 0 | 0 | 0 | 0 | 1 | 1 | 1 | 0 | 0 | 0 |
| G. | 1985 | | | | | - | | | - | - | 0 | 0 | 0 |
| | 1986 | 0 | 0 | 0 | 0 | 0 | 1195 | 2420 | 2300 | 2416 | 3182 | 2144 | 2731 |
| | 1987 | 2928 | 2517 | 2992 | 3120 | 2619 | 2929 | 2719 | 2501 | 2739 | 1943 | 5962 | 2757 |

NOTE:
Information previously furnished to NHTSA provided by AMC
Reference: EA84-015, February 17, 1986.

---

Key:

A = 3237808 cover
1981-1984 AMC/Jeep w/2 cyl head cover mounting bolts 258 CID (4.2L)

B = 8933 002 393 cover
1984/85 AMC/Jeep 4.2L w/5 cylinder head cover mounting bolts and 2 retainer nuts

C = 8983 003 857 cover
1983-85 AMC/Jeep, 2.5L (4 cyl.)

D 8933 003 691 cover
1986 AMC/Eagle Jeep Grand Wagoneer/Truck, 1987 Jeep Wrangler equipped with a 4.2L engine

E = 8983 501 398 cover kit
1981-84 AMC/Jeep 4.2L subbed from 3237 808

F 8933 004 109 cover kit
1981-86 AMC/Jeep 4.2L Used in Kit "F" 8983 503 343

G 8983 503 343 cover kit
AMC/Jeep, 4.2L

0385u/au

000449

IX