March 19, 2002

Dear Indian Motorcycle Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

REASON FOR NOTICE

Indian Motorcycle Corporation ("IMC") has determined that a defect which relates to motor vehicle safety exists in 2002 Scout and Spirit models produced through March 8, 2002. The defect is in the design of the rear fuel tank mounting brackets. Fractures can occur at the top of the joint where the bracket is welded to the tank back plate, potentially allowing gas to escape from the tank.

WHAT YOUR INDIAN DEALER WILL DO

Your IMC dealer will replace your gas tanks with tanks that have a redesigned mounting bracket. This replacement will be performed without charge to you.

WHAT YOU SHOULD DO

Please contact your IMC dealer as soon as possible to arrange a service date so the dealer may install your new gas tanks. The time necessary to replace the gas tanks is about an hour. Please ask your dealer for additional information on scheduling this service for your bike and the anticipated delivery date of the new gas tanks.

Your IMC dealer is fully prepared to assist you. Please take your motorcycle to the dealer who sold it to you, as this dealer has been notified specifically that your motorcycle needs this service and is expecting your call. If you have moved, or your dealer is no longer in operation, please contact Julie Wood at IMC customer service at 1-408-846-7228. Also, if you take your bike in on the agreed service date and the gas tank is not replaced within five days, please call Julie Wood. If you have sold or traded your bike, please let us know by completing the postage paid reply card and returning it to us.

If after contacting your dealer and IMC customer service you still have not received the necessary service without charge within a reasonable amount of time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street S. W., Washington, D.C. 20590 or call 1-888-327-4236. (Washington D.C. residents use 1-202-366-0123.)

We here at Indian apologize for any inconvenience this has caused you. Please understand that we have sent you this notice because we care about your safety and the quality of our products. We urge you to get your bike serviced promptly.

Thank you for your attention to this important matter.

George Nobile, Vice President of Warranty and Customer Service

200 EAST TENTH ST. • GILROY, CALIFORNIA • U. S. A. 95020
TEL: (408) 846-7228 • FAX: (408) 847-3902