Equipment Safety Recall Quarterly Report Information

Report Date: 2014-04-02

Calendar Quarter (circle one): January 1 – March 31
April 1 – June 30
July 1 – September 30
October 1 – December 31

Manufacturer (name, address, phone): Öhlins Racing, Box 722,
Instrumentvägen 8-10,SE-194 27 Upplands Väsby, Sweden

Name, address, email, and phone and fax numbers for the person(s) to whom inquiries about this report should be directed:
Oskar Ahlgren, Öhlins Racing, Box 722,
Instrumentvägen 8-10, SE 194 27 Upplands Väsby, Sweden

Subject equipment (type of equipment, part/model number, and any other information necessary for identifying the equipment):
Steering damper brackets sold on the aftermarket for models listed below.

Boxes framed with ☐ contain information about the initial recall that was notified 2013-06-19.

Boxes framed with ☐ contain information about the addition to the recall campaign.

Type of equipment (e.g., tire, child restraint, headlamp): Universal Steering damper kit for BMW S1000 RR
Part/Model number: SD 033, SD 037, SD 038
Size and function (where applicable):
Inclusive dates of manufacture (month and year): 2008-09 to 2013-10
Other information necessary to describe this equipment:
Total number of these items of equipment: SD 033: 666 items SD 037: 25 items SD 038: 110 items

1. NHTSA Safety Recall Campaign Number: 13E-034

Manufacturer's assigned campaign number (where applicable): N/A

2. (a) The date notification to purchasers began: Unknown as Öhlins sells to a distributor who sells to independent dealers who sells further to the end customer.

(b) The date notification of purchasers was completed: -

(c) The date notification to dealers and distributors began: 2013-07-02

(d) The date notification of dealers and distributors was completed: 2013-11-19

3. The total number of items of equipment involved: Initial: 801

NOTE: The number figures given in responses to numbers 4 and 5 below are to be stated in the cumulative (e.g., in consideration of any previous quarter's information).

4. (a) Total number inspected and remedied: 113

(b) Total number inspected, but determined NOT to require the remedy: N/A

5. Numbers of items of equipment determined to be unreachable for inspection due to:

Export: _____

Theft: _____

Scrapping: _____

Failure to receive a notification of the recall: _____

Other reasons (specify below): _____

Unknown at this point of time.

Total number of items of equipment unreachable for inspection: Unknown at this point of time.

6. The number of items of equipment repaired and/or returned by dealers, distributors, and other retailers prior to sale: 113

This report may be e-mailed to RMD.ODI@dot.gov or facsimiled to (202) 366-7882.