Equipment Safety Recall Quarterly Report Information
NHTSA Safety Recall Campaign Number: 13E-055

Report Date: **July 31, 2014**

Calendar Quarter	**April 1 – June 30, 2014**

Manufacturer:

ILJIN Global Co. Ltd.
c/o ILJIN USA Corporation
28055 Haggerty Road
Novi, MI 48377

Name, address, email, and phone and fax numbers for the person(s) to whom inquiries about this report should be directed:

Kelly T. Grubaugh
Director - Engineering & Quality Assurance
ILJIN USA Corporation
28055 Haggerty Road
Novi, MI 48377
248-848-1021 Office
734-693-4546 Mobile
Email: kelly.t.grubaugh@ILJIN.com

Subject equipment:

FEDERAL-MOGUL (MOOG) – Front wheel bearing 515082
FEDERAL-MOGUL (MOOG) – Front wheel bearing 515083
SKF USA – Front wheel bearing BR930639
SKF USA – Front wheel bearing BR930658
SKF USA – Front wheel bearing BR930695
SKF USA – Front wheel bearing BR930722

1. NHTSA Safety Recall Campaign Number: 13E-055

Manufacturer's assigned campaign number (where applicable): None

2. (a) The date notification to purchasers began:

The approved owner recall notice was sent to SKF for distribution to purchasers on **December 9, 2013**.

The approved owner recall notice was sent to Federal-Mogul for distribution to purchasers on **January 9, 2014**.

(b) The date notification of purchasers was completed:

ILJIN completed the notification of purchasers on **January 9, 2014**.

(c) The date notification to dealers and distributors began:

The original and amended Part 573 defect and noncompliance reports were sent to SKF and Federal-Mogul at the same time as they were submitted to NHTSA.

The approved recall notice was sent to SKF, who is ILJIN's distributor, on **December 9, 2013**.

The approved recall notice was sent to Federal-Mogul, who is ILJIN's distributor, on **January 9, 2014**.

(d) The date notification of dealers and distributors was completed:

The approved recall notice was sent to SKF, who is ILJIN's independent distributor, on **December 9, 2013**, with instructions to transmit a copy of the notice to SKF's dealers and retailers, as provided by 49 C.F.R. §577.7(c)(2)(iv).

ILJIN does not know the specific date on which SKF sent the notice to SKF's dealers and distributors, but SKF confirmed on **January 28, 2014**, that the notification to its dealers and distributors has been completed.

The approved recall notice was sent to Federal-Mogul, who is ILJIN's independent distributor, on **January 9, 2014**, with instructions to transmit a copy of the notice to Federal-Mogul's dealers and retailers, as provided by 49 C.F.R. §577.7(c)(2)(iv).

Federal-Mogul completed the notification of Federal-Mogul's dealers and distributors on **February 10, 2014**.

3. The total number of items of equipment involved:

FEDERAL-MOGUL (MOOG) – Front wheel bearing 515082	200
FEDERAL-MOGUL (MOOG) – Front wheel bearing 515083	570
SKF USA – Front wheel bearing BR930639	792
SKF USA – Front wheel bearing BR930658	1,512
SKF USA – Front wheel bearing BR930695	11,468
SKF USA – Front wheel bearing BR930722	252
TOTAL	14,794

NOTE: The number figures given in responses to numbers 4 and 5 below are to be stated in the cumulative (e.g., in consideration of any previous quarter's information).

4. (a) Total number inspected and remedied: 13,698

(b) Total number inspected, but determined NOT to require the remedy: 0

5. Numbers of items of equipment determined to be unreachable for inspection due to:

Export: Not yet determined.

Theft: No reports of theft at this time.

Scrapping: Not yet determined.

Failure to receive a notification of the recall: Not yet determined.

Other reasons (specify below):

Total number of items of equipment unreachable for inspection:
Not yet determined.

6. The number of items of equipment repaired and/or returned by dealers, distributors, and other retailers prior to sale: 13,698

10,709 items were repaired before distribution by SKF or Federal-Mogul to their dealers, distributors, and retailers.

2,989 items were returned by dealers, distributors, and retailers to SKF and Federal-Mogul before sale to purchasers.