Exceptional Quality. Unmatched Support.

September 5, 2014

IMPORTANT SAFETY RECALL NOTICE

[redacted]

Re: **FUEL PUMP SAFETY RECALL: NHTSA CAMPAIGN NUMBER: 14E-037**

THIS NOTICE IS SENT TO YOU IN ACCORDANCE WITH THE REQUIREMENTS OF THE NATIONAL TRAFFIC AND MOTOR VEHICLE SAFETY ACT. Airtex Products, LP has determined that a defect which relates to motor vehicle safety exists in certain E84070 Universal Electrical Fuel Pumps. Specifically, fuel pumps purchased from Airtex between December 11, 2013 and June 20, 2014. Records show that you may have purchased a pump subject to this recall.

Summary of Safety Related Defect

Airtex has determined that a defect in the manufacture of the fuel pump may cause the pump to leak fuel. Seals around electrical connectors on certain pumps shipped between December 11, 2013 and June 20, 2014 were not manufactured correctly. If the pump does not properly seal, fuel may escape, increasing the risk of a fire.

Our Remedy

Airtex will exchange fuel pump that you purchased at no charge, as well as pay for return shipment of the fuel pump that you purchased. If the pump has been installed, Airtex will pay for replacement of the pump. Please call the Airtex Customer Service Line at **1-800-880-3056** for processing instructions and assistance. The Customer Service Department is staffed between 7:30 a.m. and 4:30 p.m., central, Monday through Friday.

Complaints

If you believe that Airtex has failed or is unable to remedy the defect without charge within sixty days of your tender, you may submit a complaint related to this Notice to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. Alternatively, owners may call the toll-free Vehicle Safety Hotline at 1-888-327-4235 (TTY: 1-800-424-9153) or go to *http:/www.safercar.gov.*