IPC INFORMATION DISPLAY DEFAULTING TO ROUND TACHOMETER - BUILT ON OR BETWEEN 8/20/2013 AND 11/22/2013	TSB 14-0003

SB-10054909-9549

FORD:

2014 Fusion

ISSUE

Some 2014 Fusion vehicles built on or between 8/20/2013 and 11/22/2013, equipped with a 6F35 automatic transmission and MyFord Touch may exhibit the Instrument Panel Cluster (IPC) information display defaulting to the round tachometer each time the transmission range selector is placed in drive.

ACTION

Reprogram the IPC module to the latest calibration using IDS release 87.05 and higher. Calibration files may also be obtained at www.motorcraft.com.

OPERATION	DESCRIPTION	TIME
140003A	2014 Fusion: Reprogram The IPC (Do Not Use With Any Other Labor Operations)	0.3 Hr.

WARRANTY STATUS:

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage
Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

DEALER CODING

BASIC PART NO.	CONDITION CODE
10849	42

NOTE: The information contained in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service.The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article.The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supercede this information with updates.The most recent information is available through Ford Motor Company's on-line technical resources.